



SAURYAJYOTI RENEWABLES PVT LTD

REQUIRED PPE LIST Doc. No.: SRPL/SOP/002

Nature of work	Type of Work	Required PPE's/ Machinery	Required Documents	Remark
General work	1). Manual Material unloading & Shifting. 2). Painting work. 3). Housekeeping 4) Civil work	1. Helmet 2. Reflective jacket 3.Cut Resistance hand Gloves. 4). Safety Shoes. 5) Nose Mask 6). Ear plug 7) Rubber Gloves 8) Gum Boot. 9). White Goggles		1).All PPE's Should be ISI standard & Should be in Good Quality. 2).Helmet, jacket , safety Shoes & Cut resistance gloves is mandatory for all kind of work.
Height Work	1)Work on metal Roof 2) Installation work at Equipment.	1. Helmet 2. Reflective jacket 3.Cut Resistance hand Gloves. 4). Safety Shoes. 5) lanyard with fall arrestor 6).Full body harness with Shock absorber. 7). White Goggles	1) Onsite TPI Required for safety belt & lanyard.	1) 100% anchorage should be ensure during height activities. 2) single person single lanyard rule should follow.
Hot Work	1) Cutting/ welding / drilling	1. Helmet 2. Reflective jacket 3.Cut Resistance hand Gloves. 4). Safety Shoes. 5) white/ welding Face shield 6) White goggles for Drilling work 7) Black goggles For Fire Watcher. 8) Leather apron for welding & Cutting work 9) Leather hand Gloves 10. Fire Blanket		

Sunil Vila, 39B, Ibrahimpur Road, Jadavpur, Kolkata 700032

Phone: 9717088074/ 8902550652

E-mail: solar@ganapatiproductions.com/ganapatiproductions@gmail.com

Website:www.ganapatiproductions.com



SAURYAJYOTI RENEWABLES PVT LTD

Lifting work	material Lifting work	1). Module Lifting cage for Metal roof.	1). Onsite TPI of Lifting machine crane/hydra/Farana along with lifting tools (web sling , D-shackle etc) 2). Onsite TPI of module Lifting cage 3) legal documents of lifting machinery a) RC b) insurance c) Fitness Certificate d) PUC e) Valid DL (Specially for Crane operator 'crane ' should mention in DL. f)Physical Condition should be ok.	
Electrical Work	Cable Termination in client LT panel	1). Testing instrument(Multimeter, Meger, ERT) with valid Calibration certificate. 2) Electrical gloves	1). State Gov. wireman licenced person should be available During termination along with his mandatory Documents (ESIC , PF & Medical)	
Excavation work	Earth pit excavation	1) Mandatory PPE's. 2). Goggles 3) Ear buds 4) Nose mask	1). onsite TPI of DTH machine if excavation is doing by machinery. 2). All worker should have mandatory Legal Compliance Documents.	
Height work as per site condition	1). Cable tray / pipe Line Gi Strip drop	1). All mandatory PPE's for hight work 2) Boom lift & Scaffolding	1) On site TPI of machinery & Scaffolding. 2). Legal documents of machinery 3) scaffolding erection will be done by valid competent person only.	

Sunil Vila, 39B, Ibrahimpur Road, Jadavpur, Kolkata 700032

Phone: 9717088074/ 8902550652

E-mail: solar@ganapatiprducts.com/ganapatiprducts@gmail.com


Website:www.ganapatiprducts.com



SAURYAJYOTI RENEWABLES PVT LTD

Note:-

- 1).For any job related requirements apart from above found as per site condition. Intimation will be provide 3-4 days before.
- 2) PPE's stock should be maintained at site.



GANAPATI PRODUCTS

Sunil Vila, 39B, Ibrahimpur Road, Jadavpur, Kolkata 700032
Phone: 9717088074/ 8902550652
E-mail: solar@ganapatiproducs.com/ganapatiproducs@gmail.com
Website:www.ganapatiproducs.com



SAURYAJYOTI RENEWABLES PVT LTD



GANAPATI PRODUCTS

Sunil Vila, 39B, Ibrahimpur Road, Jadavpur, Kolkata 700032

Phone: 9717088074/ 8902550652

E-mail: solar@ganapatiproductions.com/ganapatiproductions@gmail.com

Website: www.ganapatiproductions.com