

(Ohm cm)	(S/cm)		(s)	(%)	(kOhms)	(cm2)	(cm)	(Ohm cm)	(S/cm)	(S/cm)
		3	10	+ Control (Al)	0					
		3	20	+ Control (Al)	0					
		3	30	+ Control (Al)	0					
0	#DIV/0!	3	Mean	+ Control (Al)	0	2.8274334	0.02	0	#DIV/0!	0
		3	10	- Control (acrylate)	1.00E+99					
		3	20	- Control (acrylate)	1.00E+99					
		3	30	- Control (acrylate)	1.00E+99					
1.41E+101	7.07E-102	3	Mean	- Control (acrylate)	1E+99	2.8274334	0.02	1.41E+101	7.07E-102	7.07E-102
		3	10	30	1540					
		3	20	30	1650					
		3	30	30	1740					
61261.057	1.632E-05	3	Mean	30	1643.3333	2.8274334	0.06	77440.259	1.291E-05	1.556E-05
		3	10	10	160000					
		3	20	10	160000					
		3	30	10	170000					
7539822.4	1.326E-07	3	Mean	10	163333.33	2.8274334	0.05	9236282.4	1.083E-07	1.392E-07
		3	10	1						
		3	20	1						
		3	30	1						
985831775	1.014E-09	3	Mean	3		2.8274334	0.03	0		1.004E-09
		3	10	0	1.00E+99					
		3	20	0	1.00E+99					
		3	30	0	1.00E+99					
1.41E+101	7.07E-102	3	Mean	0	1E+99	2.8274334	0.02	1.41E+101	7.07E-102	7.07E-102