

SPRING WELD LAB HOURS

MONDAY / WEDNESDAY NIGHTS:

5:00 PM - 8:30 PM

SATURDAYS:

6:00 AM - 12:00 PM

UA Welding Test, Recertification & Continuity

Description: Designed for people who must do recertification, continuity, or a welding test on any certifications. These Certifications may include PVC bonding, GFIR fusion recertification (polypro and polyethylene), Orbital, Medgas Brazing, Soldering & UA welding certs.

- **UA Welding Certs:** You must pre-qualify with one of the welding instructors, get signed off to test then turn the form in the day before test day by 12pm to Lisa Van Kirk or email the form to lisav@pipetrades.org
- **Recertification of Orbital, PVC, Soldering & Brazing, GFIR fusion:** You must come in on the 2nd Saturday of the month to recertify. **For Orbital Welding you must REGISTER by emailing Lisa Van Kirk at lisav@pipetrades.org.**
- **Continuity:** You must show up on the 2nd Saturday of the month at 7am. **NO REGISTRATION IS NEEDED**

<u>Date</u>	<u>Time</u>
January 13, 2024	7:00 AM
February 10, 2024	7:00 AM
March 9, 2024	7:00 AM
April 13, 2024	7:00 AM
May 11, 2024	7:00 AM
June 8, 2024	7:00 AM
July 13, 2024	7:00 AM
August 10, 2024	7:00 AM
September 14, 2024	7:00 AM
October 12, 2024	7:00 AM
November 2, 2024	7:00 AM
December 14, 2024	7:00 AM