



A New Strategy for Reserve Funding.

Our reserve study approach is simple. We provide you with the insight needed to make fast, accurate and informed decisions. We focus on understanding your situation and providing funding solutions that are designed with your goals in mind. By focusing on the detail and the big picture we provide the information you need to best manage your reserve fund and annual contributions.

As a long-term capital budget plan, the reserve study identifies the current status of the reserve fund and whether contributions to the fund are adequate to address future needs. The report helps the Association make necessary decisions regarding the development of their reserve fund and establish expectations in relation to the timing and cost of significant repair and replacement projects.

The reserve study recommends funding through smaller monthly contributions rather than risking large, unanticipated special assessments. Regular and ongoing reserve contributions are favored over special assessment as they help distribute expenses equally between current and future owners, and establish a stable contribution rate.

The reserve study contains 'forward looking' concepts which reflect expectations with respect to certain future events and potential financial performance. Although we believe at this time that the expectations reflected within the reserve study are reasonable, no assurances can be given that such expectations will prove correct. We recommend that the reserve study be updated annually to address changing circumstances and conditions.





6 CONTRIBUTION RANGE

Funding programs and strategies that are available to the Association.



14 PERCENT FUNDED

How well funded is the Association's reserve fund.

4 EXECUTIVE SUMMARY

Summary of reserve study outcomes and property related data.

5 KEY INSIGHTS

Snapshot of key data points, highlighting the strength of current funding strategies.

9 CURRENT FUNDING SUMMARY

Summary of current funding strategies and projected outcomes.

10 METHODOLOGY

The what, when, when and how of the reserve study process.

14 FINANCIAL ANALYSIS

Percent funded and the strength of the reserve account.

16 RESERVE COMPONENT LIST

List of reserve components, anticipated cost, remaining, and useful life estimates.

18 RESERVE EXPENSES

Projected expenses over the coming 30 years.

24 FULL FUNDING PLAN

Recommended funding plan and cash flow projection.

27 PHYSICAL ANALYSIS

Specific information regarding the physical condition of the property.

RESERVE STUDY GROUP This work is copyright and has been supplied under contract to the Association and/or its representatives. Apart from the client's right to reproduce and distribute copies of the report as required by its governing documents or state law, no part of this work may be reproduced by any process without the written permission from Reserve Study Group, LLC. Requests and inquiries concerning reproduction and rights should be addressed to the Reserve Study Group, 701 Fifth Ave, Suite 4200, Seattle WA 98104.

EXECUTIVE SUMMARY



PROPERTY SUMMARY

Eagle Ridge Homeowners' Association | Road Reserve ASSOCIATION NAME

LOCATION Arlington, WASHINGTON 98223

YEAR CONSTRUCTED 1983

NUMBER OF UNITS 146

FINANCIAL YEAR 2024 (January 1 2024 - December 31 2024)

REPORT LEVEL Level 1 Full Study with Site Visit

RESERVE FUND

PROJECT STARTING BALANCE ¹	\$43,696
FULLY FUNDED BALANCE, IDEAL	\$102,462
CURRENT PER UNIT DEFICIENCY/(SURPLUS) IN RESERVES	\$403
PERCENT FUNDED ²	43 %
INTEREST EARNED	3.00 %
INFLATION RATE ³	3.00 %

RESERVE CONTRIBUTIONS

CURRENT RESERVE FUND CONTRIBUTION	\$17,520
FULL FUNDING, MAXIMUM CONTRIBUTION	\$46,051
BASELINE FUNDING, MINIMUM CONTRIBUTION	\$43,106
SPECIAL ASSESSMENT	\$0

¹ Information in relation to the Association's finances were supplied by the Association's representative and is not audited.

² The ratio, at a particular point of time (the beginning of the Fiscal Year), of the actual (or projected) Reserve Balance to the Fully Funded Balance, expressed as a percentage (www.caionline.org). Used to highlight the strength of the Association's reserve fund.

³ Inflation rate is based upon the average annual increase of the Consumer Price Index (CPI) over the last 30-years, as published by the US Bureau of Labor Statistics (www.labor.gov).

KEY INSIGHTS



\$43,696

RESERVE ACCOUNT **BALANCE**

\$17,520


RESERVE CONTRIBUTION

\$2,633,715

PROJECTED EXPENSES **OVER 30 YEARS**

FULL FUNDING STRATEGY

Annual member contributions to the reserve fund are used to address those expenses too large or infrequent to be addressed through annual operating funds. The chart below highlights the outcome of the Full Funding strategy over the mid-to-long term.



Note: Figures based upon the expectation that the Association will continue to increase member contributions by an inflationary rate of 3.00% annually. Year-over-year change the result of projected expenses on the Association's reserve account.



CONTRIBUTION RANGE


We recommend that reserve contributions be evenly distributed between members over the life of a community. To achieve this goal, we establish an ideal contribution range within which the Association should establish ongoing payments.

\$43,106 MINIMUM BASELINE FUNDING \$46,051 **MAXIMUM FULL FUNDING**

\$17,520 **CURRENT FUNDING**

FUNDING STRATEGIES

The funding strategy chosen will have a direct impact on the growth of the Association's reserve fund. The chart below highlights the outcomes of the various funding strategies.



Note: Figures based upon the expectation that the Association will continue to increase member contributions by an inflationary rate of 3.00% annually. Year-over-year change the result of projected expenses on the Association's reserve account.



FULL FUNDING PLAN | SUMMARY

Year	Fully Funded Balance	Percentage Funded	Beginning Balance	Reserve Contribution	Special Assessment	Interest Earned	Reserve Expenditures	Ending Balance
2024	\$102,462	43%	\$43,696	\$46,051	\$0	\$2,002	\$0	\$91,748
2025	\$150,321	61%	\$91,748	\$47,432	\$0	\$3,464	\$0	\$142,644
2026	\$200,960	71%	\$142,644	\$48,855	\$0	\$4,980	\$2,122	\$194,358
2027	\$252,316	77%	\$194,358	\$50,321	\$0	\$5,311	\$84,992	\$164,997
2028	\$221,282	75%	\$164,997	\$51,830	\$0	\$5,727	\$0	\$222,555
2029	\$278,327	80%	\$222,555	\$53,385	\$0	\$7,164	\$20,867	\$262,238
2030	\$317,102	83%	\$262,238	\$54,987	\$0	\$8,692	\$0	\$325,917
2031	\$380,091	86%	\$325,917	\$56,636	\$0	\$10,627	\$0	\$393,180
2032	\$446,574	88%	\$393,180	\$58,336	\$0	\$11,002	\$111,197	\$351,321
2033	\$402,172	87%	\$351,321	\$60,086	\$0	\$11,441	\$0	\$422,848
2034	\$472,672	89%	\$422,848	\$61,888	\$0	\$13,614	\$0	\$498,350
2035	\$547,040	91%	\$498,350	\$63,745	\$0	\$15,865	\$2,768	\$575,191
2036	\$622,593	92%	\$575,191	\$65,657	\$0	\$18,241	\$0	\$659,089
2037	\$705,124	93%	\$659,089	\$67,627	\$0	\$19,074	\$114,223	\$631,567
2038	\$674,397	94%	\$631,567	\$69,656	\$0	\$19,946	\$3,025	\$718,144
2039	\$759,255	95%	\$718,144	\$71,745	\$0	\$22,387	\$15,580	\$796,697
2040	\$835,760	95%	\$796,697	\$73,898	\$0	\$25,009	\$0	\$895,604
2041	\$932,700	96%	\$895,604	\$76,115	\$0	\$27,564	\$29,751	\$969,531
2042	\$1,004,061	97%	\$969,531	\$78,398	\$0	\$28,276	\$132,415	\$943,789
2043	\$974,039	97%	\$943,789	\$80,750	\$0	\$29,525	\$0	\$1,054,064
2044	\$1,081,792	97%	\$1,054,064	\$83,173	\$0	\$32,815	\$3,612	\$1,166,440
2045	\$1,191,413	98%	\$1,166,440	\$85,668	\$0	\$36,278	\$0	\$1,288,386
2046	\$1,310,469	98%	\$1,288,386	\$88,238	\$0	\$39,975	\$0	\$1,416,599
2047	\$1,286,038	110%	\$1,416,599	\$90,885	\$0	\$40,819	\$202,845	\$1,345,457
2048	\$1,327,313	101%	\$1,345,457	\$93,611	\$0	\$41,768	\$0	\$1,480,837
2049	\$1,426,439	104%	\$1,480,837	\$96,420	\$0	\$45,871	\$0	\$1,623,128
2050	\$1,530,317	106%	\$1,623,128	\$99,312	\$0	\$50,119	\$4,313	\$1,768,246
2051	\$1,634,702	108%	\$1,768,246	\$102,292	\$0	\$54,582	\$0	\$1,925,119
2052	\$1,783,225	108%	\$1,925,119	\$105,361	\$0	\$31,380	\$1,863,586	\$198,274
2053	\$198,274	100%	\$198,274	\$108,521	\$0	\$6,940	\$42,418	\$271,317

\$46,051

3.00 %

PERCENTAGE ANNUAL ANNUAL CONTRIBUTION CONTRIBUTION INCREASE 3.00 %

ANNUAL INTEREST RATE



BASELINE FUNDING PLAN | SUMMARY

Year	Fully Funded Balance	Percentage Funded	Beginning Balance	Reserve Contribution	Special Assessment	Interest Earned	Reserve Expenditures	Ending Balance
2024	\$102,462	43%	\$43,696	\$43,106	\$0	\$1,957	\$0	\$88,760
2025	\$150,321	59%	\$88,760	\$44,400	\$0	\$3,329	\$0	\$136,488
2026	\$200,960	68%	\$136,488	\$45,732	\$0	\$4,749	\$2,122	\$184,847
2027	\$252,316	73%	\$184,847	\$47,104	\$0	\$4,977	\$84,992	\$151,936
2028	\$221,282	69%	\$151,936	\$48,517	\$0	\$5,286	\$0	\$205,738
2029	\$278,327	74%	\$205,738	\$49,972	\$0	\$6,609	\$20,867	\$241,452
2030	\$317,102	76%	\$241,452	\$51,471	\$0	\$8,016	\$0	\$300,939
2031	\$380,091	79%	\$300,939	\$53,016	\$0	\$9,823	\$0	\$363,778
2032	\$446,574	81%	\$363,778	\$54,606	\$0	\$10,064	\$111,197	\$317,252
2033	\$402,172	79%	\$317,252	\$56,244	\$0	\$10,361	\$0	\$383,857
2034	\$472,672	81%	\$383,857	\$57,932	\$0	\$12,385	\$0	\$454,173
2035	\$547,040	83%	\$454,173	\$59,669	\$0	\$14,479	\$2,768	\$525,553
2036	\$622,593	84%	\$525,553	\$61,460	\$0	\$16,688	\$0	\$603,701
2037	\$705,124	86%	\$603,701	\$63,303	\$0	\$17,347	\$114,223	\$570,129
2038	\$674,397	85%	\$570,129	\$65,202	\$0	\$18,037	\$3,025	\$650,343
2039	\$759,255	86%	\$650,343	\$67,159	\$0	\$20,284	\$15,580	\$722,205
2040	\$835,760	86%	\$722,205	\$69,173	\$0	\$22,704	\$0	\$814,082
2041	\$932,700	87%	\$814,082	\$71,248	\$0	\$25,045	\$29,751	\$880,625
2042	\$1,004,061	88%	\$880,625	\$73,386	\$0	\$25,533	\$132,415	\$847,129
2043	\$974,039	87%	\$847,129	\$75,587	\$0	\$26,548	\$0	\$949,264
2044	\$1,081,792	88%	\$949,264	\$77,855	\$0	\$29,592	\$3,612	\$1,053,098
2045	\$1,191,413	88%	\$1,053,098	\$80,191	\$0	\$32,796	\$0	\$1,166,085
2046	\$1,310,469	89%	\$1,166,085	\$82,596	\$0	\$36,221	\$0	\$1,284,903
2047	\$1,286,038	100%	\$1,284,903	\$85,074	\$0	\$36,781	\$202,845	\$1,203,912
2048	\$1,327,313	91%	\$1,203,912	\$87,627	\$0	\$37,432	\$0	\$1,328,971
2049	\$1,426,439	93%	\$1,328,971	\$90,255	\$0	\$41,223	\$0	\$1,460,449
2050	\$1,530,317	95%	\$1,460,449	\$92,963	\$0	\$45,143	\$4,313	\$1,594,242
2051	\$1,634,702	98%	\$1,594,242	\$95,752	\$0	\$49,264	\$0	\$1,739,258
2052	\$1,783,225	98%	\$1,739,258	\$98,625	\$0	\$25,703	\$1,863,586	\$0
2053	\$198,274	0%	\$0	\$101,583	\$0	\$887	\$42,418	\$60,053

\$43,106

ANNUAL CONTRIBUTION

3.00 %

PERCENTAGE ANNUAL CONTRIBUTION INCREASE 3.00 %

ANNUAL INTEREST RATE



CURRENT FUNDING PLAN | SUMMARY

Year	Fully Funded Balance	Percentage Funded	Beginning Balance	Reserve Contribution	Special Assessment	Interest Earned	Reserve Expenditures	Ending Balance
2024	\$102,462	43%	\$43,696	\$17,520	\$0	\$1,574	\$0	\$62,790
2025	\$150,321	42%	\$62,790	\$18,046	\$0	\$2,154	\$0	\$82,990
2026	\$200,960	41%	\$82,990	\$18,587	\$0	\$2,737	\$2,122	\$102,191
2027	\$252,316	41%	\$102,191	\$19,145	\$0	\$2,078	\$84,992	\$38,422
2028	\$221,282	17%	\$38,422	\$19,719	\$0	\$1,448	\$0	\$59,589
2029	\$278,327	21%	\$59,589	\$20,310	\$0	\$1,779	\$20,867	\$60,812
2030	\$317,102	19%	\$60,812	\$20,920	\$0	\$2,138	\$0	\$83,870
2031	\$380,091	22%	\$83,870	\$21,547	\$0	\$2,839	\$0	\$108,257
2032	\$446,574	24%	\$108,257	\$22,194	\$0	\$1,913	\$111,197	\$21,166
2033	\$402,172	5%	\$21,166	\$22,860	\$0	\$978	\$0	\$45,004
2034	\$472,672	10%	\$45,004	\$23,545	\$0	\$1,703	\$0	\$70,252
2035	\$547,040	13%	\$70,252	\$24,252	\$0	\$2,430	\$2,768	\$94,165
2036	\$622,593	15%	\$94,165	\$24,979	\$0	\$3,200	\$0	\$122,344
2037	\$705,124	17%	\$122,344	\$25,729	\$0	\$2,343	\$114,223	\$36,193
2038	\$674,397	5%	\$36,193	\$26,501	\$0	\$1,438	\$3,025	\$61,107
2039	\$759,255	8%	\$61,107	\$27,296	\$0	\$2,009	\$15,580	\$74,832
2040	\$835,760	9%	\$74,832	\$28,114	\$0	\$2,667	\$0	\$105,613
2041	\$932,700	11%	\$105,613	\$28,958	\$0	\$3,156	\$29,751	\$107,976
2042	\$1,004,061	11%	\$107,976	\$29,827	\$0	\$1,700	\$132,415	\$7,088
2043	\$974,039	1%	\$7,088	\$30,721	\$0	\$673	\$0	\$38,483
2044	\$1,081,792	4%	\$38,483	\$31,643	\$0	\$1,575	\$3,612	\$68,088
2045	\$1,191,413	6%	\$68,088	\$32,592	\$0	\$2,532	\$0	\$103,212
2046	\$1,310,469	8%	\$103,212	\$33,570	\$0	\$3,600	\$0	\$140,382
2047	\$1,286,038	11%	\$140,382	\$34,577	\$0	\$1,687	\$202,845	-\$26,198
2048	\$1,327,313	0%	-\$26,198	\$35,615	\$0	\$0	\$0	\$9,416
2049	\$1,426,439	1%	\$9,416	\$36,683	\$0	\$833	\$0	\$46,932
2050	\$1,530,317	3%	\$46,932	\$37,783	\$0	\$1,910	\$4,313	\$82,312
2051	\$1,634,702	5%	\$82,312	\$38,917	\$0	\$3,053	\$0	\$124,282
2052	\$1,783,225	7%	\$124,282	\$40,084	\$0	\$0	\$1,863,586	-\$1,699,219
2053	\$198,274	0%	-\$1,699,219	\$41,287	\$0	\$0	\$42,418	-\$1,700,350

\$17,520

3.00 %

PERCENTAGE ANNUAL ANNUAL CONTRIBUTION CONTRIBUTION INCREASE 3.00 %

ANNUAL INTEREST RATE

METHODOLOGY



An important aspect of living in a common area development such as a cooperative, condominium, or homeowner Association is the community's ownership and commitment to maintain its common areas.

Association members have a vested interest in maintaining and preserving their investment. To meet these obligations, the Association should prudently prepare for the future and contribute funds into a reserve account. Periodic contributions provide the freedom to gradually accumulate funds for anticipated expenditures while limiting the need to raise large sums of money through alternative means, such as special assessments.

When implementing a policy to fund major repair or replacement, the Board must educate owners about the benefits of accumulating reserve funds in advance through periodic contributions. Benefits of a systematic accumulation of funds include:

- having assurance that funds for major repairs and replacements will be available when needed;
- development of an equitable method of charging both current and future owners for ongoing use of assets:
- preservation of the market value of individual units; and
- compliance with the governing documents, statutes, mortgages, and other similar requirements.

A reserve study recommends the preferable mode of funding through smaller monthly contributions rather than facing large, unanticipated special assessments. The reserve study provides an Association with access to information and materials that will assist them in making timely and informed decisions about their reserve fund and contributions.

A reserve study is the sum of two parts: the physical and financial analysis. The physical analysis is a result of the on-site collection and review of data specific to the property's reserve components, common areas, and limited common areas. Through an onsite inspection and the use of source materials, the Reserve Specialist quantifies and establishes the reserve component inventory and assesses the physical condition of the Association's reserve components. Data from the physical analysis is used to define the scope and timing of future anticipated expenses.

The financial analysis evaluates the condition of the Association's reserve fund in relation to its income and anticipated expenses. It appraises the adequacy of the reserve fund, and associated member contributions, against the current and future expenditures of the Association. To adequately forecast these expenditures over the 30-year projection period, current costs, projected inflation, and interest rates must be established. Recommendations are then provided to establish a reserve fund that addresses anticipated expenses, without having to resort to special assessments.

Due to the long-term nature of a reserve study, certain assumptions must be made. Every effort has been made to ensure that the recommendations are based upon reliable and experienced sources in the building industry. However, there can be no quarantee that events will occur at the predicted specific intervals, or that they will occur at all. Any reserve study must be viewed in the light of circumstances existing at the actual time of the study.

PHYSICAL ANALYSIS

As part of this reserve study a comprehensive list of reserve components (major common and limited common elements) has been compiled. Estimates for the useful life, remaining life, plus current repair and replacement costs for each of these reserve components have been calculated. This list is not intended to be exhaustive. However, an inaccurate or incomplete list of components can have an adverse impact upon the Association's long-term funding plan.

Site Inspection

A site inspection is conducted to assess the general condition of the property and its common areas. The on-site inspection is visual in nature, and no destructive or invasive testing is conducted. Observations are recorded using a representative sampling of the Association's common areas and reserve components. The component inventory and associated field measurements are also substantiated as part of the inspection.

Reserve Components

Determination of what constitutes a reserve component is dependent on a number of factors. A four-part test is generally used to distinguish a reserve item from an operational or maintenance expense. A component is included as a reserve item only if it satisfies ALL criteria outlined below:

- It is part of the Association's common and limited common area responsibilities.
- It has a predictable useful service life.
- Its useful life fits within the projection period. This means that components with a life of 30 years or more may not be included as part of the report if it is determined that they will last beyond the projection period.
- Its cost for repair or replacement is too high to include as part of the operating budget.

The components of common property that an Association includes in its reserve funding plan are also dependent on the type of project, the construction properties and the Association's applicable governing documents and state statutes.

Component Useful Life

The useful life of a reserve component relates to the number of years it is expected to last, given reasonable care and maintenance. The prediction of reserve and building component life can be no more than an informed estimate based upon information made available at the time of the report's development. Consideration is given to vendor recommendations, material warranty information provided at the time of the report's development, along with other published sources. The data and service life estimates in this report are based on information gathered from various groups and industry sources as outlined below:

- Historical data and feedback from the Association:
- Management groups and maintenance managers;
- Manufacturer recommendations and industry standards:
- Published sources of service life data:
- Manufacturers' and suppliers' data.



Component Remaining Useful Life

The remaining life of a reserve component refers to the number of years left before an item's expected repair or replacement. A component's remaining life is contingent upon the following factors:

- Age/years in service:
- Physical condition;
- Frequency and quality of inspections and maintenance;
- General use:
- Environment, impact of weather and building location;
- Installation methods that meets or exceed industry standards;
- Design and quality of materials used.

In addition to deterioration or anticipated failure of a component, the longevity may be impacted by obsolescence. The accuracy of the estimate is contingent upon reliable information made available at the time of the report's development. It is important to note that even with the highest degree of diligence and experience, outcomes will vary, and no guarantee can be given as to the timing or service life of the reserve components. All service life assessments in this report are based on the assumption that installation is carried out in accordance with manufacturer's recommendations and installation instructions, together with industry standards of workmanship.

FINANCIAL ANALYSIS

An Association, like any business entity, must prepare financially for the replacement and repair of its assets. Reserve study funding analysis is an important part of the annual budget process. Reserve funding should be reviewed at least once annually to help determine the annual assessment to be charged to members. The following elements are used in the financial analysis.

Recommended Funding Rate

We advocate a program of regular reserve fund contributions and promote a gradual means of reserving for future repair and replacement expenses. Recommended contributions are set at a level where they require only minor annual increases. The rate is designed to distribute the anticipated cost of common property ownership equitably between all members over the entire projection period.

Fully Funded Balance

The Fully Funded balance is equal to the total depreciable cost of all the Association's reserve components. It is determined by dividing each reserve component's cost by its useful life, and multiplying that by the number of years the component has been in service (effectively its age). In essence, the depreciated or 'used up' value of a component is utilized to establish an amount that the Association should have saved by a particular time. The recommendations in this report are based upon a Full Funding plan, which sets the goal of achieving one hundred percent fully funded reserves by the end of the 30-year projection period. We advocate full funding as we feel that this approach provides a solid platform to address future needs, thus dramatically reducing the need for special assessment.



Percent Funded

An Association's reserve fund status is assessed by comparing the ratio of actual or projected funds available verses how much they 'should have saved'. The result is presented as a percentage and is commonly known as "percent funded". In other words, percent funded is calculated by dividing the Association's current reserve fund balance by the fully funded balance. This equation is an industry measure of how well prepared an Association is to meet its current and future repair and replacement obligations. Percent funded highlights the strength of the Association's reserve account in relation to the anticipated costs of repair and replacement.

Reserve Component Cost

Current cost estimates for reserve components are derived from a variety of sources but typically are based on cost data sourced from national construction estimators (R.S. Means) and vendor pricing acquired from regional contractors and suppliers. All cost estimates formulated from national estimators are based upon the latest specific geographical information for the area. Future cost estimates are determined by applying the assumed annual inflation rate to the current cost of each component.

Individual cost estimates are for budgeting purposes only. Actual construction costs can vary significantly due to economies of scale, material availability, labor, seasonal considerations, and other factors beyond our control. We recommend that project costs be substantiated well in advance of the anticipated date of repair and replacement. A detailed evaluation by a qualified professional should also be undertaken to establish the scope and budget of each project.

Cost estimates do not account for permits, architectural, or project management fees that may be required. Allowances and contingencies must also be added to the total as the scope of work is defined.

Inflation Rate

The effect of inflation on the cost of reserve components is a key factor in the financial projections. Historically, the cost of construction materials and labor rise at a higher rate than that experienced by the general economy. RSG has chosen to use an inflationary multiplier that is somewhat higher than the current general consumer index for inflation. The rate used is based upon the historical average of inflation over the last 30 years. This rate reflects a realistic appreciation of future costs for reserve components and assists the Association in adequately budgeting for increasing cost.

Interest Rate

The interest rate used in this report is formulated on a conservative rate of return. Unless otherwise advised by the Association, an assumed net interest rate of 1.00% is used. RSG offers no guarantee or opinion in relation to investment decisions made by the Association or the rate of return achieved.

Current Reserve Fund Balance

The analysis, recommendations, and financial projections made within this report are heavily reliant on information provided by the Association and its representatives. The starting reserve fund balance (current or projected) and member contribution totals are supplied by these sources. This information has not been audited nor have the financial projections or recommendations.

FINANCIAL ANALYSIS



This section of the report is intended to provide the association with the awareness to adequately plan for the ongoing major maintenance, repair and replacement of their common property components. The recommendations included within this report represent one scenario, and are not intended to represent the only means of achieving the association's goals. We recommend that the Board of Directors use the following information as a guide in planning for their future objectives.

Percent Funded

The Percent Funded equation is the industry measure of how well prepared an association is to meet its current and future repair and replacement obligations. Percent funded highlights the strength of the association's reserve account in relation to its anticipated costs of repair and replacement. The higher the funded level, the less exposed an association is to market conditions, unanticipated expenses or events, and fluctuations in the general economy.



An Association at or below a funding level of 30% has an increased risk of requiring special assessments to meet their ongoing obligations, as compared to Associations with higher funding levels. A level of funding at and above 60% is categorized as good or well funded. We recommend that associations look to achieve and maintain funding levels at and above 60%, with a preference to being 100% funded.



Funding Goals

There is a range of funding alternatives available to the association. In our opinion the strategy chosen should not only meet the immediate needs and risk tolerance of current members, but also the longer term needs of the association.

The association needs to establish a reserve contribution rate which, at a minimum, meets their anticipated financial needs without having to resort to special assessment or deferred maintenance. In addition, the funding goal needs to be prudent enough to meet the expectations of current members while not unfairly burdening future owners.



FULL FUNDING

Establishes a goal of achieving one hundred percent fully funded reserves by the end of the projection period.

THRESHOLD FUNDING

Sets out to keep the cash reserves above a specified dollar or percent funded amount for the duration of the projection period.

BASELINE FUNDING

Establishes a goal of maintaining a reserve account balance above zero dollars throughout the study period.

The minimum funding goal needed to meet planned expenditure is Baseline Funding. Baseline Funding maintains the reserve account at or above zero dollars, but leaves the association with no contingency to address unanticipated outcomes. Threshold funding is a strategy designed to provide for this contingency by keeping cash reserves above a specific dollar amount or percent funded level.

The reserve fund plan highlighted in this report is based upon the Full Funding program of reserve contributions. The Full Funding plan highlights an ideal level of contributions which will enable an association to be 100% funded by the end of the projection period. As stated previously, we recommend that the association implement a program that moves them toward and maintains a funding level of 60-100%.



RESERVE COMPONENT LIST

Component	Useful Life	Remaining Useful Life	Quantity	Unit of Measure	Unit Cost	Current Cost
General Site - Private Road, Asphalt, Repair & Overlay	30	28	421000	SF	\$1.75	\$736,750
General Site - Private Road, Asphalt, Repair & Seal Coat	5	3	421000	SF	\$0.18	\$75,780
General Site - Private Road, Concrete, Curb, Repair Allowance	5	3	1	Lump Sum	\$2,000.00	\$2,000
General Site - Vehicular Entry Gate, Operators, Replace	12	5	4	Each	\$4,000.00	\$16,000
General Site - Vehicular Entry Gate, Access Control, Replace	15	8	1	Lump Sum	\$8,000.00	\$8,000
General Site - Vehicular Entry Gates, Replace	30	23	2	Each	\$7,500.00	\$15,000
General Site - Entry Monument, Signage, Replace	30	15	1	Each	\$10,000.00	\$10,000
General Site - Signage, General, Allowance	3	2	1	Lump Sum	\$2,000.00	\$2,000

TOTALS \$865,530

Readers should be aware that certain property elements are considered 'long life' elements and are not accounted for within the reserve study in conjunction with elements that are or can be managed as part of the Association's operating budget.

Cost estimates do not account for permits, architectural, or project management fees that may be required. Allowances and contingencies must also be added to the total as the scope of work is defined.



FULLY FUNDED BALANCE

Component	Current Cost	Current Fully Funded Balance	Annual Cost	% Annual Cost
General Site - Private Road, Asphalt, Repair & Overlay	\$736,750	\$49,117	\$24,558	56.48%
General Site - Private Road, Asphalt, Repair & Seal Coat	\$75,780	\$30,312	\$15,156	34.86%
General Site - Private Road, Concrete, Curb, Repair Allowance	\$2,000	\$800	\$400	0.92%
General Site - Vehicular Entry Gate, Operators, Replace	\$16,000	\$9,333	\$1,333	3.07%
General Site - Vehicular Entry Gate, Access Control, Replace	\$8,000	\$3,733	\$533	1.23%
General Site - Vehicular Entry Gates, Replace	\$15,000	\$3,500	\$500	1.15%
General Site - Entry Monument, Signage, Replace	\$10,000	\$5,000	\$333	0.77%
General Site - Signage, General, Allowance	\$2,000	\$667	\$667	1.53%
TOTALS	\$865,530	\$102,462	\$43,481	100%



RESERVE EXPENSES 1-5 YEARS

Component	2024	2025	2026	2027	2028
General Site - Private Road, Asphalt, Repair & Overlay	\$0	\$0	\$0	\$0	\$0
General Site - Private Road, Asphalt, Repair & Seal Coat	\$0	\$0	\$0	\$82,807	\$0
General Site - Private Road, Concrete, Curb, Repair Allowance	\$0	\$0	\$0	\$2,185	\$0
General Site - Vehicular Entry Gate, Operators, Replace	\$0	\$0	\$0	\$0	\$0
General Site - Vehicular Entry Gate, Access Control, Replace	\$0	\$0	\$0	\$0	\$0
General Site - Vehicular Entry Gates, Replace	\$0	\$0	\$0	\$0	\$0
General Site - Entry Monument, Signage, Replace	\$0	\$0	\$0	\$0	\$0
General Site - Signage, General, Allowance	\$0	\$0	\$2,122	\$0	\$0
Annual Expenditure	\$0	\$0	\$2,122	\$84,992	\$0



RESERVE EXPENSES 6-10 YEARS

Component	2029	2030	2031	2032	2033
General Site - Private Road, Asphalt, Repair & Overlay	\$0	\$0	\$0	\$0	\$0
General Site - Private Road, Asphalt, Repair & Seal Coat	\$0	\$0	\$0	\$95,996	\$0
General Site - Private Road, Concrete, Curb, Repair Allowance	\$0	\$0	\$0	\$2,534	\$0
General Site - Vehicular Entry Gate, Operators, Replace	\$18,548	\$0	\$0	\$0	\$0
General Site - Vehicular Entry Gate, Access Control, Replace	\$0	\$0	\$0	\$10,134	\$0
General Site - Vehicular Entry Gates, Replace	\$0	\$0	\$0	\$0	\$0
General Site - Entry Monument, Signage, Replace	\$0	\$0	\$0	\$0	\$0
General Site - Signage, General, Allowance	\$2,319	\$0	\$0	\$2,534	\$0
Annual Expenditure	\$20,867	\$0	\$0	\$111,197	\$0



RESERVE EXPENSES 11-15 YEARS

Component	2034	2035	2036	2037	2038
General Site - Private Road, Asphalt, Repair & Overlay	\$0	\$0	\$0	\$0	\$0
General Site - Private Road, Asphalt, Repair & Seal Coat	\$0	\$0	\$0	\$111,285	\$0
General Site - Private Road, Concrete, Curb, Repair Allowance	\$0	\$0	\$0	\$2,937	\$0
General Site - Vehicular Entry Gate, Operators, Replace	\$0	\$0	\$0	\$0	\$0
General Site - Vehicular Entry Gate, Access Control, Replace	\$0	\$0	\$0	\$0	\$0
General Site - Vehicular Entry Gates, Replace	\$0	\$0	\$0	\$0	\$0
General Site - Entry Monument, Signage, Replace	\$0	\$0	\$0	\$0	\$0
General Site - Signage, General, Allowance	\$0	\$2,768	\$0	\$0	\$3,025
Annual Expenditure	\$0	\$2,768	\$0	\$114,223	\$3,025



RESERVE EXPENSES 16-20 YEARS

Component	2039	2040	2041	2042	2043
General Site - Private Road, Asphalt, Repair & Overlay	\$0	\$0	\$0	\$0	\$0
General Site - Private Road, Asphalt, Repair & Seal Coat	\$0	\$0	\$0	\$129,010	\$0
General Site - Private Road, Concrete, Curb, Repair Allowance	\$0	\$0	\$0	\$3,405	\$0
General Site - Vehicular Entry Gate, Operators, Replace	\$0	\$0	\$26,446	\$0	\$0
General Site - Vehicular Entry Gate, Access Control, Replace	\$0	\$0	\$0	\$0	\$0
General Site - Vehicular Entry Gates, Replace	\$0	\$0	\$0	\$0	\$0
General Site - Entry Monument, Signage, Replace	\$15,580	\$0	\$0	\$0	\$0
General Site - Signage, General, Allowance	\$0	\$0	\$3,306	\$0	\$0
Annual Expenditure	\$15,580	\$0	\$29,751	\$132,415	\$0



RESERVE EXPENSES 21-25 YEARS

Component	2044	2045	2046	2047	2048
General Site - Private Road, Asphalt, Repair & Overlay	\$0	\$0	\$0	\$0	\$0
General Site - Private Road, Asphalt, Repair & Seal Coat	\$0	\$0	\$0	\$149,558	\$0
General Site - Private Road, Concrete, Curb, Repair Allowance	\$0	\$0	\$0	\$3,947	\$0
General Site - Vehicular Entry Gate, Operators, Replace	\$0	\$0	\$0	\$0	\$0
General Site - Vehicular Entry Gate, Access Control, Replace	\$0	\$0	\$0	\$15,789	\$0
General Site - Vehicular Entry Gates, Replace	\$0	\$0	\$0	\$29,604	\$0
General Site - Entry Monument, Signage, Replace	\$0	\$0	\$0	\$0	\$0
General Site - Signage, General, Allowance	\$3,612	\$0	\$0	\$3,947	\$0
Annual Expenditure	\$3,612	\$0	\$0	\$202,845	\$0




RESERVE EXPENSES 26-30 YEARS


Component	2049	2050	2051	2052	2053
General Site - Private Road, Asphalt, Repair & Overlay	\$0	\$0	\$0	\$1,685,631	\$0
General Site - Private Road, Asphalt, Repair & Seal Coat	\$0	\$0	\$0	\$173,379	\$0
General Site - Private Road, Concrete, Curb, Repair Allowance	\$0	\$0	\$0	\$4,576	\$0
General Site - Vehicular Entry Gate, Operators, Replace	\$0	\$0	\$0	\$0	\$37,705
General Site - Vehicular Entry Gate, Access Control, Replace	\$0	\$0	\$0	\$0	\$0
General Site - Vehicular Entry Gates, Replace	\$0	\$0	\$0	\$0	\$0
General Site - Entry Monument, Signage, Replace	\$0	\$0	\$0	\$0	\$0
General Site - Signage, General, Allowance	\$0	\$4,313	\$0	\$0	\$4,713
Annual Expenditure	\$0	\$4,313	\$0	\$1,863,586	\$42,418



FULL FUNDING PLAN 1-10 YEARS

YEAR 1-10	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033
Fully Funded Balance	\$102,462	\$150,321	\$200,960	\$252,316	\$221,282	\$278,327	\$317,102	\$380,091	\$446,574	\$402,172
Percentage Funded (%)	43%	61%	71%	77%	75%	80%	83%	86%	88%	87%
Beginning Balance	\$43,696	\$91,748	\$142,644	\$194,358	\$164,997	\$222,555	\$262,238	\$325,917	\$393,180	\$351,321
Reserve Contribution	\$46,051	\$47,432	\$48,855	\$50,321	\$51,830	\$53,385	\$54,987	\$56,636	\$58,336	\$60,086
Avg Unit Contribution (mth)	\$26.28	\$27.07	\$27.89	\$28.72	\$29.58	\$30.47	\$31.39	\$32.33	\$33.30	\$34.30
Contribution Increase (%)	0.00%	3.00%	3.00%	3.00%	3.00%	3.00%	3.00%	3.00%	3.00%	3.00%
Special Assessment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Interest Earned	\$2,002	\$3,464	\$4,980	\$5,311	\$5,727	\$7,164	\$8,692	\$10,627	\$11,002	\$11,441
Reserve Expenditures	\$0	\$0	\$2,122	\$84,992	\$0	\$20,867	\$0	\$0	\$111,197	\$0
ENDING BALANCE	\$91,748	\$142,644	\$194,358	\$164,997	\$222,555	\$262,238	\$325,917	\$393,180	\$351,321	\$422,848









FULL FUNDING PLAN 11-20 YEARS

YEAR 11-20	2034	2035	2036	2037	2038	2039	2040	2041	2042	2043
Fully Funded Balance	\$472,672	\$547,040	\$622,593	\$705,124	\$674,397	\$759,255	\$835,760	\$932,700	\$1,004,061	\$974,039
Percentage Funded (%)	89%	91%	92%	93%	94%	95%	95%	96%	97%	97%
Beginning Balance	\$422,848	\$498,350	\$575,191	\$659,089	\$631,567	\$718,144	\$796,697	\$895,604	\$969,531	\$943,789
Reserve Contribution	\$61,888	\$63,745	\$65,657	\$67,627	\$69,656	\$71,745	\$73,898	\$76,115	\$78,398	\$80,750
Avg Unit Contribution (mth)	\$35.32	\$36.38	\$37.48	\$38.60	\$39.76	\$40.95	\$42.18	\$43.44	\$44.75	\$46.09
Contribution Increase (%)	3.00%	3.00%	3.00%	3.00%	3.00%	3.00%	3.00%	3.00%	3.00%	3.00%
Special Assessment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Interest Earned	\$13,614	\$15,865	\$18,241	\$19,074	\$19,946	\$22,387	\$25,009	\$27,564	\$28,276	\$29,525
Reserve Expenditures	\$0	\$2,768	\$0	\$114,223	\$3,025	\$15,580	\$0	\$29,751	\$132,415	\$0
ENDING BALANCE	\$498,350	\$575,191	\$659,089	\$631,567	\$718,144	\$796,697	\$895,604	\$969,531	\$943,789	\$1,054,064









FULL FUNDING PLAN 21-30 YEARS

YEAR 21-30	2044	2045	2046	2047	2048	2049	2050	2051	2052	2053
Fully Funded Balance	\$1,081,792	\$1,191,413	\$1,310,469	\$1,286,038	\$1,327,313	\$1,426,439	\$1,530,317	\$1,634,702	\$1,783,225	\$198,274
Percentage Funded (%)	97%	98%	98%	110%	101%	104%	106%	108%	108%	100%
Beginning Balance	\$1,054,064	\$1,166,440	\$1,288,386	\$1,416,599	\$1,345,457	\$1,480,837	\$1,623,128	\$1,768,246	\$1,925,119	\$198,274
Reserve Contribution	\$83,173	\$85,668	\$88,238	\$90,885	\$93,611	\$96,420	\$99,312	\$102,292	\$105,361	\$108,521
Avg Unit Contribution (mth)	\$47.47	\$48.90	\$50.36	\$51.87	\$53.43	\$55.03	\$56.69	\$58.39	\$60.14	\$61.94
Contribution Increase (%)	3.00%	3.00%	3.00%	3.00%	3.00%	3.00%	3.00%	3.00%	3.00%	3.00%
Special Assessment	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Interest Earned	\$32,815	\$36,278	\$39,975	\$40,819	\$41,768	\$45,871	\$50,119	\$54,582	\$31,380	\$6,940
Reserve Expenditures	\$3,612	\$0	\$0	\$202,845	\$0	\$0	\$4,313	\$0	\$1,863,586	\$42,418
ENDING BALANCE	\$1,166,440	\$1,288,386	\$1,416,599	\$1,345,457	\$1,480,837	\$1,623,128	\$1,768,246	\$1,925,119	\$198,274	\$271,317





PHYSICAL ANALYSIS



This section of the report provides specific information regarding the physical condition of the property and common area assets. The data that follows is a result of the visual [non-intrusive] site review.

SITE INSPECTION

An on-site field survey was conducted to assess the general condition of the property and its reserve components. The survey was visual in nature, and no destructive or invasive testing was conducted. Observations were recorded using a representative sampling of the Association's common areas and reserve components. The component inventory and associated field measurements were also substantiated as part of the inspection. Due to the general and non-invasive nature of the site inspection, RSG cannot comment on components and conditions not visible to the naked eye.

MAINTENANCE GUIDE

The Maintenance guide focuses on reserve components that account for a significant percentage of the Association's reserve fund budget. Ongoing review and maintenance of all common area assets is generally recommended, although in some cases it is critical that such activities occur on a frequent and regular basis. Condition and performance of the Association's common areas assets is contingent on the implementation of a comprehensive program of preventative maintenance.

COMPONENT INVENTORY

The component inventory summarizes associated costs of each reserve component, and additionally highlights those components which require further review. The inventory provides a visual reference point for understanding the Association 's common area responsibilities.






A visual noninvasive inspection of the property was conducted on April 19th 2023. Recommendations contained within the report are based upon conditions viewed as part of the site inspection as well as reference materials obtained from the client, public resources and associated vendors.





The following inventory summarizes the key data points of each reserve component funded through the Association's reserves. The list of components is unique to the Association and may serve as a general guide in determining the current condition and level of care needed to adequately maintain each component.








Currrent Cost \$75,780

Estimated Quantity 421000 SF

Work Required Maintain Action Required 2027



Currrent Cost \$2,000 Estimated Quantity

1

Lump Sum

Work Required Repair





Current Cost \$16,000 Estimated Quantity
4
Each

Work Required Replace Action Required 2029



Currrent Cost \$8,000 Estimated Quantity

1

Lump Sum

Work Required Replace



General Site - Vehicular Entry Gates, Replace

Currrent Cost \$15,000 Estimated Quantity
2
Each

Work Required Replace Action Required 2047



General Site - Entry Monument, Signage, Replace

Currrent Cost \$10,000 Estimated Quantity 1
Each

Work Required Repair





Currrent Cost \$2,000 Estimated Quantity

1

Lump Sum

Work Required Replace

DISCLOSURES



As a guideline for establishing and spending reserves, it is assumed that the reserve study will be regularly updated to address the Association's changing physical and financial circumstances. As such this report is valid at the date shown and Reserve Study Group, LLC (RSG) cannot be held responsible for subsequent changes in physical/chemical environmental conditions and/or legislation over which we have no control.

This reserve study is based on visual inspections of the physical plant's major components. No invasive or destructive testing, or testing of materials was conducted during the inspections, or at any other time during the preparation of this report. It is assumed that all building and ancillary components have been designed and constructed properly and that life cycles will approximate normal industry performance standards. RSG shall not be responsible for accurate determination of remaining life expectancies of components that may have been improperly designed and constructed. Our opinions of the remaining life expectancy of the property's components do not represent a guarantee or warranty of performance in relation to the product, materials or workmanship.

Cost estimates used represent a preliminary opinion only and are neither a quote nor a warranty of actual costs that may be incurred. These estimates are based on typical cost data that may not fully characterize the scope of the underlying property conditions. It should be anticipated that actual cost outcomes will be impacted by varying physical and economic conditions, maintenance practices, changes in technology, and future regulatory actions.

The authors of this report make no representation or warranty, expressed or implied, with respect to the contents of this publication or any part thereof and cannot accept any legal responsibility or liability for any inaccuracies, errors or omissions contained in this publication or any part thereof. Our best professional judgment has been used, however certain facts forming the basis of this report are subject to professional interpretation and differing conclusions could be reached.

RSG nor any of its representatives, agents or employees maintain management roles or vested interest in, or have other business relationships with the Association. There is no perceived or actual conflicts of interest between RSG and the Association. Our reserve studies are prepared by a reserve study professional and also comply with the requirements of the Washington Unified Common Interest Act (WUCIOA).

This reserve study should be reviewed carefully. It may not include all common and limited common element components that will require major maintenance, repair, or replacement in future years, and may not include regular contributions to a reserve account for the cost of such maintenance, repair, or replacement. The failure to include a component in a reserve study, or to provide contributions to a reserve account for a component, may, under some circumstances, require the association to (1) defer major maintenance, repair, or replacement, (2) increase future reserve contributions, (3) borrow funds to pay for major maintenance, repair, or replacement, or (4) impose special assessments for the cost of major maintenance, repair, or replacement.

GLOSSARY OF TERMS



Component

The individual line items in the Reserve Study which are included in the Physical Analysis. These elements form the building blocks for the Reserve Study.

Estimated Useful Life

The estimated time, in years, that a reserve component can be expected to serve its intended function if properly constructed in its present application or installation.

Fully Funded

When the actual (or projected) Reserve balance is equal to the Fully Funded Balance.

Fully Funded Balance (FFB)

The Reserve balance that is in direct proportion to the fraction of life "used up" of the current Repair or Replacement cost. This number is calculated for each component, then summed together for an Association total.

FFB = Current Cost x Effective Age / Useful Life

Percent Funded

The ratio, at a particular point of time, of the actual Reserve Balance to the Fully Funded Balance (FFB), expressed as a percentage.

Remaining Useful Life

The estimated time, in years, that a Reserve Component can be expected to continue to service its intended function. Projects anticipated to occur in the initial year have a "zero" Remaining Life.

Unit Cost Estimate

The cost of replacing, repairing, or restoring a Reserve Component to its original functional condition. The Current Replacement Cost would be the cost to replace, repair, or restore the component during the current year.

Unit of Measure

Various units of measure have been used to quantify the amounts and costs in relation to each reserve component. Below are the key units used as part of this report.

SF = Square Foot SY = Square Yard

LF = Linear Foot

SQUARE = 100 Square Feet (Roofing)

