




COM-LINX


Assembly Instructions Power



PART # WAP-POE36USB



3 WIRE IP68 ADAPTER



12/24VDC
BATTERY

OR



12/24VDC
ACC

OR



120/240
VAC

12ft Extension

3 WIRE IP68 ADAPTER

#Red Positive Wire
#Black Negative Wire



AG1 IS REVERSE POLARITY
PROTECTED AND WILL NOT FUNCTION
IF CONNECTED INCORRECTLY



Fuse Case: 3A

AG1
REQUIRES A
3AMP FUSE
*Included




Ring Terminal Connector:
8.4mm x 13.8mm

CROSSOVER
<https://www.crossoverdistribution.com/>



COM-LINX


Assembly Instructions Ethernet





COM-LINX

Assembly Instructions USB GPS



PART # WAP-POE36USB

IP67 USB
TYPE A



GPS



COM-LINX

Assembly Instructions Antennas

