

PRODUCT DATASHEET

OMEGA White Spirit 9000

General Description

A hydrocarbon fraction which consists mainly of C9 and C10 aliphatic isomers, but with some C9 and C10 aromatic isomers. Produced by the fractionation of either petroleum or condensate middle distillates which in turn are obtained by the distillation of crude oil or gas condensate.

Recommended Use

An effective general purpose cleaning and degreasing. As a main constituent in paint, polishes, adhesives, under body sealants, mastics, stains, wood preservatives and as a do-it-yourself thinner and cleaner.

Features

- ✓ Available in 1 USG, 5 USG, and 200 Ltrs
- ✓ Specific gravity of 0.76 0.79 gm/cm³
- ✓ Flash point 36 °C / 97 °F
- ✓ Clear (Transparent)

Application Method

Unless stated in a specific product data sheet, standard reduction should be 10% or less.

Surface Preparation

Surfaces to be painted must be clean, dry, and free of dirt, grease, oil, soap, wax, scaling paint, water soluble materials, and mildew. Remove any peeling or scaling paint and sand these areas to feather edges smooth with adjacent surfaces. Glossy areas should be dulled. Drywall surfaces must be free of sanding dust.

New plaster or masonry surfaces must be allowed to cure for 30 days before applying base coat. Cured plaster should be hard, have a slight sheen; soft, porous or powdery plaster indicate improper cure. Never sand a plaster surface; knife off any protrusions and prime plaster before and after applying patching compound.

WARNING: If you scrape, sand or remove old paint, you may release lead dust. Lead is toxic. Exposure to lead dust can cause serious illness, such as brain damage, especially in children. Pregnant women should also avoid exposure. Wear an approved respirator to control lead exposure. Carefully clean up with a vacuum and a wet mop.

Storage and Handling

The product must be stored in accordance with national regulations and should be kept in a cool and well ventilated place. Protect from heat and direct sun light, handle with care and stir well before use.

Health and Safety

Apply under well-ventilated conditions. Do not breathe or inhale mist. When applying, wear air-mask and avoid skin contact. Spillage on skin should be immediately removed with suitable cleanser, soap, or water. Eyes should be well flushed with water and medical attention to be sought immediately.

Disclaimer

The information is given in good faith. We warrant our product is of good quality and manufactured in accordance to rigid standards. Failure of this product due to misuse or bad storage is beyond the manufacturer warranty. The company pursues a policy of continuous improvement in product innovation, and as such, reserves the right to change the given data without prior notice. Contact Omega's representative or visit www.omegapaints.net for more info.

Revision date: September 2020. This datasheet supersedes the previous issue.



