

# MIRROR

NOVA SCOTIA

I HAD AN OVERHEATING PROBLEM WITH 3 LANDFILL GAS BLOWERS (BEARINGS OVERHEATING) USING VARIOUS TYPES OF GREASE OVER A PERIOD OF A COUPLE OF YEARS. I SWITCHED TO TRC PARAGON 3000 IT BROUGHT THE TEMPERATURE RANGE DOWN TO ACCEPTABLE MANUFACTURER LIMITS. IT WORKS WELL FOR ME.

Terry Barkhouse

Mirror Nova Scotia

