



CARDIAC TROPONIN PANEL # MDXPCT- 003
0.5 ml Matched Serum, K2 EDTA Plasma, and Li Heparin Plasma

ID #	Age	Gender	Ethnicity	Race	Smoker/Non-Smoker	Cause of elevated Troponin	Symptoms	Date of Event	Admitted AM/PM
7003	42	Male	Hispanic	Caucasian	Non-Smoker	Heart Attack	Chest pain, left arm numbness, Shortness of Breath	3/29/2019	AM

Sample ID	Draw	Time Point	BP	Draw Date	Troponin	Myoglobin	Matrix
A11703162	1	12-18 HRS	164/104	3/30/2019	38.2 ng/mL	16.6 ng/mL	SERUM
A11703163	1	12-18 HRS	164/104	3/30/2019	Not Tested	Not Tested	K2 EDTA
A11703164	1	12-18 HRS	164/104	3/30/2019	Not Tested	Not Tested	LIH
A11703171	2	24 HRS POST	158/100	3/31/2019	34.2 ng/mL	20.7 ng/mL	SERUM
A11703172	2	24 HRS POST	158/100	3/31/2019	Not Tested	Not Tested	K2 EDTA
A11703173	2	24 HRS POST	158/100	3/31/2019	Not Tested	Not Tested	LIH
A11703183	3	48 HRS POST	150/90	4/1/2019	28.2 ng/mL	26.3 ng/mL	SERUM
A11703184	3	48 HRS POST	150/90	4/1/2019	Not Tested	Not Tested	K2 EDTA
A11703185	3	48 HRS POST	150/90	4/1/2019	Not Tested	Not Tested	LIH
A11703189	4	72 HRS POST	150/90	4/2/2019	24.2 ng/mL	31.3 ng/mL	SERUM
A11703190	4	72 HRS POST	150/90	4/2/2019	Not Tested	Not Tested	K2 EDTA
A11703191	4	72 HRS POST	150/90	4/2/2019	Not Tested	Not Tested	LIH

Troponin Testing was performed on Tosoh AIA-360/Myoglobin Testing was performed on RayBio Human Myoglobin ELISA Kit

CAUTION: HUMAN BLOOD

All materials listed above are considered to be potentially infectious and should be handled with universal precautions.