

Dressing Tree Assembly Instructions

Tools required: Power drill (with drill bit for ¼" screws and phillips head attachment), socket wrench set or manual adjustable wrench


1. Measure and mark out holes for hitching ring screws (~2" from each side and 1" from top/bottom of MDF board)
2. Drill 4 holes using appropriate drill bit



3. Screw in the 4 screws for each hitching ring plate with power drill
4. Flip board over and secure bolts using socket wrench or manual wrench



5. Measure and mark out placement of Hanger in center of MDF board.



6. Drill holes with appropriate drill bit
7. Secure flush side of plate with a ¾" machine screw using power drill



8. Secure raised side of plate with 1 ½ " machine screw using power drill

9. Flip board over and secure bolts using socket wrench or manual wrench
10. Hang the dressing board over door by threading the straps as shown in photo



11. The hanger has enough tension that it should stay in 'flipped up' position when not in use