

OWNER: CBR AVIATION LLC

ADDRESS: 101 JEGS PLACE
DELAWARE OH 43015

OFFICE: 614 579 5573

FAX:

OPERATOR: CBR AVIATION LLC

ADDRESS: 101 JEGS PLACE
DELAWARE OH 43015

OFFICE: 614 579 5573

FAX:

ANALYST: JAKE SALINAS

EMAIL: JSALINAS@CAMPSYSTEMS.COM

+1-316-928-7883 (DIRECT)

+1-631-588-3200 (MAIN)

WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)

631-980-4222 (EFAX-CARDS)

PROJECTED: 12 MOS. to 06/29/2027

AIRCRAFT	SERIAL/REGNO: 45-134/N751JC		MODEL:	LEARJET 45		MANUFACTURER: BOMBARDIER AVIATION	
	CERTIFICATION DATE: 13-JAN-2001			LAST ACTUALS:		PROJECTED:	
				9832.1	A/C HRS	as of 31-MAY-2026	10192.10
				7527	AFL	as of 31-MAY-2026	7887
				2676.1	ACH	as of 01-MAY-2019	2796
ENGINE NO. 1	SERIAL/PART: P-116262/3060084-2		MODEL:	TFE731-20BR-1B		MANUFACTURER: HONEYWELL	
	INSTALLED ON: 01-JUN-2001			LAST ACTUALS:		PROJECTED:	
	0	ENG. HRS	0 A/C HRS	9768.2	ENG. HRS	as of 31-MAY-2026	10128.20
	0	ENC		7475	ENC	as of 31-MAY-2026	7835
ENGINE NO. 2	SERIAL/PART: P-116261/3060084-2		MODEL:	TFE731-20BR-1B		MANUFACTURER: HONEYWELL	
	INSTALLED ON: 11-SEP-2015			LAST ACTUALS:		PROJECTED:	
	7653.4	ENG. HRS	8202.7 A/C HRS	9282.8	ENG. HRS	as of 31-MAY-2026	9642.80
	5888	ENC		7118	ENC	as of 31-MAY-2026	7478

Due List Report

Model: LEARJET 45 Serial: 45-134 RegNo: N751JC HRS: 9832.1 AFL: 7527 As Of:
31-May-2026 Operator: CBR AVIATION LLC

Report Date: 29-Jun-2026

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
AE2710049		* AILERON LEADING EDGE (INTERNAL) - PERFORM BORESCOPE INSPECTION						Service ATA:27
	MOS	T:6		EFF	11-Jun-26 *		OVD	
	HRS							
	AFL							
Disposition: AIRWORTHINESS			REF: AMM 27-10-02					
E2561002		COPILOTS LIFE VEST - PERFORM INSPECTION OF LIFE VESTS						Service ATA:25
PN:63600-101	MOS	60 (+14d/-14d)		21-May-21	21-May-26	04-Jun-26	OVD	
SN:L5052577	HRS							
	AFL							
			REF: CMM 25-60-05, AMM 25-60-01					
E2561002		LAVATORY LIFE VEST - PERFORM INSPECTION OF LIFE VESTS						Service ATA:25
PN:63600-101	MOS	60 (+14d/-14d)		21-May-21	21-May-26	04-Jun-26	OVD	
SN:L5129652	HRS							
	AFL							
			REF: CMM 25-60-05, AMM 25-60-01					
E2561002		NO. 1 PASSENGER LIFE VEST - PERFORM INSPECTION OF LIFE VESTS						Service ATA:25
PN:63600-101	MOS	60		21-May-21	21-May-26		OVD	
SN:L5052589	HRS							
	AFL							
			REF: CMM 25-60-05, AMM 25-60-01					
E2561002		NO. 2 PASSENGER LIFE VEST - PERFORM INSPECTION OF LIFE VESTS						Service ATA:25
PN:63600-101	MOS	60 (+14d/-14d)		21-May-21	21-May-26	04-Jun-26	OVD	
SN:L5052585	HRS							
	AFL							
			REF: CMM 25-60-05, AMM 25-60-01					
E2561002		NO. 3 PASSENGER LIFE VEST - PERFORM INSPECTION OF LIFE VESTS						Service ATA:25
PN:63600-101	MOS	60 (+14d/-14d)		21-May-21	21-May-26	04-Jun-26	OVD	
SN:L5052575	HRS							
	AFL							
			REF: CMM 25-60-05, AMM 25-60-01					
E2561002		NO. 4 PASSENGER LIFE VEST - PERFORM INSPECTION OF LIFE VESTS						Service ATA:25
PN:63600-101	MOS	60		21-May-21	21-May-26		OVD	
SN:L5052593	HRS							
	AFL							
			REF: CMM 25-60-05, AMM 25-60-01					

Due List Report

Model: LEARJET 45 Serial: 45-134 RegNo: N751JC HRS: 9832.1 AFL: 7527 As Of:
31-May-2026 Operator: CBR AVIATION LLC

Report Date: 29-Jun-2026

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
E2561002		NO. 5 PASSENGER LIFE VEST - PERFORM INSPECTION OF LIFE VESTS						Service ATA:25
PN:63600-101	MOS	60 (+14d/-14d)		21-May-21	21-May-26	04-Jun-26	OVD	
SN:L5129638	HRS							
	AFL							
REF: CMM 25-60-05, AMM 25-60-01								
E2561002		NO. 6 PASSENGER LIFE VEST - PERFORM INSPECTION OF LIFE VESTS						Service ATA:25
PN:63600-101	MOS	60 (+14d/-14d)		21-May-21	21-May-26	04-Jun-26	OVD	
SN:L5129667	HRS							
	AFL							
REF: CMM 25-60-05, AMM 25-60-01								
E2561002		NO. 7 PASSENGER LIFE VEST - PERFORM INSPECTION OF LIFE VESTS						Service ATA:25
PN:63600-101	MOS	60 (+14d/-14d)		21-May-21	21-May-26	04-Jun-26	OVD	
SN:L5129651	HRS							
	AFL							
REF: CMM 25-60-05, AMM 25-60-01								
E2561002		NO. 8 PASSENGER LIFE VEST - PERFORM INSPECTION OF LIFE VESTS						Service ATA:25
PN:63600-101	MOS	60 (+14d/-14d)		21-May-21	21-May-26	04-Jun-26	OVD	
SN:L5129636	HRS							
	AFL							
REF: CMM 25-60-05, AMM 25-60-01								
E2561002		PILOTS LIFE VEST - PERFORM INSPECTION OF LIFE VESTS						Service ATA:25
PN:63600-101	MOS	60		21-May-21	21-May-26		OVD	
SN:L5052587	HRS							
	AFL							
REF: CMM 25-60-05, AMM 25-60-01								
N2720030		RUDDER TORQUE TUBE AND SPINDLE - PERFORM DETAILED VISUAL INSPECTION						Service ATA:27
	MOS	72 (+14d/-14d)		21-May-20	21-May-26	04-Jun-26	OVD	
	HRS			8814.5				
	AFL			6789				
Disposition: AIRWORTHINESS REF: AMM 27-20-01								
SB 45-57-16		WINGS - WING TANK DRAIN VALVE CORROSION INSPECTION, SERVICE BULLETIN						Bulletin ATA:57
	MOS	T:12		EFF	31-Mar-26 *		OVD	
	HRS							
	AFL							
Disposition: RECOMMENDED REF: BULLETINS								

Due List Report

Model: LEARJET 45 Serial: 45-134 RegNo: N751JC HRS: 9832.1 AFL: 7527 As Of:
31-May-2026 Operator: CBR AVIATION LLC

Report Date: 29-Jun-2026

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
D2910018		MAIN HYDRAULIC FILTER MANIFOLD ELEMENTS - REPLACE						Service ATA:29
	MOS			15-Oct-24				06-Jul-2026(2)
	HRS	300 (+25/-25)		9539.9	9839.9	9864.9	7.8 (+25)	
	AFL			7327				
		REF: AMM 29-10-03						
O3510007		OXYGEN CYLINDER (COMPOSITE) - SCRAP						Service ATA:35
	MOS	180 (+14d/-14d)		13-Jan-01	15-Jul-26 (M)	29-Jul-26	16 d (+14)	15-Jul-2026
	HRS			0				
	AFL			0				
Disposition: LIFE LIMIT REF:								
SB 45-27-53 R05		FLIGHT CONTROLS - INSPECTION/MODIFICATION OF THE AILERON, SERVICE BULLETIN						Bulletin ATA:27
	MOS	T:6			22-Jul-26 (M)		23 d	22-Jul-2026
	HRS							
	AFL							
Disposition: RECOMMENDED REF: BULLETINS								
D2740003		** HORIZONTAL STABILIZER ACTUATOR SECONDARY TRIM - PERFORM FUNCTIONAL TEST						Service ATA:27
	MOS			03-Apr-23				18-Aug-2026
	HRS	600 (+25/-25)		9282.3	9882.3	9907.3	50.2 (+25)	
	AFL			7144				
Disposition: AIRWORTHINESS REF: AMM 27-40-02								
D2740004		** HORIZONTAL STABILIZER ACTUATOR PRIMARY TRIM - PERFORM FUNCTIONAL TEST						Service ATA:27
	MOS			03-Apr-23				18-Aug-2026
	HRS	600 (+25/-25)		9282.3	9882.3	9907.3	50.2 (+25)	
	AFL			7144				
Disposition: AIRWORTHINESS REF: AMM 27-40-02								
057110		NO. 1 ENGINE - 150 TO 250 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS						Package ATA:05
	MOS			08-Oct-25				28-Aug-2026(3)
	HRS	150 (+100)		9678.2	(9828.2)9892.1	9928.2	60 (+100)	
	ENC			7416				
		REF: LMM 72-00-00						
057110		NO. 2 ENGINE - 150 TO 250 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS						Package ATA:05
	MOS			08-Oct-25				28-Aug-2026(3)
	HRS	150 (+100)		9192.8	(9342.8)9892.1	9442.8	60 (+100)	
	ENC			7059				
		REF: LMM 72-00-00						

Due List Report

Model: LEARJET 45 Serial: 45-134 RegNo: N751JC HRS: 9832.1 AFL: 7527 As Of:
31-May-2026 Operator: CBR AVIATION LLC

Report Date: 29-Jun-2026

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
T3220105		* LEFT MAIN LANDING GEAR ACTUATOR END CAP - REPLACE						Service ATA:32
PN:200-0303	MOS			03-Jan-11				31-Aug-2026
SN:H1984	HRS			6900.6				
	AFL	2387		5203	7590		63	
Disposition: LIFE LIMIT		REF: AMM 32-31-01						
T3220105		* RIGHT MAIN LANDING GEAR ACTUATOR END CAP - REPLACE						Service ATA:32
PN:200-0303	MOS			03-Jan-11				31-Aug-2026
SN:H1996	HRS			6900.6				
	AFL	2387		5203	7590		63	
Disposition: LIFE LIMIT		REF: AMM 32-31-01						
FAA 2025-16-09 PARA (G)(1)		INSPECT EACH BUCKLE SCREW FOR CRACKED, LOOSE, AND MISSING SCREW HEADS BY FOLLOWING THE ACCOMPLISHMENT INSTRUCTIONS, PARAGRAPHS B.(1) AND (2), OF PARKER MEGGITT SERVICE BULLETIN SB 1111475-25-001-2023, REVISION 002, DATED APRIL 1, 2024 (SB 1111475-25-001-2023 REV 002) - FOR AIRPLANES WITH BUCKLE P/N 1111475 (ALL DASH NUMBERS)						AD ATA:25
	MOS	T:12		EFF	22-Sep-26 *		85 d	22-Sep-2026
	HRS							
	AFL							
Disposition: MANDATORY		REF: AD						
FAA 2025-16-09 PARA (G)(2)		INSPECT EACH BUCKLE SCREW FOR CRACKED, LOOSE, AND MISSING SCREW HEADS BY FOLLOWING THE ACCOMPLISHMENT INSTRUCTIONS, PARAGRAPH B.(1), OF PARKER MEGGITT SB 1111548-25-001-2023, REVISION 002, DATED APRIL 1, 2024 (SB 1111548-25-001-2023 REV 002) - AIRPLANES WITH BUCKLE P/N 1111548-01						AD ATA:25
	MOS	T:12		EFF	22-Sep-26 *		85 d	22-Sep-2026
	HRS							
	AFL							
Disposition: MANDATORY		REF: AD						
FAA 2025-16-09 PARA (G)(3)		CREWMEMBER SEAT OR PASSENGER SEAT (AS AN OPTION FOR THE ACTIONS REQUIRED BY PARAGRAPH (G)(1) OR (2) OF THIS AD) - REMOVE MALE SIDE FROM THE LAP OF THE RESTRAINT SYSTEM AND FABRICATE A PLACARD STATING SEAT IS INOPERATIVE						AD ATA:25
	MOS	T:12		EFF	22-Sep-26 *		85 d	22-Sep-2026
	HRS							
	AFL							
Disposition: MANDATORY		REF: AD						
051201		PHASE B1 600 HOUR CHECKS						Package ATA:05
	MOS	24 (+14d/-14d)		15-Oct-24	15-Oct-26	29-Oct-26	108 d (+14)	15-Oct-2026
	HRS	600 (+25/-25)		9539.9	10139.9	10164.9	307.8 (+25)	
	AFL			7327				
		REF: AMM 05-10-00, AMM 05-12-01						

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time

Due List Report

Model: LEARJET 45 Serial: 45-134 RegNo: N751JC HRS: 9832.1 AFL: 7527 As Of:
31-May-2026 Operator: CBR AVIATION LLC

Report Date: 29-Jun-2026

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
051202	PHASE B2 600 HOUR CHECKS							Package ATA:05
	MOS	24 (+14d/-14d)		15-Oct-24	15-Oct-26	29-Oct-26	108 d (+14)	15-Oct-2026
	HRS	600 (+25/-25)		9539.9	10139.9	10164.9	307.8 (+25)	
	AFL			7327				
	REF: AMM 05-10-00, AMM 05-12-02							
051203	PHASE B3 600 HOUR CHECKS							Package ATA:05
	MOS	24 (+14d/-14d)		15-Oct-24	15-Oct-26	29-Oct-26	108 d (+14)	15-Oct-2026
	HRS	600 (+25/-25)		9539.9	10139.9	10164.9	307.8 (+25)	
	AFL			7327				
	REF: AMM 05-10-00, AMM 05-12-03							
051204	PHASE B4 600 HOUR CHECKS							Package ATA:05
	MOS	24 (+14d/-14d)		15-Oct-24	15-Oct-26	29-Oct-26	108 d (+14)	15-Oct-2026
	HRS	600 (+25/-25)		9539.9	10139.9	10164.9	307.8 (+25)	
	AFL			7327				
	REF: AMM 05-10-00, AMM 05-12-04							
051205	PHASE B5 600 HOUR CHECKS							Package ATA:05
	MOS	24 (+14d/-14d)		15-Oct-24	15-Oct-26	29-Oct-26	108 d (+14)	15-Oct-2026
	HRS	600 (+25/-25)		9539.9	10139.9	10164.9	307.8 (+25)	
	AFL			7327				
	REF: AMM 05-10-00, AMM 05-12-05							
051206	PHASE B6 600 HOUR CHECKS							Package ATA:05
	MOS	24 (+14d/-14d)		15-Oct-24	15-Oct-26	29-Oct-26	108 d (+14)	15-Oct-2026
	HRS	600 (+25/-25)		9539.9	10139.9	10164.9	307.8 (+25)	
	AFL			7327				
	REF: AMM 05-10-00, AMM 05-12-06							
231021A	TEST/INSPECT ATC TRANSPONDER							Service ATA:23
	MOS	24		15-Oct-24	15-Oct-26		108 d	15-Oct-2026
	HRS			9539.9				
	AFL			7327				
	REF: AMM 23-11-00, FAR FAR 91.413							
231022A	TEST/INSPECT ATC TRANSPONDER							Service ATA:23
	MOS	24		15-Oct-24	15-Oct-26		108 d	15-Oct-2026
	HRS			9539.9				
	AFL			7327				
	REF: AMM 23-11-00, FAR FAR 91.413							

? - Insufficient Information S - Suppressed Requirement * - Estimated Due(New Requirement)(EFF) - Effective C/W M - Manual Due (EBT) - Estimated Base Time

Due List Report

Model: LEARJET 45 Serial: 45-134 RegNo: N751JC HRS: 9832.1 AFL: 7527 As Of:
31-May-2026 Operator: CBR AVIATION LLC

Report Date: 29-Jun-2026

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
341001A TEST/INSPECT NO. 1 AIR DATA COMPUTER Service ATA:34								
PN:7014700-606	MOS	24		15-Oct-24	15-Oct-26		108 d	15-Oct-2026
SN:99062877	HRS			9539.9				
	AFL			7327				
REF: FAR FAR 91.411, AMM 34-17-00, CFR 14 CFR PART 43 APP E								
341002A TEST/INSPECT NO. 2 AIR DATA COMPUTER Service ATA:34								
PN:7014700-606	MOS	24		15-Oct-24	15-Oct-26		108 d	15-Oct-2026
SN:99123271	HRS			9539.9				
	AFL			7327				
REF: FAR FAR 91.411, AMM 34-17-00, CFR 14 CFR PART 43 APP E								
341025A TEST/INSPECT STANDBY ALTIMETER Service ATA:34								
PN:7634208001-003	MOS	24		15-Oct-24	15-Oct-26		108 d	15-Oct-2026
SN:164918B	HRS			9539.9				
	AFL			7327				
REF: FAR FAR 91.411, AMM 34-15-01, CFR 14 CFR PART 43 APP E								
341037A LEFT PRIMARY PITOT/STATIC PROBE - PERFORM NATIONALLY REQUIRED EQUIPMENT TESTS AND INSPECTIONS Service ATA:34								
PN:0856TJ1	MOS	24		15-Oct-24	15-Oct-26		108 d	15-Oct-2026
SN:180792	HRS			9539.9				
	AFL			7327				
REF: GENERIC NO REF, FAR FAR 91.411, CFR 14 CFR PART 43 APP E								
341038A RIGHT PRIMARY PITOT/STATIC PROBE - PERFORM NATIONALLY REQUIRED EQUIPMENT TESTS AND INSPECTIONS Service ATA:34								
PN:6634100000-003	MOS	24		15-Oct-24	15-Oct-26		108 d	15-Oct-2026
SN:226125	HRS			9539.9				
	AFL			7327				
REF: FAR FAR 91.411, AMM 34-11-00, CFR 14 CFR PART 43 APP E								
AA2560000 COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON - CLEAN BEACON SWITCH, PERFORM FUNCTIONAL TEST OF BEACON, AND PERFORM TEST OF ULB BATTERY Service ATA:25								
PN:PN	MOS	24 (+14d/-14d)		15-Oct-24	15-Oct-26	29-Oct-26	108 d (+14)	15-Oct-2026
SN:UNKNOWN	HRS			9539.9				
	AFL			7327				
REF: GENERIC NO REF								
H5323032 * EXTERIOR CABIN WINDOW COAMINGS (UNPAINTED) - PERFORM EDDY CURRENT INSPECTION Service ATA:53								
	MOS	24		15-Oct-24	15-Oct-26		108 d	15-Oct-2026
	HRS	2400		9539.9	11939.9		2107.8	
	AFL			7327				

Disposition: AIRWORTHINESS

REF: NDT PART 6/56-20-01

? - Insufficient Information S - Suppressed Requirement * - Estimated Due(New Requirement)(EFF) - Effective C/W M - Manual Due (EBT) - Estimated Base Time

Due List Report

Model: LEARJET 45 Serial: 45-134 RegNo: N751JC HRS: 9832.1 AFL: 7527 As Of:
31-May-2026 Operator: CBR AVIATION LLC

Report Date: 29-Jun-2026

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
L3411062		LEFT PRIMARY PITOT/STATIC PROBE - PERFORM DETAILED VISUAL INSPECTION						Service ATA:34
PN:0856TJ1	MOS	24 (+14d/-14d)		15-Oct-24	15-Oct-26	29-Oct-26	108 d (+14)	15-Oct-2026
SN:180792	HRS			9539.9				
	AFL			7327				
REF: AMM 34-11-01								
M3411052		LEFT PRIMARY PITOT/STATIC PROBE - VERIFY PITCH, ROLL, AND YAW ALIGNMENT						Service ATA:34
PN:0856TJ1	MOS	24 (+14d/-14d)		15-Oct-24	15-Oct-26	29-Oct-26	108 d (+14)	15-Oct-2026
SN:180792	HRS			9539.9				
	AFL			7327				
REF: AMM 34-11-01								
M5240004		AVIONIC ACCESS DOORS - PERFORM AVIONICS DOOR GAP AND MISMATCH INSPECTION						Service ATA:52
	MOS	24 (+14d/-14d)		15-Oct-24	15-Oct-26	29-Oct-26	108 d (+14)	15-Oct-2026
	HRS			9539.9				
	AFL			7327				
REF: AMM 52-40-01								
M5313001		FORWARD FUSELAGE SKIN - PERFORM PITOT-STATIC PROBE ZONE SKIN CONTOUR CHECK						Service ATA:53
	MOS	24 (+14d/-14d)		15-Oct-24	15-Oct-26	29-Oct-26	108 d (+14)	15-Oct-2026
	HRS			9539.9				
	AFL			7327				
REF: AMM 53-00-01								
U3411060		AIR DATA SYSTEM - PERFORM FUNCTIONAL TEST						Service ATA:34
	MOS	24 (+14d/-14d)		15-Oct-24	15-Oct-26	29-Oct-26	108 d (+14)	15-Oct-2026
	HRS			9539.9				
	AFL			7327				
REF: AMM 34-17-00								
Q3510005		** OXYGEN CYLINDER (COMPOSITE) AND LOW PRESSURE RELIEF VALVE - PERFORM ICC HYDROSTATIC TEST ON CYLINDER (PER DOT EXEMPTION E8162) AND FUNCTIONALLY TEST OXYGEN CYLINDER LOW PRESSURE RELIEF VALVE.						Service ATA:35
PN:806385-141	MOS	60 (+14d/-14d)		20-Dec-24	19-Oct-26 (M)	02-Nov-26	112 d (+14)	19-Oct-2026
SN:C1100579	HRS	5000 (+25/-25)		9580	14580	14605	4747.9 (+25)	
	AFL			7352				
REF: GENERIC NO REF								
051101		PHASE A1-300 HOUR CHECKS						Package ATA:05
	MOS	12 (+14d/-14d)		14-Nov-25	14-Nov-26	28-Nov-26	138 d (+14)	14-Nov-2026
	HRS	300 (+25/-25)		9767.5	10067.5	10092.5	235.4 (+25)	
	AFL			7483				
REF: AMM 05-10-00, AMM 05-11-01								

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time

Due List Report

Model: LEARJET 45 Serial: 45-134 RegNo: N751JC HRS: 9832.1 AFL: 7527 As Of:
31-May-2026 Operator: CBR AVIATION LLC

Report Date: 29-Jun-2026

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
051102	PHASE A2-300 HOUR CHECKS							Package ATA:05
	MOS	12 (+14d/-14d)		14-Nov-25	14-Nov-26	28-Nov-26	138 d (+14)	14-Nov-2026
	HRS	300 (+25/-25)		9767.5	10067.5	10092.5	235.4 (+25)	
	AFL			7483				
	REF: AMM 05-10-00, AMM 05-11-02							
051103	PHASE A3-300 HOUR CHECKS							Package ATA:05
	MOS	12 (+14d/-14d)		14-Nov-25	14-Nov-26	28-Nov-26	138 d (+14)	14-Nov-2026
	HRS	300 (+25/-25)		9767.5	10067.5	10092.5	235.4 (+25)	
	AFL			7483				
	REF: AMM 05-10-00, AMM 05-11-03							
051104	PHASE A4-300 HOUR CHECKS							Package ATA:05
	MOS	12 (+14d/-14d)		14-Nov-25	14-Nov-26	28-Nov-26	138 d (+14)	14-Nov-2026
	HRS	300 (+25/-25)		9767.5	10067.5	10092.5	235.4 (+25)	
	AFL			7483				
	REF: AMM 05-10-00, AMM 05-11-04							
051105	PHASE A5-300 HOUR CHECKS							Package ATA:05
	MOS	12 (+14d/-14d)		14-Nov-25	14-Nov-26	28-Nov-26	138 d (+14)	14-Nov-2026
	HRS	300 (+25/-25)		9767.5	10067.5	10092.5	235.4 (+25)	
	AFL			7483				
	REF: AMM 05-10-00, AMM 05-11-05							
051106	PHASE A6-300 HOUR CHECKS							Package ATA:05
	MOS	12 (+14d/-14d)		14-Nov-25	14-Nov-26	28-Nov-26	138 d (+14)	14-Nov-2026
	HRS	300 (+25/-25)		9767.5	10067.5	10092.5	235.4 (+25)	
	AFL			7483				
	REF: AMM 05-10-00, AMM 05-11-06							
256109A	(ELT) EMERGENCY LOCATOR TRANSMITTER - PERFORM NATIONALY REQUIRED FUNCTIONAL TEST							Service ATA:25
PN:453-5000-(999)	MOS	12		14-Nov-25	14-Nov-26		138 d	14-Nov-2026
SN:08550	HRS			9767.5				
	AFL			7483				
	REF: AMM 25-62-00, FAR FAR 91.207							
256109B	(ELT) EMERGENCY LOCATOR TRANSMITTER - INSPECT ELT BATTERIES							Service ATA:25
PN:453-5000-(999)	MOS	12		14-Nov-25	14-Nov-26		138 d	14-Nov-2026
SN:08550	HRS			9767.5				
	AFL			7483				
	REF: AMM 25-62-00, FAR FAR 91.207							

Due List Report

Model: LEARJET 45 Serial: 45-134 RegNo: N751JC HRS: 9832.1 AFL: 7527 As Of:
31-May-2026 Operator: CBR AVIATION LLC

Report Date: 29-Jun-2026

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
AB2431062 EMERGENCY BATTERY - PERFORM CAPACITY CHECK Service ATA:24								
PN:RG-443	MOS	12		14-Nov-25	14-Nov-26		138 d	14-Nov-2026
SN:41380605	HRS	1000 (+100/-100)		9767.5	10767.5	10867.5	935.4 (+100)	
	AFL			7483				
REF:								
W5600002 ** WINDSHIELD - PERFORM RAIN REMOVAL COATING EFFECTIVENESS TEST Service ATA:56								
	MOS	12 (+14d/-14d)		14-Nov-25	14-Nov-26	28-Nov-26	138 d (+14)	14-Nov-2026
	HRS			9767.5				
	AFL			7483				
Disposition: AIRWORTHINESS REF: AMM 56-10-01								
T1222004 NO. 1 MAIN BATTERY - LEAD-ACID BATTERIES - PERFORM BATTERY CAPACITY CHECK Service ATA:12								
PN:RG-380E/40L	MOS	6 (+1m/-1m)		15-May-26	15-Nov-26	15-Dec-26	139 d (+30)	15-Nov-2026(2)
SN:41457893	HRS			9815.8				
	AFL			7514				
REF: AMM 12-22-00, CMM 24-30-71								
T1222004 NO. 2 MAIN BATTERY - LEAD-ACID BATTERIES - PERFORM BATTERY CAPACITY CHECK Service ATA:12								
PN:RG-380E/40L	MOS	6 (+1m/-1m)		15-May-26	15-Nov-26	15-Dec-26	139 d (+30)	15-Nov-2026(2)
SN:41457894	HRS			9815.8				
	AFL			7514				
REF: AMM 12-22-00, CMM 24-30-71								
M3220136 * LEFT MAIN LANDING GEAR SHOCK STRUT CYLINDER - PERFORM ULTRASONIC INSPECTION OF THE LOWER SERVICE PORT AND FORGING PARTING LINE Service ATA:32								
PN:200-0201-101	MOS			15-Jul-22				23-Nov-2026
SN:H0149	HRS			9174.8				
	AFL	600		7072	7672		145	
Disposition: AIRWORTHINESS REF:								
M3220136 * RIGHT MAIN LANDING GEAR SHOCK STRUT CYLINDER - PERFORM ULTRASONIC INSPECTION OF THE LOWER SERVICE PORT AND FORGING PARTING LINE Service ATA:32								
PN:200-0201-102	MOS			15-Jul-22				23-Nov-2026
SN:H0142	HRS			9174.8				
	AFL	600		7072	7672		145	
Disposition: AIRWORTHINESS REF:								
057120 NO. 1 ENGINE - 300 TO 440 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS Package ATA:05								
	MOS			15-Oct-24				25-Nov-2026
	HRS	440 (-140)		9476	(9916)9979.9		147.8	
	ENC			7275				
REF: LMM 72-00-00								

? - Insufficient Information S - Suppressed Requirement * - Estimated Due(New Requirement)(EFF) - Effective C/W M - Manual Due (EBT) - Estimated Base Time

Due List Report

Model: LEARJET 45 Serial: 45-134 RegNo: N751JC HRS: 9832.1 AFL: 7527 As Of:
31-May-2026 Operator: CBR AVIATION LLC

Report Date: 29-Jun-2026

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
057120		NO. 2 ENGINE - 300 TO 440 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS						Package ATA:05
	MOS			15-Oct-24				25-Nov-2026
	HRS	440 (-140)		8990.6	(9430.6)9979.9		147.8	
	ENC			6918				
		REF: LMM 72-00-00						
AC3010006		** ANTI-ICE MANIFOLD - PERFORM BORESCOPE INSPECTION						Service ATA:30
	MOS			24-Oct-23				08-Dec-2026
	HRS	600 (+25/-25)		9392.6	9992.6	10017.6	160.5 (+25)	
	AFL			7237				
		REF: AMM 30-10-07						
E5750051		* FLAP MAIN TRACK ROLLERS - PERFORM VISUAL INSPECTION WITH FLAPS REMOVED						Service ATA:57
	MOS			13-Jan-01				16-Dec-2026
	HRS	T:10000		0	10000		167.9	
	AFL			0				
Disposition: AIRWORTHINESS		REF: AMM 05-10-00, AMM 27-50-01						
M5450027		NO. 1 ENGINE FORWARD ENGINE BEAM END FITTING - REPLACE						Service ATA:54
	MOS			13-Jan-01				16-Dec-2026
	HRS	10000 (+25/-25)		0	10000	10025	167.9 (+25)	
	AFL			0				
		REF: AMM 53-40-02						
N5710013		* WING BOX REAR SPAR LOWER CAP SKIN TERMINATION AT MS 48 - PERFORM EDDY CURRENT INSPECTION. INSPECT REAR SPAR LOWER CAP BETWEEN WS 33 AND WS 48.						Service ATA:57
	MOS			13-Jan-01				16-Dec-2026
	HRS	T:10000		0	10000		167.9	
	AFL			0				
Disposition: AIRWORTHINESS		REF: NDT PART 6/57-20-04						
N5710026		* WING BOX MID SPAR LOWER CAP - PERFORM ULTRASONIC INSPECTION. INSPECT MID SPAR LOWER CAP OUTBOARD OF ROOT RIB AT WS 33 TO WS 99.						Service ATA:57
	MOS							16-Dec-2026
	HRS	T:10000		0	10000		167.9	
	AFL							
Disposition: AIRWORTHINESS		REF: NDT PART 4/57-30-03						
N5710174		* WING BOX REAR SPAR LOWER CAP SKIN TERMINATION AT MS 48 - PERFORM ULTRASONIC INSPECTION. INSPECT REAR SPAR LOWER CAP BETWEEN WS 33 AND WS 48.						Service ATA:57
	MOS			13-Jan-01				16-Dec-2026
	HRS	T:10000		0	10000		167.9	
	AFL			0				
		REF: NDT PART 4/57-30-04						

Due List Report

Model: LEARJET 45 Serial: 45-134 RegNo: N751JC HRS: 9832.1 AFL: 7527 As Of:
31-May-2026 Operator: CBR AVIATION LLC

Report Date: 29-Jun-2026

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
M5510010		* HORIZONTAL STABILIZER AFT ROOT RIB - PERFORM EDDY CURRENT INSPECTION. INSPECT AFT ROOT RIB INTERNAL BETWEEN MID SPAR AND AFT SPAR AND UPPER AND LOWER SKINS EXTERNAL AT ATTACHMENT FASTENERS.						Service ATA:55
	MOS			24-Apr-20				30-Dec-2026
	HRS	1200		8814.5	10014.5		182.4	
	AFL			6789				
Disposition: AIRWORTHINESS		REF: NDT PART 6/55-10-03						
256076A		FIRST AID KIT - VISUALLY INSPECT PER MANUFACTURER INSTRUCTIONS						Service ATA:25
PN:AFK 1.0	MOS	12		23-Dec-25	31-Dec-26		185 d	31-Dec-2026
SN:122017021	HRS							
	AFL							
		REF: GENERIC NO REF						
Z3020005		* NO. 1 ENGINE INLET ANTI-ICE TUBE ASSEMBLY FROM THE AFT INLET BULKHEAD CONNECTION POINT FORWARD TO SPRAY RING CONNECTION, PERFORM DETAILED VISUAL/BORESCOPE INSPECTION OF THE WELDS INSIDE AND OUTSIDE OF THE TUBE AT BOTH FORWARD AND AFT ENDS.						Service ATA:30
	MOS			14-Nov-25				02-Jan-2027
	HRS	250		9767.5	10017.5		185.4	
	AFL			7483				
Disposition: AIRWORTHINESS		REF: AMM 30-20-00						
Z3020005		* NO. 2 ENGINE INLET ANTI-ICE TUBE ASSEMBLY FROM THE AFT INLET BULKHEAD CONNECTION POINT FORWARD TO SPRAY RING CONNECTION, PERFORM DETAILED VISUAL/BORESCOPE INSPECTION OF THE WELDS INSIDE AND OUTSIDE OF THE TUBE AT BOTH FORWARD AND AFT ENDS.						Service ATA:30
	MOS			14-Nov-25				02-Jan-2027
	HRS	250		9767.5	10017.5		185.4	
	AFL			7483				
Disposition: AIRWORTHINESS		REF: AMM 30-20-00						
Y2431005		BATTERY CABLES AND RECEPTACLES - PERFORM BATTERY CONNECTOR TOLERANCE CHECK						Service ATA:24
	MOS			14-Nov-25				22-Feb-2027
	HRS	300 (+25/-25)		9767.5	10067.5	10092.5	235.4 (+25)	
	AFL			7483				
		REF: AMM 24-31-00						
W5510091		* HORIZONTAL STABILIZER HINGE PRIMARY AND SECONDARY PIVOT PIN INSTALLATION AND ATTACHING HARDWARE - PERFORM DETAILED VISUAL INSPECTION						Service ATA:55
	MOS			23-Jan-24				24-Mar-2027
	HRS	625		9471.9	10096.9		264.8	
	AFL			7281				
Disposition: MANDATORY		REF: AMM 05-10-00, AMM 55-10-00						

Due List Report

Model: LEARJET 45 Serial: 45-134 RegNo: N751JC HRS: 9832.1 AFL: 7527 As Of:
31-May-2026 Operator: CBR AVIATION LLC

Report Date: 29-Jun-2026

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
057130		NO. 1 ENGINE - 500 TO 650 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS						Package ATA:05
	MOS			15-Oct-24				07-May-2027
	HRS	600 (+50/-100)		9476	(10076)10139.9	10126	307.8 (+50)	
	ENC			7275				
		REF: LMM 72-00-00						
057130		NO. 2 ENGINE - 500 TO 650 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS						Package ATA:05
	MOS			15-Oct-24				07-May-2027
	HRS	600 (+50/-100)		8990.6	(9590.6)10139.9	9640.6	307.8 (+50)	
	ENC			6918				
		REF: LMM 72-00-00						
E5750052		* FLAP NOSE ROLLERS - PERFORM VISUAL INSPECTION WITH FLAPS REMOVED						Service ATA:57
	MOS			15-Oct-24				07-May-2027
	HRS	600		9539.9	10139.9		307.8	
	AFL			7327				

Disposition: AIRWORTHINESS

REF: AMM 05-10-00