

John Glenn International Airport 4130 East 5th Avenue Columbus, Ohio 43219 614-338-0060 office

www.fineaircraft.com

2007 LEARJET 60XR N328AJ Serial # 320

Asking \$4,490,000

Contact Marc Frient 614-204-4346 marc@fineaircraft.com

Airframe

AFTT: 1,352.9 Landings: 1055

Engine(s) Enrolled on ESP Gold

#1 Engine: 1352.9 hours Cycles: 1055 Serial # PCE-CA0499, Model # PWC305A

#2 Engine: 1,352.9 hours Cycles: 1055 Serial # PCE-CA0498, Model # PWC305A

APU T-20G-10C3A, Serial # SP-E060440 Hours: 1005 Cycles:1895, No Program

Inspection Status

Phase A Due 1609TT/October 2024 Phase B Due 1847TT/November 2024 Phase C Due 2509TT/October 2027 Phase D Due 3709TT/August 2031

Exterior

Learjet Wichita: 2007 Factory painted Matterhorn White with a Pantone Blue & Pantone Gray accent stripe.

Interior

New in 2007 - Factory installed impeccable clay colored Edelman Royal hide leather seven passenger configuration in an executive arrangement with a Fwd R/S three-place divan and four single seats with swivel and reclining capabilities featuring dual bi-fold executive tables set atop a factory installed luxurious three-color custom Rhapsody wool carpet. Elegantly stained high-gloss wood veneer accented with beautiful satin nickel hardware on all cabinetry. A large forward L/S galley with microwave oven and dual hot liquid containers. Belted, flushing aft lav, externally serviced.



Avionics/Radios

Collins Pro Line 21 Avionics System including the following: Dual Collins FMS-5000 with Dual GPS-4000 TCAS II w/ Change 7 Dual GPS-4000A Receiver Three Frequency 406 ELT Dual VIR-432 VJF Navigation Single ALT-4000 Radio Altimeter Dual ADF-462 Collins FCS 3000 Autopilot DME-442 CAT II Capable Dual VHF-422C Communication, 8.33 Hz **RSVM** Certified Dual TDR-94 Mode S Transponder Rockwell Collins Datalink w/ 3rd VHF Dual RTU-4220 Radio Controller Cockpit Voice Recorder WXR 840 Radar Dual Honeywell KHF-1050 HF Rosemount Ice Detection System Dual 1500 VA Static Inverters ADS-B compliant Flight Stream 110 Rockwell Collins TWR-850 EWR Dual FSU w/ Electronic Charts System Diagnostic Pages 4 LCD PFD/MFD Display Units Honeywell Mark V EGPWS w/windshear detection 3D FMS Maps E-Maps Overlays Universal Weather Electronic Checklist

Additional Equipment:

Airshow 410 World Wide Map Coverage Cockpit Speaker Mute 15.1 Forward Video Monitor Pulsating Recognition and Landing Lights DVD Player Dual Rechargeable Flashlights XM Radio Emergency Lighting Package Cabin 10-Disc CD Changer & Player Tail Illumination Package Third Emergency Battery ICS-200 Iridium Dual Channel Telephone System Pilot and Co-pilot upgraded clocks with USB charging John Glenn International Airport 4130 East 5th Avenue Columbus, Ohio 43219 614-338-0060 office



John Glenn International Airport 4130 East 5th Avenue Columbus, Ohio 43219 614-338-0060 office





John Glenn International Airport 4130 East 5th Avenue Columbus, Ohio 43219 614-338-0060 office





John Glenn International Airport 4130 East 5th Avenue Columbus, Ohio 43219 614-338-0060 office





John Glenn International Airport 4130 East 5th Avenue Columbus, Ohio 43219 614-338-0060 office





John Glenn International Airport 4130 East 5th Avenue Columbus, Ohio 43219 614-338-0060 office





John Glenn International Airport 4130 East 5th Avenue Columbus, Ohio 43219 614-338-0060 office

