



AUTOMATIC STRAPPING MACHINE


UP TO
65
STRAPS PER
MINUTE!



- High Speed Reliability
- Easy to Operate
- Extra Length Coil Capability



PC1000 Automatic Strapping Machine



The **PC1000** is an innovative high speed automatic strapping machine. It is equipped with all industry standard features. The PC1000 offers optimal performance, high cycle speed and easy mainte-

nance. This machine is the most cost effective solution to your strapping requirements in its class today.




Standard Features

- Cycle speed is up to 65 straps per minute (depending on arch size)
- German DC brushless motor technology
- No belts, clutches, or pulleys. 30% fewer parts, less maintenance and items to go wrong
- Waist high quick change coil and strap feed
- · Easy access operating control panel
- · Easy access strap chute-no tools required
- Front foot-bar pedal plus movable foot switch
- One piece strap chute
- Sensor controlled heater
- End of coil strap ejector/loop ejector
- Electronic brake / Auto loader
- Adjustable table height from 32" to 36"
- Lockable casters
- Choice of arch sizes
- Roller top standard on arches 33" wide or wider

Benefits

- Increase Throughput Up to 65 Straps per Minute
- **Reduced Maintenance Costs** Fewer Parts/DC Brushless Motors
- **Experience Less Downtime** Extra Long Length Coils

Dimensions



ALSO AVAILABLE

PC1000SP small package machine capable of strapping packages as small as 1.7" W x 3/8" H.

Specifications

Cycle Rate: Up to 65 straps per minute dep

per minute depending on arch and package size

Package Weight:Up to 100 lbs.Strap Tension:Up to 100 lbs.

Polypropylene Strap: 5mm, 6mm, 9mm, 12mm

1/4, 3/8, 1/2

Electrical Requirements: 110V 60Hz 1 Phase **Optional:** Photo eye activation

Shipping Weight: 450 lbs.





AUTOMATED EQUIPMENT SERVICE, INC.

MAIL PROCESSING SYSTEMS

(845) 452-2100 (518) 459-4545 (914) 478-2100 (607) 733-2108

info@AESMailPro.com

