

PDM-08 – COLUMN / TURNS

FUSE RELAY DETAILS

RELAYS

1. HEAD LIGHTS DIMS – 35AMP
2. LEFT REAR TURNS – 35AMP
3. PARKING LIGHTS – 35AMP
4. RIGHT REAR TURNS – 35AMP
5. HEAD LIGHT BRIGHTS – 35AMP
6. LEFT FRONT TURNS – 35AMP
7. HORN – 35AMP
8. RIGHT FRONT TURNS – 35AMP

FUSES

1. HEAD LIGHTS DIMS – 30 AMP
2. -----
3. PARKING LIGHTS BRIGHTS – 30 AMP
4. -----
5. TURN SIGNALS – 30 AMP
6. COMBO SWITCH FEEDS – 10 AMP
7. (IGN 12V) – 15 AMP

IF THERE ARE QUESTIONS, PLEASE CALL 815-564-7812

