ENGINEERING CAD CAM CAE

(A Professional Training Institute)

Presents

CAD & CAM Practice Drawings for Beginners

S.No	Contents	Page Number
1	3D CAD Practice Drawings (Exercises 1 - 100)	05
2	Assembly Practice Drawings (Exercises 1 - 4)	106
3	Geometric Dimensioning & Tolerancing (GD&T) Practice Drawings (Ex.1 to 3)	133
4	Sheetmetal Practice Drawings (Ex.1 to 20)	137
5	CAM – Turning Practice Drawings (41 Exercises – Level 1 & Level 2)	158
6	CAM – Milling Practice Drawings (32 Exercises – Level 1 & Level 2)	200





All Dimensions are in 'mm'. **ENGINEERING CAD CAM CAE** engineeringcadcamcae2018@gmail.com


ENGINEERING CAD CAM CAE


(A Professional Training Institute)


3D CAD Practice Drawings











































































































































































































































































































ENGINEERING CAD CAM CAE


(A Professional Training Institute)


Assembly Practice Drawings













































































ENGINEERING CAD CAM CAE

(A Professional Training Institute)

Geometric Dimensioning & Tolerancing (GD&T) Practice Drawings










ENGINEERING CAD CAM CAE


(A Professional Training Institute)


Sheetmetal Practice Drawings



























































ENGINEERING CAD CAM CAE


(A Professional Training Institute)


CAM – Turning Practice Drawings























































































































ENGINEERING CAD CAM CAE

(A Professional Training Institute)

CAM – Milling Practice Drawings