
## TRIALS SHOWING % INCREASE IN LATEX DUE TO THE DTS

## YOU MUST TAP EVERY DAY WHETHER OR NOT IT IS RAINING



## NOTES: THE BELOW PROCEEDURES MUST BE ADHERED TO IN ODER TO HAVE BOTH SETS OF TREES EXPOSED TO THE SAME VARIABLES AND THUS HAVE COMPARABLE RESULTS.

- 1. ORANGE COLORED CELLS ARE CALCULATED VALUES.......(Lbs/Tree/Month) = (Lbs/Tree/Day) x (30 Days/Month)
- 2. THE EXACT NUMBER OF TREES MUST BE TAPPED FOR BOTH SETS OF TREES WITH AND WITHOUT DYNAMIC TAPPING SHIELDS (DTS).
- 3. BOTH SET OF TREES MUST HAVE TAPPING DAYS THAT START AND END ON THE SAME DAYS.
- 4. YOUR ESTABLISHED FARM SYSTEM OF ALTERNATE TAPPING DAYS MUST BE APPLIED INDEPENDENTLY TO BOTH SETS OF TREES.
- 5. RECOMMENDED ALTERNATE TAPPING DAYS ARE; MON, WED, FRI. OR, TUE, THUR, SAT.
- 6. INDEPENDENT WEIGHING MUST BE DONE FOR EACH SET OF "CUP LUMP" ON THE SAME DAY USING THE SAME SCALE.
- 7. WEIGHINGS MUST BE WITNESSED BY A FARM REPRESENTATIVE AND A DYNAMIC TAPPING SHIELD LLC REPRESENTATIVE.
- 8. WEIGHING ON DIFFERENT DAYS CAUSE ERRORS BECAUSE WATER CONTINUE TO DRAIN EFFECTING THE "CUP LUMP" WEIGHT.