

NZ2000 update

[Honeywell Home Page](#)

[NDB Sign in](#)

[How to load](#)

[Youtube tutorial](#)

- Power on the aircraft avionics and the USB data loader on the correct side (left or right FMS). [1]
- Insert the prepared USB drive into the data loader. []
- On the Control Display Unit (CDU), navigate through the menus:
 - Select NAV -> NEXT -> DATALOAD
 - Choose FR DISK (from disk/USB)
 - Select TO BOTH (to load both FMS units if applicable)
 - Press ACCEPT when prompted to Load Data Base? []
- Wait for the transfer to complete and verify the new database cycle dates on the CDU status pages.