

Progress Report Meeting to the Community Monitor Committee September 20, 2005



Outline

- **☐** Transition Activities
- **□** Landfill Inspection
- Documentation Reviewed
- ☐ Report Reviewed
- ☐ Future Work
- ☐ CM Reports for Discussion
- Conclusions



Transition Activities

- Review of documents in TechLaw files
- August 24 meeting with WMAC managers Indisduced to start wireless of compliance is sues
- Landfill tour with operations manager Neil Wise

like is godel up by band.

Total of about 67 hours or \$8,710 expended on transition (not charged)

freed charge



Landfill Inspection 8/30/005

- Truck counts within limits
- Accompanied LEA, Karen Moroz
- Slight odor, and no gas odor, except near waste water treatment plant

 desid monsource

 plant
- Daily cover appears adequate face
- Compaction appears adequate,
 no sunken areas
- Observed load checks in public area – unacceptable items are separated (†.V.') minomae overs
- Some dust, but did not appear to exceed three minute limit
- Observed torn wrap in asbestos area – customer to be notified
- Observed hazardous waste accumulation area - in a ferred wen

litter is picked up by hand.
occasional dust levels



Documentation Reviewed

- Special Occurrences Log

 July/Aug macoptake load of bothes reid

 3 htes, I customer mind. Us tomer
- Load Check Report, August
- Turbine, IC Engine and Flare downtown logs downtwe logs no musual occurrences temp report ropers temp report
- Flare temperature Report
- IC Engine Heat Input Report
- LEA Inspection Report
- Notice of Violations & 2005

Virtation Lar late youtry Jan to date one ND.V. from arguality reporting Chart records gammed Som Ime 14-16



Report Reviewed

Groundwater Intercept Barrier (GWIB) Pilot Study Report, August 2005

techlaw hydrogeologist reviewed pilot study report

dovantown logs downtone log

Notice of Violations of 2005

Son to date or grality

draf was du Jamass

di francon



Future Work

- Refine landfill inspection task
 Malle sure the she's looking at tring that are relevant.
- Develop an inspection checklist
- Develop a proposal to the CMC to change specific tasks based on actual ALRRF operations that and seem to be relevant.
- Continue landfill inspections and reviews of documentation, data, and reports



CM Reports for Discussion

- Techlaw's Response to WMAC August 8
 letter concerning CM activities
 - Independent evaluation of the groundwater interceptor barrier
 - Items continued from July 12, 2005 meeting



Conclusions based or worked past

- Environmental controls seem to be in use and effective
- ALRRF appears to be operating in accordance with landfill permits and the settlement agreement