

Incandescent Luminaires Installation Instruction



Supply connectors

3.

- 1. Supply conductors may feed through ½" trade size KO in base, or through feed end fitting.
- 2. Feed wires are provided at both ends of luminaires for supply connectors.




Supply conductors

Luminaires connections

Phase lead (hot)—	Black lead
Neutral lead—	White lead
Ground lead	Ground stud


To coupler two or more luminaires

- 1. Remove end caps where luminaires are to butt together.
- 2. Position coupler into the groove of the base so that it straddles two luminaires where they adjoin.
- 3. Tighten set screws, connect wires with wire connectors and snap in cover.



To mount 118 series Luminaires using mounting clips. (For alternate mounting method see other side)


- 1. Secure mounting clips to mounting surface with #8 screws.
- 2. Snap luminaires into mounting clips.




P: 800-421-6196 www.airey-thompson.com

To mount 130, 220, 330 series Luminaires and alternate mounting for 118.

- 1. Remove cover using a putty knife between the cover and base, starting at one end working your way to the other pry the cover off. See picture to the right.
- 2. Drill 9/32" holes in the base, as required to secure to mounting surface.
- 3. Fasten base section with #8 flat head screws.
- 4. Connect feed wires with wires connectors





- 1. Remove key hole knock outs from base.
- 2. Locate the base in desired mounting position.
- 3. Install # 8 or # 10 screws to match key hole spacing.
- 4. Connect wire with wires connectors.

