



I'm not robot



Continue

Pressure conversion chart pdf

1-40 41-80 81-200 205-500 510-900 910-1500 psi bar psi bar psi bar psi bar psi bar psi bar 1.00 0.07 41.00 2.83 81.00 5.59 205.00 14.13 510.00 35.17 910.00 62.76 2.00 0.14 42.00 2.90 82.00 5.65 210.00 14.48 520.00 35.86 920.00 63.45 3.00 0.21 43.00 2.97 83.00 5.72 215.00 14.82 530.00 36.55 930.00 64.14 4.00 0.28 44.00 3.03 84.00 5.79 220.00 15.17 540.00 37.24 940.00 64.83 5.00 0.34 45.00 3.10 85.00 5.86 225.00 15.51 550.00 37.92 950.00 65.52 6.00 0.41 46.00 3.17 86.00 5.93 230.00 15.86 560.00 38.62 960.00 66.21 7.00 0.48 47.00 3.24 87.00 6.00 235.00 16.20 570.00 39.31 970.00 66.90 8.00 0.55 48.00 3.31 88.00 6.07 240.00 16.55 580.00 40.00 980.00 67.59 9.00 0.62 49.00 3.38 89.00 6.14 245.00 16.89 590.00 40.69 990.00 68.28 10.00 0.69 50.00 3.45 90.00 6.21 250.00 17.24 600.00 41.37 1000.00 68.95 11.00 0.76 51.00 3.52 91.00 6.27 255.00 17.58 610.00 42.07 1010.00 69.66 12.00 0.83 52.00 3.59 92.00 6.34 260.00 17.93 620.00 42.76 1020.00 70.34 13.00 0.90 53.00 3.65 93.00 6.41 265.00 18.27 630.00 43.45 1030.00 71.03 14.00 0.97 54.00 3.72 94.00 6.48 270.00 18.62 640.00 44.14 1040.00 71.72 15.00 1.03 55.00 3.79 95.00 6.55 275.00 18.96 650.00 44.82 1050.00 72.41 16.00 1.10 56.00 3.86 96.00 6.62 280.00 19.31 660.00 45.52 1060.00 73.10 17.00 1.17 57.00 3.93 97.00 6.69 285.00 19.65 670.00 46.21 1070.00 73.79 18.00 1.24 58.00 4.00 98.00 6.76 290.00 20.20 680.00 43.90 1080.00 74.48 19.00 1.31 59.00 4.07 99.00 6.83 295.00 20.34 690.00 47.59 1090.00 75.17 20.00 1.38 60.00 4.14 100.00 6.90 300.00 20.69 700.00 48.27 1100.00 75.86 21.00 1.45 61.00 4.21 105.00 7.24 310.00 21.37 710.00 48.97 1120.00 77.24 22.00 1.52 62.00 4.28 110.00 7.58 320.00 22.06 720.00 49.66 1140.00 78.62 23.00 1.59 63.00 4.34 115.00 7.93 330.00 22.75 730.00 50.34 1160.00 80.00 24.00 1.65 64.00 4.41 120.00 8.27 340.00 23.44 740.00 51.03 1180.00 81.38 25.00 1.72 65.00 4.48 125.00 8.62 350.00 24.13 750.00 51.71 1200.00 82.76 26.00 1.79 66.00 4.55 130.00 8.89 360.00 24.82 760.00 52.41 1220.00 84.14 27.00 1.86 67.00 4.62 135.00 9.31 370.00 25.51 770.00 53.10 1240.00 85.52 28.00 1.93 68.00 4.69 140.00 9.65 380.00 26.21 780.00 53.79 1260.00 86.90 29.00 2.00 69.00 4.76 145.00 10.10 390.00 26.89 790.00 54.48 1280.00 88.28 30.00 2.07 70.00 4.83 150.00 10.34 400.00 27.85 800.00 55.16 1300.00 89.66 31.00 2.14 71.00 4.90 155.00 10.69 410.00 28.27 810.00 55.86 1320.00 91.03 32.00 2.21 72.00 4.97 160.00 11.03 420.00 28.96 820.00 56.55 1340.00 92.41 33.00 2.28 73.00 5.03 165.00 11.38 430.00 29.65 830.00 57.24 1360.00 93.79 34.00 2.34 74.00 5.10 170.00 11.72 440.00 30.34 840.00 57.93 1380.00 95.17 35.00 2.41 75.00 5.17 175.00 12.07 450.00 31.03 850.00 58.61 1400.00 96.55 36.00 2.48 76.00 5.24 180.00 12.41 460.00 31.72 860.00 59.31 1420.00 97.93 37.00 2.55 77.00 5.31 185.00 12.76 470.00 32.41 870.00 60.00 1440.00 99.31 38.00 2.62 78.00 5.38 190.00 13.10 480.00 33.10 880.00 60.69 1460.00 100.69 39.00 2.69 79.00 5.45 195.00 13.45 490.00 33.79 890.00 61.38 1480.00 102.07 40.00 2.76 80.00 5.52 200.00 13.79 500.00 34.48 900.00 62.06 1500.00 103.45