

Common Service Price List

	Retail Price	Time (day)
<i>Wheels&Tires</i>		
Front Tire patch	\$35	3
Rear Tire patch	\$55	3
Install New Tube	\$60	3
Front Tire replace (including parts)	\$130	7
Rear Tire replace (including parts)	\$160	7
New Tires (Excluding Installation)	\$60	< 1
Whole Front Wheel (including Hub, Tire) replace	\$300	7
Whole Rear Wheel (including Hub, Tire, motor) replace	\$550	7~14
<i>Gears&Chain</i>		
Pedal replace	\$35	< 1
Crank Arm Pair replace	\$55	3
Chain repair	\$45	3
Chain replace	\$80	3
Freewheel replace	\$65	3
Chain Guard replace	\$45	3
Mudguard-rubbing-tire adjustment	\$20	< 1
Mudguard replace	\$45	3
<i>Brakes</i>		
Brake Pad adjustment	\$40	< 1
Brake Pad replace	\$60	7
Brake Line adjustment	\$40	< 1
Brake Cable replace	\$60	7
Brake Caliper replace	\$60	3
Brake Lever replace (Excluding Brake Cables)	\$25	3
Hydraulic brake fitting replace (Including Brake Lever and Cables)	\$60	3
Disc Brake Rotor replace (Front)	\$100	3
Disc Brake Rotor replace (Rear)	\$130	3
Oil Hose replace	\$120	3
Power Steering Sensor replace	\$120	3
Disc Brake System Assembly(inc.brake lever and cables, oil hose, Disc Brake Caliper)	\$220	3
<i>Electrical Repair</i>		
Phone Holder adjustment	\$60	3
Wireless Charger Phone Holder replace	\$158	3
Headlight and Horn replace	\$60	3
Rear Light replace	\$50	3
Indicator replace	\$60	3
Remote Control replace	\$60	3
Throttle Handle replace	\$100	3
Controller replace	\$100	< 1
Wire Soldering	\$60/hr	-
<i>Accessories</i>		
Seat Support Locker replace	\$25	< 1
Seat Support replace	\$45	< 1
Saddle replace	\$65	< 1
Tire Valve replace	\$40	3
Inflate Tires	\$10	< 1
Derusting and Lubrication	\$15	< 1
New Charger	\$80	< 1
Re-tighten the dropped Screws (including parts)	\$5	< 1
Double Kickstand replace	\$55	< 1
Handlebar Stem replace	\$45	< 1
<i>Other Jobs</i>		
Regular maintenance(lub, inflation,tighten screws)	\$45	< 1
Problem finding fee *If problem is found to be covered under warranty, this fee will be returned to customer.	\$60/hr	-
Labor Cost(per hour)	\$60/hr	-
Front Mudguard Bracket replace	\$60	3
Front Fork Steerer Tube(Excluding Fork Legs) replace	\$250	7
Fork Legs replace	\$250	7
Full Suspension Frame Pivots replace	\$450~500	7~14
Trade in New Frame (Depends in condition)	\$550~650	3