

Common Service Price List

	Retail Price	Time (day)
<i>Wheels&Tires</i>		
Front Tire patch	\$35	3
Rear Tire patch	\$55	3
Install New Inner Tube	\$60	3
Front Tire (inc parts) replace	\$130	7
Rear Tire (inc parts) replace	\$160	7
New Tire (ex Installation)	\$60	< 1
Whole Front Wheel (inc hub, tire) replace	\$300	7
Whole Rear Wheel (inc hub, tire , motor) replace	\$550	7~14
<i>Gears&Chain</i>		
Pedal replace	\$35	< 1
Crank Arm Pair replace	\$55	3
Chain repair	\$45	3
Chain replace	\$80	3
Freewheel replace	\$65	3
Chain Guard replace	\$45	3
Mudguard-rubbing-tire adjustment	\$20	< 1
Mudguard replace	\$45	3
<i>Brakes</i>		
Brake Pad adjustment	\$40	< 1
Brake Pad replace	\$60	7
Brake Cable adjustment	\$40	< 1
Brake Cable replace	\$60	7
Brake Caliper (front or rear) replace	\$60	3
Brake Lever (left or right, ex Brake Cables) replace	\$25	3
Hydraulic Brake Pump (front or rear, inc brake lever and cables) replace	\$60	3
Hydraulic Disc Brake Caliper (front or rear) replace	\$80	3
Disc Brake Rotor (front) replace	\$100	3
Disc Brake Rotor (rear) replace	\$130	3
Oil Hose (front or rear) replace	\$120	3
Brake System Assembly (front or rear, inc.brake pump, oil hose,disc brake rotor)	\$220	3
<i>Electrical Repair</i>		
Phone Holder replace	\$60	3
Wireless Charger Phone Holder replace	\$158	3
Headlight replace	\$60	3

Rear Light Normal replace	\$50	3
Rear Light (with Leaser) replace	\$70	3
Indicator replace	\$60	3
4-in-1 Switch replace	\$60	3
Throttle Handle replace	\$100	3
Remote Control replace	\$60	3
Controller replace	\$100	< 1
Power Steering Sensor replace	\$120	3
Wire Soldering	\$60/hr	-
<i>Accessories</i>		
Seat Clamp replace	\$25	< 1
Seat Support Lock replace	\$25	< 1
Seat Support (with lock) replace	\$45	< 1
Saddle replace	\$65	< 1
Tire Valve replace	\$40	3
New Charger	\$80	< 1
Double Kickstand replace	\$55	< 1
Single stand replace	\$35	< 1
Handlebar Stem replace	\$45	< 1
Handlebar Grip(each) replace	\$10	< 1
<i>Other Jobs</i>		
Re-tighten the dropped Screws (inc parts)	\$5	< 1
Re-inflate tire to correct pressure	\$10	< 1
Derusting and Lubrication	\$15	< 1
Regular Maintenance(lub, inflation,tigthen screws)	\$45	< 1
Problem finding fee *If problem is found to be covered under warranty, this fee will be returned to customer.	\$60/hr	-
Labor Cost(per hour)	\$60/hr	-
Front Mudguard Bracket replace	\$60	3
Front Fork Steerer Tube(ex fork legs) raplace	\$250	7
Fork Legs raplace	\$250	7
Full Suspension Frame Pivots replace	\$450~500	7~14
Trade in New Frame (depends in condition)	\$550~650	3