



SOYAL Conversor USB - AR321CM

Manufacturing Date	Operation System	Chip Version	Driver Version
After 2021/03 ~	Win-11	PL2303-GC	High Note: Please firstly uninstall old driver before installing new driver !!! PL23XX_Prolific_DriverInstaller_V400
2013/01 ~ 2021/03	Win-10	PL2303-HXD	
2008/03 ~ 2012/12	Win-7	PL2303-HX	PL23XX_Prolific_DriverInstaller_V260

Note 1: Step by step uninstall old driver

Go to Control Panel → Device Manager	Important: required to unplug all of AR-321CM devices from computer's USB Port in the first hand
Select Ports (COM & LPT) à select "USB-to-Serial Comm Port", right click à select "Uninstall device"	
Tick the box of option "Delete the driver software for this device." à select "Uninstall"	
Reinstall new USB Driver for Win11	USB Driver version: PL23XX_Prolific_DriverInstaller_V300.exe and after

- Tools for checking chip version : PL23XX_checkChipVersion_v1020.exe
- When auto-simulated USB COM port number is more than 20, it must change number less than 20 ; Moreover, the computer must be restarted after changing the number.