

<u>Model</u>	<u>Location</u>	BMW Coverage 19.5									
		<u>2012</u>	<u>2013</u>	<u>2014</u>	<u>2015</u>	<u>2016</u>	<u>2017</u>	<u>2018</u>	<u>2019</u>	<u>2020</u>	<u>2021</u>
Last 3 digits of Bosch CDR adapter /cable number shown											
BMW	All BMW require 387 Adapter for DTM										
1 Series											
2 Series	Driver side, behind IP, rt of strg										
2 Series xdrive	Center console between seats										
3 Series	Passenger side, behind the glove box										
Active Hybrid 3	Driver side, behind IP, rt of strg										
4 Series	Passenger side, behind the glove box										
5 Series	Passenger side, behind the glove box										
6 Series	See Service Manual										
6 Series GT	Passenger side, behind the glove box										
7 Series	Passenger side, behind the glove box										
8 Series	Passenger side, behind the glove box										
X3 xDrive	Center Tunnel, Between Seats										
X5	Center Tunnel, Between Seats										
X1, X2	See Help File - Various										
X3, X4	Center Tunnel, Between Seats										
X6	See Service Manual										
X7	Center Tunnel, Under Dash										
Z4	See Service Manual										
i3, i8											
The source data for this chart is the Bosch CDR help file for Version 19.5											
Always consult the latest help file for the most accurate coverage											
Copyright Ruth Consulting LLC 2020 - Authorized for distribution by UNF-IPTM & SAE											