



SKYLIFT HEBEGERÄTE GmbH

(SKYLIFT HOISTING EQUIPMENT GmbH)

PHONE: +49 176 47638924 | E-MAIL: INQUIRY@EMPIRE-ENGG.CO

RENNBAHN STREET | OFFICE NUMBER 115 | PC 50737 | COLOGNE | GERMANY


(EINE TOCHTERGESELLSCHAFT VON EMPIRE OF ENGINEERING – SULTANAT OMAN)

Webbing Slings

- Manufactured from 100% high tenacity polyester
- Available in 1 Ply, 2 Ply, 3 Ply and 4 Ply and Endless with either soft becket eye or metal (reeve able or non-reeve able) terminal fittings
- WLL from 500 Kg to 48 Ton and to almost any lengths
- Multi leg sling also available
- Wear protectors available to protect the slings
- Factor of Safety 7:1

Round (Endless) Slings

- Manufactured from 100% high tenacity polyester
- Covered by a seamless tightly woven, heavy duty polyester tubular sleeve
- WLL 1 ton to 200 Ton
- Available from 0.5 Meter EWL up to almost any length
- Wear protectors available to protect the slings
- Factor of Safety 7:1

					
	Straight Pull	Choke Lift	basket Lift 0 to 7°	basket Lift 0 to 45°	basket Lift 45° to 60°
Colour	tonne	tonne	tonne	tonne	tonne
Violet	1	0.8	2	1.4	1
Green	2	1.6	4	2.8	2
Yellow	3	2.4	6	4.2	3
Grey	4	3.2	8	5.6	4
Red	5	4.0	10	7.0	5
Brown	6	4.8	12	8.4	6
Blue	8	6.4	16	11.2	8
Orange	10	8.0	20	14.0	10
Orange	12	9.6	24	16.8	12
Orange	15	12.0	30	21.0	15
Orange	20	16.0	40	28.0	20
Orange	30	24.0	60	42.0	30

SAFE USE INFORMATION

Deutsche

- Es sollten nur Tragegurte mit lesbaren Etiketten verwendet werden.
- Das Gewicht der Last sollte innerhalb der Nenntagfähigkeit des Hebegurts liegen.
- Die Temperatur darf 90 °C nicht überschreiten und nicht unter -40 °C.
- Testlast und Bruchlast, die auf die Rohmaterial-Chargenprobe angewendet werden, durchgeführt von autorisiertem Personal/einer Agentur.
- Die Gültigkeit des Zertifikats erlischt, wenn am Produkt eine Reparatur oder Änderung durchgeführt wird.
- Ohne vorherige schriftliche Zustimmung des Herstellers, der Prüfstelle oder des Auftraggebers darf das Prüfzeugnis in keiner Weise vervielfältigt werden.
- Gemäß den grundlegenden Sicherheitsanforderungen der Maschinenrichtlinie sind die oben genannten Produkte zum Zeitpunkt der Lieferung "SICHER ZU VERWENDEN".

Haftungsklausel:

Kommt es während der Inspektion zu Handlungen oder Unterlassungen der Inspektionsstelle gegenüber der Ausrüstung, kann diese haftbar gemacht werden. Die Inspektionsstelle haftet nicht für Mängel, die nach der Inspektion aufgrund schlechter Wartung oder unsachgemäßer Verwendung der Ausrüstung auftreten. Die Inspektionsstelle akzeptiert nach Abschluss der Inspektion keine Ansprüche hinsichtlich des Zustands oder der Sicherheit der Ausrüstung. Nach Abschluss der Inspektion besteht keinerlei Gewährleistung mehr.

English

- Only straps with readable labels should be used.
- The weight of the load should be within the rated capacity of the sling.
- The temperature must not exceed 90 °C and not below -40 °C.
- Test load and breaking load applied to the raw material batch sample carried out by authorised personnel / agency.
- The validity of the certificate expires if a repair or modification is carried out on the product.
- The test certificate may not be reproduced in any way without the prior written consent of the manufacturer, the testing center or the client.
- According to the essential safety requirements of the Machinery Directive, the above products are "SAFE TO USE" at the time of delivery.

Liability clause:

If any actions or omissions by the inspection body towards the equipment occur during the inspection, they may be held liable. The inspection body is not liable for defects that occur after the inspection due to poor maintenance or improper use of the equipment. The inspection body will not accept any claims regarding the condition or safety of the equipment after the inspection is completed. Once the inspection is complete, there is no longer any warranty.