

| Product Category | HS Code | Model Number | Short Description | PL LP (in INR) | MRP (in INR) | Standard Certificate |
|---------------------|-----------|-----------------------|---|----------------|--------------|-------------------------------------|
| Digital Multimeters | 9030 3100 | 1018H | Digital Multimeter: <ul style="list-style-type: none"> • Display : 4000 counts. • Auto range. • Diode test feature. • Capacitance test feature. • Continuity test. Inc. Accessories: LR44× 2, Instruction Manual, Hard Case  | | | |
| | 9030 3100 | 1019R | Digital Multimeter: <ul style="list-style-type: none"> • Elegant shiny-black finish • Comes with user-friendly Hard case • Large Display • Accurate reading with True-RMS technology • Electronic protection (no fuse!) on ohm and continuity ranges • Safety Standard IEC 61010-1 / 61010-031 / 61010-2-033 CAT III 300V / CAT II 600V Inc. Accessories: 9188 (Hard case), CR2032 × 1, Instruction manual  | 9656 | 11775 | Certificate of Conformity |
| | 9030 3100 | 1009 | Digital Multimeter; <ul style="list-style-type: none"> • Display : 4000 counts. • Auto range and manual range selector provided. (with range hold feature) • Resistance range provides audible continuity test. • Automatically turns power off in about 30 minutes to conserve battery life. • Direct current measurement up to 10A AC and DC. • With Holster. Inc. Accessories: 7066A (Test leads), 8919 (Ceramic fuse [10A/600V])× 1, 8923 (Fuse [0.5A/600V])× 1, R6× 2, Instruction Manual  | 6897 | 8411 | Certificate of Conformity |
| | 9030 3100 | 1021R | 211  | 11311 | 13794 | Certificate of Conformity |
| | 9030 3100 | 1051 | Digital Multimeter: For Electrical and Electronic Troubleshootings High Accuracy, High Performance and Reliable Measurements <ul style="list-style-type: none"> • 0.09% basic DC accuracy • Large display with 6,000 counts • True-RMS Measurements • Low-pass filter for motor drive measurements • User Test function Safety design for industrial use <ul style="list-style-type: none"> • Complies with IEC 61010-1 CAT IV 600V, CAT III 1000V • Terminal shutter to prevent incorrect test leads' insertion in current terminals • Very wide operating temperature range from -10 to 55°C Inc. Accessories: 7220A (Test leads), R6×4, Instruction manual, 8926 (Fuse [440mA/1000V])×1 (included), 8927 (Fuse [10A/1000V])×1 (included)  | 47069 | 57401 | Test Certificate from KEW (A4 Size) |

| | | | | | | |
|---|------------------|---------------------|---|--|--|--|
| <p>Digital Pen Type Multimeter</p> | <p>9030 3100</p> | <p>1030</p> | <p>Digital Pen Type Multimeter:</p> <ul style="list-style-type: none"> • Compact in Size, Light in Weight and Simple in Use. • Double moulding provides comfortable and good feeling in hand. • Penlight illuminates brightly the point to be measured, even in dark place. • Backlight LCD is highly visible, even in darkness. • Unique wrapping mechanism for test lead in the rear side compartment. • Unique protection mechanism for the test prod for safety. • All ranges including Ohm range are protected against overload voltage of 600V. <p>Inc. Accessories: Carrying case, LR44 (1.5V) × 2, Instruction manual</p>  | <p>7725</p> | <p>9420</p> | <p>Certificate of Conformity</p> |
| <p>AC Analog Clamp Meter</p> | <p>9030 3900</p> | <p>2608A</p> | <p>AC Analog Clamp Meter:</p> <ul style="list-style-type: none"> • DC voltage range is also available especially for checking emergency battery operated power supply. • Can measure temperature using optional probe. • Tear drop shaped transformer jaws for ease of use. <p>Inc. Accessories: 7066A (Test leads), 8923 (Fuse [0.5A/600V]) × 2, 9097 (Carrying case), R6 (AA) × 1, Instruction Manual</p>  | <p style="background-color: red;"></p> | <p style="background-color: red;"></p> | <p style="background-color: red;"></p> |
| <p>Digital AC Clamp Meters</p> | <p>9030 3900</p> | <p>2117R</p> | <p>Digital Clamp Meter:</p> <ul style="list-style-type: none"> • Fully Safety jaw • Ergonomic over-molded body gives convenient one-hand operation • Large easy-to-read display with 0.01A resolution • Accurate reading with True RMS 60/600/1000A auto-ranging • Long battery life • Safety Standard IEC 61010-1 CAT IV 300V / CAT III 600V <p>Inc. Accessories: 7066A (Test leads), 9079 (Carrying case), R03 (AAA) × 2, Instruction Manual</p>  | <p>13242</p> | <p>16149</p> | <p>Certificate of Conformity</p> |
| <p></p> | <p>9030 3900</p> | <p>200</p> | <p>Digital AC Clamp Meter:</p> <ul style="list-style-type: none"> • Measures Current up to 400A AC & Voltage up to 600V AC • Resistance, Continuity buzzer • Conductor Size *30mm • Data hold memory function and Sleep feature | <p>7449</p> | <p>9084</p> | <p>Certificate of Conformity</p> |
| <p>Digital AC/DC Clamp Meter</p> | <p>9030 3900</p> | <p>2003A</p> | <p>Digital Clamp Meter:</p> <ul style="list-style-type: none"> • Equipped to measure both AC and DC current with transformer jaws of large diameter. • Can measure AC and DC currents up to 2000A. • Output terminal for connection to recorders. <p>Inc. Accessories: 7107A (Test leads), 8201 (Output Plug), 9094 (Carrying Case), R6 (AA) × 2, Instruction Manual</p>  | <p>31726</p> | <p>38691</p> | <p>Certificate of Conformity</p> |
| <p></p> | <p>9030 3900</p> | <p>203</p> | <p>Digital Clamp Meter:</p> <ul style="list-style-type: none"> • Measures Current up to 400A AC/DC & Voltage up to 600V AC/DC • Resistance, Continuity buzzer • Conductor Size *30mm • Data hold memory function and Sleep feature | <p>11353</p> | <p>13846</p> | <p>Certificate of Conformity</p> |
| <p></p> | <p>9030 3900</p> | <p>2055</p> | <p>Digital Clamp Meter:</p> <ul style="list-style-type: none"> • Designed to meet international safety standard IEC 61010-1 CAT IV 600V. • CAT IV Clamp Meters can measure the Voltage and Current in both every low and high power circuits. • Thus, very useful for power distribution companies, power utilities and maintenance fields <p>Inc. Accessories: 7107A (Test leads), 8201 (Output Plug), 9094 (Carrying Case), R6 (AA) × 2, Instruction Manual</p>  | <p>23450</p> | <p>28597</p> | <p>Certificate of Conformity</p> |
| <p>Power Clamp Meter</p> | <p>9030 3300</p> | <p>2062</p> | <p>Power AC Clamp Meter:</p> <ul style="list-style-type: none"> • Conductor size ϕ55mm • Current up to 1000A rms • Voltage up to 1000V rms • Harmonics up to 30th • Phase rotation <p>Inc. Accessories: 7290 (Test leads), 9198 (Soft Case), LR6(AA)×2, Instruction Manual</p>  | <p>87279</p> | <p>106438</p> | <p>Certificate of Conformity</p> |

| | | | | | | |
|--|-----------|-------|---|--------|--------|-------------------------------------|
| Digital AC/DC Fork Current Tester | 9030 3900 | 2300R | Fork Current Tester: <ul style="list-style-type: none"> • True RMS reading is an essential feature for accurate measurement. • “Non Contact” voltage function indicates the presence of AC voltage by warning the user with an audible signal. • Set the DC current range to zero in one touch with the Zero Adjust function. Incl. Accessories: Carrying Case, R03 (AAA) x 2, Instruction Manual  | 16277 | 19850 | Certificate of Conformity |
| Digital AC Leakage Current Clamp Meter | 9030 3900 | 2434 | Leakage Clamp Meter <ul style="list-style-type: none"> • Least affected by external stray magnetic field. • 20mA AC max. in proximity to a 15mm-dia conductor carrying 100A AC • Frequency Selector Switch to eliminate the effect of harmonics. • Resolution 0.1mA. Incl. Accessories: 9097 Carrying Case, R03 x 2, Instruction Manual  | 34485 | 42055 | Test Certificate from KEW (B6 Size) |
| Insulation Tester Digital | 9030 3900 | 3005A | Digital Insulation/Continuity Tester <ul style="list-style-type: none"> • Bargraph to display insulation resistance. • Displays the value of external AC voltage along with flashing symbol. • Auto null function to automatically subtract the test lead resistance before displaying the real continuity resistance value. • Live circuit warning beeper. • Releasing the test button automatically discharges the charges stored in the circuit under test. • 200mA continuity measuring current to IEC 61557. • Minimum 1mA current on insulation tests to IEC 61557. Incl. Accessories: 7122B (Test leads) Pouch for test leads, 8923 (F500mA/600V fuse) x 2, R6 (AA) x 8, Shoulder Strap, Instruction Manual  | 38318 | 46729 | Test Certificate from KEW (A4 Size) |
| | 9030 3900 | 3552 | Digital Insulation / Continuity Testers <ul style="list-style-type: none"> • World's fastest measurement speed (0.5 sec.) • Six ranges available for insulation resistance test (50/100/125/250/500/1000 V) • Insulation measurement up to 40GΩ • Diagnostic Insulation Test : PI, DAR KEW3552 : With memory function Incl. Accessories : 7260 (Test leads with remote control switch, 7261A (Test leads with alligator clip) , 8017A (Extension prod long) , 9173 (Carrying case) ,9121 (Shoulder strap) , LR6 (AA) (1.5V) x4, Instruction manual  | 63863 | 77881 | Certificate of Conformity |
| | 9030 3900 | 3125A | High Voltage Insulation Tester <ul style="list-style-type: none"> • Insulation Resistance up to 1TΩ • Short-Circuit Current up to 1.5mA • Wide Test Voltage from 250V to 5000V • Diagnosis Function of PI and DAR • Newly-designed alligator clip • It comes with a tough hard case • Filter function reduces noise interference for obtaining stable measurement • Large display with Bar Graph indication and backlight • Live voltage warning • Safety standard IEC 61010-1 CAT IV 300V / CAT III 600V Incl. Accessories: 7165A (Line probe: 3m), 7264 (Earth cord: 3m), 7265 (Guard cord: 3m), 8019 (Hook type prod), 9180 (3025A Hard case), 9181 (3125A Hard case), LR14 (AAA) x 6, Instruction Manual  | 125802 | 153417 | Test Certificate from KEW (A4 Size) |
| Earth Tester Digital | 9030 3320 | 4105A | Earth Resistance Tester <ul style="list-style-type: none"> • Dust and drip proof.(designed to IEC 529 IP54) • In addition to the facility for precision measurement, test leads for simplified two wire measuring system also supplied as standard accessories. (unit can be hung from the neck for simplified measurement) • Designed to meet IEC 61010-1 safety standard. • Capable of measuring earth voltage. • Automatic warning when resistance of auxiliary earth spikes is in excess of tolerance. • Small and lightweight. Shock resistant new case material. • 2mA measuring current permits earth resistance tests without tripping earth leakage current breakers in the circuit under test. Incl. Accessories: 7095A (Earth resistance test leads) x 1set (red-20m, yellow-10m, green-5m), 8032 (Auxiliary earth spikes) x 1set, 7127A (Simplified measurement probe) x 1set, R6 (AA) x 6, Neck strap, Instruction Manual | 38899 | 47438 | Certificate of Conformity |

| | | | | | | |
|---------------------------|-----------|--------------|--|----------|-------|-------------------------------------|
| RCD Tester | 9030 3900 | 5406A | Digital RCD Tester <ul style="list-style-type: none"> • Custom microprocessor controlled for highest accuracy and reliability. • 3 LEDs for checking correct wiring status. • 0 and 180 degree phase angle switch permits quick tests and consistent readings. • Digital read-out of tripping time. | 43521 | 53075 | Test Certificate from KEW (A4 Size) |
| Phase Indicator | 9030 3390 | 8031 | Phase Indicator <ul style="list-style-type: none"> • Digital Phase Indicator with open phase checker. • Phase indicator designed to check the presence of open phase and also the phase sequence by LED and buzzer at the same time. • Small, lightweight, and portable. | 12139 | 14803 | Certificate of Conformity |
| Insulation Tester Digital | 9030 3900 | 3125B | High Voltage Insulation Tester (with reinforced Green Body) <ul style="list-style-type: none"> • Insulation Resistance up to 1TΩ • Short-Circuit Current up to 1.5mA • Wide Test Voltage from 250V to 5000V • Diagnosis Function of PI and DAR • Newly-designed alligator clip • It comes with a tough hard case • Filter function reduces noise interference for obtaining stable measurement • Large display with Bar Graph indication and backlight • Live voltage warning • Safety standard IEC 61010-1 CAT IV 300V / CAT III 600V Inc. Accessories: 7165A (Line probe), 7264 (Earth cord), 7265 (Guard cord), 8019 (Hook type prod). 9204 (Carrying case (Hard)). LR14 (Alkaline battery size C) × 8, Instruction manual | 1,25,802 | ##### | Test Certificate from KEW (A4 Size) |

