

KYORITSU


Test and Measuring Instruments



Quality and reliability is our tradition

KYORITSU

Japan
QUALITY



Digital Multimeters

1018H



DC V AC V Ω \bullet \rightarrow \leftarrow \rightarrow \leftarrow Hz DUTY DATA HOLD REL AUTO POWER OFF CAT III

- Display : 4000 counts.
- AC/DC 600V \pm 0.8% rdg Basic Accuracy.
- Auto range.
- Diode test feature.
- Capacitance test feature.

Inc. Accessories:
LR44 (AG 13) \times 2,
Hard Case
Instruction Manual

NEW

1019R



True RMS DC V AC V Ω \bullet \rightarrow \leftarrow REL AUTO POWER SAVE CAT III

- Display : 6000 counts.
- AC/DC 600V \pm 0.5% rdg Basic Accuracy
- Accurate reading with True-RMS technology
- Electronic protection (no fuse!) on ohm and continuity ranges

Inc. Accessories:
9188 (Hard case), CR2032 \times 1,
Instruction manual

1009



DC V AC V AC A DC A Ω \bullet \rightarrow \leftarrow Hz DUTY DATA HOLD REL AUTO POWER OFF CAT III

- Display : 4000 counts.
- AC/DC 600V \pm 0.6% rdg Basic Accuracy
- Auto range and manual range selector provided.
- Resistance range provides audible continuity test.
- Automatically turns power off in about 30 minutes to conserve battery life.
- Direct current measurement up to 10A AC and DC.

Inc. Accessories:
7066A (Test leads),
8919 (Ceramic fuse [10A/600V]) \times 1,
8923 (Fuse [0.5A/600V]) \times 1, R6 (AA) \times 2,
Instruction Manual

NEW

1021R



True RMS CAT II 1000V DC V AC V DC A AC A Ω \bullet \rightarrow \leftarrow Hz DUTY \odot DATA HOLD REL MAX/MIN AUTO POWER SAVE

- Display : 6000 counts.
- AC/DC 600V \pm 0.5% rdg Basic Accuracy
- Elegant and easy-to-use cabinet
- Enhanced current measuring function using an external clamp sensor
- Two detachable holders, flat and wing type
- Accurate reading with True RMS

Inc. Accessories:
Wing-type holder, Flat-type holder,
7066A (Test leads), 8919 (Ceramic fuse [10A/600V]) \times 1 (included),
9097 (Carrying case), R03 (AAA) \times 2,
Instruction manual

Digital Pen Type Multimeter

1030



DC V AC V Ω \bullet \rightarrow \leftarrow Hz \odot DATA HOLD REL AUTO POWER OFF DUTY CAT III

- Display : 6000 counts.
- AC/DC 600V \pm 0.8% rdg Basic Accuracy
- Compact in Size, Light in Weight and Simple in Use.
- Double moulding provides comfortable and good feeling in hand.
- Penlight illuminates brightly the point to be measured.
- Backlight LCD is highly visible, even in darkness.
- Unique protection mechanism for the test prod for safety.

Inc. Accessories:
Carrying case,
LR44 (AG 13, 1.5V) \times 2,
Instruction manual

AC Analog Clamp Meter

2608A



\emptyset 33 MAX 300A $^{\circ}$ C AC A DC V Ω DATA HOLD CAT III

- AC/DC 300V \pm 3% of FS Accuracy
- DC voltage range is also available especially for checking emergency battery operated power supply.
- Can measure temperature using optional probe.
- Tear drop shaped transformer jaws for ease of use.

Inc. Accessories:
7066A (Test leads), 8923 (Fuse [0.5A/600V]) \times 2,
9097 (Carrying case), R6 (AA) \times 1,
Instruction Manual

Digital AC Clamp Meters

NEW

2117R



True RMS 033 MAX 1000A AC A DC V Ω
NCV DATA HOLD AUTO POWER SAVE CAT III

- AC A-1000A $\pm 1.5\%$ rdg Basic Accuracy
- Elegant and easy-to-use cabinet
- Large display with 6000 counts and Backlight
- Enhanced current measuring function using an external clamp sensor
- Two detachable holders, flat and wing type
- Accurate reading with True RMS

Inc. Accessories:
7066A (Test leads),
9079 (Carrying case),
R03 (AAA) $\times 2$,
Instruction Manual

200



030 MAX 400A AC A DC V Ω
DATA HOLD AUTO POWER SAVE CAT III

- AC 400A $\pm 2\%$ rdg Basic Accuracy
- Measures Current up to 400A AC & Voltage up to 600V AC
- Resistance, Continuity buzzer
- Conductor Size $\phi 30\text{mm}$
- Data hold memory function and Sleep feature
- Display: 4000 counts
- Complies to IEC61010-1 (CAT. III) UL3111 & VDE0411 300V

Inc. Accessories: 7066A (Test leads),
R03 (AAA) $\times 2$
Instruction Manual

Digital AC/DC Clamp Meters

2003A



CAT IV 600V 055 MAX 2000A DC AC A DC V Ω
DATA HOLD PEAK HOLD OUTPUT HOLDING SAVE

- AC/DC 2000A $\pm 1.5\%$ rdg Basic Accuracy
- Equipped to measure both AC and DC current with transformer jaws of large diameter.
- Output terminal for connection to recorders.

Inc. Accessories: 7107A (Test leads),
8201 (Output Plug), 9094 (Carrying Case),
R6 (AA) $\times 2$,
Instruction Manual

2055



CAT IV 600V 040 MAX 1000A DC AC V DC AC A Ω
Hz DUTY NCV DATA HOLD PEAK HOLD
MAX/MIN REL AUTO POWER OFF

- AC/DC 1000A $\pm 1.5\%$ rdg Basic Accuracy
- Very useful for power distribution companies, power utilities and maintenance fields.
- Red LED, as "Non Contact Voltage" function, gives warning to the user on the presence of AC voltage.
- Double molding gives comfortable feeling in palm.
- 6039 counts with Bar Graph display.

Inc. Accessories: 7066A (Test leads),
9094 (Carrying case), R03 (AAA) $\times 2$
Instruction Manual

Digital AC/DC Clamp Meter

203



030 MAX 400A AC A DC V Ω
DATA HOLD AUTO POWER SAVE CAT III

- AC/DC 400A $\pm 3.0\%$ rdg Basic Accuracy
- Measures Current up to 400A AC/DC & Voltage up to 600V AC/DC
- Resistance, Continuity buzzer
- Conductor Size $\phi 30\text{mm}$
- Data hold memory function and Sleep feature

Inc. Accessories: 7066A (Test leads),
R03 (AAA) $\times 2$
Instruction Manual

Digital AC/DC Fork Current Tester

2300R



True RMS 010 MAX 100A DC AC A NCV DATA HOLD
AUTO POWER OFF

- AC/DC 600A $\pm 1.5\%$ rdg Basic Accuracy
- Measures Current up to 400A AC/DC & Voltage up to 600V AC/DC
- Resistance, Continuity buzzer
- Conductor Size $\phi 30\text{mm}$
- Data hold memory function and Sleep feature

Inc. Accessories: Carrying Case,
R03 (AAA) $\times 2$,
Instruction Manual

Digital AC Leakage Clamp Meter



2434

028 MAX 100A Resolution 1mA AC A DATA HOLD Filter AUTO POWER SAVE

- AC 400mA/4/100A $\pm 2\%$ rdg Basic Accuracy
- Least affected by external stray magnetic field.
- 20mA AC max. in proximity to a 15mm-dia conductor carrying 100A AC
- Frequency Selector Switch to eliminate the effect of harmonics.
- Resolution 0.1mA.

Inc. Accessories: 9097 Carrying Case, R03 (AAA) $\times 2$, Instruction Manual

Digital Earth Tester



4105A

CE

Inc. Accessories: 7095A (Earth resistance test leads) $\times 1$ set (red-20m, yellow-10m, green-5m), 8032 (Auxiliary earth spikes) $\times 1$ set, 7127A (Simplified measurement probe) $\times 1$ set, R6 (AA) $\times 6$, Neck strap, Instruction Manual Carrying case : 9084(Carrying case[Soft]).

- Earth resistance value can be read directly from the scale(0.00-1999 Ω)
- Capable of measuring earth voltage(0-200V AC)
- Dust and drip proof.(designed to IEC 60529 IP54)
- Small and lightweight. Shock resistant new case material.
- Measurement of the earth electrode resistance(3-pole method)
- Measurement of the simplified earth resistance(2-pole method)
- In addition to the facility for precision measurement, test leads for simplified two wire measuring system also supplied as standard accessories.

Digital Insulation Testers



3005A

1KV Ω AUTO POWER OFF CAT III

- Measuring range - 250V - 1000V
- Ω - upto 2000M Ω
- Bargraph to display insulation resistance.
- Displays the value of external AC voltage along with flashing symbol.
- Auto null function to automatically subtract the test lead resistance before displaying the real continuity resistance value.
- Live circuit warning beeper.
- Releasing the test button automatically discharges the charges stored in the circuit under test.

Inc. Accessories: 7122B (Test leads) Pouch for test leads, 8923 (F500mA/600V fuse) $\times 2$, R6 (AA) $\times 8$, Shoulder Strap, Instruction Manual



3125A

5KV DC AC A DC AC V Ω AUTO POWER OFF

- Wide Test Voltage from 250V to 5000V
- Insulation Resistance up to 1T Ω
- Short-Circuit Current up to 1.5mA
- Diagnosis Function of PI and DAR
- Filter function reduces noise interference for obtaining stable measurement
- Bar Graph to display Insulation Resistance

Inc. Accessories: 7165A (Line probe: 3m), 7264 (Earth cord: 3m), 7265 (Guard cord: 3m), 8019 (Hook type prod), 9180 (3025A Hard case), 9181 (3125A Hard case), LR14 (Alkaline battery size C) $\times 8$, Instruction manual

RCD Tester



5406A

- Rated Tripping current - 10/20/30/200/300/500mA
- Custom microprocessor controlled for highest accuracy and reliability.
- 3 LEDs for checking correct wiring status.
- 0 and 180 degree phase angle switch permits quick tests and consistent readings.
- Digital read-out of tripping time.
- Constant current source circuitry ensures that a fluctuating mains voltage does not affect the accuracy of readings.

Inc. Accessories: Molded plug test leads, Pouch for test leads Shoulder Strap, Instruction Manual

Phase Rotation Tester




8031

CE

- Operational voltage - 110-600V AC
- Digital Phase Indicator with open phase checker.
- Phase indicator designed to check the presence of open phase and also the phase sequence by LED and buzzer at the same time.
- Small, lightweight, and portable.

Inc. Accessories: 9029 (Carrying Case), Instruction manual

Kyoritsu Product Range: Meeting diverse user needs & Applications:



Above products are available on request.
For complete product range visit: www.kew-ltd.co.in



Repair & Calibration Centre India

Recently, **Kyoritsu Kew India** commissioned a full-fledged, techno-empowered **service centre in Mumbai**, India, which offers best-in-class global solutions with local accessibility.

With a technically trained and experienced service personnel specially groomed in customer-friendliness, quick-response paradigms and an overall culture of proactive support, the after-sale experience of Kyoritsu clients inside India has been made even more sure and easy.

India Service Centre: Contact Details:

Kyoritsu KEW India Instruments Pvt. Ltd.
C/o M/s Clear Point Instrumentation Pvt Ltd™
B2/406, 4th Floor, Boomerang, Chandivali Farm Road,
Andheri East, Mumbai – 400072.

E-mail: service@kew-india.co.in

Mobile: +91-7096110404
+91-7096610404



Quality and reliability is our tradition

KYORITSU

W: www.kew-ltd.co.in

Kyoritsu KEW India Instruments Pvt. Ltd.

#4, S P Nagar, Navrangpura, Ahmedabad-380006. India.

T : +91 98246 80404; F : +91 79 2640 9942;

E: info@kew-india.co.in

