Insured/Applicant Name:	Application / Policy #:				
Address Inspected: Tampa, FL 33611					
Actual Year Built: 1954					
Minimum Photo Requirements:  ☐ Dwelling: Each side ☐ Roof: Each slope ☐ Main electrical service panel with interior of ☐ Electrical box with panel off ☐ All hazards or deficiencies noted in this re	door label				
Be advised that Underwriting will rely on th licensed professional of your choice. This i suitability, fitness or longevity of any of the	nformation only is used		or form, that is obtained from the Florida oility and is not a warranty or assurance of the		
Electrical System Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.					
Main Panel  Type: ☑ Circuit breaker ☐ Fuse  Total Amps: 200  Is amperage sufficient for current usage? ☑ Yes ☐ No (explain)		Second Panel  Type:  Circuit breaker  Fuse  Total Amps:  N/A  Is amperage sufficient for current usage?  Yes  No (explain)			
Indicate presence of any of the following:  Cloth wiring Active knob and tube Branch circuit aluminum wiring (If present, If single strand (aluminum branch) wiring, pre Connections repaired via COPALUM crimp Connections repaired via AlumiConn	ovide details of all remediat	σ,	ntation of all work must be provided.		
Hazards Present  Blowing fuses Tripping breakers Empty sockets Loose wiring Improper grounding Corrosion Over fusing		☐ Double taps ☐ Exposed wiring ☐ Unsafe wiring ☐ Improper breaker size ☐ Scorching ☐ Other (explain)			
General condition of the electrical system:	☐ Satisfactory		I needed right of kitchen sink, laudry hall light circuit ds a repair.		
Supplemental information					
Main Panel Panel age: 10 Years Year last updated: 2010 Brand/Model: Square D	Second Panel Panel age: N/A Year last updated: Brand/Model:		Wiring Type  ☑ Copper ☑ NM, BX or Conduit		

HVAC System					
Central AC: ✓ Yes ☐ No  Central heat: ✓ Yes ☐ No  If not central heat, indicate <b>primary</b> heat source and fuel type:  Are the heating, ventilation and air conditioning systems in good working order? ✓ Yes ☐ No (explain)  Date of last HVAC servicing/inspection: Unknown					
Hazards Present  Wood-burning stove or central gas fireplace <i>not</i> professionally installed? ☐ Yes ☑ No  Space heater used as primary heat source? ☐ Yes ☑ No  Is the source portable? ☐ Yes ☑ No  Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area? ☐ Yes ☑ No					
Supplemental Information					
Age of system: 1 Year  Year last updated: 2019  (Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)					
Plumbing System					
Is there a temperature pressure relief valve on the water heater?  Yes  No Is there any indication of an active leak?  Yes  No Is there any indication of a prior leak?  Yes  No Water heater location: Laundry Room					
General condition of the following plumbing fixtures and connections	to appliances:				
Satisfactory Unsatisfactory N/A  Dishwasher  Refrigerator  Washing machine  Water heater  Showers/Tubs  Unsatisfactory  Unsatisfactory  Unsatisfactory  N/A  U  Showerisfactory  Unsatisfactory  Unsatisfactory  Unsatisfactory  Unsatisfactory  Unsatisfactory  N/A  Unsatisfactory  N/A  Unsatisfactory  N/A  Unsatisfactory  N/A  Unsatisfactory  N/A  Unsatisfactory  N/A  Showerisfactory  N/A  Unsatisfactory  Unsatisfactory  N/A  Unsatisfactory  N/A  Unsatisfactory  N/A  Unsatisfactory  N/A  Unsatisfactory  N/A  Unsatisfactory  Unsatisfactory  N/A  Unsatisfactory  N/A  Unsatisfactory  N/A  Unsatisfactory  Unsatisfactory  N/A  Unsatisfactory  N/A  Unsatisfactory  Unsatisfactory  N/A  Unsatisfactory  Unsatisfactory  N/A  Unsatisfactory  N/A  Unsatisfactory  Unsatisf	Satisfactory Unsatisfactory N/A Toilets				
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.). Permanently cap the unused drain as needed below the kitchen sink.					
Supplemental Information					
Age of Piping System:	Type of pipes (check all that apply)  Copper  PVC/CPVC  Galvanized  PEX  Polybutylene  Other (specify)				

Roof (With photos of each roof slope, this section can take the place of the Roof Inspection Form.)					
Predominant Roof		Secondary Roof			
Covering material: Dimensional Shingle	1	Covering material: Metal Porch roof			
Roof age (years): 2 Years		Roof age (years): 10 Years			
Remaining useful life (years): 16-18 Ye	ars	Remaining useful life (years): 30+ Years			
Date of last roofing permit: 02/05/2018		Date of last roofing permit:			
Date of last update: 02/05/2018		Date of last update:			
If updated (check one):		If updated (check one):			
✓ Full replacement		☐ Full replacement			
☐ Partial replacement		☐ Partial replacement			
% of replacement:		% of replacement:			
Overall condition:		Overall condition:			
✓ Satisfactory		✓ Satisfactory			
☐ Unsatisfactory (explain below)		☐ Unsatisfactory (explain below)			
Any visible signs of damage / deterioration?  (check all that apply and explain below)  Cracking Cupping/curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage  Any visible signs of leaks? Yes No  Attic/underside of decking Yes No  Interior ceilings Yes No  Additional Comments/Observations (use additional)		Any visible signs of damage / deterioration?  (check all that apply and explain below)  Cracking Cupping/curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage  Any visible signs of leaks? Yes No  Attic/underside of decking Yes No  Interior ceilings Yes No			
All 4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector.  I certify that the above statements are true and correct.					
(: X . )					
Amon Hwam	Owner/Inspector	HI3254	December 17, 2020		
Inspector Signature	Title	License Number	Date		
Bayside Building Consultants, LLC Company Name	Home Inspector License Type	813-990-0861 Work Phone			

**Special Instructions**: This sample *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

### **Photo Requirements**

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- · Dwelling: Each side
- Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- Open main electrical panel and interior door
- · Electrical box with the panel off
- · All hazards or deficiencies

#### **Inspector Requirements**

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. **Examples** include:

- · A general, residential, or building contractor
- · A building code inspector
- A home inspector

*Note:* A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

### **Documenting the Condition of Each System**

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

#### **Additional Comments or Observations**

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- · Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- · Any system determined not to be in good working order

#### **Note to All Agents**

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

















































