		DATE RECORDING TACH TOD,
	Completed 10 Piper SM. Cle Piper SM. Cle 13-02-13 Stab serviced brake for gear swing and lubricated filter. Inspect DUE: 5/2024. aircraft was ins at this time.	TOTAL TIME IN SERVICE
Jeb Ragsdale A&P 2732467	eted 100HR Inspection IAW FAR 43 appendix D referencing IM. Cleaned aircraft and lubricated all parts as req'd. C/W AD 13 Stabilator control turnbuckles next due@ 6708.8. Bled and d brakes with new fluid (aeroshell 4) MOC OK. Jacked aircraft r swing and emergency drop check. Gear MOC OK, all lights rming horn operational with no faults found. Cleaned, inspected ricated as req'd both LH and RH wings. Replaced regulator inspected ELT Ref 91.207(D), ELT Battery replacement 5/2024. Verified all Airworthiness Directives. I certify that this was inspected IAW a 100HR inspection and is found airworthy ime.	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)

DATE	TION OF INSPECTIONS, TES	TING.
	_	
	N4681J TACH: 463.8 TTAF: 4813.5 DATE: 10/25/2022	
	placed Landing gear Hydraulic power book by.	
	N: 2667 referencing Piper SM. Drained and flushed systemiced with new SANA Maintenance and flushed systemic and flushed s	
	k check	
	Maria San Masonal Maria Maria 1970/	