



# Propeller LOG BOOK



**DUNCAN  
AVIATION**



**Lincoln Airport**  
**Lincoln, Nebraska 68524**  
**CRS JGVRI94F**

**800.228.4277**  
**402.475.2611**

# Propeller Maintenance Record

Aircraft Make Piper Hub Model 74DM6-0-58  
Aircraft Model PA28-140 Hub Serial Number K-33189  
Aircraft Serial Number 28-7225276 Blade Design \_\_\_\_\_  
Aircraft N Number N2899T Blade Serial Number 1. \_\_\_\_\_  
2. \_\_\_\_\_  
3. \_\_\_\_\_  
4. \_\_\_\_\_  
Propeller Manufacturer Sensenich  
Position Installed \_\_\_\_\_

Governor Manufacturer \_\_\_\_\_  
Governor Model \_\_\_\_\_  
Governor Part Number \_\_\_\_\_  
Governor Serial Number \_\_\_\_\_

## MAINTENANCE RELEASE

TYPE OF UNIT Propeller  
MANUFACTURER Sensenich  
MODEL 74DM6-0-58 SERIAL No. A49932  
The component identified above was repaired and inspected in accordance with current Civil Air Regulations and was found worthy for return to service.  
Pertinent details of the repair are on file at this agency under WORK ORDER No. 84873 DATE 11-4-89  
SIGNED Maxwell FOR \_\_\_\_\_

**MAXWELL AIRCRAFT SERVICE, INC.**

CRYSTAL AIRPORT • MINNEAPOLIS, MINN. 55429

FAA Approved Repair Station No. 3725

(over)



**Description of all operations  
pertaining to airworthiness directives,  
service bulletins, service letters  
and minor adjustments.**

**DATE**                      **TACH**                      **DESCRIPTION OF WORK**                      **SIGNATURE**

Propeller Log

Jetsum Aviation Centre  
Sioux Gateway Airport

DATE	REGISTRATION	MAKE/MODEL	S/N	TACH	ACTT
10/1/2006	N2899T	Piper PA 28-140	28-7225276	4372	4372

Sensenich 74DM6-0-58 S/N: K-33189 PTSO 886.7

*Complied with 100 Inspection in accordance with FAR 43 Appendix D by using Piper Service Manual as a checklist. Dressed leading edges and lubricated hub.*

I certify that this propeller has been inspected in accordance with an 100 inspection per FAR 43 Appendix D and was determined to be in Airworthy condition. Details pertinent to this inspection are on file under W.O. # 13514 dated September 1, 2005.  
Signed: Don D. Moore, Inspector for JetSum Aviation Centre, CRS# SG7R549J




US Aviation Group, LLC    U.S. Aircraft Maintenance    4850 Spartan Drive    Denton, TX 76207  
LOG ID# 970    13-November-2007    AC TT 4393.8    HOBBS 2915.8  
N2899T    S/N 28-7225276    PIPER    PA-28-140    TACH 4393.8    TSMOH 1434.8    Pg 1 / 1  
ENGINE TT 4393.8    PROP TSOH 908.5

COMPLIED WITH ANNUAL INSPECTION IN ACCORDANCE WITH FAR 43 APPENDIX D. CLEANED AND DRESSED PROPELLER.  
I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH A ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION AT THIS TIME.




Richard A. Moore                      11/3/07  
Date

A&P3258613IA    FRIEDRICH H MOORE





Description of all operations pertaining to airworthiness directives, service bulletins, service letters and minor adjustments.

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
11-24-04	T-4465.1	I CERTIFY THAT THIS <u>Prop</u> HAS BEEN INSPECTED IN ACCORDANCE WITH A <u>look for Approval</u> INSPECTION AND WAS FOUND TO BE IN AIRWORTHY CONDITION.	 214 465 619265
12-23-07	T-4414.8	I CERTIFY THAT THIS <u>Prop</u> HAS BEEN INSPECTED IN ACCORDANCE WITH A <u>BAW/Aviation</u> INSPECTION AND WAS FOUND TO BE IN AIRWORTHY CONDITION.	 214 465 619265
3-24-11	T-4416.54	I CERTIFY THAT THIS <u>Prop</u> BEEN INSPECTED IN ACCORDANCE WITH A <u>look/Aviation</u> INSPECTION AND WAS FOUND TO BE IN AIRWORTHY CONDITION.	 214 465 619265

Description of all operations  
 pertaining to airworthiness directives,  
 service bulletins, service letters  
 and minor adjustments.

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
4-12-12	T-44 19.99	I CERTIFY THAT THIS <u>Prop</u> HAS BEEN INSPECTED IN ACCORDANCE WITH A <del>101h/Annex</del> INSPECTION AND WAS FOUND TO BE IN AIRWORTHY CONDITION.	 2146561920K
5-22-13	T-44 24.78	I CERTIFY THAT THIS <u>Prop</u> HAS BEEN INSPECTED IN ACCORDANCE WITH A <del>101h/Annex</del> INSPECTION AND WAS FOUND TO BE IN AIRWORTHY CONDITION.	 2143575557
6-2-14	T-44 24.97	I CERTIFY THAT THIS <u>Prop</u> HAS BEEN INSPECTED IN ACCORDANCE WITH A <del>101h/Annex</del> INSPECTION AND WAS FOUND TO BE IN AIRWORTHY CONDITION.	 2143575557

Description of all operations pertaining to airworthiness directives, service bulletins, service letters and minor adjustments.

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
7-14-15	T. 4425.1	I CERTIFY THAT THIS <u>1001/1001</u> HAS BEEN INSPECTED IN ACCORDANCE WITH A <u>1001/1001</u> INSPECTION AND WAS FOUND TO BE IN AIRWORTHY CONDITION.	 2A3575557
9-1-16	T-4425.27	I CERTIFY THAT THIS <u>1001</u> HAS BEEN INSPECTED IN ACCORDANCE WITH A <u>1001/1001</u> INSPECTION AND WAS FOUND TO BE IN AIRWORTHY CONDITION.	 2A3575557
12-15-17	T-4425.43	I CERTIFY THAT THIS <u>1001</u> HAS BEEN INSPECTED IN ACCORDANCE WITH A <u>1001/1001</u> INSPECTION AND WAS FOUND TO BE IN AIRWORTHY CONDITION.	 2A3575557
Aug 2018	T 4435.89	Remained Reg for Oil Model 14 DMG-0-58	 2A3575557

S/N 452812

**Description of all operations  
pertaining to airworthiness directives,  
service bulletins, service letters  
and minor adjustments**

**SERVICEABLE PART**

MANUFACTURER Sensenich PART NAME Propeller MODEL 74DM6-0-58 PART NO. \_\_\_\_\_ SERIAL NO. A56812

REMARKS: Overhauled, set blade angles, zygled, painted and balanced.

ACCOMPLISHED BY Tommy Sheffield

THE AIRCRAFT PROPELLER OR COMPONENT IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT REGULATIONS OF THE FEDERAL AVIATION AGENCY AND WAS FOUND AIRWORTHY FOR RETURN TO SERVICE. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS REPAIR STATION UNDER:

Order No. 22943 Date 19-Sep-18 Signed [Signature] FOR: H & H PROPELLER SERVICE  
 Signature of Authorized Representative  
 Burlington Municipal Airport  
 Burlington, NC 27215  
 F.A.A. REPAIR STATION NO. PS4R451M;

DATE	TIME
19-Sep-18	





pertaining to airworthiness directives,  
 service bulletins, service letters  
 and minor adjustments.

DATE	TACH TIME	DESCRIPTION OF WORK DESCRIPTION	SIGNATURE
19-Sep-18	TACH	Overhauled propeller m/n 74DM6-0-58, s/n A56812. Set blade angles, zyglloed, painted and balanced.  H&H Propeller Service, Inc. 3439 S. Aviation Drive Burlington, N.C. 27215 FAA Repair Station PS4R451M 1-800-334-6437	

**Description of all operations  
pertaining to airworthiness directives,  
service bulletins, service letters  
and minor adjustments.**


**DATE**

**4 October 2018 Tach: 4438.50 TAT: 4438.50 SMOH: 0 N2899T PA28-140 Piper S/N: 28-7225276**

**Propeller Sensenich Model 74DM6-0-58 S/N: A56812**

1. Installed O/H Propeller Model 74DM6-0-58 S/N A56812
2. Performed 100hr. Inspection this date IAW Scope and Detail of FAR 43 Appendix D.

I certify that this Airframe has been  
Inspected in accordance with a 100 hr.  
Inspection and determined to be  
Airworthy condition




Arthur L. Atwood II  
A&P 3168854

**1 June 2019 Tach: 4451.24 TAT: 4451.24 SMOH: 12.54 N2899T PA28-140 Piper S/N: 28-7225276**

**Propeller Sensenich Model 74DM6-0-58 S/N: A56812**

1. Performed 100hr. Inspection this date IAW Scope and Detail of FAR 43 Appendix D.



I certify that this Airframe has been  
Inspected in accordance with a 100 hr.  
Inspection and determined to be  
Airworthy condition



Arthur L. Atwood II  
A&P 3168854


**SIGNATURE**

**Description of all operations  
pertaining to airworthiness directives,  
service bulletins, service letters  
and minor adjustments.**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
12-1-2020	4652.29	CLEANED AND INSPECTION PROP (AW)	
		FAR 43 APP D. I CERTIFY THAT	
		THIS PROPELLER IS AIRWORTHY AT	
		THIS TIME. JEB RAGSDALE A&P 2732467	
N2899T TACH: 4744.11 TTAF: 4744.11 SMOH: 305.61 DATE: 4/29/2021	Sensenich 74DN/G-0-58 SN: A56812	Completed 100HR Inspection IAW FAR 43 appendix D. I certify that this propeller was inspected IAW FAR 100HR inspection and is found airworthy at this time.	
Jeb Ragsdale		A&P 2732467	

Prop  
TACH: 4555.6  
5/11/2020  
SMOH 217.10

I certify that this Propeller has been inspected in accordance with an Annual Inspection and was found to be in airworthy condition and is approved for return to service as of this 11th Day of May 2020

  
Casey P Patterson  
A&P 2786355 IA


Description of all operations  
pertaining to airworthiness directives,  
service bulletins, service letters  
and minor adjustments.

N2899T TACH: 4844.3 TTAF: 4844.3 SMOH: 405.8 DATE: 7/19/2021

Sensenich 74DM6-0-58 SN: A56812

Completed 100HR inspection IAW FAR 43 appendix D. I certify that this propeller  
was inspected IAW a 100HR inspection and is found airworthy at this time.

Jeb Ragsdale A&P 2732467




N2899T TACH: 4941.99 TTAF: 4941.99 SMOH: 503.49 DATE: 9/24/2021

Sensenich 74DM6-0-58 SN: A56812

Completed 100HR inspection IAW FAR 43 appendix D. I certify that this propeller  
was inspected IAW a 100HR inspection and is found airworthy at this time.

Jeb Ragsdale A&P 2732467




N2899T TACH: 5039.44 TTAF: 5039.44 SMOH: 500.94 DATE: 11/16/2021

Sensenich 74DM6-0-58 SN: A56812

Completed 100HR inspection IAW FAR 43 appendix D. I certify that this propeller  
was inspected IAW a 100HR inspection and is found airworthy at this time.

Jeb Ragsdale A&P 2732467





**Description of all operations  
 pertaining to airworthiness directives,  
 service bulletins, service letters  
 and minor adjustments.**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
	N2899T TACH: 5336.28 Sensenich 74DM6-0-58	TTAF: 5336.28 SN: A56812 SMOH: 897.7 Completed 100HR inspection LAW FAR 43 appendix D. I certify that this propeller was inspected at this time.	
	Jeb Ragsdale		
	N2899T TACH: 5433.88 Sensenich 74DM6-0-58	TTAF: 5433.88 SN: A56812 SMOH: 995.3 Completed 100HR inspection LAW FAR 43 appendix D. Verified all Airworthiness directives complied with at this time. I certify that this propeller was inspected at this time.	
	Jeb Ragsdale		

N2899T TACH: 5336.28 TTAF: 5336.28 SMOH: 897.7 DATE: 7/24/2022  
 Senenich 74DM6-0-58 SN: A56812  
 Completed 100HR inspection LAW FAR 43 appendix D. I certify that this propeller  
 was inspected LAW a 100HR inspection and is found airworthy at this time.  
 Jeb Ragsdale A&P 2732467

N2899T TACH: 5433.88 TTAF: 5433.88 SMOH: 995.3 DATE: 9/26/2022  
 Senenich 74DM6-0-58 SN: A56812  
 Completed 100HR inspection LAW FAR 43 appendix D. Verified all Airworthiness  
 directives complied with at this time. I certify that this propeller  
 was inspected LAW a 100HR inspection and is found airworthy at this time.  
 Jeb Ragsdale A&P 2732467



