
PRELIMINARY VIEWSHED ANALYSIS AND RENDERINGS NEW ENGLAND WASTE SYSTEMS GRANITE STATE LANDFILL

DALTON, NEW HAMPSHIRE JANUARY 2021

SHEET INDEX



VIEWSHED ANALYSES PHOTO RENDERINGS EXISTING CONDITIONS VIEWSHED FROM SHEET 1 SHEET 9 **OBSERVATION POINT 1 - EXISTING CONDITION OBSERVATION POINT 1 OBSERVATION POINT 1 - PHASE I** SHEET 10 PHASE I VIEWSHED FROM OBSERVATION SHEET 2 POINT 1 SHEET 11 **OBSERVATION POINT 1 - PHASE II** PHASE II VIEWSHED FROM OBSERVATION SHEET 3 SHEET 12 OBSERVATION POINT 1 - PHASE III (FULL POINT 1 **DEVELOPMENT**) PHASE III (FULL DEVELOPMENT) VIEWSHED SHEET 4 SHEET 13 **OBSERVATION POINT 2 - EXISTING CONDITION** FROM OBSERVATION POINT 1 **OBSERVATION POINT 2 - PHASE I** SHEET 14 **EXISTING CONDITIONS VIEWSHED FROM** SHFFT 5 **OBSERVATION POINT 2 OBSERVATION POINT 2 - PHASE II** SHEET 15 PHASE I VIEWSHED FROM OBSERVATION OBSERVATION POINT 2 - PHASE III (FULL SHEET 6 SHEET 16 POINT 2 **DEVELOPMENT**) SHEET 7 PHASE II VIEWSHED FROM OBSERVATION POINT 2 PHASE III (FULL DEVELOPMENT) VIEWSHED SHEET 8 FROM OBSERVATION POINT 2


PREPARED FOR:


NEW ENGLAND WASTE SYSTEMS


DALTON. NEW HAMPSHIRE




FILE: P./1000A/1003.19/Graphics Files/CAD/Work/Grante State Landfl CoverSt LAYOUT: 22234 COVER









Observation Point 1 – Taken from West Side of Island in Forest Lake



Existing Condition

Observation Point 1 – Taken from West Side of Island in Forest Lake



Phase I Sheet 10

Observation Point 1 – Taken from West Side of Island in Forest Lake



Phase II Sheet 11

Observation Point 1 – Taken from West Side of Island in Forest Lake



Phase III (Full Development)

Observation Point 2 – Taken on Southeast Side of Forest Lake



Existing Condition

Observation Point 2 – Taken on Southeast Side of Forest Lake



Phase I Sheet 14

Observation Point 2 – Taken on Southeast Side of Forest Lake



Phase II Sheet 15

Observation Point 2 – Taken on Southeast Side of Forest Lake



Phase III (Full Development)