

CASE NUMBER:
L534-HAN05-21HAN-52-AC
AMENDMENT:
C.A.R. REPORT: N
REPORT#:
CLIENT ASSIGNED REPORT NBR: 21HAN-52-AC

STATE OF NEW HAMPSHIRE
UNIFORM POLICE
TRAFFIC CRASH REPORT
DSMV 159 (Rev. 09/2014)



Page 1 of 5
RPT DATE: 02/02/2022
REPORTABLE: Y
HIT AND RUN: N
SCHOOL BUS RELATED: N
FATALITY: N NBR KILLED: 0
INJURED: 2 UNITS: 2
REPORT ID:

CRASH DATE:	TOWN:	COUNTY:	RESPONDER NAME:	DEPT:
WED 06/02/2021 14:39	HANOVER	GRAFTON	Sergeant Christopher D Swain	534

POLICE NOTIFIED/ARRIVED:	EMS ARRIVED:	REPORTING AGENCY NAME:	APPROVAL BY:	APPR DT:	
06/02/2021 14:39	06/02/2021 14:47	06/02/2021 14:48	Hanover Police Department	Sergeant Christopher D Swain	06/17/2021

COLLISION OCCURRED: 1 KING RD AND 129 ETNA RD
LOCATION: LAT: 43.89461 LON: -72.21766 FEET FROM MILE MARKER
PHOTOGRAPHS TAKEN: Y PHOTOGRAPHER NAME: Swain

CRASH CONDITIONS:

LAND OWNERSHIP:	RELATIVE TO TRAFFICWAY:	Trafficway, On Road
FIRST HARMFUL EVENT: Motor Vehicle in Transport	LOC 1ST HARMFUL EVENT:	On Roadway
MANNER OF IMPACT: Angle	WEATHER CONDITION:	Clear
LIGHT CONDITION: Daylight	ROAD SURFACE CONDITION:	Dry
CONTRIBUTING CIRCUMSTANCES ENVIRONMENT: None		
CONTRIBUTING CIRCUMSTANCES ROAD RELATED: None		

CRASH RELATED TO A JUNCTION OR WITHIN AN INTERCHANGE AREA: No
SPECIFIC LOCATION: Intersection
TYPE OF INTERSECTION: T-Intersection
CRASH IN OR NEAR A CONSTRUCTION, MAINTENANCE OR UTILITY WORK ZONE: No
LOCATION OF CRASH:
TYPE OF WORK ZONE:
WORKERS PRESENT: LAW ENFORCEMENT PRESENT: No

UNIT :# 1

UNIT TYPE: Medium/Heavy Trucks (more than 10,000 lbs GVWR)

Driver :

JOSHUA K WILSON DOB: 03/30/1973 PHONE: 603-632-7514
18.5 SOUTH ST Apt 7 LEBANON NH 03766 COUNTRY:

SEATING ROW: Front POSITION: Left OTHER POSITION:
HIT AND RUN: No, Did Not Leave Scene
RESTRAINT SYSTEM: Shoulder and Lap Belt Used
AIR BAG DEPLOYED: Not Deployed EJECTED: Not Ejected
INJURY STATUS: No Apparent Injury (O) INJURY AREA: TRANSPORT: Not Transported
EMS: MEDICAL FACILITY:
DRIVER LICENSE PRESENTED: U
SEX: Male
M.V.R RECOMMENDED: N ARRESTED: N # : WARNING OR SUMMONS: Y
RSA: 28:4 OFFENSE: King Road Truck Violation
CONDITION AT TIME OF CRASH: Apparently Normal
LICENSE RESTRICTIONS COMPLIED WITH:
LICENSE ENDORSEMENTS COMPLIED WITH: Except Class A and Class B Bus, Other
SPEEDING RELATED: Unknown
DRIVER DISTRACTED: Not Distracted
DRIVER ACTIONS AT TIME OF CRASH: Ran Stop Sign, Failed to Keep in Proper Lane

CASE NUMBER:
L534-HAN05-21HAN-52-AC
AMENDMENT:
C.A.R. REPORT: N
REPORT#:
CLIENT ASSIGNED REPORT NBR: 21HAN-52-AC

STATE OF NEW HAMPSHIRE
UNIFORM POLICE
TRAFFIC CRASH REPORT
DSMV 159 (Rev. 09/2014)



Page 2 of 5
RPT DATE: 02/02/2022
REPORTABLE: Y
HIT AND RUN: N
SCHOOL BUS RELATED: N
FATALITY: N NBR KILLED: 0
INJURED: 2 UNITS: 2
REPORT ID:

PHONE: 802-478-0769

VEHICLE :

OWNER: CASELLA WASTE MANAGEMENT INC
PO BOX Apt 866 RUTLAND VT 05702

MOTOR VEHICLE UNIT TYPE: Motor Vehicle in Transport
REGISTRATION PRESENTED: U
PLATE NBR: 68D01 PLATE TYPE: CO STATE: VT COLOR: BLUE
YR: 2007 MAKE: INTERNATIONAL MODEL: GARBAGE TRUCK VIN: 1HTWCAAN97J471928
INSURANCE: Y DSMV 385 ISSUED: N
INSURANCE COMPANY: OLD REPUBLIC INSURANCE POLICY NBR: MWTB31199521
VEHICLE ACTION PRIOR TO CRASH: Movements Essentially Straight Ahead
SPECIAL FUNCTION VEHICLE: No Special Function
GOVERNMENT DRIVER IS EXEMPT FROM REPORTING PURSUANT TO RSA 264:33:
EMERGENCY MOTOR VEHICLE USE: Not applicable
POSTED/STATUATORY SPEED LIMIT: Posted/Statutory Value (30) VEHICLE TRAVEL DIRECTION: Westbound
TRAFFICWAY DESCRIPTION: Two-Way, Not Divided TOTAL LANES IN ROADWAY: 2
ROAD ALIGNMENT: Straight ROAD GRADE: Downhill
TRAFFIC CONTROL DEVICE: Stop Sign WORKING PROPERLY: Yes
WHAT WAS NOT WORKING:

COMMERCIAL OR TRUCK OR BUS OR HAZMAT OR 9+ PASSENGER VEHICLE: Y
MOST HARMFUL EVENT: Motor Vehicle In Transport
CONTRIBUTING CIRCUMSTANCES MOTOR VEHICLE: Brakes

SEQUENCE OF EVENTS: Equipment Failure (blown tire, brake failure, etc.), Downhill Runaway, Motor Vehicle In Transport, Overturn/Rollover
INITIAL IMPACT AREA: Front End EXTENT OF DAMAGE: Disabling Damage
DAMAGE AREAS: All Areas
VEHICLE REMOVAL: Towed Due to Disabling Damage TOWING COMPANY: SABIL & SONS
TOWED TO: SABIL & SONS

MOTOR CARRIER CRASH REPORT

VEHICLE CONFIGURATION: Single-Unit Truck (2-axle and GVWR more than 10,000 lbs)
CARGO BODY TYPE: Garbage/Refuse GVWR/GCWR: More than 26,000 lbs BUS USE: Not a Bus
HAZMAT PLACARD: Not Applicable
4-DIGIT HAZARDOUS MATERIALS NBR: HAZMAT NAME:
CLASS NUMBER FROM BOTTOM OF DIAMOND:
RELEASED OF HAZARDOUS MATERIALS FROM THIS VEHICLE: Not Applicable
CARRIER TYPE: Interstate Carrier INSPECTION #:
CASELLA WASTE MANAGMENT INC USDOT #: 00224100 MC/MX#:
1544 WOODSTOCK RD WHITE RIVER JCT VT 05001 PHONE: 802-478-0769

UNIT :# 2

UNIT TYPE: Passenger Car

CASE NUMBER:
L534-HAN05-21HAN-52-AC
AMENDMENT:

C.A.R. REPORT: N
REPORT#:

CLIENT ASSIGNED REPORT NBR: 21HAN-52-AC

STATE OF NEW HAMPSHIRE
UNIFORM POLICE
TRAFFIC CRASH REPORT
DSMV 159 (Rev. 09/2014)



Page 3 of 5
RPT DATE: 02/02/2022
REPORTABLE: Y
HIT AND RUN: N
SCHOOL BUS RELATED: N
FATALITY: N NBR KILLED: 0
INJURED: 2 UNITS: 2
REPORT ID:

Driver : KEVIN SCOTT HART DOB: 12/04/1968 PHONE: 603-667-0947
681 ROUTE 118 CANAAN NH 03741 COUNTRY:

SEATING ROW: Front POSITION: Left OTHER POSITION:
HIT AND RUN: No, Did Not Leave Scene
RESTRAINT SYSTEM: Shoulder and Lap Belt Used
AIR BAG DEPLOYED: Deployed - Combination EJECTED: Not Ejected
INJURY STATUS: Suspected Minor Injury (B) INJURY AREA: Thorax (chest) TRANSPORT: EMS Ground
EMS: HANOVER FIRE DEPARTMENT MEDICAL FACILITY: DARTMOUTH HITCHCOCK MEDICAL CE
DRIVER LICENSE PRESENTED: U

SEX: Male
M.V.R RECOMMENDED: N ARRESTED: N #. WARNING OR SUMMONS: N
RSA: OFFENSE:
CONDITION AT TIME OF CRASH: Apparently Normal
LICENSE RESTRICTIONS COMPLIED WITH: T - Double/Triple Trailers
LICENSE ENDORSEMENTS COMPLIED WITH: Corrective Lenses
SPEEDING RELATED: No
DRIVER DISTRACTED: Not Distracted
DRIVER ACTIONS AT TIME OF CRASH: No Contributing Action

VEHICLE : OWNER: KEVIN SCOTT HART PHONE: 603-667-0947
681 ROUTE 118 Apt 118 CANAAN NH 03741

MOTOR VEHICLE UNIT TYPE: Motor Vehicle in Transport
REGISTRATION PRESENTED: U
PLATE NBR: SPDY-3 PLATE TYPE: PC STATE: NH COLOR: BLACK
YR: 2015 MAKE: HYUNDAI MODEL: SONATA VIN: 5NPE34AF0FH014905
INSURANCE: Y DSMV 385 ISSUED: N
INSURANCE COMPANY: GEICO POLICY NBR: 4508241900

VEHICLE ACTION PRIOR TO CRASH: Movements Essentially Straight Ahead
SPECIAL FUNCTION VEHICLE: No Special Function
GOVERNMENT DRIVER IS EXEMPT FROM REPORTING PURSUANT TO RSA 264:33:
EMERGENCY MOTOR VEHICLE USE: Non-Emergency, Non-Transport
POSTED/STATUATORY SPEED LIMIT: Posted/Statutory Value (30) VEHICLE TRAVEL DIRECTION: Southbound
TRAFFICWAY DESCRIPTION: Two-Way, Not Divided TOTAL LANES IN ROADWAY: 2
ROAD ALIGNMENT: Straight ROAD GRADE: Level
TRAFFIC CONTROL DEVICE: No Controls WORKING PROPERLY: Not Applicable
WHAT WAS NOT WORKING:

COMMERCIAL OR TRUCK OR BUS OR HAZMAT OR 9+ PASSENGER VEHICLE: N
MOST HARMFUL EVENT: Motor Vehicle In Transport
CONTRIBUTING CIRCUMSTANCES MOTOR VEHICLE: None

SEQUENCE OF EVENTS: Motor Vehicle In Transport
INITIAL IMPACT AREA: Front Left EXTENT OF DAMAGE: Disabling Damage
DAMAGE AREAS: All Areas
VEHICLE REMOVAL: Towed, But Not Due to Disabling Damage TOWING COMPANY: SABIL & SONS
TOWED TO: SABIL & SONS

CASE NUMBER:
L534-HAN05-21HAN-52-AC
AMENDMENT:

STATE OF NEW HAMPSHIRE
UNIFORM POLICE
TRAFFIC CRASH REPORT
DSMV 159 (Rev. 09/2014)



Page 4 of 5
RPT DATE: 02/02/2022
REPORTABLE: Y
HIT AND RUN: N
SCHOOL BUS RELATED: N
FATALITY: N NBR KILLED: 0
INJURED: 2 UNITS: 2
REPORT ID:

C.A.R. REPORT: N
REPORT#:
CLIENT ASSIGNED REPORT NBR: 21HAN-52-AC

Passenger : CIARA HART DOB: 02/01/1999 PHONE: 603-643-3019
681 ROUTE 118 CANAAN NH 03741 COUNTRY:
SEATING ROW: Front POSITION: Right OTHER POSITION:
RESTRAINT SYSTEM: None Used - Motor Vehicle Occupant
AIR BAG DEPLOYED: Deployed - Combination EJECTED: Not Ejected
INJURY STATUS: Suspected Serious Injury (A) INJURY AREA: Abdomen and Pelvis TRANSPORT: EMS Ground
EMS: HANOVER FIRE DEPARTMENT MEDICAL FACILITY: DARTMOUTH HITCHCOCK MEDICAL CE
SEX: Female

WITNESS(ES)

PERSON TYPE:
KATE POWERS SEX: F PHONE: 617-823-4441
18 BELAIR PROVIDENCE RI 02906 COUNTRY:

PERSON TYPE:
HEIDI RUTH SEX: F PHONE: 603-667-1730
23 CARRIAGE LN HANOVER NH 03755 COUNTRY:

PERSON TYPE:
JENNIFER BROWN SEX: F PHONE: 603-640-6181
3 GATES RD ETNA NH 03750 COUNTRY:

PERSON TYPE:
NATHAN SIMMONS SEX: M PHONE: 603-643-2478
133 DOGFORD RD HANOVER NH 03755 COUNTRY:

PERSON TYPE:
JANET SIMMONS SEX: F PHONE: 603-643-2478
133 DOGFORD RD ETNA NH 03750 COUNTRY:


CASE NUMBER:
L534-HAN05-21HAN-52-AC
AMENDMENT:

C.A.R. REPORT: N
REPORT#:
CLIENT ASSIGNED REPORT NBR: 21HAN-52-AC

STATE OF NEW HAMPSHIRE
UNIFORM POLICE
TRAFFIC CRASH REPORT
DSMV 159 (Rev. 09/2014)



Page 5 of 5
RPT DATE: 02/02/2022
REPORTABLE: Y
HIT AND RUN: N
SCHOOL BUS RELATED: N
FATALITY: N NBR KILLED: 0
INJURED: 2 UNITS: 2
REPORT ID:



GIST:

See supplemental narrative.

02/02/2022

Operator Information Sheet

1 of 1

21HAN-52-AC

General

Accident Date	Time	Reporting Officer	
06/02/2021	1439	Sergeant Christopher D Swain	
Location	City	State	ZIP
1 KING RD @ 129 ETNA RD	HANOVER	NH	03755

Driver

OPERATOR	Last Name	First	Middle	Suffix	Veh/Unit	<input type="checkbox"/> Injured	
	WILSON	JOSHUA	K		1	<input type="checkbox"/> Fatality	
	Number	Street	Suffix	Apt	City	State	ZIP
	18.5	SOUTH	ST	7	LEBANON	NH	03766
DOB	Home Phone	Work Phone	License State/Number				
03/30/1973	603-632-7514		NH NHL13263628				
Insurance Company			Policy Number				
OWNER	Last Name	First	Middle	Suffix	Home Phone	Work Phone	
	CASELLA WASTE MANAGEMENT INC					802-797-4153	
	Number	Street	Suffix	Apt	City	State	ZIP
		PO BOX		866	RUTLAND	VT	05702
Insurance Company			Policy Number				
OLD REPUBLIC INSURANCE			MWTB31199521				
VEHICLE	Year	Make	Model	VIN			
	2007	INTERNATIONAL	GARBAGE TRUCK	1HTWCAAN97J471928			
	Registration State/Number		Towed By	Towed To			
	VT 68D01		SABIL & SONS	SABIL & SONS			

Driver

OPERATOR	Last Name	First	Middle	Suffix	Veh/Unit	<input checked="" type="checkbox"/> Injured	
	HART	KEVIN	SCOTT		2	<input type="checkbox"/> Fatality	
	Number	Street	Suffix	Apt	City	State	ZIP
	681	ROUTE 118			CANAAN	NH	03741
DOB	Home Phone	Work Phone	License State/Number				
12/04/1968	603-667-0947		NH NHL19410294				
Insurance Company			Policy Number				
OWNER	Last Name	First	Middle	Suffix	Home Phone	Work Phone	
	Same						
	Number	Street	Suffix	Apt	City	State	ZIP
		Same					
Insurance Company			Policy Number				
GEICO			4508241900				
VEHICLE	Year	Make	Model	VIN			
	2015	HYUNDAI	SONATA	5NPE34AF0FH014905			
	Registration State/Number		Towed By	Towed To			
	NH SPDY-3		SABIL & SONS	SABIL & SONS			

NARRATIVE FOR SERGEANT CHRISTOPHER D SWAIN

Ref: 21HAN-52-AC

Entered: 06/08/2021 @ 1800 Entry ID: CDS
Modified: 06/17/2021 @ 2235 Modified ID: CDS
Approved: 06/25/2021 @ 1240 Approval ID: MGS

On June 02, 2021, at approximately 14:39 hours, I responded to the intersection of King Road and Etna Road in Etna, New Hampshire for the report of a two-vehicle motor vehicle accident. The weather was clear, the road was dry. King Road is a "T" intersection with Etna Road, King Road is also on a 19% grade prior to connecting with Etna Road where there is a stop sign at the bottom, giving Etna Road the right of way.

Unit 1: International dump style Garbage truck, owner by Casella Waste Management, operated by Joshua Wilson.

I spoke with Mr. Wilson on scene. He stated he was traveling west (down) King Road toward Etna Road. He stated around #4 King Road he applied his brakes and said they did not feel like they worked. Mr. Wilson said he began to downshift his truck to slow down but was unable to stop at the bottom. He said he turned right at Etna Road to avoid the concrete stairway on the other side of the road. As he did this, Unit 2 was traveling south on Etna Road and into Mr. Wilson's path. Mr. Wilson's truck ran over the front end of Unit 2 causing the truck to roll onto its side on and onto the embankment on the west side of Etna Road.

Unit 2: a black Hyundai Sonata, operated by Kevin Hart, with his daughter as a passenger, Ciara Hart.

Unit 2 was traveling south on Etna Road when Unit 1 went through the intersection of Etna Road and King Road causing the collision. Mr. Hart and his passenger (daughter) were transported to Dartmouth Hitchcock Medical Center (DHMC) for injuries they suffered. Officer Joe Landry went to the hospital and spoke with Mr. Hart that night. Officer Landry reported that Mr. Hart stated Unit 1 drove down King Road and failed to stop at the stop sign, entered Etna Road and collided into his vehicle. Officer Landry stated he noted no sign of impairment from Mr. Hart and was unable to speak with his daughter due to her being in surgery with a ruptured spleen and facial injuries.

I spoke with Mr. Hart on June 03, 2021, at approximately 18:30 hours, at DHMC. Mr. Hart stated he last remembered seeing Unit 1 drive through the intersection at a fast pace before they collided. Mr. Hart told me he was unsure if he ran into the truck or if the truck ran into him. I also learned that Mr. Hart had his seatbelt on, but his daughter did not. Mr. Hart stated his daughter was sitting normally in the passenger front seat and may have been asleep. Mr. Hart told me he believed he had his cruise control set around 35 mph. He also told me their dog was lying in the back seat prior to the accident.



Witnesses: Heidi Ruth who was driving north on Etna Road toward the intersection of King Road with her passenger, Kate Powers. I spoke with Ms. Ruth on the phone on June 02. Ms. Ruth stated she witnessed Unit 1 drive down King Road at a high rate of speed, fail to stop at the intersection of Etna Road and collide into Unit 2 before rolling onto the driver's side. Ms. Ruth and Powers stopped to assist at the accident as Ms. Powers has medical training as a pediatrician. Ms. Powers began a cursory examination on Ciara prior to the ambulance arriving. Ms. Powers sent an emailed statement which stated Miss Hart had facial injuries and complained of seeing white. See statement for full details.

Nathan Simmons: Mr. Simmons arrived on scene shortly after the accident occurred. Mr. Simmons stated he is a physician and evaluated Miss Hart, he described her as being alert, conversant, interactive, and noted her breathing and pulse were stable. He did note she suffered facial injuries and missing teeth. Mr. Simmons was with his wife, Janet Simmons but Mrs. Simmons did not have anything to offer in the way of a statement. See statement for full details.





Hanover Police Department
Images Associated with 21HAN-52-AC




Hanover Police Department
Images Associated with 21HAN-52-AC







Hanover Police Department Images Associated with 21HAN-52-AC




Hanover Police Department
Images Associated with 21HAN-52-AC




Hanover Police Department
Images Associated with 21HAN-52-AC



Hanover Police Department
Images Associated with 21HAN-52-AC



Hanover Police Department
Images Associated with 21HAN-52-AC



Hanover Police Department
Images Associated with 21HAN-52-AC

