

## Yellow indicates ASBESTOS DETECTED



# Yellow indicates ASESTON DETECTED LEAD-BASED PAINT



#### EL SERENO COMMUNITY BUILDING 4721 Klamath St., Los Angeles, CA

#### **DEMOLITION COST ESTIMATE:**

Item Description Community Bldg demolition Covered Porch / Terrace demolition Small office demolition Misc. work (steel joists, pipe columns removal) Concrete slab and footing demolition Terminate and cap utilities	Unit SF SF SF LS SF/LF LS	<b>Quantity</b> 3850 2600 125	\$26,950 \$9,100 \$875 \$7,600 \$7,500 \$3,000
Site Work: Yard bin rental and haul, 40 yd (2 mos) Chain link temporary constr. fence, 6' H Chain link fence, perm. constr. at Tennis Ct., 10' H Demolition equipment	LS LF LF LS	500 150	\$3,000 \$4,325 \$5,235 \$10,000
Contingency 20%			<b>\$77,585</b> \$15,915
Asbestos and Lead Removal (ROM cost estimate by URS) (Oversight industrial hygiene and air quality monitoring not included in the estimate)	LS		\$59,000
The electrical cost estimate as related to the installation of conduit, conductors, transformer and disconnect switch for feeding the existing sports field lighting panel Contingency 20%	LS		<b>\$30,000</b> \$6,000
TOTAL DEMOLITION COST:		-	\$188,500

### EL SERENO RECREATION CENTER - PROJECT ESTIMATES

COMMUNITY BUILDING	( Continued to remain	
	Asbestos / Lead Paint Abatement (RAP consultant estimate)	\$59,000
	Air monitoring (estimated) NOT included in BOE estimate	\$10,000
	Electrical service rerouting for court / skate park lights (BOE estimate)	\$30,000
	SUBTOTAL	\$177,000
	Contingency	\$18,000
	TOTAL	\$195,000
FIELD RESTROOM	State prefabricated restroom building	\$60,000
	Site prep - including new retaining wall, demo of sidewalk / existing retaining wall (estimated)	\$25,000
	Rough plumbing – sewer and water 175 ft north of Klamath St (estimated)	\$18,000
	Rough electrical (estimated)	\$15,000
	SUBTOTAL	\$118,000
	Contingency	\$12,000
	TOTAL	\$130,000