



**Examples of some of the walls, gates, needing paint (Walk-around 4-11-2023)**  
shown here are some of the lots needing paint/maintenance on rear wall/fence/gates

**Lot #52** (completely rusted to orange gate) and needs column painted



**Lot #33** blackened throughout, needs painting



**Lot #50** gate and wall need painting



**Lot #49** wall blackened, needs paint



**Lot #54** (wrought iron gate oxidized & rusted)



**Lot #40** blackened, wrought iron oxidized & rusted



**Lot #45** wall Needs paint, also wrought iron oxidized & rusted




**Lot #35** Needs paint



Lot #37 paint missing in chunks & splotches



**Lot #38 (needs paint, splotches of missing paint), discolored throughout**



**Lot #53**


brick blackened, rust stains, wrought iron oxidated & rust



**Lot #46** paint wall and pipes going along wall, paint fence oxidated & rusted



**Lot #44** wall needs paint & crack filler




**Lot #43** wall needs paint & crack filled, blackened with rust from wrought iron fence oxidized & rusted, also gate



**Lot #29** blackened



**Lot #30** column needs paint





Lot #72 Needs paint along top & bottom, and throughout & crack filled

