Handy Vet Inspections	

Insured/Applicant Name: Sandra Bullock	Date Inspected: 7-Jan-21			
Phone: 867-5309 Email:SandyStar@aol.com				
	inty: Manatee			
Actual Year Built: 2007 Insurance Co & Policy #: /				
Plumbing: Water heater, under cabinet plumbing/drains & exposed valves <u>A Florida-licensed inspector must</u> Be advised that Underwriting will rely on the information in this or a similar form to	that is obtained from the Florida licensed inspector of your choice. A 4-Point eir insurance company to obtain a new insurance policy or renew an existing policy. This 4-Point Insurance Inspection is a limited visual survey of the heating, air			
fitness or longevity of any of the systems inspected. Electrical System				
Separate documentation of any aluminum wiring remediation must be prov	ided and certified by a licensed electrician.			
Main Panel:       Type:       Image: Circuit Breaker       Image: Fuse         Total Amps:       200       Brand/Model:       Siemens         Panel Age:       13yo       Year Last updated:       2007         Is amperage sufficient for current usage?       Image: Yes       No (Explain)	2nd Panel:       Type: ☑ Circuit Breaker □ Fuse         Total Amps: 200       Brand/Model: Siemens         Panel Age: 13yo       Year Last updated: 2007         Is amperage sufficient for current usage? ☑ Yes □ No (Explain)			
3rd Panel:       Type:       Circuit Breaker       Fuse         Total Amps:        Brand/Model:          Panel Age:        Year Last updated:          Is amperage sufficient for current usage?       Yes       No (Explain)	4th Panel:       Type:       Circuit Breaker       Fuse         Total Amps:       Brand/Model:          Panel Age:       Year Last updated:          Is amperage sufficient for current usage?       Yes       No (Explain)			
Indicate presence of any of the following:         Cloth Wiring       Active knob & tube         Branch circuit aluminum wiring (If present, describe the usage of all aluminum wiring the second sec	wiring):			
* If single strand (aluminum branch) wiring, provide details of all remediat         Wiring Type: (select all types)       X Copper / NM       BX       Conduit	ion. Separate documentation of all work must be provided. Aluminum			
Hazards Present:         Blowing fuses       Loose wiring       Double taps         Over fusing       Improper grounding       Exposed wiring         Tripping breakers       Corrosion       Unsafe wiring	Empty sockets.     Other (explain below)     Improper breaker size     Scorching			
General condition of the electrical system: Satisfactory. Unsatisfacto	ory ( <b>explain)</b>			
HVAC System				
Central AC: Yes No Central Heat: Yes No Are the heating, ventilation and air conditioning systems in good working order? Age of system: <u>NEW &amp; 4 yo</u> Year last updated: <u>2020</u> If not central heat, indicate				
Wood-burning stove or central gas fireplace <i>not</i> professionally installed? Space heater used as primary heat source? Does the air handler condensate line or drain pan show signs of blockage or leak, ince <b>Hazards Present:</b>	e portable? 🗌 Yes 🛛 No			



Plumbing System				
Is there a temperature pressure relief value on the water heater? $\square$ Yes $\square$ No Water heater location: <u>Garage</u> Is there any indication of an <i>active</i> leak? $\square$ Yes $\square$ No Is there any indication of a <i>prior</i> leak? $\square$ Yes $\square$ No				
Age of Piping System: ☐ Original to home ☐ Completely re-piped ☐ Partially re-piped (Provide year and extent of renovation in comments below)	Type of pipes (check all that apply)         Copper       PEX         Polybutylene       Galvanized         PVC/CPVC       Other (specify)			
General condition of the following plumbing fixtures and connections to applian	ces:			
Satisfactory       Unsatisfactory       N/A         Dishwasher       Image: Constraint of the state of	ible 🛛 🗌 🗍			
<b>Roof</b> (With photos of each roof slope, this section can take the place	e of the Roof Inspection Form.)			
Predominant Roof	Secondary Roof			
Covering material: Cementitious Tile         Roof age (years): 13yo Remaining useful life (years): est 25+         Date of last roofing permit: 5-Dec-05         Date of last roofing permit: 5-Dec-05         If updated (check one): □ Full replacement □ Partial replacement         % of replacement:         Overall condition:         □ Satisfactory □ Unsatisfactory (explain below)	Covering material:         Covering material:         Remaining useful life (years):         Coord age (years):         Remaining useful life (years):         Date of last roofing permit:         Partial replacement:         % of replacement:         Dverall condition:            Satisfactory         Unsatisfactory (explain below)			
Any visible signs of damage / deterioration?       Any visible signs of damage / deterioration?         (check all that apply and explain below)       (check all that apply and explain below)         Cracking       Cupping/curling         Exposed asphalt       Exposed felt         Soft spots in decking       Soft spots in decking         Missing/loose/cracked tabs or tiles       Visible hail damage         Any visible signs of leaks?       Yes         Yes       No         Attic/underside of decking?       Yes         Interior ceilings?       Yes				



#### Additional Comments/Observations (use additional pages if needed):

All 4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector. I certify the above statements are true and correct.

	Owner/ Inspector	HI11344	7 Jan 21
Inspector Signature	Title	License Number	Date
Handy Vet Inspections	Home Inspector	813-981-2008	
Company Name	License Type	Work Phone	

**Special Instructions**: This sample 4-Point Inspection Form includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Documenting the Condition of Each System
The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. <i>Acceptable Condition</i> means that each system is working as intended and there are no visible hazards or deficiencies.
Additional Comments or Observations
This section of the <i>4-Point Inspection Form</i> must be completed with full details/descriptions if any of the following are noted on the inspection:
• Updates: Identify the types of updates, dates completed and by whom
Any visible hazards or deficiencies
Any system determined not to be in good working order
Note to All Agents
The writing agent must review each <i>4-Point Inspection Form</i> before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing

hazards/deficiencies.



### **Elevation Photos**



**Front Elevation** 

**Rear Elevation** 

Left Elevation

**Right Elevation** 

#### **Roof Photos**





# **Plumbing Photos**



Water Heater

Water Heater Manuf: 2019

**TPR Valve** 







# **Under Cabinet Plumbing / Drain Photos**





## **Electrical Photos**



## **HVAC Photos**



AC Condenser

Condenser Manuf: 2020

Air Handler

Air Handler Manuf: 2020





Condenser Manuf: 2020

Air Handler



Air Handler Manuf: 2015

#### **END OF REPORT**