

# FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)

(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

1. Name of the Officer	ALI MUMTAZ
2. Name of the School	BHARATIYA VIDYA BHAVAN, MONDAL PUBLIC SCHOOL,
3. Location with name of Education District/ Sub. District	MADHUPUR, NORTH & MIDDLE ANDAMAN
4. Classification of Building as specified in column 4 of the application for fitness certificate and size.	1. RCC framed structure single storied (05 Class Room)-Block-A 2. RCC framed structure single storied (05 Class Room)-Block-B 3. RCC framed structure double storied (06 Class Room)-Block-B
5. Period for which the certificate is issued	2022-2023
6. Nature of defects , if any	
a) Foundation and basement	Not Applicable
b) Superstructure	2 Nos. Single Storied & 01 No.Double Storied
c) Doors and Windows	Good condition.
d) Wood work wrought and put up	Not Applicable
e) Roof	Good
f) Flooring	No defect found
g) Miscellaneous (Cracks, etc.)	Not Visible.
7. Any major defects noticed which will render the building unsafe in any manner .	No such defects noticed
8. Whether maintenance works have been done properly	Not Applicable
9. Whether the structure is sound or not for conducting classes	Sound


**Note :** 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

## CERTIFICATE

Certified that the school building was inspected by me on 10<sup>th</sup> June 2022 and found to be fit to conduct classes for the period 2021-2022 for the reasons stated above.

Place : Diglipur

Date : 13.06.2021

  
सहायक अभियंता/Assistant Engineer  
उप मंडल नं. 117/ उप मंडल नं. 117  
निर्माण मंडल, अ.लो.नि.वि.ए डिग्लिपुर/CD, APWD, Diglipur