

FITNESS CERTIFICATE

To be filed by the Inspecting Officer (Asst. Engineer)
(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

- | | |
|---|---|
| 1. Name of the Officer | ALI MUMTAZ |
| 2. Name of the School | BVB Mondal Public Secondary School ,
Madhupur |
| 3. Location with name of Education District/ Sub. District | Madhupur, North & Middle Andaman |
| 4. Classification of Building as specified in column 4 of the Application for fitness certificate and size. | 1. Block-A:- 5 Nos Class room S/S semi RCC Framed Structure
2. Block-B:- 5 Nos Class room S/S semi RCC Framed Structure
3. Block-C:- -6Nos Class room D/S RCC framed Structure |
| 5. Period for which the certificate is issued | 2021-2022 |
| 6. Nature of defects, if any | No Defects |
| a) Foundation and basement | |
| b) Superstructure | Single / Double Storied |
| c) Doors and Windows | Good |
| d) Wood work wrought and put up | Not Applicable |
| e) Roof | Good |
| f) Flooring | No defect found |
| g) Miscellaneous (Cracks, etc.) | Not Visible. |
| 7. Any major defects noticed which will render the building unsafe in any manner . | No such defects noticed |
| 8. Whether maintenance works have been done properly | Not Applicable |
| 9. Whether the structure is sound or not for conducting classes | Sound |


Note : 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.


CERTIFICATE

Certified that the school building was inspected by me on 10th April 2021 and found to be fit to conduct classes, for the period 2021-2022 for the reasons stated above.

Place : Madhupur

Date : 10.04.2021


Junior Engineer
Madhupur Section


Assistant Engineer
Sub-Division Engineer - II
C.D. APWD Diglipur
दिगलीपुर