

CN Rail Track Realignment



Project Profile

This project involved a pre-Construction Site Assessment, monitoring of soil stripping and handling of 8-hectare soil storage location on the banks of the Peace River Valley.

Issue

We developed a plan for managing over 500,000 m³ of soil and subsequent re-vegetation of the Site.

Solution

We created a reclamation plan for the 500,000-m³ stockpile placed within a soil storage location. Work included soil quality & quantity investigation, vegetation & landscape assessment, historical site review, monitoring of the soil handling, supervising the reclamation activities and report preparation.

Outcome

We completed the site work in conjunction with a major contractor, site owner and other stakeholders. The Site has been successfully re-vegetated with good slope stability. The landowner, client and main contractor agreed we met the landowner's and the project's objectives.