

Inspection Report

Report Number: 632184

Report Generated For Customer: Sotheby's Motorsport

Date of Inspection: 3/6/2024

Location of Inspection: Henderson, NV, 89012

For Questions, call us at (866) 935-2057 or email us at services@lemonsquad.com

Important Disclosures:

This Inspection Report is governed by the terms and conditions of the order which are available at <https://lemonsquad.com/terms> and which contain important information, disclosures, and disclaimers.

This Inspection Report is for the sole and exclusive use of the Customer named above and may not be used or relied upon by any third party including, without limitation, any purchaser of a vehicle from Customer.

Without limiting the Limited Warranty, Disclaimers, Limitations on Liability and Dispute Resolution provisions of the terms and conditions (available at <https://lemonsquad.com/terms>), there are no implied or express warranties or guarantees of any kind in connection with any vehicle inspection. The vehicle inspection is intended solely as an "evaluation" of a given vehicle's condition at the time, date and place of examination. Wrench Inc., and its affiliates including LemonSquad, specifically disclaims any liability for any loss or damage arising in connection with ownership or operation of said vehicle and further disclaims any liability of any hidden wreck, flood damage or tampered components not readily apparent upon visual inspection. The items visually inspected were in the reported condition listed in the report at the time of the inspection only. A visual inspection will not identify the working condition of each and every vehicle part or component, nor will a visual inspection identify any or all missing, tampered or altered components. Intermittent component or systems issues or failures may not present themselves at the precise time of inspection and/or a vehicle may be tuned in a manner to mask or minimize any such issues; in either case, such intermittent issues may not be discoverable during inspection. Further disclaimed is any liability for any damage or defects not found during inspection. Other conditions may exist which did not occur or appear during inspection. It is the customer's responsibility to ensure the vehicle to be inspected is in a state in which the vehicle is legal to drive on public roads, safe and functioning well enough to start and drive, and located in a space that is accessible and allows the inspector full access to vehicle components. Vehicles that are not safe, legal, or in a running condition will not have a test drive performed. Inspection reports are for information only and are not to be considered a recommendation for or against the purchase of the inspected vehicle.

2019 Aston Martin DBS Superleggera



Summary

2019 Aston Martin DBS Superleggera

The exterior was examined for cosmetic issues and functionality. Our inspector found the exterior with minor scuffs. Exterior functionality was evaluated and noted with no issues.

The interior was examined for cosmetic issues and functionality. The interior was noted to be in good condition with no observable cosmetic issues. Interior functionality was evaluated and noted with no issues.

The engine bay and undercarriage components were visually examined for leakage, deterioration, and fluid conditions. Engine-bay components were noted with no issues beyond normal wear and tear. Undercarriage components were noted with no issues beyond normal wear and tear. Exhaust system components were noted to be intact with no audible leaks.

A test drive was conducted. The engine had plenty of power with no misfires. Drivetrain components were noted with no operational issues. Steering, braking, and suspension operated as designed. A scan of the onboard diagnostics revealed one manufacturer-specific code, P3222.











Tires were evaluated for tread depth and unusual wear patterns. The brand is noted to be homogeneous with an average amount of tread remaining.

Refer to the detail section and photos for additional information.

Vehicle Information







Year	2019
Make	Aston Martin
Model	DBS Superleggera
VIN	SCFRMHAV1KGR00891
Stock No.	N/A
Mileage	7992
Fuel Type	Gas
Engine Cylinders	12 Cylinder
Interior Color	Black
Exterior Color	Black
Interior Material	Leather
Transmission	Automatic
Drive Type	Rear Wheel Drive

Road Test
















Road Test	Yes
Engine Starting Easily	 Good
Tire Pressure System (TPMS)	 Good
Engine running well after Started	 Good
Transmission performance	 Good
Differential Performance	 Good
Wheel Bearing Performance	 Good
Braking Performance	 Good
Suspension Performance	 Good
Steering Performance and Alignment	 Good
Computer Diagnosis/OBD2	 Issues

P3222 Manufacturer specific.
























Exterior

Back-Up Camera	 Good
Wiper Blades	 Good
Windshield Washer	 Good
Body Panel Alignment	 Good
Scratches	 Issues
<i>Just a few small scuffs.</i>	
Paint Condition	 Good
Seals	 Good
Rust	 Good
Exterior Lights	 Good
Power Door Mirrors	 Good
Bumpers	 Good
Side Moldings	 Good
Underbody/Frame Condition	 Good
Glass	 Good
Floors	 Good
Rockers	 Good
Quarter Panels	 Good
Body Filler Used	 Good
Hood	 Good
Doors	 Good
Dings	 Good
Dents	 Good

Interior

Steering Wheel	 Good
Horn	 Good
Cruise Control	 Good
Seat Condition	 Good
Heated Seats	 Good
Seat Belts	 Good
Clock	 Good
Radio/Navigation/DVD	 Good
Inner Door Panels	 Good
Power Locks	 Good
Power Window Switches	 Good
Center Console	 Good
Dash	 Good
Dash Lights Working	 Good
Air Conditioning	 Good
Heater	 Good
Rear Defroster	 Good
Carpet	 Good
Floor Mats	 Good
Signs of Smoking?	 Good
Cup Holders	 Good
Headliner	 Good
Blower Motor	 Good
Instrument Cluster/Gauges	 Good
Unusual Odors	 Good
Window Function	 Good
Interior Trim	 Good
Sun Visors	 Good

Mechanical

Radiator Cap Sealing Properly	 Good
Air Filter	 Good
Battery Condition	 Good
Coolant Leaks	 Good
Charging System	 Good
Cooling Fan Condition Mechanical/Electronic	 Good
Hoses and Clamps Age/Cracking	 Good
Radiator Condition	 Good
Engine Coolant Condition	 Good
Belts	 Good
Power Steering System	 Good
Power Steering Fluid Condition	 Good
Engine Oil Condition	 Good
Engine Oil Leaks	 Good
Transmission Fluid Leaks	 Good
Brake System Condition	 Good
Brake Fluid Leaks	 Good
Differential leaks	 Good
Muffler System	 Good
CV Boots and Joints	 Good
Shocks and bushings Condition. Leaking?	 Good
Ball Joints and Tie Rods	 Good
Key Fob	 Good

Tire / Wheels

Manufacturer	
Driver's Front Tire	Pirelli
Passenger's Front Tire	Pirelli
Driver's 1st Axle Outer Tire	Pirelli
Passenger's 1st Axle Outer Tire	Pirelli
Size	
Driver's Front Tire	265/35/21
Passenger's Front Tire	265/35/21
Driver's 1st Axle Outer Tire	305/30/21
Passenger's 1st Axle Outer Tire	305/30/21
Axle Count	
Driver's Front Tire	1
Driver's 1st Axle Outer Tire	1
Passenger's Front Tire	1
Passenger's 1st Axle Outer Tire	1
Tire Condition	
Driver's Front Tire	No Issues
Passenger's Front Tire	No Issues
Driver's 1st Axle Outer Tire	No Issues
Passenger's 1st Axle Outer Tire	No Issues
Wheel Condition	
Driver's Front Tire	Curb Rash
Driver's 1st Axle Outer Tire	No Issues
Passenger's Front Tire	No Issues
Passenger's 1st Axle Outer Tire	Curb Rash
Tire Tread	
Driver's Front Tire	7/32
Passenger's Front Tire	7/32
Driver's 1st Axle Outer Tire	7/32
Passenger's 1st Axle Outer Tire	7/32
Spare Tire	
	No

Vehicle Images





2780.1

miles

7994



1:27pm















-SCFRMHAV1KGR00891-

ASTON MARTIN LAGONDA LTD



















left fender scuffed





















left frt wheel sc














rt rear wheel sc




























ЛІВІ ТА ПРАВІ СТОРОНИ
FRONT 4 FRONT 3 REAR 3
TIRE AND LOADING INFORMATION

TIRE AND LOADING INFORMATION

SEATING CAPACITY TOTAL 4 FRONT 2 REAR 2

The combined weight of occupants and cargo should never exceed 390 kg or 860 lbs.

TIRE	SIZE	COLD TIRE PRESSURE
FRONT	265/35 ZR21	260 kPa (38 PSI)
REAR	305/30 ZR21	280 kPa (41 PSI)
SPARE	NONE	

SEE OWNER'S MANUAL FOR ADDITIONAL INFORMATION

KY73-69014-DA

MFD DATE 03
GWR
GAWR F R
SCFRMHAV
VEHICLE IDENT

WHEEL 4 FRONT 3 REAR 2
TIRE AND LOADING INFORMATION

MFD DATE 03/19
THIS VEHICLE CONFORMS TO ALL APPLICABLE FEDERAL MOTOR VEHICLE SAFETY, BUMPER AND THEFT PREVENTION STANDARDS IN EFFECT ON THE DATE OF MANUFACTURE.
MFD BY ASTON MARTIN LAGONDA LTD
WARWICKSHIRE, ENGLAND

TIRE AND LOADING INFORMATION

LOADING CAPACITY	TOTAL 4	FRONT 2	REAR 2
------------------	---------	---------	--------

Weight of occupants and cargo should never exceed 390 kg or 860 lbs.

COLD TIRE PRESSURE	
260 kPa (38 PSI)	
280 kPa (41 PSI)	
NONE	

SEE OWNER'S MANUAL FOR ADDITIONAL INFORMATION

KY73-69014-DA

**MFD BY ASTON MARTIN LAGONDA LTD
WARWICKSHIRE, ENGLAND**

MFD DATE 03/19

GVWR 5015

GAWR F 2425
R 2735

THIS VEHICLE CONFORMS TO ALL APPLICABLE FEDERAL MOTOR VEHICLE SAFETY, BUMPER AND THEFT PREVENTION STANDARDS IN EFFECT ON THE DATE OF MANUFACTURE.


SCFRMHAV1KGR00891

VEHICLE IDENT. No.  **TYPE PCVT**

KY73-973407-AA

















A 2013

Fuel Economy and Environment

Fuel Economy
17 MPG
City 14 Highway 22

Annual fuel cost
\$2,650

CO2
5.9 gpm/gal

Annual fuel cost
\$1,000 less available

fuel economy.gov

You spend \$6,250 more in fuel costs over 5 years

Annual fuel cost
\$2,650

Annual fuel cost
\$1,000 less available

fuel economy.gov

PARTS CONTENT INFORMATION FOR VEHICLES IN THIS CATEGORY:
 MAJOR SOURCES OF FOREIGN PARTS CONTENT:
 UK 50%
 GERMANY 37%
 MORE PARTS CONTENT DOES NOT MEAN MORE EXPENSE. THE DIFFERENCE IS DUE TO PARTS PRICES.

FOR THIS VEHICLE:
FINAL ASSEMBLY POINT:
 GERMANY, MANCHESTER, UK
COUNTRY OF ORIGIN:
 GERMANY
ENGINE PARTS:
 GERMANY
TRANSMISSION PARTS:
 GERMANY

GOVERNMENT 5-STAR SAFETY RATINGS
 This vehicle has not been rated by the government for overall vehicle score, frontal crash, side crash, or rollover risk.

Source: National Highway Traffic Safety Administration (NHTSA)
 www.safercar.gov or 1-888-327-4236







WARNING
EVEN WITH ADVANCED AIR BAGS

- Children can be killed or seriously injured by the air bag
- The back seat is the safest place for children
- Never put a rear-facing child seat in the front
- Always use seat belts and child restraints
- See owner's manual for more information about air bags


RV31-921619-AB











back up camera ok













 **ASTON MARTIN LAGONDA LTD**
VEHICLE EMISSIONS CONTROL INFORMATION

Conforms to regulations: **2019 MY**


US EPA: T3BIN125 LDV **OBD II** Fuel: T2

CALIFORNIA: LEVII ULEV PC **OBD II** Fuel: T2

GROUP: KASXV05.2AM5 **2WU-TWC/2TWC/2WR-HO2S/**
EVAP: KASXR0160P1Y **2HO2S/2TC/2CAC/SFI/AIRE**

No Adjustments Needed **KY53-973268-A8**











brakes look good









BlueDriver

20384-23-LE

Your User Manual is at
the BlueDriver app
24/7 customer service
1-866-312-4074
www.bluedriver.com

1:16

LTE 



Read

Clear



SCFRMHAV1KGR00891



1 Confirmed Trouble Code

P3222 Check report for description.



Clear Confirmed & Pending Trouble Codes



0 Pending Trouble Codes


Clear Confirmed & Pending Trouble Codes



0 Permanent Trouble Codes

More Info About Permanent Codes





1 code foud







