

# Corporate Safety Services, LLP

conducted for

## XXXX General Contractors

Document No.

000283

**Audit Title** 

XXXX Nov 2013

Conducted on

11/19/13 15:41

Prepared by

Michael Rosser

Location

1234 Anywhere Drive

Personnel

John

#### Disclaimer

Although every effort will be made to ensure the information to be taught by and contained in any material provided by Corporate Safety Services personnel is technically accurate, Corporate Safety Services makes no representation or warranty as to the accuracy of such information. Furthermore, Corporate Safety Services hereby disclaims any liability, to person or property, for loss or damages, including expenses, which may arise or result from the use of any information taught, contained in any information provided, or following the procedures, including, but not limited to, fines or penalties for the violations of any federal, state or local government.

#### **Confidentiality Statement**

In order to maintain the integrity and credibility of the risk assessment processes and to protect the parties involved, it is understood that Corporate Safety Services, will not divulge to unauthorized persons any information obtained during this risk assessment unless legally obligated to do so.

### **Our Information**

Michael Rosser, OSB Corporate Safety Services of Colorado 2821 S. Parker Rd., Ste 401 Aurora, CO 80014

Phone: (303) 472-8401

mike@corporatesafetyservices.com

www.corporatesafetyservices.com

## **A**udit

Question	Response	Details	
1. General	1. General		
1.1 Did company representative accompany inspector?	Yes		
1.2 Are all Safety/HazCom/Emergency Programs on site?	Yes		
1.3 Are OSHA posters/emergency numbers posted?	Yes		
1.4 Are confined space hazards identified & addressed?	N/A		
1.5 Are safety meetings held/documented?	Yes		
1.6 Are first aid kits available & properly stocked?	Yes		
1.7 Are fire extinguishers available/charged/inspected?	Yes		
1.8 Are all rebar/pipe & other impalement hazards capped/protected?	Yes		
1.9 Are gas cylinders properly used & stored?	No	LP gas cylinders stored inside building.	



Appendix 1

1.10 Is material storage proper?	Yes	
1.11 Is housekeeping and sanitation proper & enforced?	Yes	
1.12 Are flammable materials in approved containers & properly labeled?	N/A	
1.13 Are all hand/power tools properly used/maintained/stored?	Yes	

Question	Response	Details
1.14 Are all operations performed at least 10 feet from overhead power lines?	Yes	
1.15 Are flagmen properly dressed, trained & posted?	N/A	
1.16 Is fencing/barricades/traffic control through & around site proper?	Yes	
1.17 Are access/egress locations with a change in elevation >19 inches provided with stairs, ladders or ramp?	Yes	
1.18 Is an Emergency Action Plan posted/ up to date?	N/A	
2. Equipment		
2.1 Are parts/equipment free from damage?	Yes	
2.2 Are all guards in place & working properly?	No	Masonry mixer operating with engine cover open.
Appendix 2		
2.3 Is all equipment properly maintained & inspected?	Yes	
2.4 Do backup alarms work?	Yes	
2.5 Are equipment operators properly trained?	Yes	
2.6 Are seatbelts operative & used?	N/A	
2.7 Are aerial/scissors lifts properly used?	N/A	
2.8 Are forks on the ground when parked?	N/A	
2.9 Is the forklift operator in the seat with a raised load?	N/A	

Question	Response	Details		
3. Personal Protective Equipment	3. Personal Protective Equipment			
3.1 Is all PPE provided by the employer?	Yes			
3.2 Is respiratory protection proper?	N/A			
3.3 Is hearing protection used & proper?	Yes			
3.4 Is proper foot protection worn?	No	Workers wearing tennis shoes.		
Appendix 3				
3.5 Is proper head protection worn?	Yes			
3.6 Is proper eye protection worn?	Yes			
3.7 Is hand protection/clothing proper?	Yes			
3.8 Is PPE hazard assessment complete & on file?	N/A			
3.9 Is Appendix D on file for voluntary respirator use?	N/A			
4. Electrical				
4.1 Are GFCI's or an AEG Program in use?	Yes			
4.2 Is temporary lighting used & proper?	Yes			

4.3 Are Lockout/Tagout procedures in place & used?

N/A

Question	Doonanaa	Detaile
Question	Response	Details
4.4 Are temporary cords properly used & maintained?	No	3 cords had plugs with missing ground pins.
Appendix 4		
4.5 Do all boxes/panels have covers & are all circuits labeled?	Yes	
4.6 Are arc flash hazards identified & addressed?	N/A	
4.7 Are generators over 5kv properly grounded?	N/A	
5. Fall Protection		
5.1 Are fall protection plans required & in place?	Yes	
5.2 Is fall protection provided at heights over 6 feet?	Yes	
5.3 Is fall protection equipment inspected & maintained?	Yes	
5.4 Are stairways properly protected & used?	Yes	
5.5 Are ladders properly used & maintained?	No	Worker using step ladder in closed position.
Appendix 5		
5.6 Are all floors holes properly covered or	Yes	

protected?

Question	Response	Details	
5.7 Is the roofer's warning line/roof monitor system proper?	N/A		
6. Steel Erection/Cranes	6. Steel Erection/Cranes		
6.1 Is site access/layout/storage area proper?	N/A		
6.2 Has GC provided all written documents for erection process to begin?	N/A		
6.3 Is a Steel Erection Plan required & in place?	N/A		
6.4 Is crane setup proper?	N/A		
6.5 Is crane properly maintained/copy of annual inspection available?	N/A		
6.6 Is rigging hardware inspected daily?	N/A		
6.7 Are loads properly rigged/carried?	N/A		
6.8 Are areas under swinging loads properly barricaded & enforced?	N/A		
6.9 Are rigger & signalperson trained/ qualified?	N/A		
6.10 Are steel erection procedures proper?	N/A		
6.11 Are 2-bolt connections/4 bolt column anchor requirements followed?	N/A		
6.12 Are connector requirements in compliance?	N/A		
6.13 Does Controlled Decking Zone meet standards?	N/A		
6.14 Are employees using fall protection above 15 feet?	N/A		
6.15 Are oxygen & acetylene bottles properly used & stored?	N/A		
6.16 Is a Hot Work Permit completed & posted when required?	N/A		

Question	Response	Details	
6.17 Is perimeter safety cable properly installed & used?	N/A		
7. Masonry/Scaffolding			
7.1 Is scaffold competent person on site?	Yes		
7.2 Are all scaffold users properly trained?	Yes		
7.3 Are scaffold erection/disassembly procedures proper?	Yes		
7.4 Is fall protection provided for erectors/ dismantlers?	Yes		
7.5 Are baseplates/mud sills stable & proper?	No	Scaffold had no base plates/screw jacks.	
Appendix 6			
7.6 Are all scaffold frames pinned together?	No	Scaffold frames not pinned together.	
Appendix 7			
7.7 Is scaffold tied to structure properly and are stiffbacks used?	N/A		
7.8 Are scaffold frames/planks/parts free of damage & defects?	Yes		
7.9 Are walk/work planks properly installed & set?	Yes		
7.10 Are guardrails properly installed & used?	Yes		

Question	Response	Details
7.11 Are toe boards/warning line properly installed & used?	Yes	
7.12 Is scaffold access proper?	Yes	
7.13 Are masonry walls properly braced?	N/A	
7.14 Is the Limited Access Zone set & enforced?	N/A	
7.15 Are mixer operations proper?	Yes	
7.16 Is wet-cutting or respiratory protection in place?	N/A	
8. Trenching/Excavating		
8.1 Is the trench competent person on site?	N/A	
8.2 Is the trench/excavation inspected daily?	N/A	
8.3 Has a proper soils analysis been conducted?	N/A	
8.4 What is the soil type?		
8.5 Is employee protection proper for soil type & depth?	N/A	
8.6 What type of employee protection is in place?		
8.7 Is safe access/egress provided?	N/A	
8.8 Are water removal procedures proper?	N/A	
8.9 Has the trench been evaluated as a confined space?	N/A	
8.10 Have all underground utilities been located & marked?	N/A	
8.11 Is excavated material at least 2' from edge of excavation or stop logs/barricades used?	N/A	
9. Environmental		

Question	Response	Details
9.1 Is a silt fence installed & maintained?	N/A	
9.2 Have storm water issues been addressed?	N/A	
9.3 Is a spill containment kit on site & adequate?	N/A	
9.4 Are hazardous materials (asbestos, lead, etc.) procedures in place/correct?	N/A	
10. Safety Equipment Purchase		
Safety equipment purchased if checked.		
11. Summary		
Comments		
12. Facility/Jobsite Photographs		
Photographs		

## Media



Appendix 1



Appendix 3



Appendix 2



Appendix 4



Appendix 5



Appendix 7



Appendix 6