

Well Inspection



Interior Exterior Home Inspection, Inc.

Inspector: Seth Larman

Lic# 70002235

PO Box 639

Choctaw, OK 73020

Phone: (405) 534-7366

Email: seth@inexhomeinspection.com

Sample Report






Well Inspection

Site Conditions


Date: Sample Report Time: 12:00 PM Weather: Dry Temp: 50

Were Well Record Found: YES **NO**

- Type of well: **Drilled**
- Casing Material: **PVC**
- Wellhead visible: **YES**
- Casing Wellhead 12" above Grade: **YES**
- Casing Cracked or have holes: **NO**
- Well Cap Installed: **YES**
- Is Well cap Sourced Tightly: **YES**
- Soil around well burmed: **YES**
- Any void around well to allow water to travel to bore hole: **NO**
- Any permanent structures within 10 ft of wellhead: **NO**
- Is well minimum distance from contamination: **YES** (See chart)
- Is there corrosion visible at plumbing fitting and/or Pressure tank/ Storage tank: **NO**
- Is Pitless adaptor used: **YES** Type: **SLIDE**
- Pressure tank Cut-In PSI: 40 Cut-Out: 60
- Time from Cut-In to Cut-Out with no water running: 12 Sec.
- Any water treatment devices: **YES** If yes list: Whole Home Filter
- Well Flow Test: 12 gallons per minute (GPM)
- PSI Measure at hose bib: 42
- Was the well operational during the inspection: **YES**



Location



Well Inspection



- Wellhead



- Wellhead



- Pressure Tank and Components

Well Inspection



- Water Filter



- Pressure gauge at tank



- 42 PSI at hose bit