

APPLICATION

Horizontal Production Logging Water Break Through / 3 Phase

TECHNOLOGY


LOCATION Texas, USA


Indepth Well Performance Monitoring

Horizontal Production Log Survey

CHALLENGE:

To locate the source of water break-through on a Horizontal Completion with memory HDD HZPLT on coiled tubing unit. Monitoring Performance during the survey to ensure representative data.





INDEPTH SOLUTION:

Indepth Production Solutions runs a HZPLT String with an array of multiple sensors & flowmeterswhich allows for a complete image of the lateral. In addition, surface pressure recorders are ran **in conjunction with the survey to confirm well** performance and **stability**.

CLIENT VALUE:

It was determined from the Indepth Production Solutions HDD HZPL Survey, that there are two significant inflows of water in the heal of the lateral. The operator in this case was able to remediate the issue and return the well to increased profitability. Trust Indepth Production Solutions experience and tool technology to deliver the results you can use to make accurate & efficient decisions regarding your interests.



INDEPTH PRODUCTION SOLUTIONS - 7109 ARGONNE TRAIL - SUGARLAND, TX 77479 - dheddleston@indepthps.com - 832-600-1900