

Sidewalk Conditions

Pinon







Sidewalk Gap


-  Sidewalk Gap
-  Existing Sidewalk

Bridge Pedestrian Accomodation

-  Barrier
-  Not a Barrier

FHWA Functional Class

-  Principal Arterial
-  Minor Arterial
-  Minor Collector
-  Local Road
-  New Road
-  Other/Unclassified



Source: 2021 Official Inventory and NDOT GIS



Source: Esri, DigitalGlobe, GeoEye, iSatellite, USDA, USGS, AEX, GeoEye, AeroGRID, IGN, IGP, Swiremap, and the GIS User Community