



Sidewalk Conditions

Shiprock







Sidewalk Gap

-  Sidewalk Gap
-  Existing Sidewalk









Bridge Pedestrian Accomodation


-  Barrier
-  Not a Barrier

FHWA Functional Class

-  Principal Arterial
-  Minor Arterial
-  Minor Collector
-  Local Road
-  New Road
-  Other/Unclassified

Land Use

-  Commercial
-  Residential
-  Civic/ Institutional
-  Industrial
-  Recreation
-  Agriculture
-  Utility
-  Airport



Source: 2021 Official Inventory and NDOT GIS