

YEAR 20 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
--------------------	---------------------------	-------------------	-----------------------------	---

Date: 05/10/2025 Hours: TTAF: TTENG: TTP:

Tail#: N297KE

Make: Vans

Model: Rv-8

S/N: 83116

1. Removed panels as required to gain access to inspection items, treated internally with ACF 50 / Anticorrosion compound.

2. Performed Van's SB-00036 Rev 3 Service bulletin, no damage found at this time.

3. ELT inspected visually and operationally tested to comply with FAR 91.207(d).

Battery expires on _____.

I hereby certify that this aircraft was inspected in accordance with a Conditional Inspection in the scope and detail of 14 CFR Part 43, Appendix D, and is determined to be in an airworthy condition as of the date of this logbook service record.

Engine Model: YIO-360-EXP286. Propeller Model: 300-3B(6)-A/A-72-S-R

Engine S/N: EL-39288-51E. Propeller HUB S/N: 300-3B(6)-A-1113

Propeller Blade S/N's: A-72-S-R- 1260, -1261, -1262.

ALC
AVIATION

ALVARO LAU CAMARENA

ALC AVIATION

Cert: A&P 3727664 IA

Sign:

Alvaro Lau