

					Le	ead Service Line Invento	ry Template					
*Please enter information in the empty box next to each section	Water System Na	ame	Central	Stickney Sanitary District	Sys	tem ID Number:	IL0315570)	Current Inver	ntory Date:	4/15/2025	
*Please enter totals in the empty box next to each category	Total Service lines:	746	Total Lead:	35 Total Non-Lead:	171	Total Galvanized Requi	ring replacement:	0	Total Unknown:	540	Website link to Material Inventory:	

Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Identified Since Last	Year PWS- Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	refused access to	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
		EXAMPLES:					EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:					EXAMPLES:			
							Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	If any galvanized service				Copper - No Lead			
	Lead and Copper Sample site number	Group Homes, Parks, Playgrounds, Special Care				II	Copper - Lead Solder (CLS)	r Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line	Fotos dete		If previous column	Solder (C)		IF customer refused access to property,	
	is the 7 digit number	Facilities, Hospitals,		M/leat the	Mile at the artist and a	How was the Material of this Service Line Identified?	Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)	material was never	Enter date customer was		was marked (Y), provide date the Lead	Galvanized (G)		date waiver obtained	1
	starting with "LP" or " LA". / If address is not a	Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	customer side service line installed, if known?	EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance		Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	downstream of any Lead section, mark No (N). / If Yes, that section of	notified of Lead Service Line. / If Service Line is not	Yes (Y) or No (N)	Service Line was replaced. / Leave blank if	Plastic - PVC, HDPE, PEX (P)	Yes (Y) or No (N)	by PWS or date PWS notified IDPH of refusal to sign waiver /	
	lead and copper sample site mark					Records, etc	Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)		service line should be marked as Galvanized	Lead put N/R		previous column was	Cast/Ductile Iron or Transite (O)		Leave blank if customer has not	
	"N/A"						Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)		Requiring Replacement in the appropriate			(N).			refused access.	
		6.3 6.3					Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)		immediately preceding				Leave blank if no			
		Yes (Y) or No (N)					Unknown Not Lead	Unknown (U)	Unknown (U)		column(s).				Lead Service Line was replaced.	5		
							(ONL)	Unknown Not Lead (UNL)	Unknown Not Lead (UNL)									
4715 S LATROBE AVE	N/A	N	Y	1949	1949	Record	U	L	L	L			N					101-0020
4717 S LATROBE AVE	N/A	N	Y	1957	1957	Record	U	L	L	L			N					101-0040
4800 S LATROBE AVE	N/A	N	Υ	1955	1955	Record	U	L	L	L			N					101-0285
4801 S LATROBE AVE	N/A	N	Υ	1953	1953	Record	U	L	L	L			N					101-0290
4855 S LATROBE AVE	LP1C002	N	Υ	1957	1957	Installed before lead ban	U	L	L	L			N					101-0580
5001 S LOCKWOOD AVE	N/A	N	Υ	1960	1960	Record	U	L	L	L			N					101-1350
4907 S LOCKWOOD AVE	N/A	N	Υ	1918	1918	Record	U	L	L	L			N					101-1570
4737 S LOCKWOOD AVE	N/A	N	Υ	1943	1943	Record	U	L	L	L			N					101-1980
4733 S LOCKWOOD AVE	N/A	N	Y	1956	1956	Record	U	L	L	L			N					101-2030
4736 S LOREL AVE	N/A	N	Y	1957	1957	Record	U	L	L	L			N					101-2170
4753 S LOREL AVE	LP1C005	N	Y	1960	1960	Installed before lead ban	U	L	L .	L			N					101-2250
4825 S LOREL AVE	N/A	N	Y	1958	1958	Record				L			N					101-2380
4910 S LOREL AVE	N/A LP1A026	N N	Y	1961 1966	1961 1966	Record Installed before lead ban			L	L I			N N					101-2630 101-2810
5001 S LOREL AVE 5025 S LOREL AVE	N/A	N N	Y	1950	1950	Record	11	L	L	L			N N					101-2810
5030 S LONG AVE	N/A	N	Y	1948	1948	Record	U U	ı	I	ı			N					101-2954
4905 S LONG AVE	N/A	N	Y	1957	1957	Record	U	L	L	L			N					101-3110
4830 S LONG AVE	N/A	N	Y	1948	1948	Record	U	L	L	L			N					101-3250
4811 S LONG AVE	N/A	N	Y	1958	1958	Record	U	L	L	L			N					101-3400
4743 S LONG AVE	N/A	N	Υ	1954	1954	Record	U	L	L	L			N					101-3530
4744 S LOTUS AVE	N/A	N	Υ	1953	1953	Record	U	L	L	L			N					101-3630
4806 S LOTUS AVE	LP1C006	N	Υ	1950	1950	Installed before lead ban	U	L	L	L			N					101-3720
4811 S LOTUS AVE	N/A	N	Υ	1950	1950	Record	U	L	L	L			N					101-3750
4857 S LOTUS AVE	N/A	N	Y	1957	1957	Record	U	L	L	L			N					101-3940
5040 S LOTUS AVE	LP1C027	N	Υ	1948	1948	Installed before lead ban	U	L	L	L			N					101-4410
5044 S LOTUS AVE	LP1C023	N	Y	1948	1948	Installed before lead ban	U	L	L	L			N					101-4430
4943 S LINDER AVE	N/A	N	Y	1960	1960	Record	U	L	L	L			N					101-4720
4915 S LINDER AVE	N/A	N	N	1952	1952	Field inspection only with no	U	L	L	L		10/23/2024	N					101-4880
4909 S LINDER AVE	N/A	N	N	1949	1949	Record	U	L	C	L		10/23/2024	N					101-4900
4906 S LINDER AVE	N/A	N N	N	1948	1948	Record	U	L	U	L		10/23/2024	N					101-4910
4806 S LINDER AVE	N/A	N N	Y	1948	1948	Record	U		L	L			N					101-5160
4747 S LINDER AVE	N/A	N	Į Y	1954	1954	Record	Įυ	<u> </u> L	<u> </u> L	ĮL.			N	1	<u> </u>	1	l .	101-5260



					Le	ead Service Line Invento	ry Template					
*Please enter information in the empty box next to each section	Water System Nam	ne	Central :	Stickney Sanitary District	Sys	stem ID Number:	IL0315570)	Current Inver	ntory Date:	4/15/2025	
*Please enter totals in the empty box next to each category	Total Service lines:	746 T	otal Lead:	35 Total Non-Lead:	171	Total Galvanized Requi	iring replacement:	0	Total Unknown:	540	Website link to Material Inventory:	

Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Identified Since Last	Year PWS- Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
		EXAMPLES:					EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	-				EXAMPLES:	-		
							Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	If any galvanized service							
	Lead and Copper Sample site number	Group Homes, Parks, Playgrounds, Special Care	,				Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line			If previous column	Copper - No Lead Solder (C)		IF customer refused access to property,	
	is the 7 digit number	Facilities, Hospitals,				How was the Material of this Service Line Identified?	Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)	material was never	Enter date customer was		was marked (Y), provide date the Lead	Galvanized (G)		date waiver obtained	
	starting with "LP" or " LA". / If address is not a	Clinics, Child Care Facilities	Yes (Y) or No (N)	PWS-Owned service line	What year was the customer side service line installed, if known?	EXAMPLES: Construction Records, Visual Inspections, Survey		Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	downstream of any Lead section, mark No (N). / If Yes, that section of	notified of Lead Service Line. / If Service Line is not	Yes (Y) or No (N)	Service Line was replaced. / Leave blank if	Plastic - PVC, HDPE, PEX (P)	Yes (Y) or No (N)	by PWS or date PWS notified IDPH of refusal to sign waiver. /	
	lead and copper sample site mark					Records, etc	Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)		service line should be marked as Galvanized	Lead put N/R		previous column was	Cast/Ductile Iron or Transite (O)		Leave blank if customer has not	
	"N/A"						Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)		Requiring Replacement in the appropriate			(N).			refused access.	
		Yes (Y) or No (N)					Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)		immediately preceding				Leave blank if no Lead Service Line was			
		163 (1) 01 140 (14)					Unknown Not Lead (UNL)	Unknown (U)	Unknown (U)		column(s).				replaced.			
								Unknown Not Lead (UNL)	Unknown Not Lead (UNL)									
4750 S LUNA AVE	N/A	N	Υ	1957	1957	Record	U	L	L	L			N					101-5430
5009 S LUNA AVE	N/A	N	N	1972	1972	Record	U	U	L	L		10/23/2024	N					101-6100
5016 S LUNA AVE	N/A	N	Y	1977	1977	Record	U	L	L	L			N					101-6140
4731 S LATROBE AVE	N/A	N	N	1990	1990	Installation record	UNL	С	С	NL		N/R	N					101-0170
4805 S LATROBE AVE	N/A	N	N	1997	1997	Installation record	UNL	C	C	NL		N/R	N					101-0301
4834 S LATROBE AVE	N/A	N N	N N	1999	1999	Installation record	UNL	C	C	NL		N/R	N N					101-0451
4845 S LATROBE AVE 4901 S LATROBE AVE	N/A N/A	N N	N N	1991 2001	1991 2001	Installation record Installation record	UNL	C	C	NL		N/R N/R	N N					101-0520 101-0591
4905 S LATROBE AVE	N/A	N	N	1992	1992	Installation record	UNL	C	C	NI		N/R	N					101-0630
4910 S LATROBE AVE	N/A	N	N	1998	1998	Installation record	UNL	c	С	NL		N/R	N					101-0671
4914 S LATROBE AVE	N/A	N	N	1997	1997	Installation record	UNL	С	С	NL		N/R	N					101-0681
4921 S LATROBE AVE	N/A	N	N	1990	1990	Installation record	UNL	С	С	NL		N/R	N					101-0700
4936 S LATROBE AVE	N/A	N	N	1986	1986	Installation record	UNL	С	С	NL		N/R	N					101-0760
4943 S LATROBE AVE	N/A	N	N	1985	1985	Installation record	UNL	С	С	NL		N/R	N					101-0820
4949 S LATROBE AVE	N/A	N	N	1978	1978	Installation record	UNL	С	С	NL		N/R	N					101-0840
5010 S LATROBE AVE	N/A	N	N	1995	1995	Installation record	UNL	С	С	NL		N/R	N					101-0960
5015 S LATROBE AVE	N/A	N	N	1993	1993	Installation record	UNL	С	С	NL		N/R	N					101-1010
5016 S LATROBE AVE	N/A	N	N	1990	1990	Installation record	UNL	C	C	NL		N/R	N					101-1020
5018 S LATROBE AVE	N/A	N	N	1996	1996		UNL	C	C	NL 		N/R	N 					101-1030
5022 S LATROBE AVE	N/A	N	N	1990	1990	Installation record	UNL	C	C	NL		N/R	N N					101-1080
5030 S LATROBE AVE 5027 S LOCKWOOD AVE	N/A N/A	N N	N N	1995 2000	1995 2000	Installation record Installation record	UNL	C	C	NI		N/R N/R	N N					101-1121
5027 S LOCKWOOD AVE	N/A	N	N N	1979			UNL	c	C	NI.		N/R	N N					101-1171
5021 S LOCKWOOD AVE	N/A	N	N	1978	1978	Installation record	UNL	c	С	NL		N/R	N					101-1250
5015 S LOCKWOOD AVE	N/A	N	N	1997	1997		UNL	С	С	NL		N/R	N					101-1261
5016 S LOCKWOOD AVE	N/A	N	N	1996	1996	Installation record	UNL	С	С	NL		N/R	N					101-1271
5004 S LOCKWOOD AVE	N/A	N	N	1998	1998	Installation record	UNL	С	С	NL		N/R	N					101-1321
4959 S LOCKWOOD AVE	N/A	N	N	2004	2004	Installation record	UNL	c	С	NL		N/R	N					101-1351
4956 S LOCKWOOD AVE	N/A	N	N	1990	1990	Installation record	UNL	С	С	NL		N/R	N					101-1380
4950 S LOCKWOOD AVE	N/A	N	N	2007	2007	Installation record	UNL	С	С	NL		N/R	N					101-1391
4922 S LOCKWOOD AVE	N/A	N	N	2004	2004		UNL	С	С	NL		N/R	N					101-1481
4913 S LOCKWOOD AVE	N/A	N	N	2001	2001	Installation record	UNL	c	С	NL	<u> </u>	N/R	N		<u> </u>			101-1531



					Le	ead Service Line Invento	ry Template					
*Please enter information in the empty box next to each section	Water System Na	ame	Central	Stickney Sanitary District	Sys	tem ID Number:	IL0315570)	Current Inver	ntory Date:	4/15/2025	
*Please enter totals in the empty box next to each category	Total Service lines:	746	Total Lead:	35 Total Non-Lead:	171	Total Galvanized Requi	ring replacement:	0	Total Unknown:	540	Website link to Material Inventory:	

Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area? EXAMPLES:	Service Line Newly Identified Since Last Submitted Inventory	Year PWS- Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail EXAMPLES:	PWS-Owned Service Line Material EXAMPLES:	Customer Side Service Line Material EXAMPLES:	Classification for Entire Serivice Line EXAMPLES:	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement EXAMPLES:	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
							Copper - No Lead	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)								
	Lead and Copper Sample site number	Group Homes, Parks, Playgrounds, Special Care					Solder (C) Copper - Lead Solde (CLS)		Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line	Fotos doto		If previous column	Copper - No Lead Solder (C)		IF customer refused access to property,	
	is the 7 digit number	Facilities, Hospitals,		Mark Ale a	NA/In the common than	How was the Material of this Service Line Identified?	Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)	material was never	Enter date customer was		was marked (Y), provide date the Lead	Galvanized (G)		date waiver obtained	1
	starting with "LP" or " LA". / If address is not a	Clinics, Child Care Facilities	Yes (Y) or No (N)	PWS-Owned service line	What year was the customer side service line installed, if known?	EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance		Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	downstream of any Lead section, mark No (N). / If Yes, that section of	notified of Lead Service Line. / If Service Line is not	Yes (Y) or No (N)	Service Line was replaced. / Leave blank if	Plastic - PVC, HDPE, PEX (P)	Yes (Y) or No (N)	by PWS or date PWS notified IDPH of refusal to sign waiver /	
	lead and copper sample site mark					Records, etc	Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)		service line should be marked as Galvanized	Lead put N/R		previous column was	Cast/Ductile Iron or Transite (O)		Leave blank if customer has not	
	"N/A"						Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)		Requiring Replacement in the appropriate			(N).			refused access.	
		Yes (Y) or No (N)					Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)		immediately preceding				Leave blank if no Lead Service Line was			
		res (1) or No (N)					Unknown Not Lead (UNL)	Unknown (U)	Unknown (U)		column(s).				replaced.			
								Unknown Not Lead (UNL)	Unknown Not Lead (UNL)									
4909 S LOCKWOOD AVE	N/A	N	N	1985	1985	Installation record	UNL	С	С	NL		N/R	N					101-1550
4905 S LOCKWOOD AVE	N/A	N	N	1997	1997	Installation record	UNL	С	С	NL		N/R	N					101-1581
4903 S LOCKWOOD AVE	N/A	N	N	2005	2005	Installation record	UNL	С	С	NL		N/R	N					101-1582
4839 S LOCKWOOD AVE	N/A	N	N	1998	1998	Installation record	UNL	С	С	NL		N/R	N					101-1591
4836 S LOCKWOOD AVE	N/A	N	N	1993	1993	Installation record	UNL	С	С	NL		N/R	N					101-1615
4831 S LOCKWOOD AVE	N/A	N	N	2006	2006	Installation record	UNL	С	С	NL		N/R	N					101-1650
4833 S LOCKWOOD AVE	N/A	N	N	2009	2009		UNL	С	С	NL		N/R	N					101-1651
4830 S LOCKWOOD AVE	N/A	N	N	1996	1996	Installation record	UNL	С	С	NL		N/R	N					101-1660
4828 S LOCKWOOD AVE	N/A	N 	N	1996	1996		UNL	C	C	NL		N/R	N					101-1671
4825 S LOCKWOOD AVE	N/A N/A	N N	N N	1996	1996		UNL		C	NL		N/R	N					101-1681 101-1691
4824 S LOCKWOOD AVE 4815 S LOCKWOOD AVE	N/A N/A	N N	N N	2003	2003		UNL	C	C	NL NI		N/R N/R	N N					101-1691
4809 S LOCKWOOD AVE	N/A	N	N	1996	1996		UNL	6	C	NI		N/R	N					101-1771
4807 S LOCKWOOD AVE	N/A	N	N	1996	1996		UNL	C	C	NI		N/R	N					101-1831
4805 S LOCKWOOD AVE	N/A	N	N	2008	2008		UNL	c	С	NL		N/R	N					101-1841
4801 S LOCKWOOD AVE	N/A	N	N	1996	1996		UNL	С	С	NL		N/R	N					101-1891
4746 S LOCKWOOD AVE	N/A	N	N	2005	2005		UNL	С	С	NL		N/R	N					101-1931
4740 S LOCKWOOD AVE	N/A	N	N	1993	1993		UNL	С	С	NL		N/R	N					101-1990
4731 S LOCKWOOD AVE	N/A	N	N	2006	2006	Installation record	UNL	С	С	NL		N/R	N					101-2029
5255 W 47TH ST	N/A	N	N	2009	2009	Installation record	UNL	c	С	NL		N/R	N					101-2111
5249 W 47TH ST	N/A	N	N	2009	2009	Installation record	UNL	С	С	NL		N/R	N					101-2112
4739 S LOREL AVE	N/A	N	N	1995	1995	Installation record	UNL	С	С	NL		N/R	N					101-2175
4741 S LOREL AVE	N/A	N	N	1995	1995		UNL	С	С	NL		N/R	N					101-2181
4746 S LOREL AVE	N/A	N	N	1989			UNL	С	С	NL		N/R	N					101-2210
4757 S LOREL AVE	N/A	N	N	2001	2001		UNL	C	С	NL		N/R	N					101-2251
4826 S LOREL AVE	N/A	N	N	2002			UNL	C	C	NL		N/R	N					101-2341
4832 S LOREL AVE	N/A	N	N	2008	2008		UNL	C	C	NL 		N/R	N					101-2390
4848 S LOREL AVE	N/A	N	N	1989	1989		UNL	C	C	NL NI		N/R	N					101-2480
4850 S LOREL AVE	N/A	N	N N	1987	1987		UNL	c	C	INL NI		N/R	N N					101-2500
4851 S LOREL AVE	N/A N/A	N N	N N	2001 1996	2001 1996		UNL	C	C	NI		N/R N/R	IN N					101-2511 101-2561
4903 S LOREL AVE	N/A N/A	N N	N N		1996		UNL	c	C	NI		N/R N/R	N N					101-2561
4904 S LOREL AVE	N/A	I N	IN IN	1995	1995	mstallation record	UNL	<u> </u> C	<u> </u> C	INC	1	IN/K	I N	l	1	I .	l	101-2360



					Le	ead Service Line Invento	ry Template					
*Please enter information in the empty box next to each section	Water System Na	ime	Central S	itickney Sanitary District	Sys	tem ID Number:	IL0315570		Current Inve	ntory Date:	4/15/2025	
*Please enter totals in the empty box next to each category	Total Service lines:	746	Total Lead:	35 Total Non-Lead:	171	Total Galvanized Requi	ring replacement:	Ω	Total Unknown:	540	Website link to Material Inventory:	

Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS- Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail EXAMPLES:	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
		EXAMPLES.					Copper - No Lead								EXAMPLES.			
							Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	If any galvanized service				Conner No Lond			
	Lead and Copper Sample site number	Group Homes, Parks, Playgrounds, Special Care					Copper - Lead Solde (CLS)	er Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line	Enter dete		If previous column	Copper - No Lead Solder (C)		IF customer refused access to property,	
	is the 7 digit number	Facilities, Hospitals,		MA de a de a como a de a	Mhatara	Service Line Identified?	Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)	material was never	Enter date customer was		was marked (Y), provide date the Lead	Galvanized (G)		date waiver obtained	1
	starting with "LP" or " LA". / If address is not a	Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	what year was the customer side service line installed, if known?	EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance		Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	downstream of any Lead section, mark No (N). / If Yes, that section of	notified of Lead Service Line. / If Service Line is not	Yes (Y) or No (N)	Service Line was replaced. / Leave blank if	Plastic - PVC, HDPE, PEX (P)	Yes (Y) or No (N)	by PWS or date PWS notified IDPH of refusal to sign waiver /	
	lead and copper					Records, etc	Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)		service line should be marked as Galvanized	Lead put N/R		previous column was	Cast/Ductile Iron or Transite (O)		Leave blank if	
	sample site mark "N/A"						Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)		Requiring Replacement in			(N).			customer has not refused access.	
							Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)		the appropriate immediately preceding				Leave blank if no			
		Yes (Y) or No (N)					Unknown Not Lead	Unknown (U)	Unknown (U)		column(s).				Lead Service Line was replaced.			
							(UNL)	Unknown Not Lead (UNL)	Unknown Not Lead (UNL)									
4906 S LOREL AVE	N/A	N	N	1996	1996	Installation record	UNL	C	C	NI		N/R	N					101-2590
4907 S LOREL AVE	N/A	N	N	1996	1996		UNL	C	C	NI		N/R	N					101-2591
4914 S LOREL AVE	N/A	N	N	2010	2010		UNL	C	С	NL NL		N/R	N					101-2650
4929 S LOREL AVE	N/A	N	N	2008	2008		UNL	С	С	NL		N/R	N					101-2720
4950 S LOREL AVE	N/A	N	N	2017	2017	Installation record	UNL	С	С	NL		N/R	N					101-2771
5015 S LOREL AVE	LP1A012	N	N	1989	1989	Installation record	UNL	С	С	NL		N/R	N					101-2850
5017 S LOREL AVE	N/A	N	N	2001	2001	Installation record	UNL	С	С	NL		N/R	N					101-2851
5019 S LOREL AVE	N/A	N	N	2008	2008	Installation record	UNL	С	С	NL		N/R	N					101-2860
5021 S LOREL AVE	N/A	N	N	2006	2006	Installation record	UNL	С	С	NL		N/R	N					101-2861
5046 S LONG AVE	N/A	N	N	1996	1996		UNL	С	С	NL		N/R	N					101-2920
5034 S LONG AVE	N/A	N	N	2001	2001		UNL	C	С	NL		N/R	N					101-2931
5032 S LONG AVE	N/A	N	N	2001	2001		UNL	C	C	NL		N/R	N					101-2953
5028 S LONG AVE	LP1A024	N	N	1993	1993		UNL	C -	C	NL		N/R	N					101-2955
5020 S LONG AVE	N/A	N N	N N	2001	2001		UNL	C	C	NL		N/R	N					101-2960
5012 S LONG AVE 5010 S LONG AVE	N/A LP1A021	N N	N N	1993 1993	1993 1993		UNL	C	C	NL NI		N/R N/R	N N					101-2990 101-3000
4949 S LONG AVE	N/A	N N	N	1933	1933	mstallation record	U	UNI	UNL	NL NL		N/R	N N					101-3000
4834 S LONG AVE	N/A	N	N	2013	2013	Installation record	UNL	C	C	NL NL		N/R	N					101-3020
4739 S LONG AVE	N/A	N	N	1994	1994		UNL	С	С	NL		N/R	N					101-3540
5401 W 47TH STREET	N/A	N	N				U	UNL	UNL	NL		N/R	N					101-3591
4732 S LOTUS AVE	N/A	N	N	2000	2000	Installation record	UNL	С	С	NL		N/R	N					101-3609
4736 S LOTUS AVE	N/A	N	N	1998	1998	Installation record	UNL	С	С	NL		N/R	N					101-3610
4743 S LOTUS AVE	N/A	N	N	1997	1997	Installation record	UNL	С	С	NL		N/R	N					101-3631
4756 S LOTUS AVE	N/A	N	N	1994	1994	Installation record	UNL	С	С	NL		N/R	N					101-3671
4801 S LOTUS AVE	N/A	N	N	2001	2001	Installation record	UNL	С	С	NL		N/R	N					101-3700
4814 S LOTUS AVE	N/A	N	N	1992			UNL	С	С	NL		N/R	N					101-3760
4816 S LOTUS AVE	N/A	N	N	1992	1992		UNL	С	С	NL		N/R	N					101-3780
4820 S LOTUS AVE	N/A	N	N	2008	2008		UNL	C	C	NL		N/R	N					101-3790
4842 S LOTUS AVE	N/A	N	N	1993	1993		UNL	C	C	NL 		N/R	N					101-3900
4844 S LOTUS AVE	N/A	N N	N	1993	1993		UNL		C	NL NI		N/R	N					101-3910
4909 S LOTUS AVE	N/A	N	N	1997	1997		UNL		C	NL		N/R	N					101-3991
4911 S LOTUS AVE	N/A	N	N	1997	1997	Installation record	UNL	ĮC.	lr.	INL	L	N/R	N		i		L	101-4000



					Le	ead Service Line Invento	ry Template					
*Please enter information in the empty box next to each section	Water System Nam	ne	Central :	Stickney Sanitary District	Sys	stem ID Number:	IL0315570)	Current Inver	ntory Date:	4/15/2025	
*Please enter totals in the empty box next to each category	Total Service lines:	746 T	otal Lead:	35 Total Non-Lead:	171	Total Galvanized Requi	iring replacement:	0	Total Unknown:	540	Website link to Material Inventory:	

Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS- Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail EXAMPLES:	PWS-Owned Service Line Material EXAMPLES:	Customer Side Service Line Material EXAMPLES:	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement EXAMPLES:	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account
							Copper - No Lead	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)								A
	Lead and Copper Sample site number	Group Homes, Parks, Playgrounds, Special Care					Solder (C) Copper - Lead Solde (CLS)		Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If			If previous column	Copper - No Lead Solder (C)		IF customer refused access to property,	
	is the 7 digit number					How was the Material of this Service Line Identified?	Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)	the galvanized service line material was never	Enter date customer was		was marked (Y), provide date the Lead	Galvanized (G)		date waiver obtained	
	starting with "LP" or " LA". / If address is not a	Clinics, Child Care Facilities	Yes (Y) or No (N)	PWS-Owned service line	What year was the customer side service line installed, if known?	EXAMPLES: Construction Records, Visual Inspections, Survey		Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	downstream of any Lead section, mark No (N). / If Yes, that section of	notified of Lead Service Line. / If Service Line is not	Yes (Y) or No (N)	Service Line was replaced. / Leave blank if	Plastic - PVC, HDPE, PEX (P)	Yes (Y) or No (N)	by PWS or date PWS notified IDPH of refusal to sign waiver /	
	lead and copper					Records, etc	Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)		service line should be marked as Galvanized	Lead put N/R		previous column was	Cast/Ductile Iron or Transite (O)		Leave blank if	
	sample site mark "N/A"						Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)		Requiring Replacement in			(N).			customer has not refused access.	
		V (V) - 21 (21)					Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)		the appropriate immediately preceding				Leave blank if no			
		Yes (Y) or No (N)					Unknown Not Lead	Unknown (U)	Unknown (U)		column(s).				Lead Service Line was replaced.			
							(OIVE)	Unknown Not Lead (UNL)	Unknown Not Lead (UNL)									
4948 S LOTUS AVE	N/A	N	N	1986	1986	Installation record	UNL	С	С	NL		N/R	N					101-4160
4951 S LOTUS AVE	N/A	N	N				U	UNL	UNL	NL		N/R	N					101-4180
5004 S LOTUS AVE	N/A	N	N	2001	2001	Installation record	UNL	С	С	NL		N/R	N					101-4210
5007 S LOTUS AVE	N/A	N	N	1994	1994	Installation record	UNL	С	С	NL		N/R	N					101-4240
5008 S LOTUS AVE	N/A	N	N	1998	1998	Installation record	UNL	С	С	NL		N/R	N					101-4250
5009 S LOTUS AVE	N/A	N	N	1993	1993	Installation record	UNL	С	С	NL		N/R	N					101-4260
5029 S LOTUS AVE	N/A	N	N	1991	1991	Installation record	UNL	С	С	NL		N/R	N					101-4330
5031 S LOTUS AVE	N/A	N	N	1991	1991	Installation record	UNL	С	С	NL		N/R	N					101-4350
5041 S LOTUS AVE	N/A	N	N	2001	2001		UNL	С	С	NL		N/R	N					101-4391
5040 S LINDER AVE	N/A	N	N	1996	1996		UNL	C	C	NL		N/R	N					101-4501
5038 S LINDER AVE	N/A	N	N	2007	2007		UNL	C	C	NL		N/R	N					101-4510
5036 S LINDER AVE	N/A	N	N	1998	1998		UNL	C	C	NL NI		N/R	N					101-4511
5034 S LINDER AVE 5030 S LINDER AVE	N/A N/A	N N	N N	1998 1987	1998 1987		UNL	C	C	NL		N/R N/R	N N					101-4541 101-4560
5030 S LINDER AVE	N/A	N	N N	1986	1986		UNL	C	C	NI		N/R	N					101-4560
5009 S LINDER AVE	N/A	N	N N	2006	2006		UNL	C	C	NL		N/R	N					101-4630
5001 S LINDER AVE	N/A	N	N	1996	1996		UNL	С	С	NL NL		N/R	N					101-4661
4925 S LINDER AVE	N/A	N	N	2018	2018		UNL	С	С	NL		N/R	N					101-4840
4921 S LINDER AVE	N/A	N	N	1992	1992		UNL	С	С	NL		N/R	N					101-4860
4912 S LINDER AVE	N/A	N	N	2001	2001	Installation record	UNL	С	С	NL		N/R	N					101-4890
4858 S LINDER AVE	N/A	N	N	1984	1984	Installation record	UNL	с	С	NL		N/R	N					101-4950
4851 S LINDER AVE	N/A	N	N	2015	2015	Installation record	UNL	С	С	NL		N/R	N					101-4981
4849 S LINDER AVE	N/A	N	N	2014	2014	Installation record	UNL	С	С	NL		N/R	N					101-4990
4835 S LINDER AVE	N/A	N	N	2005			UNL	С	С	NL		N/R	N					101-5052
4827 S LINDER AVE	N/A	N	N	2005			UNL	С	С	NL		N/R	N					101-5070
4829 S LINDER AVE	N/A	N	N	2005			UNL	С	С	NL		N/R	N					101-5071
4816 S LINDER AVE	N/A	N	N	2009	2009		UNL	C	С	NL		N/R	N					101-5110
4817 S LINDER AVE	N/A	N	N	2009			UNL	C	C	NL NI		N/R	N					101-5111
4814 S LINDER AVE	N/A	N	N N	2008			UNL	c	C	NL NI		N/R	N N					101-5115
4811 S LINDER AVE 4812 S LINDER AVE	N/A N/A	N N	N N	2008 1999	2008 1999		UNL	C	C	NL NL		N/R N/R	IN N					101-5130 101-5140
4757 S LINDER AVE	N/A N/A	N N	N N	1999			UNL		1	NI		N/R	N N					101-5140



					Le	ead Service Line Invento	ry Template					
*Please enter information in the empty box next to each section	Water System Na	me	Central	Stickney Sanitary District	Sys	stem ID Number:	IL0315570)	Current Inver	ntory Date:	4/15/2025	
*Please enter totals in the empty box next to each category	Total Service lines:	746	Total Lead:	35 Total Non-Lead:	171	Total Galvanized Requi	ring replacement:	Ο	Total Unknown:	540	Website link to Material Inventory:	

Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Identified Since Last	Year PWS- Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	refused access to	Date of customer waiver or IDPH notification, if customer refused access to property	
		EXAMPLES:					Copper - No Lead		EXAMPLES:						EXAMPLES:	1		
							Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	If any galvanized service				Copper - No Lead			
	Lead and Copper Sample site number	Group Homes, Parks, Playgrounds, Special Care	,			II	Copper - Lead Solde (CLS)	r Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line	Futur data		If previous column	Solder (C)		IF customer refused access to property,	
	is the 7 digit number	Facilities, Hospitals,		Mark Ab -	14/h-a-t	How was the Material of this Service Line Identified?	Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)	material was never	Enter date customer was		was marked (Y), provide date the Lead	Galvanized (G)		date waiver obtained	1
	starting with "LP" or " LA". / If address is not a	Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	customer side service line	EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance		Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	downstream of any Lead section, mark No (N). / If Yes, that section of	notified of Lead Service Line. / If Service Line is not	Yes (Y) or No (N)	Service Line was replaced. / Leave blank if	Plastic - PVC, HDPE, PEX (P)	Yes (Y) or No (N)	by PWS or date PWS notified IDPH of refusal to sign waiver /	:
	lead and copper					Records, etc	Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)		service line should be marked as Galvanized	Lead put N/R		previous column was	Cast/Ductile Iron or Transite (O)		Leave blank if	
	sample site mark "N/A"						Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)		Requiring Replacement in			(N).			customer has not refused access.	
							Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)		the appropriate immediately preceding				Leave blank if no			
		Yes (Y) or No (N)					Unknown Not Lead	Unknown (U)	Unknown (U)		column(s).				Lead Service Line wa replaced.	s		
							(UNL)	Unknown Not Lead (UNL)	Unknown Not Lead (UNL)						replaced.			
								onknown not Lead (ONL)	onknown Not Lead (ONL)									
4752 S LINDER AVE	N/A	N N	N N	2000	2000	Installation record	UNL	C	C	NL NI		N/R	N N					101-5231
4722 S LUNA AVE 4724 S LUNA AVE	N/A N/A	N N	N N	2006	2006	Installation record Installation record	UNL	C	C	NL NI		N/R N/R	N N					101-5331
4726 S LUNA AVE	N/A N/A	N	N	2004	2004	Installation record	UNL	C	C	NI		N/R	N N					101-5341
4742 S LUNA AVE	N/A	N	N	1996	1996	Installation record	UNL	C	C	NI		N/R	N					101-5351
4752 S LUNA AVE	N/A	N	N	1990	1990	Installation record	UNL	С	С	NL		N/R	N					101-5450
4800 S LUNA AVE	N/A	N	N	2001	2001	Installation record	UNL	С	С	NL		N/R	N					101-5511
4804 S LUNA AVE	N/A	N	N	2001	2001	Installation record	UNL	С	С	NL		N/R	N					101-5522
4806 S LUNA AVE	N/A	N	N	2002	2002	Installation record	UNL	С	С	NL		N/R	N					101-5531
4807 S LUNA AVE	N/A	N	N	1979	1979	Installation record	UNL	С	С	NL		N/R	N					101-5540
4808 S LUNA AVE	N/A	N	N	2002	2002	Installation record	UNL	С	С	NL		N/R	N					101-5541
4810 S LUNA AVE	N/A	N	N	2002	2002	Installation record	UNL	С	С	NL		N/R	N					101-5551
4817 S LUNA AVE	N/A	N	N	2006	2006	Installation record	UNL	С	С	NL		N/R	N					101-5578
4819 S LUNA AVE	N/A	N	N	2006	2006	Installation record	UNL	С	С	NL		N/R	N					101-5579
4841 S LUNA AVE	N/A	N	N	1994	1994	Installation record	UNL	С	С	NL		N/R	N					101-5640
4843 S LUNA AVE	N/A	N	N	1993	1993		UNL	C	C	NL		N/R	N					101-5660
4845 S LUNA AVE	N/A	N	N	1993	1993	Installation record	UNL	C	C	NL NI		N/R	N N					101-5680
4847 S LUNA AVE	N/A	N N	N	1993	1993	Installation record	UNL	C	C	NL NI		N/R	N N					101-5700
4859 S LUNA AVE	N/A N/A	N N	N N	2001	2001	Installation record	UNL	C	C	NI.		N/R N/R	N N					101-5770 101-5801
4902 S LUNA AVE 4904 S LUNA AVE	N/A N/A	N N	N N	2009	2009	Installation record Installation record	UNL	C	C	NI		N/R N/R	N N					101-5801
4913 S LUNA AVE	N/A N/A	N N	N	1999	1999	Installation record	UNL	c	C	NL		N/R	N					101-5810
4915 S LUNA AVE	N/A	N	N	1992	1992		UNL	C	С	NL		N/R	N					101-5870
5003 S LUNA AVE	N/A	N	N	2007	2007	Installation record	UNL	С	С	NL		N/R	N					101-6062
5002 S LUNA AVE	N/A	N	N	1995	1995	Installation record	UNL	С	С	NL		N/R	N					101-6080
5041 S LUNA AVE	N/A	N	N	1992	1992	Installation record	UNL	С	С	NL		N/R	N					101-6201
5042 S LUNA AVE	N/A	N	N	2007	2007	Installation record	UNL	С	С	NL		N/R	N					101-6281
5044 S LUNA AVE	N/A	N	N	2007	2007	Installation record	UNL	С	С	NL		N/R	N					101-6290
5023 S CENTRAL AVE	N/A	N	N	1989	1989	Installation record	UNL	С	С	NL		N/R	N					101-6380
5021 S CENTRAL AVE	N/A	N	N	2008	2008	Installation record	UNL	С	С	NL		N/R	N					101-6381
5019 S CENTRAL AVE	N/A	N	N	2007	2007	Installation record	UNL	С	С	NL		N/R	N					101-6390
5017 S CENTRAL AVE	N/A	N	N	1991	1991	Installation record	UNL	C	C	NL		N/R	N				<u> </u>	101-6410



					Le	ead Service Line Invento	ry Template					
*Please enter information in the empty box next to each section	Water System Na	ame	Central	Stickney Sanitary District	Sys	tem ID Number:	IL0315570)	Current Inver	ntory Date:	4/15/2025	
*Please enter totals in the empty box next to each category	Total Service lines:	746	Total Lead:	35 Total Non-Lead:	171	Total Galvanized Requi	ring replacement:	0	Total Unknown:	540	Website link to Material Inventory:	

Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Identified Since Last	Year PWS- Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	refused access to	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
		EXAMPLES:					EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	-				EXAMPLES:			
							Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	If any galvanized service				Copper - No Lead			
	Lead and Copper Sample site number	Group Homes, Parks, Playgrounds, Special Care				II	Copper - Lead Solder (CLS)	r Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line	Futur data		If previous column	Solder (C)		IF customer refused access to property,	
		Facilities, Hospitals,				How was the Material of this Service Line Identified?	Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)	material was never	Enter date customer was		was marked (Y), provide date the Lead	Galvanized (G)		date waiver obtained	
	starting with "LP" or " LA". / If address is not a	Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	EXAMPLES: Construction Records, Visual Inspections, Survey		Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	downstream of any Lead section, mark No (N). / If Yes, that section of	notified of Lead Service Line. / If Service Line is not	Yes (Y) or No (N)	Service Line was replaced. / Leave blank if	Plastic - PVC, HDPE, PEX (P)	Yes (Y) or No (N)	by PWS or date PWS notified IDPH of refusal to sign waiver. /	
	lead and copper					Records, etc	Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)		service line should be marked as Galvanized	Lead put N/R		previous column was	Cast/Ductile Iron or Transite (O)		Leave blank if	
	sample site mark "N/A"						Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)		Requiring Replacement in			(N).			customer has not refused access.	
							Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)		the appropriate immediately preceding				Leave blank if no			
		Yes (Y) or No (N)					Unknown Not Lead	Unknown (U)	Unknown (U)		column(s).				Lead Service Line was replaced.	5		
							(UNL)	Unknown Not Lead (UNL)	Unknown Not Lead (UNL)						·			
5011 S CENTRAL AVE	N/A	N	N	1992	1992	Installation record	UNL	C	C	NII		N/R	N					101-6430
4957 S CENTRAL AVE	N/A	N	N	1999	1999	Installation record	UNL	C	C	NI		N/R	N					101-6450
4917 S CENTRAL AVE	N/A	N	N	1333	1555	installation record	U	UNI	UNL	NL.		N/R	N					101-6470
4851 S CENTRAL #13855	N/A	N	N				U	UNL	UNL	NL		N/R	N					101-6481
4839 S CENTRAL AVE	N/A	N	N				U	UNL	UNL	NL		N/R	N					101-6490
4837 S CENTRAL AVE	N/A	N	N	1967	1967	Diameter of Pipe	U	UNL	UNL	NL		N/R	N					101-6495
4817 S CENTRAL AVE	N/A	N	N				U	С	С	NL		N/R	N					101-6510
4813 S CENTRAL AVE	N/A	N	N				U	С	С	NL		N/R	N					101-6520
4811 S CENTRAL AVE	N/A	N	N				U	С	С	NL		N/R	N					101-6530
4807 S CENTRAL AVE	N/A	N	N				U	С	С	NL		N/R	N					101-6540
4759 S CENTRAL AVE	N/A	N	N	1979	1979	Installation record	UNL	С	С	NL		N/R	N					101-6550
4751-55 S CENTRAL AVE	N/A	N	N				U	C .	C	NL		N/R	N					101-6560
4731 S CENTRAL AVE	N/A	N	N				U 	C	C	NL 		N/R	N					101-6600
5000 S LARAMIE AVE	N/A	N	N					C	C	NL 		N/R	N N					101-6610
5219 W 47TH STREET 5203 W 47TH STREET	N/A N/A	N N	N N				11	0	U	11			N N					101-0010 101-0011
5247 W 47TH STREET	N/A	N N	N N				U	lu .	П	U U			N N					101-0011
5235 W 47TH STREET	N/A	N	N				U	U	U	U			N					101-0012
4706 S LATROBE AVE	N/A	N	N	1961	1961		U	U	U	U			N					101-0030
4708 S LATROBE AVE	N/A	N	N	1961	1961		U	U	U	U			N					101-0050
4710 S LATROBE AVE	N/A	N	N	1961	1961		U	U	U	U			N					101-0060
4712 S LATROBE AVE	N/A	N	N	1961	1961		U	U	U	U			N					101-0070
4721 S LATROBE AVE	N/A	N	N	1971	1971		U	U	U	U			N					101-0080
4714 S LATROBE AVE	N/A	N	N	1961	1961		U	U	U	U			N					101-0090
4723 S LATROBE AVE	N/A	N	N	1958	1958		U	U	U	U			N					101-0100
4725 S LATROBE AVE	N/A	N	N	1958	1958		U	U	U	U			N					101-0110
4716 S LATROBE AVE	N/A	N	N	1958	1958		U	U	U	U			N					101-0120
4727 S LATROBE AVE	N/A	N	N				U	U	U	U			N					101-0130
4718 S LATROBE AVE	N/A	N	N	1958	1958		U	U	U 	U			N					101-0140
4729 S LATROBE AVE	N/A	N	N	1958	1958		U	U	U	U			N N					101-0150
4720 S LATROBE AVE	N/A N/A	N N	N N	1961 1961	1961				U	U			N N					101-0160 101-0180
4722 S LATROBE AVE	N/A	I N	I N	1301	1961	<u> </u>	Į0	Jo	Jo	Įυ	1	<u> </u>	IN IN	1	I	I	I	101-0100



					Le	ead Service Line Invento	ry Template					
*Please enter information in the empty box next to each section	Water System Na	me	Central	Stickney Sanitary District	Sys	stem ID Number:	IL0315570)	Current Inver	ntory Date:	4/15/2025	
*Please enter totals in the empty box next to each category	Total Service lines:	746	Total Lead:	35 Total Non-Lead:	171	Total Galvanized Requi	ring replacement:	Ο	Total Unknown:	540	Website link to Material Inventory:	

Service Address	Lead and Copper Sample site number.		Service Line Newly Identified Since Last Submitted Inventory	Year PWS- Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	: Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
		EXAMPLES:					EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:					EXAMPLES:	4		
							Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	If any galvanized service				Copper - No Lead			
	Lead and Copper Sample site number	Group Homes, Parks, Playgrounds, Special Care	,			How was the Material of this	Copper - Lead Solde (CLS)	er Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line	Enter date		If previous column	Solder (C)		IF customer refused access to property,	
	is the 7 digit number	Facilities, Hospitals,		Milestones	14/h4	Service Line Identified?	Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)	material was never	customer was		was marked (Y), provide date the Lead	Galvanized (G)		date waiver obtained	
	starting with "LP" or " LA". / If address is not a	Clinics, Child Care Facilities	Yes (Y) or No (N)	PWS-Owned service line	What year was the customer side service line installed, if known?	EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance		Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	downstream of any Lead section, mark No (N). / If Yes, that section of	notified of Lead Service Line. / If Service Line is not	Yes (Y) or No (N)	Service Line was replaced. / Leave blank if	Plastic - PVC, HDPE, PEX (P)	Yes (Y) or No (N)	by PWS or date PWS notified IDPH of refusal to sign waiver /	
	lead and copper					Records, etc	Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)		service line should be marked as Galvanized	Lead put N/R		previous column was	Cast/Ductile Iron or Transite (O)		Leave blank if	
	sample site mark "N/A"						Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)		Requiring Replacement in			(N).			customer has not refused access.	
							Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)		the appropriate immediately preceding				Leave blank if no			
		Yes (Y) or No (N)					Unknown Not Lead	Unknown (U)	Unknown (U)		column(s).				Lead Service Line was replaced.	5		
							(UNL)	Unknown Not Lead (UNL)	Unknown Not Lead (UNL)						·			
4724 S LATROBE AVE	21/2	N.	N	1000	1000				U.				N.					101 0100
	N/A N/A	N N	N N	1960 1958	1960 1958		U		U	U			N N					101-0190
4737 S LATROBE AVE 4726 S LATROBE AVE	N/A N/A	N N	N N	1958	1958		U	U	11	U			N N					101-0200
4741 S LATROBE AVE	N/A	N	N	1973	1973		II	U U	II	II			N N					101-0210
4728 S LATROBE AVE	N/A	N	N	1960	1960		IJ	U	U	IJ			N					101-0230
4743 S LATROBE AVE	N/A	N	N	1975	1975		U	U	U	U			N					101-0240
4744 S LATROBE AVE	N/A	N	N	1945	1945		U	U	U	U			N					101-0250
4748 S LATROBE AVE	N/A	N	N	1955	1955		U	U	U	U			N					101-0260
4755 S LATROBE AVE	N/A	N	N	1959	1959		U	U	U	U			N					101-0270
4752 S LATROBE AVE	N/A	N	N	1956	1956		U	U	U	U			N					101-0280
4806 S LATROBE AVE	N/A	N	N	1943	1943		U	U	U	U			N					101-0300
4808 S LATROBE AVE	N/A	N	N	1942	1942		U	U	U	U			N					101-0310
4807 S LATROBE AVE	N/A	N	N	1943	1943		U	U	U	U			N					101-0320
4810 S LATROBE AVE	N/A	N	N	1955	1955		U	U	U	U			N					101-0330
4811 S LATROBE AVE	N/A	N	N	1971	1971		U	U	U	U			N					101-0340
4812 S LATROBE AVE	N/A	N N	N	1948	1948		U	U	U	U			N N					101-0350
4813 S LATROBE AVE 4814 S LATROBE AVE	N/A N/A	N N	N N	1960 1945	1960 1945		II	111	U U	11			N N					101-0360 101-0370
4814 S LATROBE AVE	N/A N/A	N N	N N	1945	1945		II	u u	II .	II.			N N					101-0370
4816 S LATROBE AVE	N/A	N	N	1949	1949		U	U	U	Ū			N					101-0390
4817 S LATROBE AVE	N/A	N	N	1960	1960		U	U	U	U			N					101-0400
4818 S LATROBE AVE	N/A	N	N	1954	1954		U	U	U	U			N					101-0410
4819 S LATROBE AVE	N/A	N	N	1962	1962		U	U	U	U			N					101-0420
4821 S LATROBE AVE	N/A	N	N	1960	1960		U	U	U	U			N					101-0430
4832 S LATROBE AVE	N/A	N	N	1952	1952		U	U	U	U			N					101-0440
4823 S LATROBE AVE	N/A	N	N	1960	1960		U	U	U	U			N					101-0450
4839 S LATROBE AVE	N/A	N	N	1961	1961		U	U	U	U			N					101-0460
4836 S LATROBE AVE	N/A	N	N	1938	1938		U	U	U	U			N					101-0470
4841 S LATROBE AVE	N/A	N	N	1928	1928		U	U	U	U			N					101-0480
4838 S LATROBE AVE	N/A	N	N	1950	1950		U	U	U	U			N					101-0490
4843 S LATROBE AVE	N/A	N	N	1955	1955		U	U	U 	U			N					101-0500
4840 S LATROBE AVE	N/A	N	N	1933	1933		U	Įυ	Įυ	U			N	1		<u> </u>	l .	101-0510



					Le	ead Service Line Invento	ry Template					
*Please enter information in the empty box next to each section	Water System Na	ame	Central	Stickney Sanitary District	Sys	tem ID Number:	IL0315570)	Current Inver	ntory Date:	4/15/2025	
*Please enter totals in the empty box next to each category	Total Service lines:	746	Total Lead:	35 Total Non-Lead:	171	Total Galvanized Requi	ring replacement:	0	Total Unknown:	540	Website link to Material Inventory:	

Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Identified Since Last	Year PWS- Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
		EXAMPLES:					EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	-				EXAMPLES:			
							Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	If any galvanized service				Comment of the Comment			
	Lead and Copper Sample site number	Group Homes, Parks, Playgrounds, Special Care					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line	- · · · ·		If previous column	Copper - No Lead Solder (C)		IF customer refused access to property,	
	is the 7 digit number	Facilities, Hospitals,				How was the Material of this Service Line Identified?	Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)	material was never	Enter date customer was		was marked (Y), provide date the Lead	Galvanized (G)		date waiver obtained	
	starting with "LP" or " LA". / If address is not a	Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance		Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	downstream of any Lead section, mark No (N). / If Yes, that section of	notified of Lead Service Line. / If Service Line is not	Yes (Y) or No (N)	Service Line was replaced. / Leave blank if	Plastic - PVC, HDPE, PEX (P)	Yes (Y) or No (N)	by PWS or date PWS notified IDPH of refusal to sign waiver. /	
	lead and copper sample site mark					Records, etc	Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)		service line should be marked as Galvanized	Lead put N/R		previous column was	Cast/Ductile Iron or Transite (O)		Leave blank if customer has not	
	"N/A"						Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)		Requiring Replacement in the appropriate			(N).			refused access.	
		V (M) N- (N)					Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)		immediately preceding				Leave blank if no			
		Yes (Y) or No (N)					Unknown Not Lead	Unknown (U)	Unknown (U)		column(s).				Lead Service Line was replaced.	5		
							(One)	Unknown Not Lead (UNL)	Unknown Not Lead (UNL)									
4848 S LATROBE AVE	N/A	N	N	1940	1940		U	U	U	U			N					101-0530
1/2 LATROBE AVE 4845	N/A	N	N				U	U	U	U			N					101-0540
4847 S LATROBE AVE	N/A	N	N	1946	1946		U	U	U	U			N					101-0550
4852 S LATROBE AVE	N/A	N	N				U	U	U	U			N					101-0560
4849 S LATROBE AVE	N/A	N	N	1946	1946		U	U	U	U			N					101-0561
4854 S LATROBE AVE	N/A	N	N	1959	1959		U	U	U	U			N					101-0570
4856 S LATROBE AVE	N/A	N	N	1918	1918		U	U	U	U			N					101-0590
4900 S LATROBE AVE	N/A	N	N	1943	1943		U 		U 	U 			N 					101-0600
4902 S LATROBE AVE 4903 S LATROBE AVE	N/A N/A	N N	N N	1936 1936	1936 1936		11		U	11			N N					101-0610 101-0620
4904 S LATROBE AVE	N/A	N	N	1938	1938		U	II	II	U			N					101-0640
4906 S LATROBE AVE	N/A	N	N	1330	1950		U	U	U	U			N					101-0641
4907 S LATROBE AVE	N/A	N	N	1936	1936		U	U	U	U			N					101-0650
4908 S LATROBE AVE	N/A	N	N	1949	1949		U	U	U	U			N					101-0660
4909 S LATROBE AVE	N/A	N	N	1936	1936		U	U	U	U			N					101-0670
4912 S LATROBE AVE	N/A	N	N	1934	1934		U	U	U	U			N					101-0680
4915 S LATROBE AVE	N/A	N	N	1957	1957		U	U	U	U			N					101-0690
4918 S LATROBE AVE	N/A	N	N	1938	1938		U	U	U	U			N					101-0710
4920 S LATROBE AVE	N/A	N	N	1954	1954		U	U	U	U			N					101-0720
4923 S LATROBE AVE	N/A	N	N	1919	1919		U	U	U	U			N					101-0730
4922 S LATROBE AVE	N/A	N	N	1941	1941		U	U	U	U			N					101-0740
4925 S LATROBE AVE	N/A	N N	N	1959	1959		U	U	U	U			N N					101-0750
4938 S LATROBE AVE 4927 S LATROBE AVE	N/A N/A	N N	N N	1968 1954	1968 1954		11		11	11			N N					101-0770 101-0780
4940 S LATROBE AVE	N/A N/A	N N	N N	1935	1935		II		11	11			N N					101-0780
4941 S LATROBE AVE	N/A	N	N	1935	1935		U		II	U U			N N					101-0790
4942 S LATROBE AVE	N/A	N	N	1967	1967		U	U	U	U			N					101-0810
4944 S LATROBE AVE	N/A	N	N	1966	1966		U	U	U	U			N					101-0830
4952 S LATROBE AVE	N/A	N	N	1956	1956		U	U	U	U			N					101-0850
4957 S LATROBE AVE	N/A	N	N	1957	1957		U	U	U	U			N					101-0860
4956 S LATROBE AVE	N/A	N	N	1944	1944		U	U	U	U			N					101-0870
4959 S LATROBE AVE	N/A	N	N	1974	1974		U	U	U	U			N					101-0880



					Le	ead Service Line Invento	ry Template					
*Please enter information in the empty box next to each section	Water System Nam	ne	Central :	Stickney Sanitary District	Sys	stem ID Number:	IL0315570)	Current Inver	ntory Date:	4/15/2025	
*Please enter totals in the empty box next to each category	Total Service lines:	746 T	otal Lead:	35 Total Non-Lead:	171	Total Galvanized Requi	iring replacement:	0	Total Unknown:	540	Website link to Material Inventory:	

	Land and Carrer			Year PWS-	Very Contamor					Classification for	Was Galvanized	Data Customan	Was a Lead Service				Date of customer waiver	
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	or IDPH notification, if customer refused access to property	Water Account Number
		EXAMPLES:					EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:					EXAMPLES:			
							Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	If any galvanized service							
	Lead and Copper Sample site number	Group Homes, Parks, Playgrounds, Special Care	,				Copper - Lead Solde (CLS)	r Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line			If previous column	Copper - No Lead Solder (C)		IF customer refused access to property,	
	is the 7 digit number	Facilities, Hospitals,				How was the Material of this Service Line Identified?	Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)	material was never	Enter date customer was		was marked (Y), provide date the Lead	Galvanized (G)		date waiver obtained	i
	starting with "LP" or " LA". / If address is not a	Clinics, Child Care Facilities	Yes (Y) or No (N)	PWS-Owned service line	What year was the customer side service line installed, if known?	EXAMPLES: Construction Records, Visual Inspections, Survey		Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	downstream of any Lead section, mark No (N). / If Yes, that section of	notified of Lead Service Line. /	Yes (Y) or No (N)	Service Line was replaced. / Leave blank if	Plastic - PVC, HDPE, PEX (P)	Yes (Y) or No (N)	by PWS or date PWS notified IDPH of refusal to sign waiver /	
	lead and copper					Response, Maintenance Records, etc	Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)		service line should be marked as Galvanized	If Service Line is not Lead put N/R		previous column was	Cast/Ductile Iron or Transite (O)		Leave blank if	
	sample site mark "N/A"						Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)		Requiring Replacement in			(N).			customer has not refused access.	
							Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)		the appropriate immediately preceding				Leave blank if no			
		Yes (Y) or No (N)					Unknown Not Lead	Unknown (U)	Unknown (U)		column(s).				Lead Service Line was replaced.			
							(UNL)	Unknown Not Lead (UNL)	Unknown Not Lead (UNL)						·			
4958 S LATROBE AVE	N/A	N	N	1949	1949		11		11				N					101-0890
5000 S LATROBE AVE	N/A	N N	N	1949	1949		11	11	11	II			N N					101-0890
5001 S LATROBE AVE	N/A	N	N	1960	1960		U	u	U	U			N					101-0910
5004 S LATROBE AVE	N/A	N	N	1960	1960		U	U	U	U			N					101-0920
5003 S LATROBE AVE	N/A	N	N	1960	1960		U	U	U	U			N					101-0930
5008 S LATROBE AVE	N/A	N	N	1936	1936		U	U	U	U			N					101-0940
5005 S LATROBE AVE	N/A	N	N				U	U	U	U			N					101-0950
1/2 LATROBE AVE 5010	N/A	N	N				U	U	U	U			N					101-0961
5011 S LATROBE AVE	N/A	N	N	1960	1960		U	U	U	U			N					101-0970
5012 S LATROBE AVE	N/A	N	N	1960	1960		U	U	U	U			N					101-0980
5013 S LATROBE AVE	N/A	N	N	1916	1916		U	U	U	U			N					101-0990
5014 S LATROBE AVE	N/A	N	N	1950	1950		U	U	U	U			N					101-1000
1/2 LATROBE AVE 5018	N/A	N	N				U	U 	U	U			N					101-1031
5019 S LATROBE AVE	N/A N/A	N N	N N	1918	1918		U	U	U				N					101-1040
5021 S LATROBE AVE 5020 S LATROBE AVE	N/A N/A	N N	N N	1928 1932	1928 1932		11	11	11	11			N N					101-1050 101-1060
5020 S LATROBE AVE	N/A	N N	N	1932	1932		IJ	u	U	U			N N					101-1060
5025 S LATROBE AVE	N/A	N	N	1940	1940		U	U	U	U			N					101-1070
5024 S LATROBE AVE	N/A	N	N	1914	1914		U	U	U	U			N					101-1100
5027 S LATROBE AVE	N/A	N	N	1936	1936		U	U	U	U			N					101-1110
5026 S LATROBE AVE	N/A	N	N	1972	1972		U	U	U	U			N					101-1120
5029 S LATROBE AVE	N/A	N	N	1936	1936	-	U	U	U	U			N					101-1130
5216 W 51ST STREET	N/A	N	N				U	U	U	U			N					101-1131
5218 W 51ST STREET	N/A	N	N				U	U	U	U			N					101-1132
5031 S LOCKWOOD AVE	N/A	N	N	1965	1965		U	U	U	U			N					101-1140
5044 S LOCKWOOD AVE	N/A	N	N	1948	1948		U	U	U	U			N					101-1150
5029 S LOCKWOOD AVE	N/A	N	N	1949	1949		U	U	U	U			N					101-1160
5028 S LOCKWOOD AVE	N/A	N	N	1976	1976		U	U	U	U			N					101-1170
5026 S LOCKWOOD AVE	N/A	N	N	1910	1910		U		U	U			N					101-1180
5025 S LOCKWOOD AVE	N/A N/A	N N	N N	1952	1952		U	U	U	U			N					101-1190
5022 S LOCKWOOD AVE 5023 S LOCKWOOD AVE	N/A N/A	N N	N N	1964 1955	1964 1955		U II	11	11	11			N					101-1210 101-1220
JUZJ J LUCKWOOD AVE	IN/M	IN	IN	1533	1333		0	I _C	I _C		1		IN IN	L	1		l .	101-1220



					Le	ead Service Line Invento	ry Template					
*Please enter information in the empty box next to each section	Water System Nam	ne	Central :	Stickney Sanitary District	Sys	stem ID Number:	IL0315570)	Current Inver	ntory Date:	4/15/2025	
*Please enter totals in the empty box next to each category	Total Service lines:	746 T	otal Lead:	35 Total Non-Lead:	171	Total Galvanized Requi	iring replacement:	0	Total Unknown:	540	Website link to Material Inventory:	

Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Identified Since Last	Year PWS- Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail EXAMPLES:	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	: Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
		Ero um EEO					Copper - No Lead								270 1111 2201			
							Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	If any galvanized service				Copper - No Lead			
	Lead and Copper Sample site number	Group Homes, Parks, Playgrounds, Special Care	,				Copper - Lead Solde (CLS)	r Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line			If previous column	Solder (C)		IF customer refused access to property,	
	is the 7 digit number	Facilities, Hospitals,				How was the Material of this Service Line Identified?	Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)	material was never	Enter date customer was		was marked (Y), provide date the Lead	Galvanized (G)		date waiver obtained	t
	starting with "LP" or " LA". / If address is not a	Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	customer side service line	EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance		Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	downstream of any Lead section, mark No (N). / If Yes, that section of	notified of Lead Service Line. / If Service Line is not	Yes (Y) or No (N)	Service Line was replaced. / Leave blank if	Plastic - PVC, HDPE, PEX (P)	Yes (Y) or No (N)	by PWS or date PWS notified IDPH of refusal to sign waiver /	
	lead and copper					Records, etc	Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)		service line should be marked as Galvanized	Lead put N/R		previous column was	Cast/Ductile Iron or Transite (O)		Leave blank if	
	sample site mark "N/A"						Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)		Requiring Replacement in			(N).			customer has not refused access.	
							Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)		the appropriate immediately preceding				Leave blank if no			
		Yes (Y) or No (N)					Unknown Not Lead	Unknown (U)	Unknown (U)		column(s).				Lead Service Line wa replaced.	s		
							(UNL)	Unknown Not Lead (UNL)	Unknown Not Lead (UNL)									
FOR CLOCKHOOD AVE	N1/0	N	N	1054	1054			iii	II				N.					101 1220
5020 S LOCKWOOD AVE 5021 1/2 S LOCKWOOD AVE	N/A N/A	N N	N N	1954	1954		U		U	U			N N					101-1230 101-1240
5021 1/2 S LOCKWOOD AVE	N/A N/A	N N	N N	1909	1909		U .		11	U			N N					101-1240
5019 S LOCKWOOD AVE	N/A	N	N	1961	1961		U	U	U	IJ			N					101-1270
5017 S LOCKWOOD AVE	N/A	N	N	1913	1913		U	U	U	U			N					101-1280
5008 S LOCKWOOD AVE	N/A	N	N	1925	1925		U	U	U	U			N					101-1290
5011 S LOCKWOOD AVE	N/A	N	N	1953	1953		U	U	U	U			N					101-1300
5009 S LOCKWOOD AVE	N/A	N	N	1947	1947		U	U	U	U			N					101-1310
5005 S LOCKWOOD AVE	N/A	N	N	1960	1960		U	U	U	U			N					101-1330
5000 S LOCKWOOD AVE	N/A	N	N	1952	1952		U	U	U	U			N					101-1340
4958 S LOCKWOOD AVE	N/A	N	N	1941	1941		U	U	U	U			N					101-1360
4943 S LOCKWOOD AVE	N/A	N	N	1930	1930		U	U	U	U			N					101-1370
4952 S LOCKWOOD AVE	N/A	N	N	1955	1955		U	U	U	U			N					101-1390
4945 S LOCKWOOD AVE	N/A	N	N	1946	1946		U	U	U	U			N					101-1400
4933 S LOCKWOOD AVE	N/A	N	N	1956	1956		U	U	U	U			N					101-1410
4934 S LOCKWOOD AVE	N/A	N N	N N	1946	1946		U	U	U	U			N N					101-1420
4932 S LOCKWOOD AVE 4929 S LOCKWOOD AVE	N/A N/A	N N	N N	1970 1949	1970 1949		II	111	11	II.			N N					101-1430 101-1440
4929 S LOCKWOOD AVE	N/A N/A	N N	N N	1949	1949		II	111	II	10			N N					101-1440
4928 S LOCKWOOD AVE	N/A	N N	N	1970	1970		II	111	II	lu lu			N					101-1450
4925 S LOCKWOOD AVE	N/A	N N	N	1948	1948		U	U	U	U			N					101-1470
4926 S LOCKWOOD AVE	N/A	N	N	1970	1970		U	U	U	U			N					101-1480
4923 S LOCKWOOD AVE	N/A	N	N	1949	1949		U	U	U	U			N					101-1490
4918 S LOCKWOOD AVE	N/A	N	N	1919	1919		U	U	U	U			N					101-1500
4917 S LOCKWOOD AVE	N/A	N	N	1950	1950		U	U	U	U			N					101-1510
4914 S LOCKWOOD AVE	N/A	N	N				U	U	U	U			N					101-1511
4912 S LOCKWOOD AVE	N/A	N	N	1913	1913		U	U	U	U			N					101-1520
4915 S LOCKWOOD AVE	N/A	N	N	1965	1965		U	U	U	U			N					101-1530
4910 S LOCKWOOD AVE	N/A	N	N	1925	1925		U	U	U	U			N					101-1540
4908 S LOCKWOOD AVE	N/A	N	N	1927	1927		U	U	U	U			N					101-1560
4902 S LOCKWOOD AVE	N/A	N	N				U	U	U	U			N					101-1580
4901 S LOCKWOOD AVE	N/A	N	N	1963	1963		U	U	U	U	L		N			1	1	101-1590



					Le	ead Service Line Invento	ry Template					
*Please enter information in the empty box next to each section	Water System Na	ame	Central	Stickney Sanitary District	Sys	tem ID Number:	IL0315570)	Current Inver	ntory Date:	4/15/2025	
*Please enter totals in the empty box next to each category	Total Service lines:	746	Total Lead:	35 Total Non-Lead:	171	Total Galvanized Requi	ring replacement:	0	Total Unknown:	540	Website link to Material Inventory:	

Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Identified Since Last	Year PWS- Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
		EXAMPLES:					EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:					EXAMPLES:			
							Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	If any galvanized service				Copper - No Lead			
	Lead and Copper Sample site number	Group Homes, Parks, Playgrounds, Special Care				No. of the second of the secon	Copper - Lead Solde (CLS)	r Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line	Foton data		If previous column	Solder (C)		IF customer refused access to property,	
	is the 7 digit number	Facilities, Hospitals,				How was the Material of this Service Line Identified?	Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)	material was never	Enter date customer was		was marked (Y), provide date the Lead	Galvanized (G)		date waiver obtained	i
	starting with "LP" or " LA". / If address is not a	Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance		Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	downstream of any Lead section, mark No (N). / If Yes, that section of	notified of Lead Service Line. / If Service Line is not	Yes (Y) or No (N)	Service Line was replaced. / Leave blank if	Plastic - PVC, HDPE, PEX (P)	Yes (Y) or No (N)	by PWS or date PWS notified IDPH of refusal to sign waiver /	
	lead and copper					Records, etc	Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)		service line should be marked as Galvanized	Lead put N/R		previous column was	Cast/Ductile Iron or Transite (O)		Leave blank if	
	sample site mark "N/A"						Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)		Requiring Replacement in			(N).			customer has not refused access.	
							Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)		the appropriate immediately preceding				Leave blank if no			
		Yes (Y) or No (N)					Unknown Not Lead	Unknown (U)	Unknown (U)		column(s).				Lead Service Line was replaced.			
							(UNL)	Unknown Not Lead (UNL)	Unknown Not Lead (UNL)						replaceu.			
														1				
4838 S LOCKWOOD AVE	N/A N/A	N	N N	1942	1942 1942		U		U	U			N N					101-1600 101-1610
4838 S LOCKWOOD AVE 4837 S LOCKWOOD AVE	N/A N/A	N N	N N	1942 1929	1942		U .	11	11	0			N N					101-1610
4834 S LOCKWOOD AVE	N/A	N	N	1917	1917		II	II	11	u			N N					101-1630
4835 S LOCKWOOD AVE	N/A	N	N	1944	1944		U	U	U	u			N					101-1640
4829 S LOCKWOOD AVE	N/A	N	N	1954	1954		U	U	U	U			N					101-1670
4827 S LOCKWOOD AVE	N/A	N	N	1956	1956		U	U	U	U			N					101-1690
4824 1/2 S LOCKWOOD AVE	N/A	N	N				U	U	U	U			N					101-1692
4826 S LOCKWOOD AVE	N/A	N	N	1949	1949		U	U	U	U			N					101-1700
4823 S LOCKWOOD AVE	N/A	N	N	1938	1938		U	U	U	U			N					101-1710
4822 S LOCKWOOD AVE	N/A	N	N	1957	1957		U	U	U	U			N					101-1720
4820 S LOCKWOOD AVE	N/A	N	N	1958	1958		U	U	U	U			N					101-1730
4819 S LOCKWOOD AVE	N/A	N	N	1965	1965		U	U	U	U			N					101-1740
4818 S LOCKWOOD AVE	N/A	N	N	1958	1958		U	U	U	U			N					101-1750
4817 S LOCKWOOD AVE	N/A	N	N	1965	1965		U	U	U	U			N					101-1760
4816 S LOCKWOOD AVE	N/A	N N	N	1959	1959		U	U	U	U			N					101-1770
4813 S LOCKWOOD AVE	N/A N/A	N N	N N	1958	1958		U		11	11			N N					101-1780 101-1790
4814 S LOCKWOOD AVE 4811 S LOCKWOOD AVE	N/A N/A	N N	N N	1958	1958		II	111	11	11			N N					101-1790
4812 S LOCKWOOD AVE	N/A	N	N	1959	1959		U	U	U	U			N					101-1810
4810 S LOCKWOOD AVE	N/A	N	N	1946	1946		U	U	U	U			N					101-1820
4806 S LOCKWOOD AVE	N/A	N	N	1960	1960		U	U	U	U			N					101-1840
4804 S LOCKWOOD AVE	N/A	N	N	1960	1960		U	U	U	U			N					101-1850
4803 S LOCKWOOD AVE	N/A	N	N	1944	1944		U	U	U	U			N					101-1860
4802 S LOCKWOOD AVE	N/A	N	N	1960	1960		U	U	U	U			N					101-1870
4800 S LOCKWOOD AVE	N/A	N	N	1960	1960		U	U	U	U			N					101-1890
4759 S LOCKWOOD AVE	N/A	N	N	1944	1944		U	U	U	U			N					101-1900
4756 S LOCKWOOD AVE	N/A	N	N	1943	1943		U	U	U	U			N					101-1910
4755 S LOCKWOOD AVE	N/A	N	N	1942	1942		U	U	U	U			N					101-1920
4745 S LOCKWOOD AVE	N/A	N	N	1965	1965		U	U	U	U			N					101-1930
4743 S LOCKWOOD AVE	N/A	N	N	1945	1945		U	U	U	U			N					101-1950
4744 S LOCKWOOD AVE	N/A	N	N	1943	1943		U	ĮU .	U	ĮU			N	<u> </u>	<u> </u>	1		101-1960



					Le	ead Service Line Invento	ry Template					
*Please enter information in the empty box next to each section	Water System Na	ime	Central S	itickney Sanitary District	Sys	tem ID Number:	IL0315570		Current Inve	ntory Date:	4/15/2025	
*Please enter totals in the empty box next to each category	Total Service lines:	746	Total Lead:	35 Total Non-Lead:	171	Total Galvanized Requi	ring replacement:	Ω	Total Unknown:	540	Website link to Material Inventory:	

Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS- Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Accoun Number
		270 1111 2201					Copper - No Lead								270 1111 2231			
							Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	If any galvanized service				Copper - No Lead			
	Lead and Copper Sample site number	Group Homes, Parks, Playgrounds, Special Care					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line			If previous column	Solder (C)		IF customer refused access to property,	
	is the 7 digit number	Facilities, Hospitals,				How was the Material of this Service Line Identified?	Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)	material was never	Enter date customer was		was marked (Y), provide date the Lead	Galvanized (G)		date waiver obtained	
	starting with "LP" or " LA". / If address is not a	Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	EXAMPLES: Construction Records, Visual Inspections, Survey		Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	downstream of any Lead section, mark No (N). / If Yes, that section of	notified of Lead Service Line. /	Yes (Y) or No (N)	Service Line was replaced. / Leave blank if	Plastic - PVC, HDPE, PEX (P)	Yes (Y) or No (N)	by PWS or date PWS notified IDPH of refusal to sign waiver. /	
	lead and copper					Response, Maintenance Records, etc	Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)		service line should be marked as Galvanized	If Service Line is not Lead put N/R		previous column was	Cast/Ductile Iron or Transite (O)		Leave blank if	
	sample site mark "N/A"						Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)		Requiring Replacement in			(N).			customer has not refused access.	
							Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)		 the appropriate immediately preceding 				Leave blank if no			
		Yes (Y) or No (N)					Unknown Not Lead	Unknown (U)	Unknown (U)		column(s).				Lead Service Line was replaced.	5		
							(UNL)	Unknown Not Lead (UNL)	Unknown Not Lead (UNL)									
742 C L OCIVILOOD AVE			N	4054	4054													404 4070
742 S LOCKWOOD AVE 720 S LOCKWOOD AVE	N/A N/A	N N	N N	1951 1960	1951 1960		U	0	U	U			N N					101-1970 101-2000
35 S LOCKWOOD AVE	N/A N/A	N N	N N	1967	1960		II		11	11			N N					101-2010
716 S LOCKWOOD AVE	N/A	N	N	1958	1958		IJ	U	U	U			N					101-2010
714 S LOCKWOOD AVE	N/A	N	N	1961	1961		U	U	U	U			N					101-2040
712 S LOCKWOOD AVE	N/A	N	N	1960	1960		U	U	U	U			N					101-2050
710 S LOCKWOOD AVE	N/A	N	N	1958	1958		U	U	U	U			N					101-2060
711 S LOCKWOOD AVE	N/A	N	N	1961	1961		U	U	U	U			N					101-2070
708 S LOCKWOOD AVE	N/A	N	N	1960	1960		U	U	U	U			N					101-2080
707 S LOCKWOOD AVE	N/A	N	N	1960	1960		U	U	U	U			N					101-2090
706 S LOCKWOOD AVE	N/A	N	N	1958	1958		U	U	U	U			N					101-2100
705 S LOCKWOOD AVE	N/A	N	N	1958	1958		U	U	U	U			N					101-2110
705 S LOREL AVE	N/A	N	N	1958	1958		U	U	U	U			N					101-2120
707 S LOREL AVE	N/A	N	N	1958	1958		U	U	U	U			N					101-2130
09 S LOREL AVE	N/A	N	N	1958	1958			U		U			N					101-2140
11 S LOREL AVE 37 S LOREL AVE	N/A N/A	N N	N N	1958 1956	1958 1956		U	U	U	U			N N					101-2150 101-2160
40 S LOREL AVE	N/A N/A	N N	N N	1956	1956		II		II	U			N N					101-2180
44 S LOREL AVE	N/A	N	N	1937	1957		U	U	U	U			N N					101-2190
43 S LOREL AVE	N/A	N	N	1953	1953		U	U	U	U			N					101-2190
48 S LOREL AVE	N/A	N	N	,,,,			U	U	U	U			N					101-2220
49 S LOREL AVE	N/A	N	N	1961	1961		U	U	U	U			N					101-2230
50 S LOREL AVE	N/A	N	N				U	U	U	U			N					101-2231
51 S LOREL AVE	N/A	N	N	1960	1960		U	U	U	U			N					101-2240
52 S LOREL AVE	N/A	N	N				U	U	U	U			N					101-2260
58 S LOREL AVE	N/A	N	N	1966	1966		U	U	U	U			N					101-2270
59 S LOREL AVE	N/A	N	N	1964	1964		U	U	U	U			N					101-2280
01 S LOREL AVE	N/A	N	N				U	U	U	U			N					101-2290
03 S LOREL AVE	N/A	N	N				U	U	U	U			N					101-2300
99 S LOREL AVE	N/A	N	N	1958	1958			U	U	U 			N					101-2310
11 S LOREL AVE	N/A	N	N N	1958 1961	1958 1961		U	U	U	U			N					101-2320 101-2330



					L	ead Service Line Invento	ry Template					
*Please enter information in the empty box next to each section	Water System Na	ame	Central	Stickney Sanitary District	Sy	stem ID Number:	IL0315570)	Current Inver	ntory Date:	4/15/2025	
*Please enter totals in the empty box next to each category	Total Service lines:	746	Total Lead:	35 Total Non-Lead:	171	Total Galvanized Requi	ring replacement:	0	Total Unknown:	540	Website link to Material Inventory:	

Service Address	Lead and Copper Sample site number.		Service Line Newly Identified Since Last Submitted Inventory	Year PWS- Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Materia ever downstream of Lead?	Notified of Lead	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Accoun Number
		EXAMPLES:					EXAMPLES: Copper - No Lead	EXAMPLES:		EXAMPLES:	_				EXAMPLES:			
							Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	If any galvanized service				Comment No. 1			
	Lead and Copper Sample site number	Group Homes, Parks, Playgrounds, Special Care	,				Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line			If previous column	Copper - No Lead Solder (C)		IF customer refused access to property,	
	is the 7 digit number	Facilities, Hospitals	,			How was the Material of this Service Line Identified?	Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)	material was never	Enter date customer was		was marked (Y), provide date the Lead	Galvanized (G)		date waiver obtained	
	starting with "LP" or " LA". / If address is not a	Clinics, Child Care Facilities	Yes (Y) or No (N)	PWS-Owned service line	What year was the customer side service line installed, if known?	EXAMPLES: Construction Records, Visual Inspections, Survey		Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	downstream of any Lead section, mark No (N). / If Yes, that section of	notified of Lead Service Line. /	Yes (Y) or No (N)	Service Line was replaced. / Leave blank if	Plastic - PVC, HDPE, PEX (P)	Yes (Y) or No (N)	by PWS or date PWS notified IDPH of refusal to sign waiver. /	
	lead and copper					Response, Maintenance Records, etc	Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)		service line should be marked as Galvanized	If Service Line is not Lead put N/R		previous column was	Cast/Ductile Iron or Transite (O)		Leave blank if	
	sample site mark "N/A"						Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)		Requiring Replacement in			(N).			customer has not refused access.	
							Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)		the appropriate immediately preceding				Leave blank if no			
		Yes (Y) or No (N)					Unknown Not Lead	Unknown (U)	Unknown (U)		column(s).				Lead Service Line wa replaced.	5		
							(UNL)	Unknown Not Lead (UNL)	Unknown Not Lead (UNL)						.,			
000 01 0051 41/5	21/2		N															404 2222
806 S LOREL AVE 804 S LOREL AVE	N/A N/A	N N	N N				<u>U</u>		U	11			N N					101-2332 101-2334
804 S LOREL AVE	N/A N/A	N N	N N				<u> </u>		11	11			N N					101-2334
819 S LOREL AVE	N/A	N	N	1960	1960		<u> </u>	11	II.	11			N					101-2350
821 S LOREL AVE	N/A	N	N	1958	1958		U	II	U	U			N					101-2360
828 S LOREL AVE	N/A	N	N N	1953	1953		U	u	U	u			N					101-2370
829 S LOREL AVE	N/A	N	N	1958	1958		U	U	U	U			N					101-2400
833 S LOREL AVE	N/A	N	N	1958	1958		U	U	U	U			N					101-2410
836 S LOREL AVE	N/A	N	N	1950	1950		U	U	U	U			N					101-2420
837 S LOREL AVE	N/A	N	N	1958	1958		U	U	U	U			N					101-2430
840 S LOREL AVE	N/A	N	N	1957	1957		U	U	U	U			N					101-2440
841 S LOREL AVE	N/A	N	N	1957	1957		U	U	U	U			N					101-2450
846 S LOREL AVE	N/A	N	N	1958	1958		U	U	U	U			N					101-2460
847 S LOREL AVE	N/A	N	N	1946	1946		U	U	U	U			N					101-2470
849 S LOREL AVE	N/A	N	N	1961	1961		U	U	U	U			N					101-2490
852 S LOREL AVE	N/A	N	N	1956	1956		U	U	U	U			N					101-2510
853 S LOREL AVE	N/A	N	N	1954	1954		U	U	U	U			N					101-2520
858 S LOREL AVE	N/A	N	N	1954	1954		U	U	U	U			N					101-2530
857 S LOREL AVE	N/A	N	N	1958	1958		U	U 	U	U			N					101-2540
901 S LOREL AVE	N/A	N	N	1938	1938		U		U 	U 			N 					101-2550
900 S LOREL AVE	N/A	N	N N	1950	1950		U	U	U	U			N					101-2560
905 S LOREL AVE 909 S LOREL AVE	N/A N/A	N N	N N	1965 1970	1965 1970		U II	U	U U	11			N N					101-2570 101-2600
909 S LOREL AVE	N/A N/A	N	N N	1970	1970		11		II	11			N N					101-2610
915 S LOREL AVE	N/A	N	N	1976	1976		U	U	U	Ů			N					101-2620
917 S LOREL AVE	N/A	N	N	1956	1956		U	U	U	U			N					101-2640
919 S LOREL AVE	N/A	N	N	1956	1956		U	U	U	U			N					101-2660
916 S LOREL AVE	N/A	N	N	1952	1952		U	U	U	U			N					101-2670
925 S LOREL AVE	N/A	N	N	1957	1957		U	U	U	U			N					101-2680
924 S LOREL AVE	N/A	N	N	1944	1944		U	U	U	U			N					101-2690
927 S LOREL AVE	N/A	N	N	1957	1957		U	U	U	U			N					101-2700
926 S LOREL AVE	N/A	N	N	1948	1948		U	U	U	U			N					101-2710



					Le	ead Service Line Invento	ry Template					
*Please enter information in the empty box next to each section	Water System Na	me	Central	Stickney Sanitary District	Sys	stem ID Number:	IL0315570)	Current Inver	ntory Date:	4/15/2025	
*Please enter totals in the empty box next to each category	Total Service lines:	746	Total Lead:	35 Total Non-Lead:	171	Total Galvanized Requi	ring replacement:	Ο	Total Unknown:	540	Website link to Material Inventory:	

Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS- Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
				mstaneu							Leau:							
		EXAMPLES:					EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:					EXAMPLES:			
							Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	If any galvanized service				Copper - No Lead			
	Lead and Copper Sample site number	Group Homes, Parks, Playgrounds, Special Care					Copper - Lead Solde (CLS)	er Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line	Futur data		If previous column	Solder (C)		IF customer refused access to property,	
	is the 7 digit number	Facilities, Hospitals,				How was the Material of this Service Line Identified?	Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)	material was never	Enter date customer was		was marked (Y), provide date the Lead	Galvanized (G)		date waiver obtained	1
	starting with "LP" or " LA". / If address is not a	Clinics, Child Care Facilities	Yes (Y) or No (N)	PWS-Owned service line	What year was the customer side service line installed, if known?	EXAMPLES: Construction Records, Visual Inspections, Survey		Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	downstream of any Lead section, mark No (N). / If Yes, that section of	notified of Lead Service Line. /	Yes (Y) or No (N)	Service Line was replaced. / Leave blank if	Plastic - PVC, HDPE, PEX (P)	Yes (Y) or No (N)	by PWS or date PWS notified IDPH of refusal to sign waiver. /	
	lead and copper					Response, Maintenance Records, etc	Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)		service line should be marked as Galvanized	If Service Line is not Lead put N/R		previous column was	Cast/Ductile Iron or Transite (O)		Leave blank if	
	sample site mark "N/A"						Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)		Requiring Replacement in	, ,		(N).	dilatte (U)		customer has not refused access.	
	,						Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)		 the appropriate immediately preceding 				Leave blank if no			
		Yes (Y) or No (N)					Unknown Not Lead	Unknown (U)	Unknown (U)		column(s).				Lead Service Line was replaced.			
							(UNL)	* * *	1 1		•				replaced.			
								Unknown Not Lead (UNL)	Unknown Not Lead (UNL)									
4933 S LOREL AVE	N/A	N	N	1952	1952		U	U	U	U			N					101-2721
4934 S LOREL AVE	N/A	N	N	1950	1950		U	U	U	U			N					101-2730
4938 S LOREL AVE	N/A	N	N	1961	1961			U 	U	U			N					101-2740
4940 S LOREL AVE	N/A	N 	N	1949	1949					U 			N					101-2750
4945 S LOREL AVE	N/A N/A	N N	N N	1957 1960	1957 1960		<u>U</u>		U	U			N N					101-2760 101-2770
4944 S LOREL AVE 4956 S LOREL AVE	N/A	N N	N	1953	1953				11	11			N					101-2770
4955 S LOREL AVE	N/A	N	N	1955	1955			11	П	li li			N					101-2790
5005 S LOREL AVE	N/A	N	N	1950	1950		U.	II	П	U			N					101-2820
5009 S LOREL AVE	N/A	N N	N	1961	1961		U	U	U	U			N					101-2830
5011 S LOREL AVE	N/A	N	N	1944	1944		U	U	U	U			N					101-2840
5023 S LOREL AVE	N/A	N	N	1950	1950		U	U	U	U			N					101-2870
5024 S LOREL AVE	N/A	Υ	N				U	U	U	U			N					101-2880
5332 W 51ST STREET	N/A	N	N				U	U	U	U			N					101-2892
5336 W 51ST STREET	N/A	N	N				U	U	U	U			N					101-2893
5338 W 51ST STREET	N/A	N	N				U	U	U	U			N					101-2894
5058 S LONG AVE	N/A	N	N	1949	1949		U	U	U	U			N					101-2900
5050 S LONG AVE	N/A	N	N	1942	1942		U	U	U	U			N					101-2910
5040 S LONG AVE	N/A	N	N	1956	1956		U	U	U	U			N					101-2930
5018 S LONG AVE	N/A	N	N	1941	1941		U	U	U	U			N					101-2975
5016 S LONG AVE	N/A	N	N	1946	1946		U	U	U	U			N					101-2980
5004 S LONG AVE	N/A	N	N	1945	1945		<u>U</u>	U 	U	U			N					101-3010
4937 S LONG AVE	N/A	N	N	1953	1953		U		U	U			N					101-3030
4931 S LONG AVE 4929 S LONG AVE	N/A N/A	N N	N N	1952 1965	1952 1965		U	11	U	11			N					101-3040 101-3050
4929 S LONG AVE	N/A N/A	N N	N N	1965	1965		II	111	II	11			N N					101-3050
4919 S LONG AVE	N/A	N N	N	1957	1962		U	u .	U .	U			N					101-3060
4915 S LONG AVE	N/A	N	N	1959	1959		U	u	U	u			N					101-3080
4913 S LONG AVE	N/A	N	N	1959	1959		U	U	U	U			N					101-3090
4909 S LONG AVE	N/A	N N	N	1959	1959		U	U	U	U			N					101-3100
4901 S LONG AVE	N/A	N	N	1944	1944		U	U	U	U			N					101-3120
4859 S LONG AVE	N/A	N	N	1955	1955		II.	u	u	li .			N					101-3140



					L	ead Service Line Invento	ry Template					
*Please enter information in the empty box next to each section	Water System Nai	me	Central S	itickney Sanitary District	Sy	stem ID Number:	IL0315570)	Current Inver	ntory Date:	4/15/2025	
*Please enter totals in the empty box next to each category	Total Service lines:	746	Total Lead:	35 Total Non-Lead:	171	Total Galvanized Requi	ring replacement:	0	Total Unknown:	540	Website link to Material Inventory:	

Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Identified Since Last	Year PWS- Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?		Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
		EXAMPLES:					EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:					EXAMPLES:			
							Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	If any galvanized service				Carrage National			
	Lead and Copper Sample site number	Group Homes, Parks, Playgrounds, Special Care					Copper - Lead Solde (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line			If previous column	Copper - No Lead Solder (C)		IF customer refused access to property,	
	is the 7 digit number	Facilities, Hospitals,				How was the Material of this Service Line Identified?	Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)	material was never	Enter date customer was		was marked (Y), provide date the Lead	Galvanized (G)		date waiver obtained	t
	starting with "LP" or " LA". / If address is not a	Clinics, Child Care Facilities	Yes (Y) or No (N)	PWS-Owned service line	What year was the customer side service line installed, if known?	EXAMPLES: Construction Records, Visual Inspections, Survey		Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	downstream of any Lead section, mark No (N). / If Yes, that section of	notified of Lead Service Line. /	Yes (Y) or No (N)	Service Line was replaced. / Leave blank if	Plastic - PVC, HDPE, PEX (P)	Yes (Y) or No (N)	by PWS or date PWS notified IDPH of refusal to sign waiver. /	
	lead and copper					Response, Maintenance Records, etc	Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)		service line should be marked as Galvanized	If Service Line is not Lead put N/R		previous column was	Cast/Ductile Iron or Transite (O)		Leave blank if	
	sample site mark "N/A"						Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)		Requiring Replacement in			(N).			customer has not refused access.	
							Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)		the appropriate immediately preceding				Leave blank if no			
		Yes (Y) or No (N)					Unknown Not Lead	Unknown (U)	Unknown (U)		column(s).				Lead Service Line was replaced.	5		
							(UNL)	Unknown Not Lead (UNL)	Unknown Not Lead (UNL)						.,			
49EO S LONG AVE	N/A	N	N	1040	1949		11		11				N					101 3150
4850 S LONG AVE 4853 S LONG AVE	N/A	N	N	1949 1952	1949		U		11	11			N N					101-3150 101-3160
4848 S LONG AVE	N/A	N	N	1949	1949		I	II	II	U			N					101-3170
4849 S LONG AVE	N/A	N	N	1953	1953		U	U	U	U			N					101-3180
4844 S LONG AVE	N/A	N	N	1948	1948		U	U	U	U			N					101-3190
4845 S LONG AVE	N/A	N	N	1951	1951		U	U	U	U			N					101-3200
4839 S LONG AVE	N/A	N	N	1962	1962		U	U	U	U			N					101-3220
4837 S LONG AVE	N/A	N	N	1960	1960		U	U	U	U			N					101-3230
4835 S LONG AVE	N/A	N	N	1958	1958		U	U	U	U			N					101-3240
4826 S LONG AVE	N/A	N	N	1948	1948		U	U	U	U			N					101-3260
4831 S LONG AVE	N/A	N	N	1960	1960		U	U	U	U			N					101-3270
4829 S LONG AVE	N/A	N	N	1958	1958		U	U	U	U			N					101-3280
4824 S LONG AVE	N/A	N	N	1962	1962		U	U	U	U			N					101-3290
4825 S LONG AVE	N/A	N	N	1958	1958		U	[U	U	U			N					101-3300
4816 S LONG AVE 4823 S LONG AVE	N/A N/A	N N	N N	1957 1958	1957 1958		U		U	U			N N					101-3310 101-3320
4823 S LONG AVE 4814 S LONG AVE	N/A	N	N N	1958	1958		II .		П	U			N N					101-3320
4819 S LONG AVE	N/A	N	N	1958	1958		U	U	U	U			N					101-3340
4812 S LONG AVE	N/A	N	N	1960	1960		U	U	U	U			N					101-3350
4817 S LONG AVE	N/A	N	N	1958	1958		U	U	U	U			N					101-3360
4810 S LONG AVE	N/A	N	N	1959	1959		U	U	U	U			N					101-3370
4815 S LONG AVE	N/A	N	N	1958	1958		U	U	U	U			N					101-3380
4808 S LONG AVE	N/A	N	N	1960	1960		U	U	U	U			N					101-3390
4806 S LONG AVE	N/A	N	N	1958	1958		U	U	U	U			N					101-3410
4807 S LONG AVE	N/A	N	N	1958	1958		U	U	U	U			N					101-3420
4800 S LONG AVE	N/A	N	N	1959	1959		U	U	U	U			N					101-3430
4801 S LONG AVE	N/A	N	N	1958	1958		U	U	U	U			N					101-3440
4760 S LONG AVE	N/A	N	N	1950	1950		U 	U I	U	U			N					101-3450
4759 S LONG AVE	N/A	N N	N	1950	1950		U	U	U	U			N					101-3460
4756 S LONG AVE	N/A N/A	N N	N N	1949 1949	1949 1949		U	U	U III	11			N N					101-3470 101-3480
4755 S LONG AVE 4750 S LONG AVE	N/A N/A	N N	N N	1949	1949		11		11	11			N N					101-3480
+1303 LONG AVE	IN/A	IN IN	IN IN	1320	1320	1	U	Io.	lo.	Io.		1	I N	1	1	1	<u> </u>	101-3430



					Le	ead Service Line Invento	ry Template					
*Please enter information in the empty box next to each section	Water System Na	ame	Central	Stickney Sanitary District	Sys	tem ID Number:	IL0315570)	Current Inver	ntory Date:	4/15/2025	
*Please enter totals in the empty box next to each category	Total Service lines:	746	Total Lead:	35 Total Non-Lead:	171	Total Galvanized Requi	ring replacement:	0	Total Unknown:	540	Website link to Material Inventory:	

Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Identified Since Last	Year PWS- Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
		EXAMPLES:					EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:					EXAMPLES:	-		
							Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	If any galvanized service				Course National			
	Lead and Copper Sample site number	Group Homes, Parks, Playgrounds, Special Care					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line	- · · · ·		If previous column	Copper - No Lead Solder (C)		IF customer refused access to property,	
	is the 7 digit number	Facilities, Hospitals,				How was the Material of this Service Line Identified?	Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)	material was never	Enter date customer was		was marked (Y), provide date the Lead	Galvanized (G)		date waiver obtained	1
	starting with "LP" or " LA". / If address is not a	Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance		Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	downstream of any Lead section, mark No (N). / If Yes, that section of	notified of Lead Service Line. / If Service Line is not	Yes (Y) or No (N)	Service Line was replaced. / Leave blank if	Plastic - PVC, HDPE, PEX (P)	Yes (Y) or No (N)	by PWS or date PWS notified IDPH of refusal to sign waiver. /	
	lead and copper sample site mark					Records, etc	Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)		service line should be marked as Galvanized	Lead put N/R		previous column was	Cast/Ductile Iron or Transite (O)		Leave blank if customer has not	
	"N/A"						Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)		Requiring Replacement in the appropriate			(N).			refused access.	
		V (N) N- (N)					Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)		immediately preceding				Leave blank if no			
		Yes (Y) or No (N)					Unknown Not Lead	Unknown (U)	Unknown (U)		column(s).				Lead Service Line was replaced.	5		
							(ONE)	Unknown Not Lead (UNL)	Unknown Not Lead (UNL)									
4753 S LONG AVE	N/A	N	N	1971	1971		U	U	U	U			N					101-3500
4748 S LONG AVE	N/A	N	N	1956	1956		U	U	U	U			N					101-3510
4751 S LONG AVE	N/A	N	N	1968	1968		U	U	U	U			N					101-3520
4735 S LONG AVE	N/A	N	N	1949	1949		U	U	U	U			N					101-3550
4721 S LONG AVE	N/A	N	N	1971	1971		U	U	U	U			N					101-3560
4719 S LONG AVE	N/A	N	N	1972	1972		U	U	U	U			N					101-3570
4717 S LONG AVE	N/A	N	N	1971	1971		U	U	U	U			N					101-3580
4715 S LONG AVE	N/A	Y	N				U	U	U	U			N					101-3590
4734 S LOTUS AVE 4740 S LOTUS AVE	N/A N/A	N	N N	1949	1949		U	0	U	U			N N					101-3611 101-3620
4747 S LOTUS AVE	N/A	N N	N N	1949	1949		П		п	U			N N					101-3620
4748 S LOTUS AVE	N/A	N	N	1952	1950		11	11	11	11			N					101-3650
4752 S LOTUS AVE	N/A	N	N	1960	1960		U	U	U	u			N					101-3660
4755 S LOTUS AVE	N/A	N	N	1945	1945		U	U	U	U			N					101-3670
4759 S LOTUS AVE	N/A	N	N	1952	1952		U	U	U	U			N					101-3680
4758 S LOTUS AVE	N/A	N	N	1956	1956		U	U	U	U			N					101-3690
4802 S LOTUS AVE	N/A	N	N	1954	1954		U	U	U	U			N					101-3710
4807 S LOTUS AVE	N/A	N	N	1950	1950		U	U	U	U			N					101-3730
4812 S LOTUS AVE	N/A	N	N	1950	1950		U	U	U	U			N					101-3740
4815 S LOTUS AVE	N/A	N	N	1950	1950		U	U	U	U			N					101-3770
4821 S LOTUS AVE	N/A	N	N	1949	1949		U	U	U	U			N					101-3800
4824 S LOTUS AVE	N/A	N	N	1954	1954		U	U	U	U			N					101-3810
4819 S LOTUS AVE	N/A	N	N	1960	1960		U	U	U	U			N					101-3820
4828 S LOTUS AVE	N/A	N	N	1957	1957		U	U 	U 	U			N					101-3830
4827 S LOTUS AVE	N/A	N	N	1955	1955		U	U	U	U			N					101-3840
4832 S LOTUS AVE	N/A	N N	N	1948	1948		U	U	U	U			N 					101-3850
4831 S LOTUS AVE 4840 S LOTUS AVE	N/A N/A	N N	N N	1952 1956	1952 1956		U		U	11			N N					101-3860 101-3870
4840 S LOTUS AVE 4833 S LOTUS AVE	N/A N/A	N N	N N	1956	1956		U II		П	11			N N					101-3870
4848 S LOTUS AVE	N/A	N N	N N	1952	1952		II		II	U			N N					101-3880
4855 S LOTUS AVE	N/A	N	N	1950	1950		U	U	U	U			N					101-3930
4852 S LOTUS AVE	N/A	N	N	1950	1950			l		1			N					101-3950



					Le	ead Service Line Invento	ry Template					
*Please enter information in the empty box next to each section	Water System Na	ame	Central	Stickney Sanitary District	Sys	tem ID Number:	IL0315570)	Current Inver	ntory Date:	4/15/2025	
*Please enter totals in the empty box next to each category	Total Service lines:	746	Total Lead:	35 Total Non-Lead:	171	Total Galvanized Requi	ring replacement:	0	Total Unknown:	540	Website link to Material Inventory:	

Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS- Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Materia ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
		EXAMPLES:					EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:					EXAMPLES:			
							Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	If any galvanized service				Copper - No Lead			
	Lead and Copper Sample site number	Group Homes, Parks, Playgrounds, Special Care	,				Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line	Subsurdata		If previous column	Solder (C)		IF customer refused access to property,	
	is the 7 digit number	Facilities, Hospitals,	,			How was the Material of this Service Line Identified?	Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)	material was never	Enter date customer was		was marked (Y), provide date the Lead	Galvanized (G)		date waiver obtained	
	starting with "LP" or " LA". / If address is not a	Clinics, Child Care Facilities	Yes (Y) or No (N)	PWS-Owned service line	What year was the customer side service line installed, if known?	EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance		Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	downstream of any Lead section, mark No (N). / If Yes, that section of	notified of Lead Service Line. / If Service Line is not	Yes (Y) or No (N)	Service Line was replaced. / Leave blank if	Plastic - PVC, HDPE, PEX (P)	Yes (Y) or No (N)	by PWS or date PWS notified IDPH of refusal to sign waiver. /	
	lead and copper					Records, etc	Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)		service line should be marked as Galvanized	Lead put N/R		previous column was	Cast/Ductile Iron or Transite (O)		Leave blank if	
	sample site mark "N/A"						Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)		Requiring Replacement in			(N).			customer has not refused access.	
		60					Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)		the appropriate immediately preceding				Leave blank if no			
		Yes (Y) or No (N)					Unknown Not Lead	Unknown (U)	Unknown (U)		column(s).				Lead Service Line wa replaced.	5		
							(UNL)	Unknown Not Lead (UNL)	Unknown Not Lead (UNL)						·			
4900 S LOTUS AVE	N/A	N	N	1950	1950		U	U	U	U			N					101-3960
4901 S LOTUS AVE	N/A	N	N	1952	1952		U	U	U	U			N					101-3970
4905 S LOTUS AVE	N/A	N	N	1952	1952		U	U	U	U			N					101-3980
4908 S LOTUS AVE	N/A	N	N	1951	1951		U	U	U	U			N					101-3990
4910 S LOTUS AVE	N/A	N	N	1951	1951		U	U	U	U			N					101-4010
4915 S LOTUS AVE	N/A	N	N	1949	1949		U	U	U	U			N					101-4020
4912 S LOTUS AVE	N/A	N	N	1948	1948		U	U	U	U			N					101-4030
4919 S LOTUS AVE	N/A	N	N	1956	1956		U	U	U	U			N					101-4040
4926 S LOTUS AVE	N/A	N	N	1951	1951		U	U	U	U			N					101-4050
4933 S LOTUS AVE	N/A	N 	N	1955	1955		U 		U 	U 			N 					101-4060
4924 S LOTUS AVE 4935 S LOTUS AVE	N/A N/A	N N	N N	1957 1958	1957 1958		U		U	U			N N					101-4070 101-4080
4938 S LOTUS AVE	N/A N/A	N	N	1936	1938		11		11	11			N N					101-4090
4941 S LOTUS AVE	N/A	N	N N	1949	1949		II	11	11	111			N					101-4100
4930 S LOTUS AVE	N/A	N	N	1960	1960		II	II	U	U			N					101-4110
4943 S LOTUS AVE	N/A	N	N	1947	1947		U	U	U	U			N					101-4120
4946 S LOTUS AVE	N/A	N	N	1957	1957		U	U	U	U			N					101-4130
4945 S LOTUS AVE	N/A	N	N	1954	1954		U	U	U	U			N					101-4140
4950 S LOTUS AVE	N/A	N	N	1960	1960		U	υ	U	U			N					101-4170
4952 S LOTUS AVE	N/A	N	N	1961	1961		U	U	U	U			N					101-4190
5001 S LOTUS AVE	N/A	N	N	1949	1949		U	U	U	U			N					101-4200
5005 S LOTUS AVE	N/A	N	N	1956	1956		U	U	U	U			N					101-4220
5008-1/2 S LOTUS AVE	N/A	N	N				U	Ü	U	U			N					101-4249
5010 S LOTUS AVE	N/A	N	N	1971	1971		U	U	U	U			N					101-4270
5011 S LOTUS AVE	N/A	N	N	1946	1946		U	U	U	U			N					101-4280
5012 S LOTUS AVE	N/A	N	N	1972	1972		U	U	U	U			N					101-4290
5013 S LOTUS AVE	N/A	N	N	1946	1946		U	U I	U 	U			N					101-4300
5014 S LOTUS AVE	N/A	N	N N	1972	1972		U	U	U	U			N					101-4310 101-4320
5016 S LOTUS AVE 5028 S LOTUS AVE	N/A N/A	N N	N N	1972 1950	1972 1950		U		11	11			N N					101-4320
5035 S LOTUS AVE	N/A N/A	N N	N N	1950	1950		II .		II	U U			N N					101-4340
3033 3 LO 103 AVE	N/A N/A	N	N	1918	1937								N N					101-4370



					Le	ead Service Line Invento	ry Template					
*Please enter information in the empty box next to each section	Water System Na	ame	Central	Stickney Sanitary District	Sys	tem ID Number:	IL0315570)	Current Inver	ntory Date:	4/15/2025	
*Please enter totals in the empty box next to each category	Total Service lines:	746	Total Lead:	35 Total Non-Lead:	171	Total Galvanized Requi	ring replacement:	0	Total Unknown:	540	Website link to Material Inventory:	

Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS- Owned Service Line was Installed	Year Customer Side Service Line was Installed		Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Materia ever downstream of Lead?	Notified of Lead	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
		EXAMPLES:					EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:					EXAMPLES:			
							Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	If any galvanized service				Copper - No Lead			
	Lead and Copper Sample site number	Group Homes, Parks, Playgrounds, Special Care	,			No. of the state o	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line	Partie data		If previous column	Solder (C)		IF customer refused access to property,	
	is the 7 digit number	Facilities, Hospitals,	,			How was the Material of this Service Line Identified?	Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)	material was never	Enter date customer was		was marked (Y), provide date the Lead	Galvanized (G)		date waiver obtained	
	starting with "LP" or " LA". / If address is not a	Clinics, Child Care Facilities	Yes (Y) or No (N)	PWS-Owned service line	What year was the customer side service line installed, if known?	EXAMPLES: Construction Records, Visual Inspections, Survey		Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	downstream of any Lead section, mark No (N). / If Yes, that section of	notified of Lead Service Line. /	Yes (Y) or No (N)	Service Line was replaced. / Leave blank if	Plastic - PVC, HDPE, PEX (P)	Yes (Y) or No (N)	by PWS or date PWS notified IDPH of refusal to sign waiver. /	
	lead and copper					Response, Maintenance Records, etc	Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)		service line should be marked as Galvanized	If Service Line is not Lead put N/R		previous column was	Cast/Ductile Iron or Transite (O)		Leave blank if	
	sample site mark "N/A"						Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)		Requiring Replacement in			(N).			customer has not refused access.	
							Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)		the appropriate immediately preceding				Leave blank if no			
		Yes (Y) or No (N)					Unknown Not Lead	Unknown (U)	Unknown (U)		column(s).				Lead Service Line wa replaced.	S		
							(UNL)	Unknown Not Lead (UNL)	Unknown Not Lead (UNL)						10,1000			
FOR CLOTHE AVE	NI/A	N		1040	1040				U.				N					101 1200
5039 S LOTUS AVE 5036 S LOTUS AVE	N/A N/A	N N	N N	1948 1947	1948 1947		U II		U II	U II			N N					101-4380
5043 S LOTUS AVE	N/A	N	N	1946	1946		II	II	II	U			N					101-4400
5045 S LOTUS AVE	N/A	N	N	1952	1952		U	U	U	U			N					101-4420
5052 S LOTUS AVE	N/A	N	N	1947	1947		U	U	U	U			N					101-4440
5051 S LOTUS AVE	N/A	N	N	1948	1948		U	U	U	U			N					101-4450
5444 W 51ST STREET	N/A	N	N				U	U	U	U			N					101-4451
5446 W 51ST STREET	N/A	N	N				U	U	U	U			N					101-4452
5448 W 51ST STREET	N/A	N	N				U	U	U	U			N					101-4453
5050 S LINDER AVE	N/A	N	N	1947	1947		U	U	U	U			N					101-4460
5048 S LINDER AVE	N/A	N	N	1946	1946		U	U	U	U			N					101-4470
5042 S LINDER AVE	N/A	N	N	1948	1948		U 		U 	U 			N					101-4480
5039 S LINDER AVE 5037 S LINDER AVE	N/A N/A	N N	N	1947 1947	1947 1947		U		U	0			N N					101-4490 101-4500
5035 S LINDER AVE	N/A N/A	N N	N	1947	1947		U .	11	П	U U			N N					101-4500
5031 S LINDER AVE	N/A	N	N	1948	1948		U	U	U	U			N					101-4540
5032 S LINDER AVE	N/A	N	N	1918	1918		U	U	U	U			N					101-4550
5021 S LINDER AVE	N/A	N	N	1946	1946		U	U	U	U			N					101-4580
5024 S LINDER AVE	N/A	N	N	1946	1946		U	U	U	U			N					101-4590
5017 S LINDER AVE	N/A	N	N	1965	1965		U	U	U	U			N					101-4600
5020 S LINDER AVE	N/A	N	N	1946	1946		U	U	U	U			N					101-4610
5015 S LINDER AVE	N/A	N	N	1951	1951		U	U	U	U			N					101-4620
5010 S LINDER AVE	N/A	N	N	1950	1950		U	Ü	U	U			N					101-4640
5003 S LINDER AVE	N/A	N	N	1957	1957		U	U	U	U			N					101-4650
5002 S LINDER AVE	N/A	N	N	1946	1946		U	U	U	U			N					101-4660
4949 S LINDER AVE	N/A	N	N				U	U 	U	U			N					101-4670
4960 S LINDER AVE	N/A	N	N	1952	1952		U	U	U	U			N					101-4680
4947 S LINDER AVE	N/A N/A	N	N N	1960 1960	1960		U	U	U	U			N					101-4690 101-4710
4945 S LINDER AVE 4952 S LINDER AVE	N/A N/A	N N	N N	1960	1960 1948		II		U U	11			N N					101-4710
4952 S LINDER AVE	N/A N/A	N N	N N	1948	1948		II	II	II	II .			N N					101-4740
13 12 3 EINDER AVE	N/A	N	N	1967	1967				ť				N					101-4740



					Le	ead Service Line Invento	ry Template					
*Please enter information in the empty box next to each section	Water System Na	ime	Central S	itickney Sanitary District	Sys	tem ID Number:	IL0315570		Current Inve	ntory Date:	4/15/2025	
*Please enter totals in the empty box next to each category	Total Service lines:	746	Total Lead:	35 Total Non-Lead:	171	Total Galvanized Requi	ring replacement:	Ω	Total Unknown:	540	Website link to Material Inventory:	

Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Identified Since Last	Year PWS- Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
		EXAMPLES:					EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:					EXAMPLES:			
							Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	If any galvanized service				Copper - No Lead			
	Lead and Copper Sample site number	Group Homes, Parks, Playgrounds, Special Care				II	Copper - Lead Solde (CLS)	r Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line	Foton data		If previous column	Solder (C)		IF customer refused access to property,	
	is the 7 digit number	Facilities, Hospitals,				How was the Material of this Service Line Identified?	Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)	material was never	Enter date customer was		was marked (Y), provide date the Lead	Galvanized (G)		date waiver obtained	4
	starting with "LP" or " LA". / If address is not a	Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line 'installed, if known?	EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance		Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	downstream of any Lead section, mark No (N). / If Yes, that section of	notified of Lead Service Line. / If Service Line is not	Yes (Y) or No (N)	Service Line was replaced. / Leave blank if	Plastic - PVC, HDPE, PEX (P)	Yes (Y) or No (N)	by PWS or date PWS notified IDPH of refusal to sign waiver /	
	lead and copper					Records, etc	Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)		service line should be marked as Galvanized	Lead put N/R		previous column was	Cast/Ductile Iron or Transite (O)		Leave blank if	
	sample site mark "N/A"						Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)		Requiring Replacement in			(N).			customer has not refused access.	
							Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)		the appropriate immediately preceding				Leave blank if no			
		Yes (Y) or No (N)					Unknown Not Lead	Unknown (U)	Unknown (U)		column(s).				Lead Service Line was replaced.			
							(UNL)	Unknown Not Lead (UNL)	Unknown Not Lead (UNL)						·			
4939 S LINDER AVE	N/A	N	N	1960	1960		U	U	U	U			N					101-4760
4948 S LINDER AVE	N/A	N	N	1967	1967		U	U	U	U			N					101-4770
4937 S LINDER AVE	N/A	N	N	1960	1960		U	U	U	U			N					101-4780
4946 S LINDER AVE	N/A	N	N	1967	1967		U	U	U	U			N					101-4790
4932 S LINDER AVE	N/A	N	N				U	U	U	U			N					101-4810
4931 S LINDER AVE	N/A	N	N	1955	1955		U	U	U	U			N					101-4820
4924 S LINDER AVE	N/A	N	N				U	U	U	U			N					101-4825
4922 S LINDER AVE	N/A	N	N				U	U	U	U			N					101-4830
4920 S LINDER AVE 4916 S LINDER AVE	N/A N/A	N N	N N	1948 1951	1948 1951		U		U	U			N N					101-4850 101-4870
4916 S LINDER AVE	N/A N/A	N	N N	1951	1951		П	11	11	11			N N					101-4870
4900 S LINDER AVE	N/A	N	N	1950	1950		u	II.	11	U			N					101-4930
4859 S LINDER AVE	N/A	N	N	1949	1949		u	U	U	U			N					101-4940
4856 S LINDER AVE	N/A	N	N	1948	1948		U	U	U	U			N					101-4960
4855 S LINDER AVE	N/A	N	N				U	U	U	U			N					101-4970
4853 S LINDER AVE	N/A	N	N				U	U	U	U			N					101-4971
4850 S LINDER AVE	N/A	N	N	1964	1964		U	U	U	U			N					101-4980
4854 S LINDER AVE	N/A	N	N	1964	1964		U	U	U	U			N					101-5000
4852 S LINDER AVE	N/A	N	N	1948	1948		U	U	U	U			N					101-5010
4847 S LINDER AVE	N/A	N	N	1954	1954		U	U	U	U			N					101-5020
4836 S LINDER AVE	N/A	N	N	1949	1949		U	U	U	U			N					101-5030
4841 S LINDER AVE	N/A	N	N	1959	1959		U	U	U	U			N					101-5040
4832 S LINDER AVE	N/A	N	N	1948	1948		U	U	U	U			N					101-5050
4837 S LINDER AVE	N/A	N	N	1950	1950			U	U	U 			N					101-5051
4824 S LINDER AVE	N/A	N	N	1954	1954		U	U	U	U			N					101-5080
4821 S LINDER AVE	N/A N/A	N N	N N	1948	1948		U	U III	IU	U			N					101-5090
4818 S LINDER AVE 4815 S LINDER AVE	N/A N/A	N N	N N	1977 1956	1977 1956		11		11	11			N N					101-5100 101-5120
4813 S LINDER AVE	N/A N/A	N N	N N	1320	1330		U	lu .	U	U			N					101-5125
4807 S LINDER AVE	N/A	N	N	1951	1951		U	U	U	U			N					101-5150
4804 S LINDER AVE	N/A	N	N	1948	1948		U	U	U	U		_	N					101-5161
4800 S LINDER AVE	N/A	N	N	1955	1955		п	п	11	lu .			N					101-5170



					Le	ead Service Line Invento	ry Template					
*Please enter information in the empty box next to each section	Water System Na	ame	Central	Stickney Sanitary District	Sys	tem ID Number:	IL0315570)	Current Inver	ntory Date:	4/15/2025	
*Please enter totals in the empty box next to each category	Total Service lines:	746	Total Lead:	35 Total Non-Lead:	171	Total Galvanized Requi	ring replacement:	0	Total Unknown:	540	Website link to Material Inventory:	

Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS- Owned Service Line was Installed	Year Customer Side Service Line was Installed		Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Materia ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?		Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
		EXAMPLES:					EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:					EXAMPLES:			
							Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	If any galvanized service				Copper - No Lead			
	Lead and Copper Sample site number	Group Homes, Parks, Playgrounds, Special Care	,			No.	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service lin			If previous column	Solder (C)		IF customer refused access to property,	
	is the 7 digit number	Facilities, Hospitals,	,			How was the Material of this Service Line Identified?	Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)	material was never	Enter date customer was		was marked (Y), provide date the Lead	Galvanized (G)		date waiver obtained	
	starting with "LP" or " LA". / If address is not a	Clinics, Child Care Facilities	Yes (Y) or No (N)	PWS-Owned service line	What year was the customer side service line installed, if known?	EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance		Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	downstream of any Lead section, mark No (N). / If Yes, that section of	notified of Lead Service Line. / If Service Line is not	Yes (Y) or No (N)	Service Line was replaced. / Leave blank if	Plastic - PVC, HDPE, PEX (P)	Yes (Y) or No (N)	by PWS or date PWS notified IDPH of refusal to sign waiver. /	
	lead and copper					Records, etc	Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)		service line should be marked as Galvanized	Lead put N/R		previous column was	Cast/Ductile Iron or Transite (O)		Leave blank if	
	sample site mark "N/A"						Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)		Requiring Replacement in			(N).			customer has not refused access.	
		63					Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)		the appropriate immediately preceding				Leave blank if no			
		Yes (Y) or No (N)					Unknown Not Lead	Unknown (U)	Unknown (U)		column(s).				Lead Service Line wa replaced.	S		
							(UNL)	Unknown Not Lead (UNL)	Unknown Not Lead (UNL)						·			
4801 S LINDER AVE	N/A	N	N	1948	1948		U	U.	U	u			N					101-5180
4758 S LINDER AVE	N/A	N	N	1340	1540		U	U	U	U			N					101-5181
4755 S LINDER AVE	N/A	N	N	1950	1950		U	U	U	U			N					101-5200
4756 S LINDER AVE	N/A	N	N	1957	1957		U	U	U	U			N					101-5210
4751 S LINDER AVE	N/A	N	N	1950	1950		U	U	U	U			N					101-5220
4749 S LINDER AVE	N/A	N	N	1956	1956		U	U	U	U			N					101-5230
4750 S LINDER AVE	N/A	N	N	1954	1954		U	U	U	U			N					101-5240
4748 S LINDER AVE	N/A	N	N	1950	1950		U	U	U	U			N					101-5250
4732 S LINDER AVE	N/A	N	N	1972	1972		U	U	U	U			N					101-5270
4730 S LINDER AVE	N/A	N	N	1973	1973		U	U	U	U			N					101-5280
4739 S LINDER AVE	N/A	N	N	1954	1954		U	U	U	U			N					101-5290
4728 S LINDER AVE	N/A	N	N	1974	1974		U	U	U	U			N					101-5300
4737 S LINDER AVE	N/A	N	N	1953	1953		Ü	U	U	U			N					101-5310
4726 S LINDER AVE	N/A	N N	N N	1971	1971		U	U	U				N N					101-5320
4720 S LUNA AVE 4723 S LUNA AVE	N/A N/A	N N	N N	1949 1954	1949 1954		U		U	11			N N					101-5330 101-5340
4725 S LUNA AVE	N/A	N N	N	1954	1954		11		П	11			N N					101-5340
4727 S LUNA AVE	N/A	N	N	1977	1977		Ū	U	U	U			N					101-5360
4744 S LUNA AVE	N/A	N	N	1966	1966		U	U	U	U			N					101-5380
4746 S LUNA AVE	N/A	N	N	1965	1965		U	U	U	U			N					101-5390
4745 S LUNA AVE	N/A	N	N	1965	1965		U	U	U	U			N					101-5400
4748 S LUNA AVE	N/A	N	N	1969	1969		U	U	U	U			N					101-5410
4747 S LUNA AVE	N/A	N	N	1965	1965		U	U	U	U			N					101-5420
4749 S LUNA AVE	N/A	N	N	1966	1966		U	U	U	U			N					101-5440
4751 S LUNA AVE	N/A	N	N	1966	1966		U	U	U	U			N					101-5460
4753 S LUNA AVE	N/A	N	N	1966	1966		U	U	U	U			N					101-5470
4756 S LUNA AVE	N/A	N	N	1957	1957		U	U	U	U			N					101-5480
4755 S LUNA AVE	N/A	N	N	1965	1965		U	U	U	U			N					101-5490
4759 S LUNA AVE	N/A	N	N	1953	1953		U	U	U	U			N					101-5500
4758 S LUNA AVE	N/A	N	N	1959	1959		U	U	U	U			N					101-5510
4801 S LUNA AVE	N/A	N	N	1950	1950		U	U	U	U			N					101-5520
4805 S LUNA AVE	N/A	N	N	1978	1978		In	Įυ	U	U			N			1		101-5530



					Le	ead Service Line Invento	ry Template					
*Please enter information in the empty box next to each section	Water System Na	ime	Central S	itickney Sanitary District	Sys	tem ID Number:	IL0315570		Current Inve	ntory Date:	4/15/2025	
*Please enter totals in the empty box next to each category	Total Service lines:	746	Total Lead:	35 Total Non-Lead:	171	Total Galvanized Requi	ring replacement:	Ω	Total Unknown:	540	Website link to Material Inventory:	

Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Identified Since Last	Year PWS- Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
		EXAMPLES:					EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:					EXAMPLES:			
							Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	If any galvanized service				Copper - No Lead			
	Lead and Copper Sample site number	Group Homes, Parks, Playgrounds, Special Care				How was the Material of this	Copper - Lead Solde (CLS)	r Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line	Enter dete		If previous column	Solder (C)		IF customer refused access to property,	
	is the 7 digit number	Facilities, Hospitals,				How was the Material of this Service Line Identified?	Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)	material was never	Enter date customer was		was marked (Y), provide date the Lead	Galvanized (G)		date waiver obtained	i
	starting with "LP" or " LA". / If address is not a	Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	what year was the customer side service line installed, if known?	EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance		Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	downstream of any Lead section, mark No (N). / If Yes, that section of	notified of Lead Service Line. / If Service Line is not	Yes (Y) or No (N)	Service Line was replaced. / Leave blank if	Plastic - PVC, HDPE, PEX (P)	Yes (Y) or No (N)	by PWS or date PWS notified IDPH of refusal to sign waiver /	
	lead and copper					Records, etc	Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)		service line should be marked as Galvanized	Lead put N/R		previous column was	Cast/Ductile Iron or Transite (O)		Leave blank if	
	sample site mark "N/A"						Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)		Requiring Replacement in			(N).			customer has not refused access.	
		v (v) ··· (··					Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)		the appropriate immediately preceding				Leave blank if no			
		Yes (Y) or No (N)					Unknown Not Lead	Unknown (U)	Unknown (U)		column(s).				Lead Service Line was replaced.			
							(UNL)	Unknown Not Lead (UNL)	Unknown Not Lead (UNL)						·			
4809 S LUNA AVE	N/A	N	N	1948	1948		U	U	U	U			N					101-5550
4812 S LUNA AVE	N/A	N	N	1966	1966		U	U	U	U			N					101-5560
4813 S LUNA AVE	N/A	N	N	1952	1952		U	U	U	U			N					101-5570
4826 S LUNA AVE	N/A	N	N	1966	1966		U	U	U	U			N					101-5580
4833 S LUNA AVE	N/A	N	N	1953	1953		U	U	U	U			N					101-5590
4828 S LUNA AVE	N/A	N	N	1966	1966		U	U	U	U			N					101-5600
4830 S LUNA AVE	N/A	N	N	1960	1960		U	U	U	U			N					101-5610
4835 S LUNA AVE	N/A	N 	N 	1952	1952		U		U 	U 			N					101-5620
4832 S LUNA AVE 4834 S LUNA AVE	N/A N/A	N N	N N	1960 1972	1960 1972		U	11	11	U			N N					101-5630 101-5650
4836 S LUNA AVE	N/A	N	N	1972	1972		U U	П	II	U			N					101-5670
4840 S LUNA AVE	N/A	N	N	1972	1972		IJ	u	U	U			N					101-5690
4842 S LUNA AVE	N/A	N	N	1966	1966		U	U	U	U			N					101-5710
4849 S LUNA AVE	N/A	N	N	1961	1961		U	U	U	U			N					101-5720
4844 S LUNA AVE	N/A	N	N	1966	1966		U	U	U	U			N					101-5730
4851 S LUNA AVE	N/A	N	N	1966	1966		U	U	U	U			N					101-5740
4846 S LUNA AVE	N/A	N	N	1961	1961		U	U	U	U			N					101-5750
4848 S LUNA AVE	N/A	N	N	1961	1961		U	U	U	U			N					101-5760
4860 S LUNA AVE	N/A	N	N	1960	1960		U	U	U	U			N					101-5780
4901 S LUNA AVE	N/A	N	N	1950	1950		U	U	U	U			N					101-5790
4900 S LUNA AVE	N/A	N	N	1978	1978		U	U	U	U			N					101-5800
4905 S LUNA AVE	N/A	N	N				U	U	U	U			N					101-5820
4911 S LUNA AVE	N/A	N	N	1949	1949		U	U 	U	U			N					101-5830
4908 S LUNA AVE	N/A	N	N	1950	1950		U		U	U			N					101-5840
4912 S LUNA AVE	N/A	N	N	1964	1964		U		U				N N					101-5860 101-5880
4914 S LUNA AVE 4918 S LUNA AVE	N/A N/A	N N	N N	1964 1952	1964 1952		11	11	U U	11			N N					101-5880
4917 S LUNA AVE	N/A N/A	N N	N N	1952	1952		II	111	II	U			N N					101-5890
4931 S LUNA AVE	N/A	N	N	1973	1973		U	U	U	U			N					101-5910
4930 S LUNA AVE	N/A	N	N	1966	1966		U	U	U	U			N					101-5920
4933 S LUNA AVE	N/A	N	N	1973	1973		U	U	U	U			N					101-5930
4932 S LUNA AVE	N/A	N	N	1954	1954		П	u	u	u			N					101-5940



					L	ead Service Line Invento	ry Template					
*Please enter information in the empty box next to each section	Water System Nai	me	Central S	itickney Sanitary District	Sy	stem ID Number:	IL0315570)	Current Inver	ntory Date:	4/15/2025	
*Please enter totals in the empty box next to each category	Total Service lines:	746	Total Lead:	35 Total Non-Lead:	171	Total Galvanized Requi	ring replacement:	0	Total Unknown:	540	Website link to Material Inventory:	

Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Identified Since Last	Year PWS- Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	
		EXAMPLES:					EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:					EXAMPLES:			
							Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	If any galvanized service				Copper - No Lead			
	Lead and Copper Sample site number	Group Homes, Parks, Playgrounds, Special Care					Copper - Lead Solde (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)	line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line			If previous column	Solder (C)		IF customer refused access to property,	
	is the 7 digit number	Facilities, Hospitals,				How was the Material of this Service Line Identified?	Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)	material was never	Enter date customer was		was marked (Y), provide date the Lead	Galvanized (G)		date waiver obtained	1
	starting with "LP" or " LA". / If address is not a	Clinics, Child Care Facilities	Yes (Y) or No (N)	PWS-Owned service line	What year was the customer side service line installed, if known?	EXAMPLES: Construction Records, Visual Inspections, Survey		Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)	downstream of any Lead section, mark No (N). / If Yes, that section of	notified of Lead Service Line. /	Yes (Y) or No (N)	Service Line was replaced. / Leave blank if	Plastic - PVC, HDPE, PEX (P)	Yes (Y) or No (N)	by PWS or date PWS notified IDPH of refusal to sign waiver. /	
	lead and copper					Response, Maintenance Records, etc	Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)		service line should be marked as Galvanized	If Service Line is not Lead put N/R		previous column was	Cast/Ductile Iron or Transite (O)		Leave blank if	
	sample site mark "N/A"						Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)		Requiring Replacement in			(N).			customer has not refused access.	
							Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)		 the appropriate immediately preceding 				Leave blank if no			
		Yes (Y) or No (N)					Unknown Not Lead	Unknown (U)	Unknown (U)		column(s).				Lead Service Line was replaced.			
							(UNL)	Unknown Not Lead (UNL)	Unknown Not Lead (UNL)									
4935 S LUNA AVE	N/A	N	N	1949	1949		<u>U</u>	l	U 				N					101-5950
4949 S LUNA AVE	N/A N/A	N N	N N	1951 1951	1951 1951		U		U	U			N N					101-5960 101-5970
4934 S LUNA AVE 4951 S LUNA AVE	N/A N/A	N N	N N	1951	1951		U .		11	11			N N					101-5970
4936 S LUNA AVE	N/A	N	N	1972	1972		U U	II.	II	U			N					101-5990
4938 S LUNA AVE	N/A	N	N	1972	1972		U	U	U	U			N					101-6000
4948 S LUNA AVE	N/A	N	N	1950	1950		U	U	U	U			N					101-6010
4953 S LUNA AVE	N/A	N	N	1952	1952		U	U	U	U			N					101-6020
4952 S LUNA AVE	N/A	N	N	1950	1950		U	U	U	U			N					101-6030
4955 S LUNA AVE	N/A	N	N	1946	1946		U	U	U	U			N					101-6040
4956 S LUNA AVE	N/A	N	N	1952	1952		U	U	U	U			N					101-6050
4959 S LUNA AVE	N/A	N	N	1962	1962		U	U	U	U			N					101-6060
5001 S LUNA AVE	N/A	N	N				U	U	U	U			N					101-6061
5005 S LUNA AVE	N/A	N	N	1972	1972		U	U	U	U			N					101-6070
5007 S LUNA AVE	N/A	N	N	1972	1972		U	U	U	U			N					101-6090
5011 S LUNA AVE	N/A	N	N	1971	1971		U	U	U	U			N					101-6110
5013 S LUNA AVE	N/A	N N	N N	1972	1972		11		11	11			N					101-6120
5018 S LUNA AVE 5033 S LUNA AVE	N/A N/A	N N	N N	1978 1948	1978 1948		11		11	U U			N N					101-6150 101-6160
5022 S LUNA AVE	N/A N/A	N N	N N	1948	1948		II	lu	II	u			N N					101-6160
5037 S LUNA AVE	N/A	N	N	1960	1960		U	U	U	U			N					101-6180
5026 S LUNA AVE	N/A	N	N	1944	1944		U	U	U	U			N					101-6190
5039 S LUNA AVE	N/A	N	N				U	U	U	U			N					101-6200
5030 S LUNA AVE	N/A	N	N	1967	1967		U	U	U	U			N					101-6210
5032 S LUNA AVE	N/A	N	N	1967	1967		U	U	U	U			N					101-6220
5045 S LUNA AVE	N/A	N	N	1924	1924		U	U	U	U			N					101-6230
5034 S LUNA AVE	N/A	N	N	1918	1918		U	U	U	U			N					101-6240
5036 S LUNA AVE	N/A	N	N	1967	1967		U	U	U	U			N					101-6250
5040 S LUNA AVE	N/A	N	N	1957	1957		U	U	U	U			N					101-6260
5049 S LUNA AVE	N/A	N	N	1922	1922		U	U	U	U			N					101-6270
5051 S LUNA AVE	N/A	N	N	1960	1960		U	U	U	U			N					101-6280
5053 S LUNA AVE	N/A	N	N	1960	1960		U	U	U	U			N	<u> </u>	<u> </u>	l		101-6300

Illinois Environmental
Protection Agency

					L	ead Service Line Invento	ry Template					
*Please enter information in the empty box next to each section	Water System Na	ame	Central St	ickney Sanitary District	Sy	stem ID Number:	IL0315570		Current Inve	ntory Date:	4/15/2025	
*Please enter totals in the empty box next to each category	Total Service lines:	746	Total Lead:	35 Total Non-Lead:	171	Total Galvanized Requi	ring replacement:	0	Total Unknown:	540	Website link to Material Inventory:	

Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS- Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Serivice Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
		EXAMPLES:	yes (Y) or No (N)	service line	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:					EXAMPLES:			
							Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of			Constant				
	Lead and Copper Sample site number						Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacemnt (GRR)			Enter date customer was notified of Lead Service Line. / Service Line is not Lead put N/R Enter date customer was notified of Lead Service Line was replaced. / Leave blank if previous column was replaced. / Leave blank if previous column was (N).	was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was	Copper - No Lead Solder (C)		IF customer refused access to property,	
	is the 7 digit number						Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)		Litter date			Galvanized (G)		date waiver obtained by PWS or date PWS	
	starting with "LP" or " LA". / If address is not a						Lead (L)	Galvanized Requiring Replacemnt (GRR)	Galvanized Requiring Replacemnt (GRR)	Non-Lead (NL)		notified of Lead Service Line. /			Plastic - PVC, HDPE, PEX (P)	Yes (Y) or No (N)		
	lead and copper sample site mark "N/A"						Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)		service line should be marked as Galvanized	llouid be alvanized Lead put N/R acement in priate preceding			Transite (O) Leave blank if no			
		Yes (Y) or No (N)					Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)		Requiring Replacement in the appropriate							
							Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)		immediately preceding							
							Unknown Not Lead (UNL)	Unknown (U)	Unknown (U)		column(s).			Lead Service Line was replaced.	was			
								Unknown Not Lead (UNL)	Unknown Not Lead (UNL)									
5058 S LUNA AVE	N/A	N	N	1933	1933		U	U	U	U			N					101-6310
5055 S LUNA AVE	N/A	N	N	1960	1960		U	U	U	U			N					101-6320
5055 S CENTRAL AVE	N/A	N	N	1916	1916		U	U	U	U			N					101-6330
5051 S CENTRAL AVE	N/A	N	N	1941	1941		U	U	U	U			N					101-6350
5047 S CENTRAL AVE	N/A	N	N				U	U	U	U			N					101-6360
5027 S CENTRAL AVE	N/A	N	N	1947	1947		U	U	U	U			N					101-6370
5017 1/2 S CENTRAL AVE	N/A	N	N				U	U	U	U			N					101-6400
5015 S CENTRAL AVE	N/A	N	N	1928	1928		U	U 	U	U			N					101-6420
4901 S CENTRAL AVE	N/A	N	N	4057	4057		U	U I	U	U			N N					101-6475
4835 S CENTRAL AVE	N/A	N	N	1957	1957		U	U	U	U			N					101-6500
					1		1				1							