



Lead Service Line Inventory Template		
--------------------------------------	--	--

*Please enter information in the empty box next to each section	Water System Name		Central Stickney Sanitary District			System ID Number:		IL0315570		Current Inventory Date:		4/15/26							
*Please enter totals in the empty box next to each category	Total Service lines:		746		Total Lead:	340		Total Non-Lead:	304		Total Galvanized Requiring replacement:		0		Total Unknown:	102		Website link to Material Inventory:	

Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA" / If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc....	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)						Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)							
		Copper - Lead Solder (CLS)						Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacement (GRR)	Galvanized (G)							
		Galvanized (G)						Galvanized (G)	Galvanized (G)	Unknown (U)	Plastic - PVC, HDPE, PEX (P)							
		Lead (L)						Galvanized Requiring Replacement (GRR)	Galvanized Requiring Replacement (GRR)	Non-Lead (NL)	Cast/Ductile Iron or Transite (O)							
		Cast/Ductile Iron or Transite (O)						Lead (L)	Lead (L)		Plastic - PVC, HDPE, PEX (P)							
		Plastic - PVC, HDPE, PEX (P)						Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)		Unknown (U)							
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)		Unknown (U)	Unknown Not Lead (UNL)	Unknown Not Lead (UNL)	Unknown Not Lead (UNL)											
4715 S LATROBE AVE	LC1T001	N	N	1949	1949	Sample Site Record	U	L	L	L		12/15/25	N					101-0020
4717 S LATROBE AVE	LC1T002	N	N	1957	1957	Sample Site Record	U	L	L	L		12/15/25	N					101-0040
4800 S LATROBE AVE	LC1T003	N	N	1955	1955	Sample Site Record	U	L	L	L		12/15/25	N					101-0285
4801 S LATROBE AVE	LC1T004	N	N	1953	1953	Sample Site Record	U	L	L	L		12/15/25	N					101-0290
4855 S LATROBE AVE	N/A	N	N	1957	1957	Installed before lead ban	U	L	L	L		12/15/25	N					101-0580
5001 S LOCKWOOD AVE	LC1T008	N	N	1960	1960	Sample Site Record	U	L	L	L		12/15/25	N					101-1350
4907 S LOCKWOOD AVE	LC1T007	N	N	1918	1918	Sample Site Record	U	L	L	L		12/15/25	N					101-1570
4737 S LOCKWOOD AVE	LC1T006	N	N	1943	1943	Sample Site Record	U	L	L	L		12/15/25	N					101-1980
4733 S LOCKWOOD AVE	LC1T005	N	N	1956	1956	Sample Site Record	U	L	L	L		12/15/25	N					101-2030
4736 S LOREL AVE	LC1T009	N	N	1957	1957	Sample Site Record	U	L	L	L		12/15/25	N					101-2170
4753 S LOREL AVE	N/A	N	N	1960	1960	Visual inspection	UNL	C	C	NL		N/R	N					101-2250
4825 S LOREL AVE	LC1T010	N	N	1958	1958	Sample Site Record	U	L	L	L		12/15/25	N					101-2380
4910 S LOREL AVE	lot	N	N	1961	1961	Sample Site Record	U	L	L	L		12/15/25	N					101-2630
5001 S LOREL AVE	N/A	N	N	1966	1966	Visual inspection	L	L	L	L		12/15/25	N					101-2810
5025 S LOREL AVE	LC1T012	N	N	1950	1950	Visual inspection	L	L	L	L		12/15/25	N					101-2890
5030 S LONG AVE	LC1T017	N	N	1948	1948	Sample Site Record	U	L	L	L		12/15/25	N					101-2954
4905 S LONG AVE	LC1T016	N	N	1957	1957	Sample Site Record	U	L	L	L		12/15/25	N					101-3110
4830 S LONG AVE	LC1T015	N	N	1948	1948	Sample Site Record	U	L	L	L		12/15/25	N					101-3250
4811 S LONG AVE	LC1T014	N	N	1958	1958	Sample Site Record	U	L	L	L		12/15/25	N					101-3400
4743 S LONG AVE	LC1T013	N	N	1954	1954	Sample Site Record	U	L	L	L		12/15/25	N					101-3530
4744 S LOTUS AVE	LC1T018	N	N	1953	1953	Sample Site Record	U	L	L	L		12/15/25	N					101-3630
4806 S LOTUS AVE	N/A	N	N	1950	1950	Installed before lead ban	U	L	L	L		12/15/25	N					101-3720
4811 S LOTUS AVE	LC1T019	N	N	1950	1950	Sample Site Record	U	L	L	L		12/15/25	N					101-3750
4857 S LOTUS AVE	LC1T020	N	N	1957	1957	Sample Site Record	U	L	L	L		12/15/25	N					101-3940
5040 S LOTUS AVE	N/A	N	N	1948	1948	Installed before lead ban	U	L	L	L		12/15/25	N					101-4410
5044 S LOTUS AVE	N/A	N	N	1948	1948	Visual inspection	L	L	L	L		12/15/25	N					101-4430
4943 S LINDER AVE	LC1T023 - INACTIVE	N	N	1960	1960	Sample Site Record	U	L	L	L		12/15/25	N					101-4720
4915 S LINDER AVE	N/A	N	N	1952	1952	Field inspection only with no record	U	L	L	L		10/23/24	N					101-4880
4909 S LINDER AVE	N/A	N	N	1949	1949	Record	U	L	C	L		10/23/24	N					101-4900
4906 S LINDER AVE	N/A	N	N	1948	1948	Visual inspection	L	L	L	L		12/15/25	N					101-4910
4806 S LINDER AVE	LC1T022 - INACTIVE	N	N	1948	1948	Sample Site Record	U	L	L	L		12/15/25	N					101-5160
4747 S LINDER AVE	LC1T021 - INACTIVE	N	N	1954	1954	Sample Site Record	U	L	L	L		12/15/25	N					101-5260
4750 S LUNA AVE	LC1T024 - INACTIVE	N	N	1957	1957	Sample Site Record	U	L	L	L		12/15/25	N					101-5430
5009 S LUNA AVE	N/A	N	N	1972	1972	Visual inspection	L	L	L	L		12/15/25	N					101-6100
5016 S LUNA AVE	LC1T025 - INACTIVE	N	N	1977	1977	Visual inspection	L	L	L	L		12/15/25	N					101-6140
4731 S LATROBE AVE	N/A	N	N	1990	1990	Installation record	UNL	C	C	NL		N/R	N					101-0170
4805 S LATROBE AVE	N/A	N	N	1997	1997	Installation record	UNL	C	C	NL		N/R	N					101-0301
4834 S LATROBE AVE	N/A	N	N	1999	1999	Installation record	UNL	C	C	NL		N/R	N					101-0451
4845 S LATROBE AVE	N/A	N	N	1991	1991	Installation record	UNL	C	C	NL		N/R	N					101-0520
4901 S LATROBE AVE	N/A	N	N	2001	2001	Installation record	UNL	C	C	NL		N/R	N					101-0591
4905 S LATROBE AVE	N/A	N	N	1992	1992	Installation record	UNL	C	C	NL		N/R	N					101-0630



Lead Service Line Inventory Template	
--------------------------------------	--

*Please enter information in the empty box next to each section	Water System Name		Central Stickney Sanitary District			System ID Number:		IL0315570		Current Inventory Date:		4/15/26	
*Please enter totals in the empty box next to each category	Total Service lines:		746		Total Lead:	340		Total Non-Lead:	304		Total Galvanized Requiring replacement:	0	
											Total Unknown:	102	
											Website link to Material Inventory:		

Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)									
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacement (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)									
		Lead (L)					Galvanized Requiring Replacement (GRR)	Galvanized Requiring Replacement (GRR)	Non-Lead (NL)									
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)										
		Plastic - PVC, HDPE, PEX (P)					Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)										
		Unknown (U)					Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)										
Unknown Not Lead (UNL)	Unknown (U)	Unknown (U)																
							Unknown Not Lead (UNL)	Unknown Not Lead (UNL)	Unknown Not Lead (UNL)									
4820 S LOTUS AVE	N/A	N	N	2008	2008	Installation record	UNL	C	C	NL		N/R	N					101-3790
4842 S LOTUS AVE	N/A	N	N	1993	1993	Installation record	UNL	C	C	NL		N/R	N					101-3900
4844 S LOTUS AVE	N/A	N	N	1993	1993	Installation record	UNL	C	C	NL		N/R	N					101-3910
4909 S LOTUS AVE	N/A	N	N	1997	1997	Installation record	UNL	C	C	NL		N/R	N					101-3991
4911 S LOTUS AVE	N/A	N	N	1997	1997	Installation record	UNL	C	C	NL		N/R	N					101-4000
4948 S LOTUS AVE	N/A	N	N	1986	1986	Installation record	UNL	C	C	NL		N/R	N					101-4160
4951 S LOTUS AVE	N/A	N	N			Record	U	UNL	UNL	NL		N/R	N					101-4180
5004 S LOTUS AVE	N/A	N	N	2001	2001	Installation record	UNL	C	C	NL		N/R	N					101-4210
5007 S LOTUS AVE	N/A	N	N	1994	1994	Installation record	UNL	C	C	NL		N/R	N					101-4240
5008 S LOTUS AVE	N/A	N	N	1998	1998	Installation record	UNL	C	C	NL		N/R	N					101-4250
5009 S LOTUS AVE	N/A	N	N	1993	1993	Installation record	UNL	C	C	NL		N/R	N					101-4260
5029 S LOTUS AVE	N/A	N	N	1991	1991	Installation record	UNL	C	C	NL		N/R	N					101-4330
5031 S LOTUS AVE	N/A	N	N	1991	1991	Installation record	UNL	C	C	NL		N/R	N					101-4350
5041 S LOTUS AVE	N/A	N	N	2001	2001	Installation record	UNL	C	C	NL		N/R	N					101-4391
5040 S LINDER AVE	N/A	N	N	1996	1996	Installation record	UNL	C	C	NL		N/R	N					101-4501
5038 S LINDER AVE	N/A	N	N	2007	2007	Installation record	UNL	C	C	NL		N/R	N					101-4510
5036 S LINDER AVE	N/A	N	N	1998	1998	Installation record	UNL	C	C	NL		N/R	N					101-4511
5034 S LINDER AVE	N/A	N	N	1998	1998	Installation record	UNL	C	C	NL		N/R	N					101-4541
5030 S LINDER AVE	N/A	N	N	1987	1987	Installation record	UNL	C	C	NL		N/R	N					101-4560
5028 S LINDER AVE	N/A	N	N	1986	1986	Installation record	UNL	C	C	NL		N/R	N					101-4570
5009 S LINDER AVE	N/A	N	N	2006	2006	Installation record	UNL	C	C	NL		N/R	N					101-4630
5001 S LINDER AVE	N/A	N	N	1996	1996	Installation record	UNL	C	C	NL		N/R	N					101-4661
4925 S LINDER AVE	N/A	N	N	2018	2018	Installation record	UNL	C	C	NL		N/R	N					101-4840
4921 S LINDER AVE	N/A	N	N	1992	1992	Installation record	UNL	C	C	NL		N/R	N					101-4860
4912 S LINDER AVE	N/A	N	N	2001	2001	Installation record	UNL	C	C	NL		N/R	N					101-4890
4858 S LINDER AVE	N/A	N	N	1984	1984	Installation record	UNL	C	C	NL		N/R	N					101-4950
4851 S LINDER AVE	N/A	N	N	2015	2015	Installation record	UNL	C	C	NL		N/R	N					101-4981
4849 S LINDER AVE	N/A	N	N	2014	2014	Installation record	UNL	C	C	NL		N/R	N					101-4990
4835 S LINDER AVE	N/A	N	N	2005	2005	Installation record	UNL	C	C	NL		N/R	N					101-5052
4827 S LINDER AVE	N/A	N	N	2005	2005	Installation record	UNL	C	C	NL		N/R	N					101-5070
4829 S LINDER AVE	N/A	N	N	2005	2005	Installation record	UNL	C	C	NL		N/R	N					101-5071
4816 S LINDER AVE	N/A	N	N	2009	2009	Installation record	UNL	C	C	NL		N/R	N					101-5110
4817 S LINDER AVE	N/A	N	N	2009	2009	Installation record	UNL	C	C	NL		N/R	N					101-5111
4814 S LINDER AVE	N/A	N	N	2008	2008	Installation record	UNL	C	C	NL		N/R	N					101-5115
4811 S LINDER AVE	N/A	N	N	2008	2008	Installation record	UNL	C	C	NL		N/R	N					101-5130
4812 S LINDER AVE	N/A	N	N	1999	1999	Installation record	UNL	C	C	NL		N/R	N					101-5140
4757 S LINDER AVE	N/A	N	N	1986	1986	Installation record	UNL	C	C	NL		N/R	N					101-5190
4752 S LINDER AVE	N/A	N	N	2000	2000	Installation record	UNL	C	C	NL		N/R	N					101-5231
4722 S LUNA AVE	N/A	N	N	2006	2006	Installation record	UNL	C	C	NL		N/R	N					101-5331
4724 S LUNA AVE	N/A	N	N	2004	2004	Installation record	UNL	C	C	NL		N/R	N					101-5341
4726 S LUNA AVE	N/A	N	N	2004	2004	Installation record	UNL	C	C	NL		N/R	N					101-5342



Lead Service Line Inventory Template	
--------------------------------------	--

*Please enter information in the empty box next to each section	Water System Name		Central Stickney Sanitary District			System ID Number:		IL0315570		Current Inventory Date:		4/15/26							
*Please enter totals in the empty box next to each category	Total Service lines:		746		Total Lead:	340		Total Non-Lead:	304		Total Galvanized Requiring replacement:		0		Total Unknown:	102		Website link to Material Inventory:	


Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)									
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacement (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)									
		Lead (L)					Galvanized Requiring Replacement (GRR)	Galvanized Requiring Replacement (GRR)	Non-Lead (NL)									
		Cast/Ductile Iron or Transite (Q)					Lead (L)	Lead (L)										
		Plastic - PVC, HDPE, PEX (P)					Cast/Ductile Iron or Transite (Q)	Cast/Ductile Iron or Transite (Q)										
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)																
Unknown Not Lead (UNL)	Unknown (U)	Unknown (U)																
							Unknown Not Lead (UNL)	Unknown Not Lead (UNL)	Unknown Not Lead (UNL)									
5000 S LARAMIE AVE	N/A	N	N			Record	U	C	C	NL		N/R	N					101-6610
5219 W 47TH STREET	N/A	N	N			Visual inspection	UNL	C	C	NL		N/R	N					101-0010
5203 W 47TH STREET	N/A	N	N				U	U	U	U		12/15/25	N					101-0011
5247 W 47TH STREET	N/A	N	N				U	U	U	U		12/15/25	N					101-0012
5235 W 47TH STREET	N/A	N	N				U	U	U	U		12/15/25	N					101-0013
4706 S LATROBE AVE	N/A	N	N	1961	1961	Installation record	L	L	L	L		12/15/25	N					101-0030
4708 S LATROBE AVE	N/A	N	N	1961	1961		U	U	U	U		12/15/25	N					101-0050
4710 S LATROBE AVE	N/A	N	N	1961	1961	Installation record	L	L	L	L		12/15/25	N					101-0060
4712 S LATROBE AVE	N/A	N	N	1961	1961	Installation record	L	L	L	L		12/15/25	N					101-0070
4721 S LATROBE AVE	N/A	N	N	1971	1971	Visual inspection	L	L	L	L		12/15/25	N					101-0080
4714 S LATROBE AVE	N/A	N	N	1961	1961	Installation record	L	L	L	L		12/15/25	N					101-0090
4723 S LATROBE AVE	N/A	N	N	1958	1958	Visual inspection	L	L	L	L		12/15/25	N					101-0100
4725 S LATROBE AVE	N/A	N	N	1958	1958	Visual inspection	L	L	L	L		12/15/25	N					101-0110
4716 S LATROBE AVE	N/A	N	N	1958	1958	Visual inspection	L	L	L	L		12/15/25	N					101-0120
4727 S LATROBE AVE	N/A	N	N			Visual inspection	L	L	L	L		12/15/25	N					101-0130
4718 S LATROBE AVE	N/A	N	N	1958	1958	Visual inspection	C	C	C	NL		N/R	N					101-0140
4729 S LATROBE AVE	N/A	N	N	1958	1958		U	U	U	U		12/15/25	N					101-0150
4720 S LATROBE AVE	N/A	N	N	1961	1961	Visual inspection	L	L	L	L		12/15/25	N					101-0160
4722 S LATROBE AVE	N/A	N	N	1961	1961	Visual inspection	L	L	L	L		12/15/25	N					101-0180
4724 S LATROBE AVE	N/A	N	N	1960	1960	Visual inspection	L	L	L	L		12/15/25	N					101-0190
4737 S LATROBE AVE	N/A	N	N	1958	1958		U	U	U	U		12/15/25	N					101-0200
4726 S LATROBE AVE	N/A	N	N	1958	1958	Visual inspection	L	L	L	L		12/15/25	N					101-0210
4741 S LATROBE AVE	N/A	N	N	1973	1973	Visual inspection	UNL	C	C	NL		N/R	N					101-0220
4728 S LATROBE AVE	N/A	N	N	1960	1960	Visual inspection	L	L	L	L		12/15/25	N					101-0230
4743 S LATROBE AVE	N/A	N	N	1975	1975	Visual inspection	UNL	C	C	NL		N/R	N					101-0240
4744 S LATROBE AVE	N/A	N	N	1945	1945	Visual inspection	L	L	L	L		12/15/25	N					101-0250
4748 S LATROBE AVE	N/A	N	N	1955	1955	Visual inspection	L	L	L	L		12/15/25	N					101-0260
4755 S LATROBE AVE	N/A	N	N	1959	1959	Visual inspection	L	L	L	L		12/15/25	N					101-0270
4752 S LATROBE AVE	N/A	N	N	1956	1956	Visual inspection	L	L	L	L		12/15/25	N					101-0280
4806 S LATROBE AVE	N/A	N	N	1943	1943	Visual inspection	UNL	C	C	NL		N/R	N					101-0300
4808 S LATROBE AVE	N/A	N	N	1942	1942	Visual inspection	L	L	L	L		12/15/25	N					101-0310
4807 S LATROBE AVE	N/A	N	N	1943	1943	Visual inspection	L	L	L	L		12/15/25	N					101-0320
4810 S LATROBE AVE	N/A	N	N	1955	1955	Visual inspection	L	L	L	L		12/15/25	N					101-0330
4811 S LATROBE AVE	N/A	N	N	1971	1971	Visual inspection	UNL	C	C	NL		N/R	N					101-0340
4812 S LATROBE AVE	N/A	N	N	1948	1948	Visual inspection	UNL	C	C	NL		N/R	N					101-0350
4813 S LATROBE AVE	N/A	N	N	1960	1960	Visual inspection	L	L	L	L		12/15/25	N					101-0360
4814 S LATROBE AVE	N/A	N	N	1945	1945	Visual inspection	UNL	C	C	NL		N/R	N					101-0370
4815 S LATROBE AVE	N/A	N	N	1960	1960		U	U	U	U		12/15/25	N					101-0380
4816 S LATROBE AVE	N/A	N	N	1949	1949	Visual inspection	L	L	L	L		12/15/25	N					101-0390
4817 S LATROBE AVE	N/A	N	N	1960	1960	Visual inspection	L	L	L	L		12/15/25	N					101-0400
4818 S LATROBE AVE	N/A	N	N	1954	1954		U	U	U	U		12/15/25	N					101-0410




Lead Service Line Inventory Template	
--------------------------------------	--

*Please enter information in the empty box next to each section	Water System Name		Central Stickney Sanitary District			System ID Number:		IL0315570		Current Inventory Date:		4/15/26							
*Please enter totals in the empty box next to each category	Total Service lines:		746		Total Lead:	340		Total Non-Lead:	304		Total Galvanized Requiring replacement:		0		Total Unknown:	102		Website link to Material Inventory:	

Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)									
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacement (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)									
		Lead (L)					Galvanized Requiring Replacement (GRR)	Galvanized Requiring Replacement (GRR)	Non-Lead (NL)									
		Cast/Ductile Iron or Transite (Q)					Lead (L)	Lead (L)										
		Plastic - PVC, HDPE, PEX (P)					Cast/Ductile Iron or Transite (Q)	Cast/Ductile Iron or Transite (Q)										
		Unknown (U)					Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)										
Unknown Not Lead (UNL)	Unknown (U)	Unknown (U)																
						Unknown Not Lead (UNL)												
4819 S LATROBE AVE	N/A	N	N	1962	1962	Visual inspection	L	L	L	L		12/15/25	N					101-0420
4821 S LATROBE AVE	N/A	N	N	1960	1960	Visual inspection	L	L	L	L		12/15/25	N				101-0430	
4832 S LATROBE AVE	N/A	N	N	1952	1952	Visual inspection	L	L	L	L		12/15/25	N				101-0440	
4823 S LATROBE AVE	N/A	N	N	1960	1960	Visual inspection	UNL	C	C	NL			N				101-0450	
4839 S LATROBE AVE	N/A	N	N	1961	1961	Visual inspection	L	L	L	L		12/15/25	N				101-0460	
4836 S LATROBE AVE	N/A	N	N	1938	1938	Visual inspection	L	L	L	L		12/15/25	N				101-0470	
4841 S LATROBE AVE	N/A	N	N	1928	1928	Visual inspection	L	L	L	L		12/15/25	N				101-0480	
4838 S LATROBE AVE	N/A	N	N	1950	1950		U	U	U	U		12/15/25	N				101-0490	
4843 S LATROBE AVE	N/A	N	N	1955	1955	Visual inspection	L	L	L	L		12/15/25	N				101-0500	
4840 S LATROBE AVE	N/A	N	N	1933	1933	Visual inspection	L	L	L	L		12/15/25	N				101-0510	
4848 S LATROBE AVE	N/A	N	N	1940	1940	Visual inspection	L	L	L	L		12/15/25	N				101-0530	
1/2 LATROBE AVE 4845	N/A	N	N				U	U	U	U		12/15/25	N				101-0540	
4847 S LATROBE AVE	N/A	N	N	1946	1946		U	U	U	U		12/15/25	N				101-0550	
4852 S LATROBE AVE	N/A	N	N			Visual inspection	L	L	L	L		12/15/25	N				101-0560	
4849 S LATROBE AVE	N/A	N	N	1946	1946		U	U	U	U		12/15/25	N				101-0561	
4854 S LATROBE AVE	N/A	N	N	1959	1959	Visual inspection	UNL	C	C	NL		N/R	N				101-0570	
4856 S LATROBE AVE	N/A	N	N	1918	1918	Visual inspection	L	L	L	L		12/15/25	N				101-0590	
4900 S LATROBE AVE	N/A	N	N	1943	1943	Visual inspection	L	L	L	L		12/15/25	N				101-0600	
4902 S LATROBE AVE	N/A	N	N	1936	1936	Visual inspection	UNL	C	C	NL		N/R	N				101-0610	
4903 S LATROBE AVE	N/A	N	N	1936	1936	Visual inspection	UNL	C	C	NL		N/R	N				101-0620	
4904 S LATROBE AVE	N/A	N	N	1938	1938		U	U	U	U		12/15/25	N				101-0640	
4906 S LATROBE AVE	N/A	N	N				U	U	U	U		12/15/25	N				101-0641	
4907 S LATROBE AVE	N/A	N	N	1936	1936	Visual inspection	UNL	C	C	NL		N/R	N				101-0650	
4908 S LATROBE AVE	N/A	N	N	1949	1949	Visual inspection	UNL	C	C	NL		N/R	N				101-0660	
4909 S LATROBE AVE	N/A	N	N	1936	1936	Visual inspection	UNL	C	C	NL		N/R	N				101-0670	
4912 S LATROBE AVE	N/A	N	N	1934	1934	Visual inspection	L	L	L	L		12/15/25	N				101-0680	
4915 S LATROBE AVE	N/A	N	N	1957	1957		U	U	U	U		12/15/25	N				101-0690	
4918 S LATROBE AVE	N/A	N	N	1938	1938		U	U	U	U		12/15/25	N				101-0710	
4920 S LATROBE AVE	N/A	N	N	1954	1954		U	U	U	U		12/15/25	N				101-0720	
4923 S LATROBE AVE	N/A	N	N	1919	1919	Visual inspection	L	L	L	L		12/15/25	N				101-0730	
4922 S LATROBE AVE	N/A	N	N	1941	1941	Visual inspection	UNL	C	C	NL			N				101-0740	
4925 S LATROBE AVE	N/A	N	N	1959	1959	Visual inspection	L	L	L	L		12/15/25	N				101-0750	
4938 S LATROBE AVE	N/A	N	N	1968	1968	Visual inspection	UNL	C	C	NL		N/R	N				101-0770	
4927 S LATROBE AVE	N/A	N	N	1954	1954	Visual inspection	L	L	L	L		12/15/25	N				101-0780	
4940 S LATROBE AVE	N/A	N	N	1935	1935	Visual inspection	L	L	L	L		12/15/25	N				101-0790	
4941 S LATROBE AVE	N/A	N	N	1949	1949	Visual inspection	L	L	L	L		12/15/25	N				101-0800	
4942 S LATROBE AVE	N/A	N	N	1967	1967		U	U	U	U		12/15/25	N				101-0810	
4944 S LATROBE AVE	N/A	N	N	1966	1966	Visual inspection	L	L	L	L		12/15/25	N				101-0830	
4952 S LATROBE AVE	N/A	N	N	1956	1956	Visual inspection	L	L	L	L		12/15/25	N				101-0850	
4957 S LATROBE AVE	N/A	N	N	1957	1957	Visual inspection	L	L	L	L		12/15/25	N				101-0860	
4956 S LATROBE AVE	N/A	N	N	1944	1944	Visual inspection	UNL	C	C	NL		N/R	N				101-0870	










Lead Service Line Inventory Template	
--------------------------------------	--

*Please enter information in the empty box next to each section	Water System Name		Central Stickney Sanitary District			System ID Number:		IL0315570		Current Inventory Date:		4/15/26							
*Please enter totals in the empty box next to each category	Total Service lines:		746		Total Lead:	340		Total Non-Lead:	304		Total Galvanized Requiring replacement:		0		Total Unknown:	102		Website link to Material Inventory:	

Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	EXAMPLES:	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)						Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)								
		Copper - Lead Solder (CLS)						Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacement (GRR)								
		Galvanized (G)						Galvanized (G)	Galvanized (G)	Unknown (U)								
		Lead (L)						Galvanized Requiring Replacement (GRR)	Galvanized Requiring Replacement (GRR)	Non-Lead (NL)								
		Cast/Ductile Iron or Transite (O)						Lead (L)	Lead (L)									
		Plastic - PVC, HDPE, PEX (P)						Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)									
		Unknown (U)						Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)									
Unknown Not Lead (UNL)	Unknown (U)	Unknown (U)																
							Unknown Not Lead (UNL)	Unknown Not Lead (UNL)	Unknown Not Lead (UNL)									
4814 S LOCKWOOD AVE	N/A	N	N	1958	1958	Visual inspection	L	L	L	L		12/15/25	N					101-1790
4811 S LOCKWOOD AVE	N/A	N	N	1953	1953		U	U	U	U		12/15/25	N					101-1800
4812 S LOCKWOOD AVE	N/A	N	N	1959	1959	Visual inspection	L	L	L	L		12/15/25	N					101-1810
4810 S LOCKWOOD AVE	N/A	N	N	1946	1946	Visual inspection	UNL	C	C	NL		N/R	N					101-1820
4806 S LOCKWOOD AVE	N/A	N	N	1960	1960	Visual inspection	L	L	L	L		12/15/25	N					101-1840
4804 S LOCKWOOD AVE	N/A	N	N	1960	1960	Visual inspection	L	L	L	L		12/15/25	N					101-1850
4803 S LOCKWOOD AVE	N/A	N	N	1944	1944	Visual inspection	L	L	L	L		12/15/25	N					101-1860
4802 S LOCKWOOD AVE	N/A	N	N	1960	1960	Visual inspection	L	L	L	L		12/15/25	N					101-1870
4800 S LOCKWOOD AVE	N/A	N	N	1960	1960	Visual inspection	L	L	L	L		12/15/25	N					101-1890
4759 S LOCKWOOD AVE	N/A	N	N	1944	1944		U	U	U	U		12/15/25	N					101-1900
4756 S LOCKWOOD AVE	N/A	N	N	1943	1943	Visual inspection	L	L	L	L		12/15/25	N					101-1910
4755 S LOCKWOOD AVE	N/A	N	N	1942	1942		U	U	U	U		12/15/25	N					101-1920
4745 S LOCKWOOD AVE	N/A	N	N	1965	1965		U	U	U	U		12/15/25	N					101-1930
4743 S LOCKWOOD AVE	N/A	N	N	1945	1945	Visual inspection	L	L	L	L		12/15/25	N					101-1950
4744 S LOCKWOOD AVE	N/A	N	N	1943	1943	Visual inspection	UNL	C	C	NL		N/R	N					101-1960
4742 S LOCKWOOD AVE	N/A	N	N	1951	1951	Visual inspection	L	L	L	L		12/15/25	N					101-1970
4720 S LOCKWOOD AVE	N/A	N	N	1960	1960	Visual inspection	C	C	C	NL		N/R	N					101-2000
4735 S LOCKWOOD AVE	N/A	N	N	1967	1967	Visual inspection	L	L	L	L		12/15/25	N					101-2010
4716 S LOCKWOOD AVE	N/A	N	N	1958	1958	Visual inspection	L	L	L	L		12/15/25	N					101-2020
4714 S LOCKWOOD AVE	N/A	N	N	1961	1961	Installation record	L	L	L	L		12/15/25	N					101-2040
4712 S LOCKWOOD AVE	N/A	N	N	1960	1960	Installation record	L	L	L	L		12/15/25	N					101-2050
4710 S LOCKWOOD AVE	N/A	N	N	1958	1958		U	U	U	U		12/15/25	N					101-2060
4711 S LOCKWOOD AVE	N/A	N	N	1961	1961	Installation record	L	L	L	L		12/15/25	N					101-2070
4708 S LOCKWOOD AVE	N/A	N	N	1960	1960		U	U	U	U		12/15/25	N					101-2080
4707 S LOCKWOOD AVE	N/A	N	N	1960	1960	Installation record	C	C	C	NL		N/R	N					101-2090
4706 S LOCKWOOD AVE	N/A	N	N	1958	1958		U	U	U	U		12/15/25	N					101-2100
4705 S LOCKWOOD AVE	N/A	N	N	1958	1958	Visual inspection	L	L	L	L		12/15/25	N					101-2110
4705 S LOREL AVE	N/A	N	N	1958	1958		U	U	U	U		12/15/25	N					101-2120
4707 S LOREL AVE	N/A	N	N	1958	1958	Installation record	L	L	L	L		12/15/25	N					101-2130
4709 S LOREL AVE	N/A	N	N	1958	1958		U	U	U	U		12/15/25	N					101-2140
4711 S LOREL AVE	N/A	N	N	1958	1958	Installation record	L	L	L	L		12/15/25	N					101-2150
4737 S LOREL AVE	N/A	N	N	1956	1956	Visual inspection	L	L	L	L		12/15/25	N					101-2160
4740 S LOREL AVE	N/A	N	N	1957	1957	Visual inspection	UNL	C	C	NL		N/R	N					101-2180
4744 S LOREL AVE	N/A	N	N	1978	1978	Visual inspection	L	L	L	L		12/15/25	N					101-2190
4743 S LOREL AVE	N/A	N	N	1953	1953	Visual inspection	UNL	C	C	NL		N/R	N					101-2200
4748 S LOREL AVE	N/A	N	N			Visual inspection	L	L	L	L		12/15/25	N					101-2220
4749 S LOREL AVE	N/A	N	N	1961	1961	Visual inspection	L	L	L	L		12/15/25	N					101-2230
4750 S LOREL AVE	N/A	N	N				U	U	U	U		12/15/25	N					101-2231
4751 S LOREL AVE	N/A	N	N	1960	1960	Visual inspection	L	L	L	L		12/15/25	N					101-2240
4752 S LOREL AVE	N/A	N	N			Visual inspection	L	L	L	L		12/15/25	N					101-2260
4758 S LOREL AVE	N/A	N	N	1966	1966	Visual inspection	L	L	L	L		12/15/25	N					101-2270









Lead Service Line Inventory Template	
--------------------------------------	--

*Please enter information in the empty box next to each section	Water System Name		Central Stickney Sanitary District			System ID Number:		IL0315570		Current Inventory Date:		4/15/26							
*Please enter totals in the empty box next to each category	Total Service lines:		746		Total Lead:	340		Total Non-Lead:	304		Total Galvanized Requiring replacement:		0		Total Unknown:	102		Website link to Material Inventory:	

Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If / Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)									
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacement (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)									
		Lead (L)					Galvanized Requiring Replacement (GRR)	Galvanized Requiring Replacement (GRR)	Non-Lead (NL)									
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)										
		Plastic - PVC, HDPE, PEX (P)					Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)										
		Unknown (U)					Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)										
		Unknown Not Lead (UNL)					Unknown (U)	Unknown (U)										
									Unknown Not Lead (UNL)	Unknown Not Lead (UNL)					Unknown Not Lead (UNL)			
4725 S LUNA AVE	N/A	N	N	1977	1977	Visual inspection	UNL	C	C	NL		N/R	N					101-5350
4727 S LUNA AVE	N/A	N	N	1977	1977	Visual inspection	UNL	C	C	NL		N/R	N					101-5360
4744 S LUNA AVE	N/A	N	N	1966	1966	Visual inspection	UNL	C	C	NL		N/R	N					101-5380
4746 S LUNA AVE	N/A	N	N	1965	1965	Visual inspection	UNL	C	C	NL		N/R	N					101-5390
4745 S LUNA AVE	N/A	N	N	1965	1965	Visual inspection	UNL	C	C	NL		N/R	N					101-5400
4748 S LUNA AVE	N/A	N	N	1969	1969	Visual inspection	L	L	L	L		12/15/25	N					101-5410
4747 S LUNA AVE	N/A	N	N	1965	1965		U	U	U	U		12/15/25	N					101-5420
4749 S LUNA AVE	N/A	N	N	1966	1966	Visual inspection	UNL	C	C	NL		N/R	N					101-5440
4751 S LUNA AVE	N/A	N	N	1966	1966	Visual inspection	UNL	C	C	NL		N/R	N					101-5460
4753 S LUNA AVE	N/A	N	N	1966	1966	Visual inspection	UNL	C	C	NL		N/R	N					101-5470
4756 S LUNA AVE	N/A	N	N	1957	1957	Visual inspection	L	L	L	L		12/15/25	N					101-5480
4755 S LUNA AVE	N/A	N	N	1965	1965		U	U	U	U		12/15/25	N					101-5490
4759 S LUNA AVE	N/A	N	N	1953	1953	Visual inspection	L	L	L	L		12/15/25	N					101-5500
4758 S LUNA AVE	N/A	N	N	1959	1959	Visual inspection	UNL	C	C	NL		N/R	N					101-5510
4801 S LUNA AVE	N/A	N	N	1950	1950	Visual inspection	L	L	L	L		12/15/25	N					101-5520
4805 S LUNA AVE	N/A	N	N	1978	1978	Visual inspection	L	L	L	L		12/15/25	N					101-5530
4809 S LUNA AVE	N/A	N	N	1948	1948	Visual inspection	UNL	C	C	NL		N/R	N					101-5550
4812 S LUNA AVE	N/A	N	N	1966	1966	Visual inspection	L	L	L	L		12/15/25	N					101-5560
4813 S LUNA AVE	N/A	N	N	1952	1952	Visual inspection	L	L	L	L		12/15/25	N					101-5570
4826 S LUNA AVE	N/A	N	N	1966	1966	Visual inspection	L	L	L	L		12/15/25	N					101-5580
4833 S LUNA AVE	N/A	N	N	1953	1953	Visual inspection	L	L	L	L		12/15/25	N					101-5590
4828 S LUNA AVE	N/A	N	N	1966	1966	Visual inspection	UNL	C	C	NL		N/R	N					101-5600
4830 S LUNA AVE	N/A	N	N	1960	1960	Visual inspection	L	L	L	L		12/15/25	N					101-5610
4835 S LUNA AVE	N/A	N	N	1952	1952	Visual inspection	L	L	L	L		12/15/25	N					101-5620
4832 S LUNA AVE	N/A	N	N	1960	1960	Visual inspection	L	L	L	L		12/15/25	N					101-5630
4834 S LUNA AVE	N/A	N	N	1972	1972	Visual inspection	L	L	L	L		12/15/25	N					101-5650
4836 S LUNA AVE	N/A	N	N	1972	1972	Visual inspection	L	L	L	L		12/15/25	N					101-5670
4840 S LUNA AVE	N/A	N	N	1972	1972	Visual inspection	L	L	L	L		12/15/25	N					101-5690
4842 S LUNA AVE	N/A	N	N	1966	1966	Visual inspection	UNL	C	C	NL		N/R	N					101-5710
4849 S LUNA AVE	N/A	N	N	1961	1961	Visual inspection	L	L	L	L		12/15/25	N					101-5720
4844 S LUNA AVE	N/A	N	N	1966	1966	Visual inspection	UNL	C	C	NL		N/R	N					101-5730
4851 S LUNA AVE	N/A	N	N	1966	1966	Visual inspection	UNL	C	C	NL		N/R	N					101-5740
4846 S LUNA AVE	N/A	N	N	1961	1961	Visual inspection	UNL	C	C	NL		N/R	N					101-5750
4848 S LUNA AVE	N/A	N	N	1961	1961	Visual inspection	L	L	L	L		12/15/25	N					101-5760
4860 S LUNA AVE	N/A	N	N	1960	1960	Visual inspection	UNL	C	C	NL		N/R	N					101-5780
4901 S LUNA AVE	N/A	N	N	1950	1950	Visual inspection	UNL	C	C	NL		N/R	N					101-5790
4900 S LUNA AVE	N/A	N	N	1978	1978	Visual inspection	L	L	L	L		12/15/25	N					101-5800
4905 S LUNA AVE	N/A	N	N			Visual inspection	UNL	C	C	NL		N/R	N					101-5820
4911 S LUNA AVE	N/A	N	N	1949	1949		U	U	U	U		12/15/25	N					101-5830
4908 S LUNA AVE	N/A	N	N	1950	1950	Visual inspection	UNL	C	C	NL		N/R	N					101-5840
4912 S LUNA AVE	N/A	N	N	1964	1964	Visual inspection	L	L	L	L		12/15/25	N					101-5860



Lead Service Line Inventory Template	
--------------------------------------	--

*Please enter information in the empty box next to each section	Water System Name		Central Stickney Sanitary District			System ID Number:		IL0315570		Current Inventory Date:		4/15/26							
*Please enter totals in the empty box next to each category	Total Service lines:		746		Total Lead:	340		Total Non-Lead:	304		Total Galvanized Requiring replacement:		0		Total Unknown:	102		Website link to Material Inventory:	

Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA". If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.	
		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)									
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacement (GRR)									
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)									
		Lead (L)					Galvanized Requiring Replacement (GRR)	Galvanized Requiring Replacement (GRR)	Non-Lead (NL)									
		Cast/Ductile Iron or Transite (Q)					Lead (L)	Lead (L)										
		Plastic - PVC, HDPE, PEX (P)					Cast/Ductile Iron or Transite (Q)	Cast/Ductile Iron or Transite (Q)										
Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)																
Unknown Not Lead (UNL)	Unknown (U)	Unknown (U)																
							Unknown Not Lead (UNL)	Unknown Not Lead (UNL)	Unknown Not Lead (UNL)									
4914 S LUNA AVE	N/A	N	N	1964	1964	Visual inspection	UNL	C	C	NL		N/R	N					101-5880
4918 S LUNA AVE	N/A	N	N	1952	1952	Visual inspection	UNL	C	C	NL		N/R	N					101-5890
4917 S LUNA AVE	N/A	N	N	1950	1950	Visual inspection	L	L	L			12/15/25	N					101-5900
4931 S LUNA AVE	N/A	N	N	1973	1973	Visual inspection	L	L	L			12/15/25	N					101-5910
4930 S LUNA AVE	N/A	N	N	1966	1966	Visual inspection	L	L	L			12/15/25	N					101-5920
4933 S LUNA AVE	N/A	N	N	1973	1973	Visual inspection	L	L	L			12/15/25	N					101-5930
4932 S LUNA AVE	N/A	N	N	1954	1954	Visual inspection	L	L	L			12/15/25	N					101-5940
4935 S LUNA AVE	N/A	N	N	1949	1949	Visual inspection	UNL	C	C	NL		N/R	N					101-5950
4949 S LUNA AVE	N/A	N	N	1951	1951	Visual inspection	L	L	L			12/15/25	N					101-5960
4934 S LUNA AVE	N/A	N	N	1951	1951	Visual inspection	UNL	C	C	NL		N/R	N					101-5970
4951 S LUNA AVE	N/A	N	N	1947	1947		U	U	U			12/15/25	N					101-5980
4936 S LUNA AVE	N/A	N	N	1972	1972	Visual inspection	L	L	L			12/15/25	N					101-5990
4938 S LUNA AVE	N/A	N	N	1972	1972	Visual inspection	UNL	C	C	NL		N/R	N					101-6000
4948 S LUNA AVE	N/A	N	N	1950	1950	Visual inspection	UNL	C	C	NL		N/R	N					101-6010
4953 S LUNA AVE	N/A	N	N	1952	1952	Visual inspection	L	L	L			12/15/25	N					101-6020
4952 S LUNA AVE	N/A	N	N	1950	1950	Visual inspection	L	L	L			12/15/25	N					101-6030
4955 S LUNA AVE	N/A	N	N	1946	1946	Visual inspection	L	L	L			12/15/25	N					101-6040
4956 S LUNA AVE	N/A	N	N	1952	1952	Visual inspection	UNL	C	C	NL		N/R	N					101-6050
4959 S LUNA AVE	N/A	N	N	1962	1962	Visual inspection	L	L	L			12/15/25	N					101-6060
5001 S LUNA AVE	N/A	N	N				U	U	U			12/15/25	N					101-6061
5005 S LUNA AVE	N/A	N	N	1972	1972	Visual inspection	L	L	L			12/15/25	N					101-6070
5007 S LUNA AVE	N/A	N	N	1972	1972	Visual inspection	UNL	C	C	NL		N/R	N					101-6090
5011 S LUNA AVE	N/A	N	N	1971	1971	Visual inspection	L	L	L			12/15/25	N					101-6110
5013 S LUNA AVE	N/A	N	N	1972	1972	Visual inspection	L	L	L			12/15/25	N					101-6120
5018 S LUNA AVE	N/A	N	N	1978	1978	Visual inspection	L	L	L			12/15/25	N					101-6150
5033 S LUNA AVE	N/A	N	N	1948	1948	Visual inspection	UNL	C	C	NL		N/R	N					101-6160
5022 S LUNA AVE	N/A	N	N	1956	1956	Visual inspection	L	L	L			12/15/25	N					101-6170
5037 S LUNA AVE	N/A	N	N	1960	1960	Visual inspection	UNL	C	C	NL		N/R	N					101-6180
5026 S LUNA AVE	N/A	N	N	1944	1944	Visual inspection	L	L	L			12/15/25	N					101-6190
5039 S LUNA AVE	N/A	N	N				U	U	U			12/15/25	N					101-6200
5030 S LUNA AVE	N/A	N	N	1967	1967	Visual inspection	L	L	L			12/15/25	N					101-6210
5032 S LUNA AVE	N/A	N	N	1967	1967	Visual inspection	L	L	L			12/15/25	N					101-6220
5045 S LUNA AVE	N/A	N	N	1924	1924	Visual inspection	L	L	L			12/15/25	N					101-6230
5034 S LUNA AVE	N/A	N	N	1918	1918	Visual inspection	L	L	L			12/15/25	N					101-6240
5036 S LUNA AVE	N/A	N	N	1967	1967		U	U	U			12/15/25	N					101-6250
5040 S LUNA AVE	N/A	N	N	1957	1957	Visual inspection	L	L	L			12/15/25	N					101-6260
5049 S LUNA AVE	N/A	N	N	1922	1922	Visual inspection	UNL	C	C	NL		N/R	N					101-6270
5051 S LUNA AVE	N/A	N	N	1960	1960	Visual inspection	L	L	L			12/15/25	N					101-6280
5053 S LUNA AVE	N/A	N	N	1960	1960	Visual inspection	L	L	L			12/15/25	N					101-6300
5058 S LUNA AVE	N/A	N	N	1933	1933	Visual inspection	L	L	L			12/15/25	N					101-6310
5055 S LUNA AVE	N/A	N	N	1960	1960	Visual inspection	L	L	L			12/15/25	N					101-6320

 Illinois Environmental Protection Agency																		
Lead Service Line Inventory Template																		
*Please enter information in the empty box next to each section	Water System Name			Central Stickney Sanitary District			System ID Number:		IL0315570		Current Inventory Date:		4/15/26					
*Please enter totals in the empty box next to each category	Total Service lines:			746	Total Lead:	340	Total Non-Lead:	304	Total Galvanized Requiring replacement:		0	Total Unknown:	102	Website link to Material Inventory:				
Service Address	Lead and Copper Sample site number.	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property	Water Account Number
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA". / If address is not a lead and copper sample site mark "N/A"	EXAMPLES:	Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES:	EXAMPLES:	EXAMPLES:	EXAMPLES:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.	
							Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)					Copper - No Lead Solder (C)			
							Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacement (GRR)					Galvanized (G)			
							Galvanized (G)	Galvanized (G)	Galvanized (G)	Unknown (U)								
							Lead (L)	Galvanized Requiring Replacement (GRR)	Galvanized Requiring Replacement (GRR)	Non-Lead (NL)								
							Cast/Ductile Iron or Transite (O)	Lead (L)	Lead (L)									
							Plastic - PVC, HDPE, PEX (P)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)									
							Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)									
							Unknown Not Lead (UNL)	Unknown (U)	Unknown (U)									
								Unknown Not Lead (UNL)	Unknown Not Lead (UNL)									
5055 S CENTRAL AVE	N/A	N	N	1916	1916		U	U	U	U		12/15/25	N					101-6330
5051 S CENTRAL AVE	N/A	N	N	1941	1941	Visual inspection	L	L	L	L		12/15/25	N					101-6350
5047 S CENTRAL AVE	N/A	N	N			Visual inspection	L	L	L	L		12/15/25	N					101-6360
5027 S CENTRAL AVE	N/A	N	N	1947	1947	Visual inspection	UNL	C	C	NL		N/R	N					101-6370
5017 1/2 S CENTRAL AVE	N/A	N	N				U	U	U	U		12/15/25	N					101-6400
5015 S CENTRAL AVE	N/A	N	N	1928	1928	Visual inspection	L	L	L	L		12/15/25	N					101-6420
4901 S CENTRAL AVE	N/A	N	N				U	U	U	U		12/15/25	N					101-6475
4835 S CENTRAL AVE	N/A	N	N	1957	1957		U	U	U	U		12/15/25	N					101-6500