

Home Inspectors Pro (424) 281-6940

SEWER INSPECTION REPORT

Purpose:

GENERAL INSPECTION

Recommended Action:

RECOMMEND YEARLY MAINTENANCE/CLEANING

Summary:

MAIN SEWER DRAIN LINE WAS ACCESSED AT ROOF SEWER VENT. SEWER MAIN DRAIN IS MADE OF CAST IRON AND CLAY TO FOLLOW. UPON INSPECTION OF THE SEWER LINE SEWER DRAIN WAS IN SERVICEABLE CONDITION AT THE TIME OF THE INSPECTION WITH NO SIGNS OF ROOTS OR OBSTRUCTIONS.

Location

sample address

Inspector

sample inspector



3/13/2018 2:20:43 PM

0' 0"



3/13/2018 2:20:55 PM

77' 4"



3/13/2018 2:21:24 PM

61' 9"



3/13/2018 2:21:34 PM

56' 4"



3/13/2018 2:22:42 PM

38' 4"



3/13/2018 2:22:59 PM

33' 8"



3/13/2018 2:23:22 PM

31' 9"



3/13/2018 2:23:58 PM

21' 1"