

** WARNING! Editing this file can cause it to become unusable with the Radon software.

Software Version: 2.2.0

File Revision: A

Sun Nuclear Corporation

Continuous Radon Monitor: 1028

Serial Number: 211749021

Calibration Factor 1: 2.99681

Calibration Factor 2: -1

Calibration Date: 01/13/2017

Mitigation System Installed: 0

Mitigation System Working: 0

Inspection Company:

Name:

Company Name: Company Name

Address 1: None

Address 2: None

City: None

State: None

Zip: 00000

Phone: 321-123-4567

License Number: None

Customer Billing Information:

Name: Scott Frey

Address 1: 2408 Center Point Rd

Address 2:

City: Hendersonville

State: TN

Zip: 37075

Phone : 6156682821

Customer Site Information

Name: Scott Frey

Address 1: 2408 Center Point Rd

Address 2:

City: Hendersonville

State: TN

Zip: 37075

Phone : 6156682821

Battery: 8.7

Measurement Interval Index: 0

Duration Interval Index: 10

Unit Index: 1

Delay Index: 0

Number of Measurements: 73

Date: 02/19/2017

Time Counts Flags

pCi/l

19:59 0.0

20:59 0.0

21:59 0.0

22:59 4.0

23:59 3.0

Date: 02/20/2017

Time Counts Flags

pCi/l

00:59 6.0

01:59 2.0

02:59 2.0

03:59 11.0

04:59 11.0

05:59 10.0

06:59 11.0

07:59 15.0

08:59 19.0

09:59 17.0

10:59 18.0

11:59 12.0

12:59 24.0

13:59 18.0

14:59 16.0

15:59 19.0

16:59 15.0

17:59 7.0

18:59 11.0

19:59 7.0

20:59 4.0

21:59 5.0

22:59 7.0

23:59 1.0

Date: 02/21/2017

Time Counts Flags

pCi/l

00:59 2.0

01:59 4.0

02:59 7.0

03:59 9.0

04:59 3.0

05:59 2.0

06:59 7.0

07:59 12.0

08:59 4.0

09:59 5.0

10:59 4.0

11:59 9.0

12:59 7.0

13:59 12.0

14:59 12.0

15:59 6.0

16:59 4.0

17:59 7.0

18:59 3.0

19:59 0.0

20:59 3.0

21:59 6.0

22:59 6.0

23:59 2.0

Date: 02/22/2017

Time Counts Flags

pCi/l

00:59 4.0

01:59 1.0

02:59 1.0

03:59 1.0

04:59 6.0

05:59 5.0

06:59 3.0

07:59 3.0

08:59 6.0

09:59 4.0

10:59 4.0

11:59 6.0

12:59 7.0

13:59 6.0

14:59 5.0

15:59 6.0

16:59 9.0

17:59 11.0

18:59 9.0

