

Drews Creek Irrigation Diversion Dam



Exhibit 1: October 2019 – Irrigation Diversion looking upstream to the northwest. Boards are in place to divert water to meadow. White tube is a fish return pipe connected to fish screen.



Exhibit 4: June 2020 – Photo showing irrigation water intake and fish screen.



Exhibit 3: June 2020 – Irrigation Diversion looking to the northwest as drop boards are in place diverting water to the east ditch system. Erosion around structure as high spring flows overtop dam.



Exhibit 2: October 2019 – Irrigation Diversion looking downstream to the south. Tarp is used to support leaky drop boards. Structure will be replaced with a fish ladder constructed west side of diversion.