

Historic Property Survey Summary

County: **Forsyth**

SSN: **FY00725**

Blockface#:

Quad: Kernersville
PIN:
X: -80.0801 Y: 36.11420
DOT Project #:
OSA#:

Update Mo: **06** Yr: **2007**

No Alt
 Alt
 Det
 Rehab
 Removed
 Outbldg Loss
 No Acc.
 Not Fnd
 FileMsg
 Newly ID'd
 Needs Resch.

Property Name: Rufus Hastings House
Street or 911 Address: 601 S. Main St
Location Description:
Town/vicinity: Kernersville
District: South Main Street Historic District (NR District) Contributing Building
District Dates: NRdate: 2/25/1988 SLdate: DOEdate:
Local District:

<input type="checkbox"/> Recommended for SL	<input type="checkbox"/> StudyList	SLDate:	<input type="checkbox"/> NR	NRDate:	NR #
<input type="checkbox"/> DOE	DOEdate:	DOE Type:	Local Status	Local#:	Ownership: Private

Principal Resource Material Integrity: **High** Condition: **Good** Location Integrity: **Original**

Architectural Data: Date: ca. 1880s	Major Style Group: 19th-20th c. trad/vern
Construction: Balloon Frame	
Ext. Material: Weatherboard:Plain	Later Covering: None
Height: 2 story Roof: Side Gable Plan: Center passage Core Form (Domestic): I-House	
1st Design Source and attribution: Unknown	

Major Theme	2nd Theme:
Group Association:	Religious Affiliation
Historic Function: Domestic - single dwelling	

Written Summary

This weatherboarded I-house has a hip-roofed front porch with turned posts, elaborate sawnwork brackets, a spindle frieze, a sawtooth cornice with turned pendants, and a wooden railing; original two-over-two sash windows; a bracketed cornice with gable end returns; a pressed metal shingle roof; a brick chimney with a corbelled stack on the south elevation; and a one-story rear ell with six-over-sash windows and shed addition on its south elevation. Five frame outbuildings were included in the National Register nomination; only two are still extant (HF).

Outbuildings/Features

FeatureType	Material	CircaDate	Condition	Contrib
Shed - general storage front-gable, metal roof; German siding; two front doors	Frame	1930	Good	C
Garage front-gable, metal roof; German siding; double-leaf door	Frame	1930	Good	C

Actions

Year	Month	Surveyor	Action/Report
1979	10	Taylor, Gwynne	Original County/Municipal Survey
1987	10	Oswald, Virginia	Survey for NRHD nomination
2007	06	Fearnbach, Heather, EPE	Survey Update